

Lot: C1

COMFORTDELGRO ENGINEERING PTE LTD

Date: 18.05.2018

Time: 14:23:54

REPAIR ESTIMATE

Page: 1

FWD-CP(P)

TS
13 Fri

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305161828
 REGN NO : SH 8382C
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 28.07.2016
 DATE/TIME IN : 18.05.2018 02:00
 ACCIDENT DATE : 18.05.2018

1430

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	REAR BUMPER	1	603.60	20.00	482.88	DE ✓
0002	04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	225.00	20.00	180.00	X
0003	04-01-0103-0739-G	REAR BUMPER SPONGE	1	143.40	20.00	114.72	?
0004	04-01-0103-0740-G	REAR BUMPER REINFORCMENT	1	504.30	20.00	403.44	?
0005	04-01-0103-0743-G	REAR BUMPER REIN-BRKT RH	1	180.00	20.00	144.00	?
0006	04-01-0103-0783-G	REAR BUMPER SIDE BRKT RH	1	49.00	20.00	39.20	na ✓
0007	04-01-0103-0852-G	REAR BUMPER REFLECTOR RH	1	32.00	20.00	25.60	?
0008	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	na ✓
0009	04-01-0103-0585-A	TAILLAMP RH	1	565.60	20.00	452.48	CRA ✓
0010	04-01-0103-0583-G	BOOTLID LAMP RH	1	556.80	20.00	445.44	X
0011	02-01-0103-0054-G	EXHAUST MUFFLER RH	1	954.00	20.00	763.20	Repair ✓
0012	02-01-0103-0086-G	EXHAUST CENTRE PIPE	1	1,150.30	20.00	920.24	?
0013	09-01-9999-0068-A	REVERSE SENSOR	1	135.70	200	135.70	scr ✓

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 18.05.2018

Time: 14:23:54

Page: 2

Fri TS

FWD-CP(P)

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305161828
REGN NO : SH 8382C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 28.07.2016
DATE/TIME IN : 18.05.2018 02:00
ACCIDENT DATE : 18.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0103-1150-A REAR BUMPER MAT 1 50.00 0.20 50.00 ne/

SUB-TOTAL : 4,174.50

JOB NATURE

0000 L PANEL BEATING
0001 23-502 SPRAYPAINT ON AFFECTED AREA
0002 17-01 CHECK ALL LIGHTING
0003 20-00 TUFF COAT ON AFFECTED PARTS.
0004 L R/I REVERSE SENSOR
0005 L R/I EXHAUST SYSTEM
0006 23-01 TOWING FEE

~~560.00~~ 300
~~600.00~~ 360
~~40.00~~ 30
~~40.00~~ 20
~~120.00~~ 60
~~120.00~~ 60
~~60.00~~

SUB-TOTAL : 1,540.00

CTO

Rasul
Hp 90010068
4 1/2 days
p/p
18/05/18 @ 1700
Rasul by paint

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 18.05.2018

Time: 14:23:54

Page: 3

TS
3 Fri

FWD-CP/P

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305161828
REGN NO : SH 8382C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 28.07.2016
DATE/TIME IN : 18.05.2018 02:00
ACCIDENT DATE : 18.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 5,714.50

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

Lamfs



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

Date: <u>18/05/18</u> Time Received: <u>0200</u>		3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	4. Type of Towing: ☒ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up
Name of Customer: <u>Teo Ee cheng</u> Contact No. <u>9:178 6400</u> Vehicle No. <u>SH 8382 C</u> Make / Model / Colour: <u>Blue 140</u> Email: _____		5. Nature of Service: ☐ Jumpstart ☐ Recovery ☐ Change Tyre / Battery	6. Parts Replaced/Remarks: _____ _____

Location: <u>227A COMPASSVALE DR</u>		8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi	
Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Senoko ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others: _____			

0. Odometer Reading: _____	11. Radio / CD Player ☐ OK ☐ Faulty ☐ Not tested					
Fuel Level: <table border="1"><tr><td>F</td><td>1/4</td><td>1/2</td><td>3/4</td><td>E</td></tr></table>	F	1/4	1/2	3/4	E	
F	1/4	1/2	3/4	E		

Job Attended

12. Tow Truck / Recovery Van: ☐ VRS ☒ QA ☐ GAO ☐ TZ ☐ YISHUN ☐ OTHERS TOWING		 #: Cracked X: Dented /: Scatched O: Missing Signature of Customer: <u>[Signature]</u>
Name of Driver: <u>[Signature]</u>		
Vehicle No.: <u>YN 3901K</u>		
Time Dispatch: <u>0200 0200</u>		
Time of Arrival: <u>0230</u> Time Completed: <u>0300</u>		

Cash Invoice Details (if applicable)

13. Cash Invoice No.:	_____
-----------------------	-------

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
- b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
- c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

<u>18/05/18</u> Date	<u>0230</u> Time	<u>[Signature]</u> Signature of Customer
-------------------------	---------------------	---

14. WORKSHOP