22/03/2002

ASS. REC. BY: | REF: CS3 | FCI18009273 | R/24d 3 | Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Lurene jaw of FCI Date/Time: 21/05/2018 @ 4:17pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJU 5722m Insured: SHC 7668S

at Workshop m/s: Car Doctor Tel: 66355773

of BLK 3, 391A Woodlands Rd Yew Tee Ind. Est

Policy No: Claim No: D18003969MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 17/05/2018

(Client's Record)

23/05/2018

CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement:

Date/Time: 9.18am @ 22/5/18 Person Contacted: Sylvester Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SJU 5722 - X
	SHC 7668S - CS/MSG17015735/TIvbe2 DOA: 14/8/2017
	After repair: 28/5/2018.
	MV 24K - ~~25K~~ 13/6/18

Ramu | REF: FCI | 28683

ASSIGNMENT

From: Date: 23/5/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJU 5722

at Workshop m/s Car Doctor

of B/KC3, 391A woodlands Rd Yew Tee

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record) Morning

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 24K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJU5722M Yr Regn: 2009 / DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA JAZZ 1.5 LAT c.c 1497

Colour BLUG A/C: Insured / Std / NI / NA

Sp.Reading 142233 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMGE88509S201379

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	17/05/18	D.O.I.	23/05/18 12-25

Survey held at Car Doctor

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/5/18	submit PRS Report.

Date/Time File Pass to?

1)

Date/Time File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) ___S + RS ___SI

☐ Interview ($) Photos

☐ Tech. Invs ($) Others

☐ Weekend ($)

TOTAL

Report Format : PRS

Lump Sum / I.B.I: ($)

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref : CS3/FCI18009273/R1z4d3

Date : 22-05-2018

Code : FCI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

	Insured Veh.	SHC 7668S	Veh. Inspected	SJU 5722
	Policy No.		Coverage ($)	0.00
	Claim No.	D18003969MFSH	Excess ($)	0.00
	Assign From	CWS (LURENE JAW)	Assign Date	22/05/2018

2. Vehicle Particulars & Condition

	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			

3. Conditions of Tyres

		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

4. Description of Damages

5. General Information

	Accident Date	17/05/2018	Inspection Date
	Survey held at	CAR DOCTOR PTE LTD BLK C3 WOODLANDS ROAD 391E SINGAPORE 677901	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

MS FirstCapital

MS First Capital Insurance Limited Co Reg. No. 199000106C GST Reg. No. M2-0001676-9
6 Raffles Quay #21-00 Singapore 048580
Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877
Tel: (65) 6507 3848 Fax: (65) 6507 3849
www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date	17-05-2018	**Our Ref No.**	D18003969MFSH
Accident Date	17-05-2018	**Claim Type.**	Third Party
Insured Vehicle	SHC7668S	**Third Party Vehicle.**	SJU5722
Survey Location	BLK 3 391A WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE		
Contact Person.	MR SYLVESTER		
Contact No.	66355773/ 83633284	**Fax No.**	67338183
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	**Fax No.**	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CAR DOCTOR PTE LTD	**Attention.**	NIL
Cc : TP Solicitor	CHIA S ARUL LLC	**TP Solicitor Fax No.**	NA
Officer Incharge	LURENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240484) PRI Documents Close

PRI Header Details

Claim No	D18003969MFSH	**Policy No**	D-18088937MFSH	**Claimant S.No & Name**	1 & CHIA S AI
Workshop Name	CAR DOCTOR PTE LTD (Contact Person : MR SYLVESTER)	**Survey Location & Contact Details**	BLK 3 391A WOODLANDS ROAD YEW TEE INDUSTRIAL I **Mobile:** 83633284 , **Phone:** 66355773 , **Fax:** 6733818 **EmailId:** IZHAR@CHIAARUL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	**Instructions To Surveyor**	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	**Insured Vehicle No**	SHC7668S	**TP Vehicle No**	SJU5722
PRI Recieved Date	18-05-2018 07:57:03 PM	**Surveyor Appointed Date**	21-05-2018 04:15:52 PM	**Surveyor Accept Date**	22-05-2018 0

Survey Report Upload

Surveyor Inspection Date *:		**Surveyor Report Date**	22-05-2018	**Upload Survey Report *:**	Choose File

Vehicle Particulars

Make	Please Select Make	**Model**	Please Select Model	**Year**	Select Year
Chasis No		**Engine No**		**Mileage**	
Color		**Cubic Capacity**			

Multiple Documents Upload

Upload Multiple Documents

File Name **Action**

Surveyor Job Remarks

Remarks		Save

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	17/05/2018 13:02
Date Of Accident	17/05/2018 07:40
Exact Location Of Accident	JTN OF CPARK EXIT AT BLK 420 AND JURONG WEST ST 42
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJU5722M
Insured/Policyholder	
Name Of Registered Owner	TAN LYE HUAT
NRIC No	S0022868J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83998263
Alternative Phone No	OFFICE-83998263
Vehicle Particulars	
Manufacturer	HONDA
Model	JAZZ-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ17-006527
Cover Note Number	
Driver	
Name of Driver	TAN PENG AN
NRIC No	S8440621Z
Date Of Birth	24/12/1984
Occupation	INDOOR
Date Of Driving Pass	12/11/2009
Driving Experience	8 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82885584
Fax Number	
Contact Number	
EMail Address	TANPENGAN@OUTLOOK.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

   I understand, acknowledge, agree and consent that:

   (a) My insurer, my workshop and the General Insurance Association of Singapore ("**GIA**") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

   (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

   (ii) investigating the accident and/or my claims;

   (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

   (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

   (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")

   (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

   (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

   (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

   (e) the information so collected under (d) above may be shared / disclosed:

   (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

   (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time: 17/5/18 1150	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17/5/18 at about 0742, I was driving my vehicle (SJU5722M) out of Blk 420 Jurong West St 42 carpark. Before I drive out to the main road, I stop before yellow box and I looked left & right, I saw a car stop out of yellow box on my right. I turned right and then a taxi suddenly hit my car from the opposite direction, the taxi overtake the car which stop on a yellow box & drove against the traffic.

1 passenger: maybelline Tan Ying Rui Daughter

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time: 17/5/18 1150	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2868J
Vehicle Details	
Vehicle No.:	SJU5722M
Vehicle to be Exported:	No
Intended De-registration Date:	23 May 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5L AT ABS D/AB HID 2WD 5DR
Primary Colour:	Purple
Manufacturing Year:	2008
Engine No.:	L15A71001659
Chassis No.:	JHMGE88509S201379
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	$22,901.00
Original Registration Date:	16 Dec 2009
First Registration Date:	16 Dec 2009
Transfer Count:	0
Actual ARF Paid:	$22,901.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Dec 2019
PARF Rebate Amount:	$12,595.00
Intended COE Rebate Details	
COE Expiry Date:	15 Dec 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	$18,502.00
COE Rebate Amount:	$2,885.00
Total Rebate Amount:	**$15,480.00**

The information contained herein is correct as at 23 May 2018

OK

24,000
15,480
8520
8K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2868J
Vehicle Details	
Vehicle No.:	SJU5722M
Vehicle to be Exported:	No
Intended De-registration Date:	13 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5L AT ABS D/AB HID 2WD 5DR
Primary Colour:	Purple
Manufacturing Year:	2008
Engine No.:	L15A71001659
Chassis No.:	JHMGE88509S201379
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	$22,901.00
Original Registration Date:	16 Dec 2009
First Registration Date:	16 Dec 2009
Transfer Count:	0
Actual ARF Paid:	$22,901.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Dec 2019
PARF Rebate Amount:	$12,595.00
Intended COE Rebate Details	
COE Expiry Date:	15 Dec 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	$18,502.00
COE Rebate Amount:	$2,785.00
Total Rebate Amount:	**$15,380.00**

The information contained herein is correct as at 13 Jun 2018

Dep 9652/yr
804/~~4~~ mth

OK

NV 24k - 25k

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref: CS3/FCI18009273/R1z4d3s2
Date: 22-06-2018
Code: FCI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

	Insured Veh.	SHC 7668S	Veh. Inspected	SJU 5722M
	Policy No.	D-18088937MFSH	Coverage ($)	0.00
	Claim No.	D18003969MFSH	Excess ($)	0.00
	Assign From	LURENE JAW	Assign Date	21/05/2018

2. Vehicle Particulars & Condition

	Make & Model	HONDA JAZZ 1.5LAT	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JHMGE88509S201379	Colour	BLUE
	Odometer	142233 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		

3. Conditions of Tyres

		Size	Make	Balance
	R/H Front Tyre	195/65R15	MICHELIN	6 mm
	L/H Front Tyre	195/65R15	MICHELIN	6 mm
	R/H Rear Tyre	195/65R15	MICHELIN	6 mm
	L/H Rear Tyre	195/65R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.



5. General Information

	Accident Date	17/05/2018	Inspect Date / Time	23/05/2018 (12:25 PM)
	Survey held at	CAR DOCTOR PTE LTD BLK C3 WOODLANDS ROAD 391A SINGAPORE 677964		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) MARKET VALUE:$24,000.00

Report Ref No. CS3/FCI18009273/R1z4d3s2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser