

22/03/2002

ASS. REC. BY:

REF: CS3/MSB18009296/G24d362

Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

Melman

From (Person):

Muhd Ashik

of

MSLH

Date/Time: 22/05/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 6259H

Insured:

SLS 769Z

at Workshop m/s

William Lee Car Air Con

Tel:

9455 7994

of

No. 2 Kaki Bukit Ave 2 #01-34

Policy No:

77636744MTR

Claim No:

559041

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/05/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:43am @ 22/5/18

Person Contacted:

Mr. William

Vehicle: IN OUT

Date/Time	Action/Instruction (X) Estimate	
	SJT 6259H - NA/INC18009109/K4	DOA: 18/5/2018
	SLS 769Z - NA/INC18009109/K4	DOA: 18/5/18
06081018	Confirmed with Eliza Ho, Insured under MSLH	
	After repair: 28/5/2018	

REF:

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 2JT 6254H Yr Regn: 23 Oct / 2009

Type: M/Ca / M/Cyclg / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante 1.6 c.c. 1591

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 142868 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHDU418MAUG1755

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 / 65 R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Ecopia

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 18052018

D.O.I. 20052018

Survey held at


William Lee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$4,000 - \$5,000

  
 8/8/2008

Date/Time: File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time: File Return to?

Transportation:

2)

Add Fee: ☐ : Site Insp (\$)

) \$ + RS \$

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Other:

☐ : Weekend (\$)

)

Report Format : PRS

Lump Sum / I.B.I. (\$)

TOTAL

10

130



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18009296/Gz4d3

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 22-05-2018



Code : MSG

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLS 769Z	Veh. Inspected	SJT 6259H
Policy No.	27636744MTR	Coverage (\$)	0.00
Claim No.	559041	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	22/05/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	18/05/2018	Inspection Date	22/05/2018
Survey held at	NO.2 KAKI BUKIT AVE 2 # 01-34		
Repairer	WILLIAM LEE CAR AIR CON ENGINEERING		

### 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 May 2018		06 Aug 2018 17:36 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	TRANS EUROKARS PTE LTD, Co. Reg. No.: 199103859N	
Main Claimant:	EXCEL MOTORING, Co. Reg. No.: 53180222A	
Vehicle Reg. No.:	SJT6259H	Date of Loss: 18/05/2018 19:00 - :59 [102 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 559041	27636744MTR (Comprehensive) Coverage: 01/01/2018 - 31/12/2018
Vehicle Reg. No. (Insured):	SLS769Z	Policy No. (Claimant):
		Excess: S\$2,000.00
Repairer:	- Not Applicable - (-)	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/08/2018]	
Driver/Custodian (Insured):	PUAR CHENG LOONG (), NRIC: S7614891J, Tel: +6596611093	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Celine Fong (LKKAuto)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Monday, 6 August 2018 4:32 PM  
**To:** 'Muhd Ashik B Madi'; 'Eliza Ho'  
**Cc:** assignments  
**Subject:** RE: AIG ref: 2939374253SG-003, accident involving SLS769Z and SJT6259H on 18 May 2018

Dear Muhd Ashik,

Kindly assist upload this case in Merimen for us submit Pre-repair Inspection report to your good office.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Loh, Chee-Heng [mailto:[Chee-Heng.Loh@aig.com](mailto:Chee-Heng.Loh@aig.com)]  
**Sent:** Friday, 20 July, 2018 4:33 PM  
**To:** Eliza Ho <[Eliza\\_Ho@sg.msig-asia.com](mailto:Eliza_Ho@sg.msig-asia.com)>; [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** Muhd Ashik B Madi <[ashik\\_madi@sg.msig-asia.com](mailto:ashik_madi@sg.msig-asia.com)>  
**Subject:** RE: AIG ref: 2939374253SG-003, accident involving SLS769Z and SJT6259H on 18 May 2018

Dear Eliza,

You may liaise with Nivitha from LKK regarding the third party survey.

Dear Nivitha (LKK),

MSIG will be handling the claim. Kindly liaise with Eliza on this case.

Thank you.

Best regards,

**Loh Chee Heng**

**AIG**

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1881 | Fax +(65) 6835 7416

[Chee-Heng.Loh@aig.com](mailto:Chee-Heng.Loh@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**Follow us:**



**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

**From:** Eliza Ho [[mailto:Eliza\\_Ho@sg.msig-asia.com](mailto:Eliza_Ho@sg.msig-asia.com)]

**Sent:** Friday, July 20, 2018 4:24 PM

**To:** Loh, Chee-Heng

**Cc:** Muhd Ashik B Madi

**Subject:** RE: AIG ref: 2939374253SG-003, accident involving SLS769Z and SJT6259H on 18 May 2018

Msig Ref: 559041

Dear Chee Heng,

As spoken, your insured vehicle SLS769Z was driven by our insured Trans Eurokars Pte Ltd during his servicing when the accident happen. Therefore Trans Eurokars will claim under their Motor Trade policy.

Please help to inform LKK on this matter and we will liaise with third party repairer William Lee Car Air-con separately.

Thank you.

**Eliza Ho**

Assistant Executive, Claims Services (Motor)

D: +65 6594 2554 | F: +65 6225 7402 | [eliza\\_ho@sg.msig-asia.com](mailto:eliza_ho@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

**From:** Clara Milah Yeo

**Sent:** Friday, 20 July, 2018 2:37 PM

**To:** Eliza Ho <[Eliza\\_Ho@sg.msig-asia.com](mailto:Eliza_Ho@sg.msig-asia.com)>

**Cc:** Foo Ai Ngoh <[aingoh\\_foo@sg.msig-asia.com](mailto:aingoh_foo@sg.msig-asia.com)>

**Subject:** FW: AIG ref: 2939374253SG-003, accident involving SLS769Z and SJT6259H on 18 May 2018

Dear Eliza,

For your attention.

Thank you.

Sincerely,





**Clara Milah Yeo**

Senior Admin Officer, Claims Services (Motor)

Direct line +65 6594 2560 | Direct fax +65 6225 7402 | [milah@sg.msig-asia.com](mailto:milah@sg.msig-asia.com)

**MSIG**

2016 Insurer Claims Stars of the Year

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | [www.msig.com.sg](http://www.msig.com.sg) | Follow us on    

A member of **MS&AD** INSURANCE GROUP

**From:** Koh Lay Hoon

**Sent:** Friday, 20 July 2018 2:27 PM

**To:** Clara Milah Yeo <[Milah@sg.msig-asia.com](mailto:Milah@sg.msig-asia.com)>

**Subject:** FW: AIG ref: 2939374253SG-003, accident involving SLS769Z and SJT6259H on 18 May 2018

---

**From:** Loh, Chee-Heng [<mailto:Chee-Heng.Loh@aig.com>]

**Sent:** Friday, July 20, 2018 11:01 AM

**To:** [williamleecar@gmail.com](mailto:williamleecar@gmail.com); Claims <[claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)>

**Subject:** AIG ref: 2939374253SG-003, accident involving SLS769Z and SJT6259H on 18 May 2018

Without Prejudice

Dear Mr Lee,

As spoken, our insured vehicle SLS769Z was driven by Mazda's technician, covered under motor trade policy with MSIG Insurance.

Kindly direct your claim to MSIG.

Dear MSIG,

Kindly be informed that our appointed surveyor, LKK Auto Consultants Pte Ltd, had been assigned to survey the third party vehicle. Kindly inform the case handler to contact us if required.

Thank you.

Best regards,

Loh Chee Heng

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1881 | Fax +(65) 6835 7416

[Chee-Heng.Loh@aig.com](mailto:Chee-Heng.Loh@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**Follow us:**



**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please

immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



**TOMMY CHOO, MARK GO LLC**

**Advocates & Solicitors**      **Commissioner for Oaths**      **Notary Public**  
**UEN NO : 201523418E**  
**(a law corporation with limited liability)**

151 CHIN SWEE ROAD #14-15/16  
 MANHATTAN HOUSE  
 SINGAPORE 169876  
 TEL : (65) 6632 2455  
 FAX : (65) 6638 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: [llhling@tomg.com.sg](mailto:llhling@tomg.com.sg); [mdmling@tomg.com.sg](mailto:mdmling@tomg.com.sg)  
 Our Ref : TCMG/SJT6259H/0518/WLC

Your Ref : SLS 769 Z

21 May 2018

M/s AIG Asia Pacific Insurance Pte Ltd  
 78 Shenton Way#07-16  
 AIG Building  
 Singapore 079120

Attn: Motor Claims Department

Dear Sirs,

**PRE-REPAIR INSPECTION NOTICE**

We act for M/s Excel Motoring, the owner and/or driver of motor vehicle no. SJT 6259 H which was involved in an accident along Leng Kee Road on 18 May 2018 at 19:30 hours.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. SLS 769 Z for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s William Lee Car Air Con, No 2 Kaki Bukit Avenue 2 Auto Hub #01-34, Singapore- William Lee @ 9455 7994 or Ah Leng 97975757).

If we do not hear from you within the next two (2) working days, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,

**LING LEONG HUI (MR)**  
 cc.  
 M/s William Lee Car Air Con  
 (Yref: SJT6259H)

**BY EMAIL**

DIRECTOR : LING LEONG HUI

CONSULTANTS: TOMMY CHOO TUCK SOON  
POOTS LAURENCE JAMES

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	0222A
<b>Vehicle Details</b>	
Vehicle No.:	SJT6259H
Vehicle to be Exported:	No
Intended De-registration Date:	07 Aug 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	G4FC9U745122
Chassis No.:	KMH DU41BMAU891755
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,539.00
Original Registration Date:	23 Oct 2009
First Registration Date:	23 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$11,539.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Oct 2019
PARF Rebate Amount:	\$6,346.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	22 Oct 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,019.00
COE Rebate Amount:	\$1,812.00
<b>Total Rebate Amount:</b>	<b>\$8,158.00</b>

The information contained herein is correct as at 07 Aug 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/05/2018 15:33
Date Of Accident	18/05/2018 19:30
Exact Location Of Accident	LENG KEE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT6259H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	EXCEL MOTORING
Co Reg No	53180222A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88115028
Alternative Phone No	OFFICE-88115028

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5095127768-01
Cover Note Number	

### Driver

Name of Driver	RAMESH S/O MUTHU KUMAR
NRIC No	S7625455I
Date Of Birth	02/08/1976
Occupation	OUTDOOR
Date Of Driving Pass	09/04/2003
Driving Experience	15 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-88115028
Fax Number	
Contact Number	OTHERS-88115028
EMail Address	NOEMAIL

Address	BLK 432C YISHUN AVENUE 1 #05-545
Postcode	763432
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	DRIZZLING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS769Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PUAR CHENG LOONG
NRIC/Passport Number	S7614891J
Contact Number	96611093 / 66036114
Address	TRANS EUROKARS MAZDA
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*Ramesh*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

*19/5/2018*

### Sketch Plan #2

SKETCH PLAN

Long Kirk Rd

W. 12th

A - SJT 6259 H

B - SLS 769 Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle A was driving along Lehigh Rd, suddenly  
Vehicle B ~~turn~~ turn in front ~~illegally~~ illegally into  
my lane and hit my <sup>front</sup> right side position.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time \_\_\_\_\_

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 May 2018		06 Aug 2018 17:36 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>TRANS EUROKARS PTE LTD</b> , Co. Reg. No.: 199103859N								
Main Claimant:	<b>EXCEL MOTORING</b> , Co. Reg. No.: 53180222A								
Vehicle Reg. No.:	<b>SJT6259H</b>	Date of Loss:	18/05/2018 19:00 - :59 [102 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 559041</b>	Policy/Cover Note No.:	27636744MTR (Comprehensive) Coverage: 01/01/2018 - 31/12/2018						
Vehicle Reg. No. (Insured):	<b>SLS769Z</b>	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	<b>- Not Applicable - (-)</b>								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Muhd Ashik B Madi</b> - 6594 2548]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Imm.Advice due 07/08/2018]								
Driver/Custodian (Insured):	PUAR CHENG LOONG (), NRIC: S7614891J, Tel: +6596611093								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SJT6259H (559041)  
[SLS769Z]  
TP  
EXCEL MOTORING  
May 18 2018 7:00PM  
[TRANS EUROKARS PTE LTD]

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)								Thumbnail	Print	
1	06/08/18 17:31	Accident Statement From:OD - Reg. No: SLS769Z, Claimant: TRANS EUROKARS PTE LTD							1	Load HTM		
Photos/Images									3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
2	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
3	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
4	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
5	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
6	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
7	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
8	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
9	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
10	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
11	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
12	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
13	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
14	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
15	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
16	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
17	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
18	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
19	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
20	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
21	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
22	07/08/18 09:22	General View							1	Load JPG	<input checked="" type="checkbox"/>	
23	07/08/18 09:26	Photo After Spray							1	Load JPG	<input checked="" type="checkbox"/>	
24	07/08/18 09:26	Photo After Spray							1	Load JPG	<input checked="" type="checkbox"/>	
25	07/08/18 09:26	Photo After Spray							1	Load JPG	<input checked="" type="checkbox"/>	
26	07/08/18 09:26	Photo After Spray							1	Load JPG	<input checked="" type="checkbox"/>	
27	07/08/18 09:26	Photo After Spray							1	Load JPG	<input checked="" type="checkbox"/>	
28	07/08/18 09:26	Photo After Spray							1	Load JPG	<input checked="" type="checkbox"/>	
29	07/08/18 09:26	Photo After Spray							1	Load JPG	<input checked="" type="checkbox"/>	
30	07/08/18 09:26	Photo After Spray							1	Load JPG	<input checked="" type="checkbox"/>	
31	07/08/18 09:26	Photo After Spray							1	Load JPG	<input checked="" type="checkbox"/>	
32	07/08/18 09:26	Photo After Spray							1	Load JPG	<input checked="" type="checkbox"/>	
33	07/08/18 09:26	Photo After Spray							1	Load JPG	<input checked="" type="checkbox"/>	
34	07/08/18 09:26	Photo After Spray							1	Load JPG	<input checked="" type="checkbox"/>	



Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
35	07/08/18 09:26	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
36	07/08/18 09:26	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	06/08/18 17:31	SJT6259H E- FILE REPORT From:OD - Reg. No: SLS769Z, Claimant: TRANS EUROKARS PTE LTD		Load PDF	
2	06/08/18 17:36	Direct Survey by LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^v

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18009296/GZ4D3E2

Date: 10/08/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27636744MTR

Claimant Vehicle No : SJT6259H

Insured Vehicle No : SLS769Z

Date of Loss: 18/05/2018

Nature of Claim: TP

Claim No: 559041

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT6259H**

Make &amp; Model: HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A)

Engine No: G4FC9U745122

Reg. Date: 23/10/2009 (Man. Year: 2009)

Chassis No: KMH DU41BMAU891755

Colour: Red

Odometer: 142868 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Ecopia 5 mm

Rear Left Side: Ecopia 5 mm

Front Right Side: Ecopia 5 mm

Rear Right Side: Ecopia 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 06/08/2018

Date Inspected: 22/05/2018 Inspected At:

NO.2 KAKI BUKIT AVE 2 # 01-34  
Repairer : WILLIAM LEE CAR AIR CON  
ENGINEERING

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 10 Aug 2018)

**Parts:** 143      HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJT6259H)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >