

INS. CASE OWNER:

CC 4 / III1800 9307, T1 mb3 9

LKK:  
IDAC:

Surveyor:

Touhid

DOI:

ASSIGNMENT

25/5/18

Date / Time:

16/5/18

Registered in Merimen:

2/5/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

GHC 8275K

Name of Insured:

LPL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

15/5/18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

MOHAMED KHR ISHAK

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MT1870041

Policy No.:

M10-0015

Make / Model:

HYUNDAI

Place of Accident:

UPP SERANATON RW 7

KORAN CROSS UPPAYAT

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

LEAFAR PV

SL57866E



INSRS:

WSP:

Tel:

Liability:

RMKS:

LKC  
KIR

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

16/5/18

Korhan

24/4

Reply Pnya (4) on OI AVE - pending reply

9/9/18

FLE -&gt; Shu PET to clw up

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / CIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

( days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

SS

(Agreed / Assessed)

BOLA S/N No.:

Repair Cost:

SS

Loss of Rental (LOR):

SS

( days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Tapi

III

M

SLS 7866E

Date 25/05/2018

Sales / Cost

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect vehicle from

SLS 7866E

at Workshop no.

Cycle & Carriage  
209 Pandan Garden

Insured

Policy No.

Claims No.

Sum Insured

Excess


(Owner's Record)

Make of Vch

Don.

(Policy Condition)

Harm

Remark: The veh had commenced its  
repair at the time of inspection

Bal. or Market Value

IDAC Accident Report

Consistent? Yes or No

QIA / PR Seen

Consistent? Yes or No

Est. Repairs

6-7

days

Res.

Yes or No

Lim Sum

%

3 Val

Yes or No

CA / REV / REP / 24 HRS

Date

Person Contacted

Vehicle IN / OUT

Date / Time

Action / Instruction

Vehicle

SLS 7866E

2017 oct

Type (M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover)

Truck / Trailer or

Make

Max Carate K3

1591

Colour

white

A/C Insured / Std / Nil / NA

Sp. Reading

9635

T/Ratio Insured / Std / Nil / NA

Eng/No

C/No

KNAFX41/MJS3747143

Gen. Cond Good / Fair / Poor / Burnt

Steering Insured / Jammed / Leaked / Burnt or

Brake Insured / Jammed / Leaked / Burnt or

Mod Nil / S/Rim / STD A/Rim or

Tyre Size

F: 205/55R16

R: 2 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Max on

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A

D.O.I

25/5/18 curis

Survey held at

OC Pandan Garden

Des. of Damages: Fnt / Rear / O/S / N/S / W / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Submit

PIP \$ 4497.00 (Red \$ 329/440) - excluded  
check items  
\$ 1467.00

Time / Date / Time

☐

Prel. Report

Days Of Repair:

Time / Date / Time

☐

Final Report

Resurvey No. of Trip:

Time / Date / Time

Add Fee:

☐

Self Ins. \$5

☐

Interins. \$5

☐

Cash \$5

☐

Insurance \$5

Report Format

Lump Sum / L.R.

Survey Fee

Transport

Insurance

Other

Total

Total

Total



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18009307/mb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 22-05-2018	
		Code : III2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 8275K	Veh. Inspected	SLS 7866E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	15/05/2018	Inspection Date	
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Mok Chun Kwong Jeffrey	Cust No/Name /Mr Mok Chun Kwong Jeffrey
Blk 253 Bangkit Road	Reg No/Reg Date SLS7866E / 04/10/201
#01-242	Date In/Mileage / 0
Singapore 670253	Chassis No KNAFX411MJ5747145
Contact No Mobile: 96569631JEFFERY	Engine No G4FGHH682299
	Make/Model KIA/CERATO K3 1.6 A EX BWY
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	19/05/2018/ 10:30	QUD	247 / DonBong	28880		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1650 2200.00
RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, BUMPER RETAINER, REPAIR LH REAR FENDER, REPAIR LH REAR DOOR							60 80.00
E PNT88000							1260 1680.00
REMOVE AND INSTALL PARKING ASSIST							40 80.00
E PNT98000							30 50.00
PAINT WORK SPRAY REAR BUMPER FACE, LH REAR FENDER, LH REAR DOOR AND AFFECTED PORTION							225? 550.00
M SUNDRY							at 400.00
PERFORM RUST PREVENTION							✓ 120.00
A 54900099							✓ 200.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							20 50.00
A 30000001							photo 225? 550.00
RENEW LH REAR WHEEL HUB BEARING AND AFFECTED PARTS							at 400.00
M SUNDRY							✓ 120.00
SUPPLY LH REAR SPORT RIM SSW266							✓ 200.00
A WHEELALIGNMENTBP							20 50.00
To Conduct Computerize Full Wheel Alignment							at 688.00
A 10028901							at 29.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							at 29.00
USING HI-SCAN PRO TEST							at 347.00
M SUNDRY							at 2.00
SUNDRIES							at 78.00
M COVER-RR BUMPER				1.00	688.00	00.00	at 788.00
M BRACKET-RR BUMPER SIDE MTG,LH				1.00	29.00	00.00	at 75.00
M BRACKET-RR BUMPER SIDE MTG,RH				1.00	29.00	00.00	at 340.00
M COVER-RR BUMPER,CTR				1.00	347.00	00.00	at 2.00
M RETAINER-BUMPER SIDE MTG				2.00	1.00	00.00	at 788.00
M RETAINER				4.00	2.00	00.00	at 75.00
M LAMP ASSY-REAR COMBINATION,LH				1.00	788.00	00.00	at 340.00
M GUARD ASSY-REAR WHEEL,LH				1.00	75.00	00.00	
M HUB ASSY-RR WHEEL				1.00	340.00	00.00	
SURVEYOR NAME: <u>Tanphu</u>							
SURVEYOR SIGNATURE: <u>[Signature]</u>							

*Estimate*

SURVEYOR NAME: Tan Jiah

SURVEYOR SIGNATURE: Tan Jiah

Confirm & accepted by the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

DATE: 25/5/18 @ 1115

REMARKS: Resurvey before paint

sur @ lkhauto.com

6-7 days

**Nett** 7,716.00  
**7% GST on** 540.12  
**Total Payable** 8,256.12

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## Niitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Monday, 21 May 2018 4:55 PM  
**To:** Don Bong Kiong Hua; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** Manivel Priyadarshini  
**Subject:** RE: TP INDIA CLAIM SLS7866E AGAINST SHC8275K DOA 15.05.2018  
**Attachments:** [Untitled].pdf; WhatsApp Image 2018-05-16 at 10.25.15 AM(1).jpeg; WhatsApp Image 2018-05-16 at 10.25.15 AM.JPEG; WhatsApp Image 2018-05-16 at 10.25.16 AM(1).jpeg; WhatsApp Image 2018-05-16 at 10.25.16 AM(2).jpeg

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLS7866E and let us have your report urgently.

This claim will be handled by Ms Priya.

\*Kindly upload this survey request email to merimen.

Thank You.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

8.59amg 22/5/2018  
Person @ Don Bong  
vehicle not in

---

**From:** Don Bong Kiong Hua [mailto:kionghua.bong@cyclecarriage.com.sg]  
**Sent:** 21 May, 2018 3:19 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** Andre Chow En De <andre.chow@cyclecarriage.com.sg>  
**Subject:** RE: TP INDIA CLAIM SLS7866E AGAINST SHC8275K DOA 15.05.2018  
**Importance:** High

Hi Officer,

- We choose LKK Auto Consultants Pte Ltd

---

**From:** Motor Claim - III [mailto:motorclaim@iii.com.sg]  
**Sent:** Monday, 21 May, 2018 2:36 PM  
**To:** Don Bong Kiong Hua  
**Subject:** RE: TP INDIA CLAIM SLS7866E AGAINST SHC8275K DOA 15.05.2018

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd

- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

---

**From:** Don Bong Kiong Hua [<mailto:kionghua.bong@cyclecarriage.com.sg>]

**Sent:** 21 May, 2018 2:02 PM

**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>

**Cc:** Andre Chow En De <[andre.chow@cyclecarriage.com.sg](mailto:andre.chow@cyclecarriage.com.sg)>; Coco Lu Ting <[coco.lu@cyclecarriage.com.sg](mailto:coco.lu@cyclecarriage.com.sg)>; Edwin Abcede Caina <[edwin.caina@cyclecarriage.com.sg](mailto:edwin.caina@cyclecarriage.com.sg)>; Tay Jian Ye <[jianye.tay@cyclecarriage.com.sg](mailto:jianye.tay@cyclecarriage.com.sg)>

**Subject:** FW: TP INDIA CLAIM SLS7866E AGAINST SHC8275K DOA 15.05.2018

**Importance:** High

Dear Officer In-Charge,

This email is with regards to the above accident which has been reported by our customer. We have since been instructed by him/her (motor vehicle number SLD7866E), to submit a claim on his/her behalf as we are the authorized repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number SHC8275K) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

Do let me know the liability at the soonest possible.

Don Bong  
Claim Division Operations  
209 Pandan Gardens  
Singapore 609339



**CYCLE & CARRIAGE**

Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339  
T: +65 6568 4501 • F: +65 6565 1240 • [www.cyclecarriage.com.sg](http://www.cyclecarriage.com.sg)

 A member of the Jardine Cycle & Carriage Group

**DISCLAIMER:-** This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended



recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

**DISCLAIMER:-** This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.





## Hsiao Tong (LKKAuto)

---

**From:** Bevan Lim (LKK Auto)  
**Sent:** Thursday, 14 June 2018 4:03 PM  
**To:** Don Bong Kiong Hua  
**Cc:** Vic (LKKAuto); Admin A; CS A Team  
**Subject:** Your Ref: SLS7866E Our Ref: CC4/III18009307/T1mb3 ACCIDENT INVOLVING SHC8275K & SLS7866 ON 21/02/2018  
**Attachments:** OI GIA REPORT.pdf

### WITHOUT PREJUDICE

Your Ref: **SLS7866E**  
Our Ref: **CC4/III18009307/T1mb3**

Dear Sir/Madam,

### ACCIDENT INVOLVING SHC8275K & SLS7866 ON 15/05/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is unclear / our Insured is disputing for the above mentioned case. Our insured also filing Third Party claim against your client's insurer. Enclosed herewith is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request the CCTV footage / accident scene photos / evidence in order to seek further instruction from our principal.

Thank you.


Best Regards,

Bevan Lim | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [BevanLim@lkkauto.com](mailto:BevanLim@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

## Print Sent Message

This mail is associated with :

**\*SLS7866E (MCT18050421)**  
**[SHC8275K]**

TP

MOK CHUN KWONG JEFFREY  
May 15 2018 7:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Cycle & Carriage KIA Pte Ltd

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 07/09/2019 10:34 AM.  
**To** manivel@iii.com.sg  
**CC** III\_SG; chewht@lkkauto.com; admin-a@lkkauto.com  
**Subject** <Submit WP report>MCT18050421

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that we have inspected third-party vehicle SLS7866E on 25/05/2018 at Cycle & Carriage. Liability is unclear. There is no further action initiated by third-party repairer for their claim up-to-date.

In view of non-development from the third-party, we will proceed to temporarily close this outstanding claim file and submit our WP report to your good-office.

Thank you.

Hsiao Tong

<-- Original Message -->

From: LKK\_HQ  
To: III\_SG  
Sent On: 27/05/2019 04:59 PM  
Subject: Re: Alert - Adj Mandate Maintained - SLS7866E - Claim Handler: Priya

Dear Priya,

Manage to get the AVF from CDGE? Still awaiting for your reply on OI AVF.

May I know who is the handler for this case in CDGE so I can also directly email the handler to request for the AVF as well.

Thanks

<-- Original Message -->

From: III\_SG  
To: LKK\_HQ  
Sent On: 25/05/2018 10:13 AM  
Subject: Alert - Adj Mandate Maintained - SLS7866E - Claim Handler: Priya

Maintained: Requested video footage from CDGE, one received will forward the same to you.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

W P

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 May 2018 <a href="#">Edit Reg</a>		21 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$44,497.00</b> <a href="#">Edit Estimates</a>	<b>\$44,497.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -		
Main Claimant:	MOK CHUN KWONG JEFFREY, ID: S0224903J		
Vehicle Reg. No.:	SLS7866E	Date of Loss:	15/05/2018 19:00 - :59 (7 Months and 11 Days From LTA Reg Date (Man Yr))
Claim Type:	TP / MCT18050421	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHCB275K	Policy No. (Claimant):	1700060525
		Excess:	
Repairer:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens, 609339 West Coast - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 01/06/2018]		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III\_SG (25/05/2018): Alert - Adj Mandate Maintained - SLS7866E - Claim Handler: Priya
























## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLS7866E (MCT18050421)  
[SHC8275K]  
TP  
MOK CHUN KWONG JEFFREY  
May 15 2018 7:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Cycle & Carriage KIA Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>		<b>View</b> <a href="#">View in Browser</a>		
<b>Photos/Images</b>		3 per page <input type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
2	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
3	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
4	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
5	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
6	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
7	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
8	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
9	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
10	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
11	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
12	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
13	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
14	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
15	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
16	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
17	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
18	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
19	07/09/19 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>		1 per page <input type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/05/18 16:52	EMAIL FROM III DD 22052018	 Load PDF	
2	22/05/18 16:52	TP EST & GIA REPORT	 Load PDF	
3	30/05/18 09:07	TP ESTIMATE- MARKED	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	23/05/18 08:43	Singapore Accident Statement	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		<a href="#">Reset</a>   <a href="#">Save</a>   <a href="#">Print</a>
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18009307/T1PB3Q2

Date: 18/09/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant: SLS7866E Insured Vehicle No: SHC8275K  
 Vehicle No: SLS7866E  
 Date of Loss: 15/05/2018 Nature of Claim: TP Claim No: MCT18050421

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLS7866E  
 Make & Model: KIA FORTE K3, 1.6 (A) Engine No: G4FGHH682299  
 Reg. Date: 04/10/2017 (Man. Year: 2017) Chassis No: KNAFX411MJ5747145  
 Colour: White Odometer: 9635 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm  
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,756.00	1,137.00	1,619.00	58.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,960.00	3,360.00	1,600.00	32.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,716.00</b>	<b>4,497.00</b>	<b>3,219.00</b>	<b>41.72</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>540.12</b>	<b>314.79</b>	<b>225.33</b>	<b>41.72</b>
<b>Nett Amount (S\$)</b>	<b>8,256.12</b>	<b>4,811.79</b>	<b>3,444.33</b>	<b>41.72</b>

## INSPECTION

Date of Assignment: 21/05/2018  
 Date Inspected: 25/05/2018 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)  
 209 Pandan Gardens  
 Singapore 609339  
 Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Sep 2019)
<b>Parts:</b>	143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLS7866E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*COVER -RR BUMPER	Deformed	688.00 FS	*688.00 FS
3	1		*BRACKET -RR BUMPER SIDE MTG ,LH	Necessary	29.00 FS	*29.00 FS
4	1		*BRACKET -RR BUMPER SIDE MTG ,RH	*Check	29.00 FS	*- FS
5	1		*COVER-RR BUMPER ,CTR	Not Necessary	347.00 FS	*- FS
6	2		*RETAINER -BUMPER SIDE MTG	*Check	2.00 FS	*- FS
7	4		*RETAINER	*Check	8.00 FS	*- FS
8	1		*LAMP ASSY -REAR COMBINATION ,LH	*Check	788.00 FS	*- FS
9	1		*GUARD ASSY -REAR WHEEL ,LH	*Check	75.00 FS	*- FS
10	1		*HUB ASSY -RR WHEEL	*Check	340.00 FS	*- FS
11	1		*LH REAR SPORT RIM SSW266	Cut	400.00 FS	*400.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)      2,756.00      1,137.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE,BUMPER RETAINER ,REPAIR LH REAR FENDER ,REPAIR LH REAR DOOR	New	2,200.00	1,650.00
2	REMOVE AND INSTALL PARKING ASSIST	New	80.00	60.00
3	PAINT WORK SPRAY REAR BUMPER FACE ,LH REAR FENDER ,LH REAR DOOR AND AFFECTED PORTION	New	1,680.00	1,260.00
4	PERFORM RUST PREVENTION	New	80.00	40.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	50.00	30.00
6	RENEW LH REAR WHEEL HUB BEARING AND AFFECTED PARTS (*Check)	New	550.00	0.00
7	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	200.00	200.00
Gross Labour Cost (S\$)			<b>4,960.00</b>	<b>3,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >