

Our Ref : T 0518 / SH 6746A /CL(st)		ENGINEERING
Your Ref:		O TO ID IO F STORY OF DISTANCE
Date : 30-May-18	CDGE Taxi Claims Dept	ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701
AIG ASIA PACIFIC INSURANCE PTE LTD	59 Loyang Drive 4th Floor	Mainline +65 6383 6280 Facsimilie +65 6280 9755
CHARTIS Buliding	Singapore 508969	www.cdge.com.sg
78 Shenton Way		Company Registration No: 199506048W
#07-16		Workshops
Singapore 079120 Attn: Motor Claims Department WITHOUT PR	REHIDICE	Braddell 205 Braddell Road Singapore 579701
Dear Sir		Loyang 59 Loyang Drive Singapore 508969
	JR INSURED <u>SGF 57Y</u> 18.05.18	Sin Ming 383 Sin Ming Drive Singapore 575717
We are the authorised repair workshop for Comfort Trans Vehicle No: SH 6746A which was involved in the cap The vehicle owner and the taxi driver concerned have red in presenting their claims against the party responsible fo the damage to the vehicle.	ptioned accident with you quested and authorized u	ur insured vehicle ingapore 609286 us to assist them arising from 320 Ubi Road 3 Singapore 408649 Senoko
As the accident was caused by the negligent act of your in	nsured driving SGF 57Y	24 Senoko Loop Singapore 758156
we are submitting these claim for your consideration on b	ehalf of the claimants.	Sungei Kadut
TAXI OWNER'S CLAIM	0 400	7 Sungei Kadut Way Singapore 728791
1 Cost of Repair 2 2 days Loss of Rental @ \$ 117.00 per of		44.51 Yishun Industrial Park A
3 Survey Report Fees (Surveyed by M/s LKK)	\$	Singapore 768732
4 GIA / LTA Search Fees	\$	7.49
5 GIA / Police Report Fees	\$	-
6 Towing / Medical / Transporation	\$	-
	Sub Total: \$ 1,52	26.00
HIRER'S CLAIM	davs \$ 16	60.00
7 days Loss of Income @\$ 80.00_ per d		
1	Total Claims : \$ 1,68	36.00
We enclose herewith the following documents to support		pcs.
a) Original repair bill and photocopies of photographsb) LTA search slip/s of : SGF 57Y	0	poo.
c) GIA / Police report/s of : SH 6746A		
d) Letter of authority from owner / hirer / operator		
	Certificate of Insurance	
() Witness statement/s (x) Downtime/Mile		

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully Cecilia Lee Executive

CDGE Claims Department

COMFORTDELGRO

Tel: 6214 8354 Fax: 6214 1843 Email: cecilialee@sparkcarcare.com

This is a computer generated letter. No signature is required.

A member of







LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

SONATA SH6746A , SGF57Y

ON 18-May-18 13:10

ALONG

ALONG SIMS AVE BEFORE LOR 21 GEYLANG

I / We

LOW PUAY THIAN

(Hirer) NRIC No .:

S1181916H

and/or

(Relief) NRIC No .:

Taxi Number

SH6746A

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of

"ComfortDelGro Engineering Pte Ltd".

Date

18-May-2018

Name of Hirer

LOW PUAY THIAN

Hirer NRIC

S1181916H

Signature:

One

Address

411 EUNOS ROAD 5 #10-124

400411

Contact No.

96305807



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

650.00

COMPANY REG. NO.: 199506048W Page: 1

	801.00 AIG A	04 SIA PACIFIC INS	RANCE PTE LTD	VEHCLE SH 6746	NO A	TNV. NO/DATE 91374348 25.05.2018			
	#08-1 SINGA	6 78 SHENTON WAY	7.CHARTIS BUILD	MAKE HYUNDAT		JOB NO. 305162402			
	CONTA	CT NO: 641.93000	3225094	MODEL (-40		DATE/TIME IN 21.05.2018 08:30			
				DATE 0 20.12.					
	Descr	iption: 39 18.0	05.18	CHASSIS CODE KMHLB41UMHU099359					
	S/No	Part No.		Qty	Unit Price	%Disc	Net.		
	PART	REQUISITION							
	0001	04-01-0103-0579	140VC COVER ASSY-RR BUMPE	1	603.60	20.00	482.88		
	0002	04-01-0101-011	HYUNDAL BUMPER COVER CLIP	1.0	2.20	20.00	17.60		
	0003	04-01-0103-1150	140VC PROTECTOR MAT	1	50.00	0.00	50.00		
				SUB-TOTAL	4 4	5	50.48		
	JOB N	ATURE							
	0001	L	PANEL BEATING- REAR	200.00		200.00			
	0002	23-502	SPRAYPAINT ON AFFECTED AREA	1.8	0.00	180.00			
١	0003	20-05	RENEW ADVERTISMENT STICKER-	25	0.00	250.00			
	0004	L	REMOVE/REFIX REVERSE SENSOR	2	0.00	20.00			

WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OF ACCIDENTAL DAMAGE, THE COMPANY AGCEPTS OF RESPONSIBILITY FOR CARS OF OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED

SUB-TOTAL

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91374348	1,284.51	

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCR DELIVERY GI NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS, OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPT IN GOOD ORDER.

INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.

PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OF DISCREPANCIAL WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL THEAT THIS INVOICE A



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 57970

Mainline + 65 6383 6280 Facsimile + 65 6280 9755 Workshops

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W Page:

801.0004

AIG ASIA PACIFIC INSURANCE PTF LTD

#08-16 78 SHENTON WAY CHARTIS BUILD SINGAPORE SG 079120

CONTACT NO: 64193000

3225094

VEHCLE NO SH 6746A

INV. NO/DATK 91374348 25.05.2018

MAKE HYUNDAT

JOB NO. 305162402

MODEL. I - 40

ODOMETER READING

DATE OF REG 20.12.2017

DATE/TIME IN 21.05.2018 08:30

CHASSIS CODE KMHT.B41UMHU099359

Items total

1,200.48

Add GST @

7,000 %

84.03

Invoice amount

1,284.51

Issued by

KATHERINETAN 25.05.2018 11:30:40

Repair type : CLSO/57/57 Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

AMOUNT BANK/CHQ No. ACCOUNT No. INVOICE No. 91374348 1,284,51 8010004

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT18050480

Date: 25 May 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

18/05/2018 @ 13:10 hrs

ALONG

ALONG SIMS AVE BEFORE LOR 21 GEYLANG

INVOLVING

SGF57Y

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SH6746A (the "Taxi"). The Taxi was hired to LOW PUAY THIAN IC NO S1181916H a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$117.00 per day (inclusive of GST).

Please be advised that the Taxi was insured with MS First Capital Insurance Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

Line	September 1994	-	to de compressión de la compressión de	electric consta	1	-			-	-	·	-	-
	HOURS OPERATED (TIME)	TO	8/90		8/10	6.60		H30					
	HOURS OF	FROM	1703	720n	1772	7	0830						
	MILEAGE TRAVELLED (KM)		326	118	205	41	14	on					
	MILEAGE READING		070252	070470	97067F	269910		\ \ \ \					
171161	SH 67461		M. G. Je	KM	17. 6 121.	LW Y	Heident,	Repair 1 F	A CONTRACTOR OF THE PROPERTY O				THE REPORT OF THE PROPERTY OF
	DATE		19/5/18	20/17/18	20/5/18	21/18	21/5/18	22/5/18					
	HOURS OPERATED (TIME)	10	Samuel Samuel										
		FROM											
	MILEAGE	TRAVELLED (KM)											
		<u>o</u>											

.

Insurance Particulars Enquiry By Agents Detail

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time

Search Status Insurance Company Code

Insurance Company Name

SGF57Y

18 May 2018 / 13:10:00

Successful

A04

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Previous

OK













