

ASS. REC. BY:

REF: 03/CT118009313/ T1cd3

Special Instruction:

Survivor
Menmen

From (Person):

Taufik
Jawyn Tay

ASSIGNMENT (Office)

of CTI

Date/Time: 22/5/18 @ 3.30pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 6524T

Insured:

SKP 9093H

at Workshop m/s

SK Automobile

Tel:

6789 5155

of

1 Soon Lee Street # 04-44/45

Policy No:

DMPCSN1523241702

Claim No:

SNM18D02530C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/05/2018

CA / REV / REP. / REV 24 HRS

lwp

23/5/2018

H.O.D. Endorsement:

Date/Time:

5.07pm @ 22/5/18

Person Contacted:

Huey Lee

Vehicle

(IN) OUT

Date/Time

Action/Instruction (✓) Estimate

SLT 6524T-X

SKP 9093H-X

ASSIGNMENT

From:

Date:

23/05/2018

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLT 6524T

at Workshop m/s

SK Automobile

of 1 soon lee street # 04-14/45

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS (wp)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLT 6524T

Yr Regn:

2017, NOV

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra

cc 1591

Colour:

Grey

A/C

Insured / Std / NI / NA

Sp. Reading:

6263

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM HD841CM 34570218

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

as is

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Roadstone

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

23/5/18

Survey held at

SK Auto

Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/7

Inspected with w/s Hk Xing cost 4900, 6 days (Red. 12,370.48, 712)

Date/Time: File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation

1 S + RS 9

1 Photo

1 Other

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week-end (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

4900

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18009313/T1rd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 22-05-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 9093H	Veh. Inspected	SLT 6524T
Policy No.	DMPCSN1523241702	Coverage (\$)	0.00
Claim No.	SNM18D02530C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	22/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/05/2018	Inspection Date
Survey held at	1 SOON LEE STREET # 04-44/45	
Repairer	SK AUTOMOBILE PTE LTD	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2018		22 May 2018 15:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	MOSA BIN AHMAD
Vehicle Reg. No.:	SLT6524T
Claim Type:	TP / SNM18D02530C02
Vehicle Reg. No. (Insured):	SKP9093H
Date of Loss:	19/05/2018 00:00 - :59
Policy/Cover Note No.:	DMPCSN1523241702
Policy No. (Claimant):	
Excess:	S\$0.00
Repairer:	SK Automobile Pte Ltd (Pioneer) 1 Soon Lee Street #04-44/45, Pioneer Centre, 627605 Pioneer - Tel:
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/06/2018]
Adj Asg. Remarks:	NO EST, CASE WITH SJE.

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Julie Johari <julie@skauto.com.sg>
Sent: Tuesday, 22 May, 2018 11:02 AM
To: Claims Dept of CTI
Cc: Pioneer Workshop; XIONG
Subject: ARRANGE PRI FOR SLT 6524T (YOUR REF: SKP 9093H)
Attachments: ARRANGE PRI FOR SLT 6524T.pdf; SLT 6524T_GIA REPORT.pdf

Dear Sir/Madam, **'WITHOUT PREJUDICE'**

Kindly arrange surveyor to survey our client vehicle at **(URGENT)**

1 Soon Lee Street

#04-44 / 45 Pioneer Centre

Singapore 627605

Contact Person: Xiong - 8121 0478

Michael - 9018 3598

Your Insured: SKP 9093H

DOA : 19.05.2018

Place: ROAD 1 SIMS AVENUE

Time: 22:30hrs

Please do not hesitate to contact me should you have any queries thereof.

Best Regards,



Julie

SK Automobile Pte Ltd (201500047H)

23 Kaki Bukit Avenue 4

#03-01 VICOM Inspection Centre

Singapore 415933

Tel: 6789 5155

Fax: 6783 5155

DID: 9623 4440

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	996F
Vehicle Details	
Vehicle No.:	SLT6524T
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jul 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	G4FGHU806337
Chassis No.:	KMHD841CMJU570298
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$11,960.00
Original Registration Date:	06 Nov 2017
First Registration Date:	06 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$11,960.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Nov 2027
PARF Rebate Amount:	\$8,970.00
Intended COE Rebate Details	
COE Expiry Date:	05 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$24,761.00
COE Rebate Amount:	\$20,462.00
Total Rebate Amount:	\$29,432.00

The information contained herein is correct as at 31 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/05/2018 15:59
Date Of Accident	19/05/2018 22:30
Exact Location Of Accident	ALONG ROAD 1 SIM AVE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLT6524T
Insured/Policyholder	
Name Of Registered Owner	MOSA BIN AHMAD
NRIC No	S7014996F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98321497
Alternative Phone No	OFFICE-60000000
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	ELANTRA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P2023946
Cover Note Number	
Driver	
Name of Driver	MOSA BIN AHMAD
NRIC No	S7014996F
Date Of Birth	02/05/1970
Occupation	INDOOR
Date Of Driving Pass	16/01/2006
Driving Experience	12 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98321497
Fax Number	
Contact Number	OFFICE-60000000
Email Address	NOEMAIL

Address	BLK 279 TOH GUAN ROAD #09-197
Postcode	600279
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	T/20180519/20155
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Report Please refer to Police Report

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP9093H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance company.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Benefits Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (c) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: 
NIC/PIN No.: 

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER POLICE REPORT NO. T/2018CS19/2155

DECLARATION

We declare the foregoing particulars are true in every respect.

Moxi
Policyholder's Signature
Date & Time:

Moxi
Driver's Signature
(If driver is not the policyholder)
Date & Time:

L
Reporting Centre Personnel's Signature
Name: Rennell
KRIC/ENR100: 571318090

Police Report



**SINGAPORE
POLICE FORCE**



T/20180519/2155

2 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180519/2155

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SLT6524T	AXA INSURANCE SINGAPORE PTE LTD	P2023946	06/11/2017	05/11/2018

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MOSA BIN AHMAD		ID No. S7014996F
Related Vehicle	SLT6524T (Car)		Contact No. 98321497
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 19/5/18 at about 2230hrs

While traveling straight along Sims Avenue, a car while exiting from a carpark hit onto the right back door of my vehicle. I tried to stop the driver to exchange particulars for insurance purposes but she ignored me and drove off.

TEO HIN TYRES

11 KAKI BUKIT ROAD 1
#01-01 EUNOS TECHNOLINK
SINGAPORE 415939
TEL: 67455711

Work Order: R002275
Company: SK AUTOMOBILE
License: SLT6524T
Odometer:
Date: 20/05/2018 9:00

HYUNDAI ELANTRA

Front : Left

Actual	Before	Specified Range
-1°02'	-1°02'	-1°20' 0°10'
-3°01'	3°01'	2°05' 3°35'
-0°01'	-0°01'	-0°05' 0°07'
12°54'	12°54'	
11°53'	11°53'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°02'	-1°02'	-1°20' 0°10'
-3°01'	3°01'	2°05' 3°35'
-0°02'	-0°01'	-0°05' 0°07'
12°54'	12°54'	
11°53'	11°53'	

Front

	Actual	Before	Specified Range
Cross Camber	-0°07'	-0°12'	-1°20' 0°10'
Cross Caster	-0°04'	-0°04'	-1°20' 0°10'
Cross SAI	-0°24'	-0°28'	
Cross Toe	-0°01'	-0°24'	-1°20' 0°10'
Cross Turning Diff.			

Rear : Left

Actual	Before	Specified Range
-1°13'	-1°11'	-1°53' 0°26'
-0°37'	0°09'	0°06' 0°16'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°12'	-1°12'	-1°53' 0°26'
-0°08'	-0°08'	0°06' 0°16'

Rear

	Actual	Before	Specified Range
Cross Camber	-0°48'	-0°48'	-0°45' 0°45'
Total Toe	-0°35'	-0°35'	-0°12' 0°33'
Thrust Angle	-0°00'	-0°02'	



SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
1 Soon Lee Street #04-44/45
Pioneer Centre
Singapore 627605
Tel: 626204438 Fax : 6484 1111

TO	: CHINA TAIPING	DATE	: 21-May-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SLT6524T
ADDRESS	:	MODEL	: HYUNDAI 'ELANTRA
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>		DATE	:
		TIME	:
THIRD PARTY REQUESTOR / CONTACT : KUMAR 9897 3736			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR RH	1	\$ 782.00	\$ 782.00
2	REAR DOOR RH	1	\$ 754.00	\$ 754.00
3	REAR DOOR INNER LOCK RH	1	\$ 227.20	\$ 227.20
4	REAR DOOR INNER TRIM RH	1	\$ 448.00	\$ 448.00
5	REAR DOOR INNER SPONGE RH	1	\$ 50.00	\$ 50.00
6	REAR DOOR SPEAKER RH	1	\$ 241.00	\$ 241.00
7	REAR DOOR INNER STEP GARNISH RH	1	\$ 95.00	\$ 95.00
8	REAR DOOR HINGE RH	2	\$ 58.00	\$ 116.00
9	REAR DOOR LOCK CATCHER RH	1	\$ 16.40	\$ 16.40
10	REAR DOOR WEATHER STRIP RH	1	\$ 174.80	\$ 174.80
11	REAR DOOR OUTER WEATHERSTRIP RH	1	\$ 115.00	\$ 115.00
12	REAR DOOR REGULATOR WITCH BOARD RH	1	\$ 233.20	\$ 233.20
13	REAR DOOR FRAME WEATHER STRIP RH	1	\$ 116.50	\$ 116.50
14	REAR BUMPER	1	\$ 489.00	\$ 489.00
15	REAR BUMPER RETAINER RH	1	\$ 54.50	\$ 54.50
16	REAR FENDER RH	1	\$ 985.00	\$ 985.00
17	REAR FENDER INNER COWLING RH	1	\$ 98.70	\$ 98.70
18	REAR WINDSCREEN MOULDING	1	\$ 129.80	\$ 129.80

bt ✓
bt ✓
? bt ✓
X }
X }
X }
? de ✓
Ry ✓
cut ✓
X an
3X an
X an
cut ✓
Ry ✓
? de ✓
X an

19	REAR SIDE SKIRT	1	\$ 1,817.00	\$ 1,817.00
20	REAR ABS SENSOR	1	\$ 452.00	\$ 452.00
21	REAR WHEEL RIM RH	1	\$ 1,054.00	\$ 1,054.00
22	REAR AXLE	1	\$ 2,410.00	\$ 2,410.00
23	REAR SHOCK ABSORBER RH	1	\$ 348.00	\$ 348.00
24	REAR WHEEL BEARING RH	1	\$ 321.00	\$ 321.00

4512.20

3609.76

TOTAL PRICE \$ 11,528.10
LESS 20% \$ 2,305.62
SUB TOTAL PRICE \$ 9,222.48

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP SET	1	\$ 65.00	\$ 65.00
2	REAR BUMPER LOWER LID	1	\$ 1,200.00	\$ 1,200.00
3	REAR FENDER RH SEALANT	1	\$ 80.00	\$ 80.00
4	REAR FENDER INNER COWLING CLIP SET	1	\$ 120.00	\$ 120.00
5	REAR FENDER INNER TRIM CLIPS SET	1	\$ 118.00	\$ 118.00
6	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00
7	REAR WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
8	REAR DOOR SEALANT RH	1	\$ 80.00	\$ 80.00
9	REAR DOOR FRAME STEP GARNISH CLIP RH	1	\$ 45.00	\$ 45.00
10	REAR DOOR INNER TRIM CLIP RH SET	1	\$ 80.00	\$ 80.00
11	REAR WHEEL TYRE	1	\$ 450.00	\$ 450.00

TOTAL \$ 2,378.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	700.
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,500.00	800
3	TUFF COAT	\$ 250.00	30.
4	WIRING CHECK	\$ 60.00	20.
5	REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 380.00	60.
6	WHEEL ALIGNMENT	\$120.00	80.
7	ABS LIGHT RESET	\$350.00	X m
8	TRANSFER REAR DOOR MECHANISM	\$80.00	60
9	REMOVE & REINSTALL REAR WINDOW GLASS	\$80.00	X m

10	CONDUCT WATER LEAKAGE TEST	\$ 80.00		X an
11	REMOVE AND REPLACE REAR WINDSCREEN	\$ 140.00		X un
12	REMOVE AND REFIT REAR UNDERCARRIGE	\$ 550.00		photo 150%
13	MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00		100

TOTAL

\$5,670.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,600.48
 TOTAL LABOUR COST : \$ 5,670.00
 TOTAL REPAIR COST : \$ 17,270.48

APPROVED DETAILS

EXCESS :
 NO. OF WORKING DAY::
 RE-SURVEY :
 PART BY PART OR LUMP SUM :
 DATE & TIME OF SURVEY :
 SURVEYED BY :
 CONTACT NUMBER :
 FAX NUMBER :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by

Signature:

Date:

3609.76

530

2000

6139.76

4594900

6 days

Tanlim 97495419

23/5/18 @ 1130

wr

Resurvey after repair

6 days

sur @ 11:00am

30/5/18

3 check diagnosis of vehicle

2000

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118009313/T1CD3N2

Date: 31/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1523241702
Claimant Vehicle No :	SLT6524T	Insured Vehicle No :	SKP9093H
Date of Loss:	19/05/2018	Nature of Claim:	TP
		Claim No:	SNM18D02530C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT6524T	Engine No:	G4FGHU806337
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHD841CMJU570298
Reg. Date:	06/11/2017 (Man. Year: 2017)	Odometer:	6263 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R17	Rear Tyre Size:	215/45R17
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,600.48	4,139.76	7,460.72	64.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,670.00	2,000.00	3,670.00	64.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,270.48	6,139.76	11,130.72	64.45
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	17,270.48	4,900.00	12,370.48	71.63
+ GST 7.00/7.00% (S\$)	1,208.93	343.00	865.93	71.63
Nett Amount (S\$)	18,479.41	5,243.00	13,236.41	71.63

INSPECTION

Date of Assignment:	22/05/2018	
Date Inspected:	23/05/2018	Inspected At:
		1 Soon Lee Street #04-44/45
		Pioneer Centre
		Singapore 627605
		Repairer: SK Automobile Pte Ltd
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2019)
Parts: 143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLT6524T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Bent	782.00 FL	*782.00 FL
2	1		*REAR DOOR RH	Bent	754.00 FL	*754.00 FL
3	1		*REAR DOOR INNER LOCK RH	Bent	227.20 FL	*227.20 FL
4	1		*REAR DOOR INNER TRIM RH	Not Necessary	448.00 FL	*- FL
5	1		*REAR DOOR INNER SPONGE RH	Not Necessary	50.00 FL	*- FL
6	1		*REAR DOOR SPEAKER RH	Not Necessary	241.00 FL	*- FL
7	1		*REAR DOOR INNER STEP GARNISH RH	Deformed	95.00 FL	*95.00 FL
8	2		*REAR DOOR HINGE RH	Bent	116.00 FL	*116.00 FL
9	1		*REAR DOOR LOCK CATCHER RH	Repair	16.40 FL	*- FL
10	1		*REAR DOOR WEATHER STRIP RH	Cut	174.80 FL	*174.80 FL
11	1		*REAR DOOR OUTER WEATHERSTRIP RH	Not Necessary	115.00 FL	*- FL
12	1		*REAR DOOR REGULATOR WITCH BOARD RH	Not Necessary	233.20 FL	*- FL
13	1		*REAR DOOR FRAME WEATHER STRIP RH	Not Necessary	116.50 FL	*- FL
14	1		*REAR BUMPER	Cut	489.00 FL	*489.00 FL
15	1		*REAR BUMPER RETAINER RH	Necessary	54.50 FL	*54.50 FL
16	1		*REAR FENDER RH	Repair	985.00 FL	*- FL
17	1		*REAR FENDER INNER COWLING RH	Deformed	98.70 FL	*98.70 FL
18	1		*REAR WINDSCREEN MOULDING	Not Necessary	129.80 FL	*- FL
19	1		*REAR SIDE SKIRT	Cut	1,817.00 FL	*800.00 FL
20	1		*REAR ABS SENSOR	Not Necessary	452.00 FL	*- FL
21	1		*REAR WHEEL RIM RH	Cut	1,054.00 FL	*600.00 FL
22	1		*REAR AXLE	Not Necessary	2,410.00 FL	*- FL
23	1		*REAR SHOCK ABSORBER RH	Not Necessary	348.00 FL	*- FL
24	1		*REAR WHEEL BEARING RH	Bent	321.00 FL	*321.00 FL
25	1		*SET REAR BUMPER CLIP	Necessary	65.00 FS	*20.00 FS
26	1		*REAR BUMPER LOWER LID	Cut	1,200.00 FS	*300.00 FS
27	1		*REAR FENDER RH SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*SET REAR FENDER INNER COWLING CLIP	Necessary	120.00 FS	*10.00 FS
29	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	118.00 FS	*- FS
30	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
32	1		*REAR DOOR SEALANT RH	Necessary	80.00 FS	*20.00 FS
33	1		*REAR DOOR FRAME STEP GARNISH CLIP RH	Not Necessary	45.00 FS	*- FS
34	1		*SET REAR DOOR INNER TRIM CLIP RH	Necessary	80.00 FS	*20.00 FS
35	1		*REAR WHEEL TYRE	Cut	450.00 FS	*160.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,906.10	5,042.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,305.62	902.44
Total Parts (\$\$)	11,600.48	4,139.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,800.00	700.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,500.00	800.00
3	TUFF COAT	New	250.00	30.00
4	WIRING CHECK	New	60.00	20.00
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	380.00	60.00
6	WHEEL ALIGNMENT	New	120.00	80.00
7	ABS LIGHT RESET	New	350.00	0.00
8	TRANFER REAR DOOR MECHANISM	New	80.00	60.00
9	REMOVE & REINSTALL REAR WINDOW GLASS	New	80.00	0.00
10	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
11	REMOVE AND REPLACE REAR WINDSCREEN	New	140.00	0.00
12	REMOVE AND REFIT REAR UNDERCARRIAGE	New	550.00	150.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	100.00
Gross Labour Cost (\$\$)			5,670.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >