

22/03/2007

ASS. REC. BY:

REF: CS3/AIG18009302/Nz4d3

Special Instruction:

Surveyor  
Mainmen

Naz

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

22/5/18 @ 12:58pm

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 8391L

Insured:

SDL 5555Y

at Workshop m/s

D's Griffith Concepts

Tel:

8608 3456

of

25 Kaki Bukit Road 4 # 06-26

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/05/2018

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

10:26am @ 23/5/18

Person Contacted:

Dave

Vehicle:

IN /  OUT

Date/Time	Action/Instruction ( X ) Estimate	
	SLQ 8391L - NA / TMI 18009038 / 24	DOA: 17/5/18
	SDL 5555Y - NA / TMI 18009038 / 24	DOA: 17/5/18
24/5/18	dismantled	

31220118 NA2

REF: A19

ASSIGNMENT

From: \_\_\_\_\_ Date: 23/5/2018

Estimated Cost: \_\_\_\_\_

OD  TP  WS  TP RES  OD RES  EVA  INV  MV

To Inspect Vehicle No: SLQ 8391L

at Workshop m/s D's Graffiti Concepts

of 25 kaki Bukit Rd 4 # 08-26

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: SLQ 8391L Yr Regn: 1

Type:  M.Car  M.Cycle  Bus  Van  Lorry  Taxi  Prime Mover

Truck / Trailer or \_\_\_\_\_

Make: HYUNDAI ELANTRA c.c. \_\_\_\_\_

Colour: WHITE A/C:  Insured  Std  NI  NA

Sp. Reading: 21,456 T/Radio:  Insured  Std  NI  NA

Eng/No: \_\_\_\_\_

C/No: KMH841CMJU508467

Gen. Cond: Good  Fair  Poor  Burnt

Steering:  Inorder  Jammed  Leaked  Burnt or \_\_\_\_\_

Brake:  Inorder  Jammed  Leaked  Burnt or \_\_\_\_\_

Modi: Nil  S/Rim   STD A/Rim or \_\_\_\_\_

Tyre Size: F: 215/45 R17

R: 11

BS  DUN  EXNOVA  GY  FS  LIZA  MIC  OHTSU  PIR  SUMI

TOYO/YOKO or FALKEN

Front	Rear
R/Bal. <u>7</u> mm	R/Bal. <u>7</u> mm
L/Bal. <u>7</u> mm	L/Bal. <u>7</u> mm
D.O.A. _____	D.O.I. <u>23/5/18</u>

Survey held at D's GRAFFITI CONCEPTS

Des. of Damages: Frt  Rear  O/S  N/S  UIC  Rooftop or O/S FRONT

The UIC / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Wp

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
<u>28/5/18</u>	<u>Submit DAR Report</u>

RECEIVED 30 MAY 2018

Date/Time File Pass to?  : Preli. Report

1)  : Final Report

Date/Time File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$) \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:  Site Insp (\$) \_\_\_\_\_ ) \$ + RS \_\_\_\_\_ SI

Interview (\$) \_\_\_\_\_ ) Photos

Tech. Invs (\$) \_\_\_\_\_ ) Others

Weekend (\$) \_\_\_\_\_ )

TOTAL 180

20

200

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDL5555Y AND SLQ8391L ON 17/05/2018**

From: Chin, Lee-Ying  
To: 'assignments', Admin A  
Cc: Fong, Andy-SY  
Sent: Tuesday, 22 May, 2018 12:58:32 PM  
Attachments:  [SDL5555Y - PRI.TIF](#)

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** G S Lim & Partners [<mailto:gslimlaw@singnet.com.sg>]  
**Sent:** Monday, May 21, 2018 3:07 PM  
**To:** Lim, Sheng Yang  
**Subject:** PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDL5555Y AND SLQ8391L ON 17/05/2018

Your Reference : HL/DGC/11833/18/ck  
Our Reference : 5476566806SG003

Dear Sirs

We refer to your email of even date.

Pursuant to State Courts Practice Directions Amendment No. 1 of 2016, our client is not agreeable to your list of surveyors. Our client's appointed surveyor is Mr Fong Kok Heng (Automax Survey).

Please contact and liaise with the workshop directly to arrange for the pre-repair survey of our client's damaged vehicle and obtain the requisite documents from them.

Workshop	M/s D's Graffiti Concepts Pte Ltd
Address	25 Kaki Bukit Road 4 #06-26 Synergy @ KB Singapore 417800 #06-26
Contact Person	Mr Dave
Tel No.	86083456

Thank you.

Regards,

**G S Lim & Partners** | 150 South Bridge Road #02-30 Fook Hai Building Singapore 058727

☎ 65324518 | 📠 65325410 | ✉ [gslimlaw@singnet.com.sg](mailto:gslimlaw@singnet.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**林 錦 秀 律 師 館** **G S LIM & PARTNERS**

Advocates & Solicitors  
Notary Public  
Commissioner for Oaths

**HENRY G S LIM**  
LLB (Hons) (London)  
Barrister-at-Law (Lincoln's Inn)

**DAVID YONG KHUNG LIN**  
LLB (Hons) (University of Bristol)

150 South Bridge Road  
#02-30 Fook Hai Building  
Singapore 058727  
Tel 65324518 Fax 65325410  
email : gslimlaw@singnet.com.sg  
UEN 53131358A  
GST Reg No. M90361086A

Our Reference : HL/DGC/11833/18/ck  
Your Reference :

18 May 2018

M/S AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#08-16  
SINGAPORE 079120

**BY FAX 64153727 ONLY**

Attn : Motor Claims Department

Dear Sirs

**PRE-REPAIR SURVEY – NOTIFICATION OF INSPECTION  
ACCIDENT ALONG BAYFRONT AVE INVOLVING SLQ 8391L & SDL 5555Y ON 17.05.18**

We are instructed b M/s D's Graffiti Concepts Pte Ltd to notify you of a road traffic accident on 17.05.18 along Bayfront Ave involving our client's vehicle registration number SLQ 8391L & SDL 5555Y driven by your insured at the material time. A copy of the Singapore Accident Statement is attached.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully



**HENRY G S LIM**

Encl

cc : M/s D's Graffiti Concepts Pte Ltd



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18009362/Nz4d3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 23-05-2018



Code : AIG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SDL 5555Y	Veh. Inspected	SLQ 8391L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	23/05/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	17/05/2018	Inspection Date	23/05/2018
Survey held at	-		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

MNA118064675 / National Assessment Centre Services - Ubl  
 ENTRY DATE & TIME: 18/05/2018 10:44  
 SUBMITTED BY: Jackson Ho Zhao Tian

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report	18/05/2018 10:44
Date Of Accident	17/05/2018 16:20
Exact Location Of Accident	BAYFRONT AVE AFTER JUNC SHEARES LINK
Country/State of Loss	SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ8391L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KOH WEI HAO
NRIC No	S9047319J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91508506
Alternative Phone No	OFFICE-91508506
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	ELANTRA AD 1.6 GLS AT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MU008362
Cover Note Number	
<b>Driver</b>	
Name of Driver	KOH WEI HAO
NRIC No	S9047319J
Date Of Birth	26/11/1990
Occupation	INDOOR
Date Of Driving Pass	10/07/2009
Driving Experience	8 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91508506
Fax Number	
Contact Number	OFFICE-91508506
Email Address	NOEMAIL

Address BLK 688C WOODLANDS DRIVE 75  
#13-46  
Postcode 733688  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

**General Information of the Accident**

Type Of Accident COLLISION - CHANGE/CROSS LANE  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident 2  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 3  
Passenger 1

NAME: : NG ZHAO WEI (HUANG ZHAOWEI)  
GENDER: : MALE

Passenger 2

NAME: : TAN JIAN HUAI, EDDY (CHEN JIANHUAI)  
GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? YES  
If Yes, Please state which Police Station

Police Station Name

GEYLANG NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 132 PAYA LEBAR ROAD, POSTCODE: 409014, COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-8486999 - FAX NO: 68486799

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

REFER TO POLICE REPORT - T/20180518/2040.

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: VIDEO FOOTAGE WITH DRIVER  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SDL555Y  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR

Name of Driver LIM HAN POH  
NRIC/Passport Number S1412345H  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver) 1

**DETAILS OF INJURED PERSON 1**

Name KOH WEI HAO  
Approximate Age  
Injuries Sustain NECK & BACK  
Injured person in which vehicle? SLQ8391L  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode

**DETAILS OF INJURED PERSON 2**

Name NG ZHAO WEI (HUANG ZHAOWEI)  
Approximate Age  
Injuries Sustain NECK  
Injured person in which vehicle? SLQ8391L  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode

**DETAILS OF INJURED PERSON 3**

Name TAN JIAN HUAI, EDDY (CHEN JIANHUI)  
Approximate Age  
Injuries Sustain BACK  
Injured person in which vehicle? SLQ8391L  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode

## Accident Sketch Plan


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims (including the settlement of the claims and any necessary investigations relating to the claims);
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and adjudication in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



T/20180518/2040

Police Station of Origin:  
Geylang N.P.C  
132 Paya Lebar Road SINGAPORE 409014  
Tel No: 1800-8486999

1 of 4

Report No. T/20180518/2040

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/05/2018 11:38		Vide Report No.:		Station Diary No.: 43	
<b>Informant's Particulars</b>					
Name of Informant: KOH WEI HAO			Address: APT BLK 688C WOODLANDS DRIVE 75 #13-46 SINGAPORE 733688		
ID Type / ID No.: NRIC NO / S9047319J			Contact No.: Home/Office:		Mobile: 91508506
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 27	Date of Birth: 26/11/1990	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SAF PERSONNEL			Driving Licence Information: Class: 3		Date of Expiry:

<b>Sensitive Information of the Accident</b>					
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/05/2018 16:20	Type of Location: Straight Road	
Location: Along Road 1 BAYFRONT AVENUE					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SDL5555Y	Car				Slightly Damaged	0
SLQ8391L	Car	HYUNDAI	ELANTRA AD 1.6 GLS AT	White	Slightly Damaged	2

<b>Details of Vehicle Insurance</b>					
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date	



**SINGAPORE  
POLICE FORCE**



T/20180518/2040

Police Station Of Origin:  
Geylang N.P.C  
132 Paya Lebar Road SINGAPORE 409014  
Tel No: 1800-8486999

2 of 4

Report No. T/20180518/2040

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SLQ8391L	TOKIO MARINE INSURANCE SINGAPORE LTD.	MU008362	25/07/2017	24/07/2018

Details of Person Involved				
----------------------------	--	--	--	--

Any Pedestrian Involved: No				
-----------------------------	--	--	--	--

No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
---------------------------------	--	--------------------------------	--	--

Passenger				
-----------	--	--	--	--

Name	TAN EDDY	ID No.	S9037912G	
------	----------	--------	-----------	--

Related Vehicle	SLQ8391L (Car)	Contact No.	97432621	
-----------------	----------------	-------------	----------	--

Hospital/Clinic	ASIA ONE CHIROPRACTIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
-----------------	-----------------------	--	-----------------------------------	--

Date Treatment	18/05/2018	Date Discharge	18/05/2018	
----------------	------------	----------------	------------	--

No. of Days granted Medical Leave	03	Degree of Injury	Slight	
-----------------------------------	----	------------------	--------	--

Driver				
--------	--	--	--	--

Name	KOH WEI HAO	ID No.	S9047319J	
------	-------------	--------	-----------	--

Related Vehicle	SLQ8391L (Car)	Contact No.	91508506	
-----------------	----------------	-------------	----------	--

Hospital/Clinic	ADMIRALTY FAMILY CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL	
-----------------	---------------------------------	--	---------------------------------	--

Date Treatment	18/05/2018	Date Discharge	18/05/2018	
----------------	------------	----------------	------------	--

No. of Days granted Medical Leave	03	Degree of Injury	Slight	
-----------------------------------	----	------------------	--------	--

Passenger				
-----------	--	--	--	--

Name	NG ZHAO WEI	ID No.	S9021762C	
------	-------------	--------	-----------	--

Related Vehicle	SLQ8391L (Car)	Contact No.	97772795	
-----------------	----------------	-------------	----------	--

Hospital/Clinic	ADMIRALTY FAMILY CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
-----------------	---------------------------------	--	-----------------------------------	--

Date Treatment	18/05/2018	Date Discharge	18/05/2018	
----------------	------------	----------------	------------	--

No. of Days granted Medical Leave	02	Degree of Injury	Slight	
-----------------------------------	----	------------------	--------	--



**SINGAPORE  
POLICE FORCE**



T/20180518/2040

Police Station Of Origin:  
Geylang N.P.C  
132 Paya Lebar Road SINGAPORE 409014  
Tel No: 1800-8486999

3 of 4

Report No. T/20180518/2040

## CONTINUATION OF REPORT

Driver			
Name	LIM HAN POH	ID No.	S1412345H
Related Vehicle	NIL	Contact No.	96168228
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 17.05.2018 at about 1619hrs, I was driving along Bayfront avenue on lane 3 of the 3 lane road when a vehicle on the 2nd lane wanted to make a sharp left turn from his lane into Marina Bay Sands Shoppe Taxi/ Drop off point and cut into my lane. I braked upon seeing that he wanted to cut into my lane however the vehicle still proceeded and collided to the front right side of my vehicle. We then exchanged particulars. The damages to my vehicle are front right bumper dented and scratches, front right headlight scratched and cracked, rims and wheel damaged. My passengers and I suffered from body and neck aches due to the impact.



**SINGAPORE  
POLICE FORCE**



T/20180518/2040

Police Station Of Origin:  
Geylang N.P.C  
132 Paya Lebar Road SINGAPORE 409014  
Tel No: 1800-8486999

4 of 4

Report No. T/20180518/2040

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
G /  
Staff Sgt RUZIANA BINTE MUHAMMAD RUDY

Signature Of Informant:  
*[Handwritten Signature]*


Signature Of Interpreter:  
Not applicable

Date/Time:  
18/05/2018 11:38

Officer In Charge Of Case:  
TP / AEIT /  
SSI KASMAWATI BTE SAMIAN  
Contact No.: 65476179

Classification Of Case:

Authentication Stamp  
NP168

  
SINGAPORE  
POLICE FORCE  
SIGNATURE

Condition (CON)

(1)Went (2)Demol (3)Distorted (4)Cracked (5)Cut (6)Scratched (07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary (12)Missing (13)Torn (14)Unconfirmed (15)Not Working

ACTION (AC)

(1)Replace (✓) (2)Repair (X) (3)Check (?) (4)Not Consistent (NC)

Aug 2005

**MOTOR CAR (Frt)**

Vehicle No: SLQ 8391 L

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frnt Number Plate			
1002	991887	Frnt Number Plate Base			
1003	991889	Frnt Number Plate Garnish			
1004	991300	Frnt Bumper	DM	✓	
1005	992341	Frnt Bumper Clips	NEC	✓	
1006	991325	Frnt Bumper Bracket			
1007	991462	Frnt Bumper Side Retainer			
1008	991433	Frnt Bumper Reinforcement			
1009	991318	Frnt Bumper Beam			
1010	991468	Frnt Bumper Sponge			
1011	991427	Frnt Bumper Protector			
1012	991420	Frnt Bumper Pad			
1013	991363	Frnt Bumper Grille			
1014	991301	Frnt Bumper Moulding			
1015	991407	Frnt Bumper Lower Spoiler	CRK	✓	
1016	991438	Frnt Bumper Sensor			
1017	995100	Frnt LH Bumper Fog Lamp Cover			
1018	991355	Frnt RH Bumper Fog Lamp Cover			
1019	995079	Frnt LH Bumper Fog Lamp			
1020	995080	Frnt RH Bumper Fog Lamp			
1021	991793	Frnt Grille			
1022	991328	Frnt Grille Emblem			
1023	991799	Frnt Grille Chrome Moulding			
1024	991222	Frnt Apron Panel			
1025	992013	Frnt Support Panel			
1026	992025	Frnt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frnt Brace Panel			
1029	995153	Frnt LH Headlamp Assy			
1030	991821	Frnt RH Headlamp Assy	SCR	✓	
1031	995088	Frnt LH Side Lamp			
1032	995089	Frnt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frnt Exhaust Manifold			
1064	991713	Frnt Exhaust Manifold Cover			
1065	991054	Frnt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frnt LH Chassis Member			
1093	991520	Frnt RH Chassis Member			
1094	990728	Frnt Vertical Cross Member			
1095	991863	Frnt Lower Cross Member			
1096	995070	Frnt LH Fender			
1097	995072	Frnt LH Fender Inner Panel			
1098	995147	Frnt LH Fender Lamp			
1099	995148	Frnt LH Fender Protector			
1100	991740	Frnt LH Fender Inner Shield			
1101	995179	Frnt LH Mudflap			
1102	995170	Frnt LH Wheel Rim			
1103	994025	Frnt LH Rim Cover			
1104	995065	Frnt LH Tyre			
1105	995071	Frnt RH Fender	SCR	R	
1106	991739	Frnt RH Fender Inner Panel			
1107	991744	Frnt RH Fender Lamp			
1108	991752	Frnt RH Fender Protector	CRK	✓	
1109	991740	Frnt RH Fender Inner Shield			
1110	991884	Frnt RH Mudflap			
1111	992087	Frnt RH Wheel Rim	CHT	✓	
1112	994025	Frnt RH Rim Cover			
1113	995065	Frnt RH Tyre			
1114	992093	Frnt Windscreen Glass			
1115	992117	Frnt Windscreen Rubber			
1116	992108	Frnt Windscreen Moulding			
1117	992098	Frnt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frnt Wiper Arm			
1121	992142	Frnt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frnt Driver Seat			
1133	991922	Frnt RH Seat Belt Assy			
1134	991899	Frnt Passenger Seat			
1135	995182	Frnt LH Seat Belt Assy			
1136	990247	Sticker			
		Front RH lower arm	Distort	✓	
		Front RH knuckle arm	Distort	✓	
		Front RH absorber	Distort	✓	

No of Items:

Accessories:

original copy

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 May 2018 <a href="#">Edit Reg</a>		22 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>LIM HAN POH</b> , ID: S1412345H								
Main Claimant:	<b>KOH WEI HAO</b> , ID: S9047319J								
Vehicle Reg. No.:	<b>SLQ8391L</b>	Date of Loss:	17/05/2018 16:00 - :59 [9 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 5476566806SG</b>	Policy/Cover Note No.:	2100331873 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SDL5555Y</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>D's Graffiti Concepts (HQ)</b> 25 Kaki bt Road 4 #06-26 Synergy @ KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ] BernardJiQian.Ler@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Muhammad Nazril Bin Abdullah</b> ] ... [Final Rpt due 05/06/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG (25/05/2018): <b>Request To Upload TP GIA Report</b>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLQ8391L (5476566806SG)  
[SDL5555Y]  
TP  
KOH WEI HAO  
May 17 2018 4:00PM  
[LIM HAN POH]  
D's Graffiti Concepts

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	<b>View</b>	View in Browser <span style="font-size: small;">▼</span>	
<b>Photos/Images</b>						3 per page <span style="font-size: small;">▼</span>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	25/05/18 11:10	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
2	25/05/18 11:10	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
3	25/05/18 11:10	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
4	25/05/18 11:10	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
5	25/05/18 11:10	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
6	25/05/18 11:10	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
7	25/05/18 11:10	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
8	25/05/18 11:11	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
9	25/05/18 11:11	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
10	25/05/18 11:11	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
11	25/05/18 11:11	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
12	25/05/18 11:11	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
13	25/05/18 11:11	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
14	25/05/18 11:11	<b>Reinspection Photo</b>		Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>						1 per page <span style="font-size: small;">▼</span>	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		
1	25/05/18 16:08	<b>OI GIA REPORT</b>		Load PDF			

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG18009362/NZ4D3E2

**Date:** 31/05/2018

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100331873
Claimant Vehicle No : SLQ8391L	Insured Vehicle No :	SDL5555Y
Date of Loss: 17/05/2018	Nature of Claim:	TP Claim No: 5476566806SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ8391L	Engine No:	G4FGHU673271
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU508467
Reg. Date:	25/07/2017 (Man. Year: 2017)	Odometer:	21456 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	22/05/2018	
Date Inspected:	23/05/2018	Inspected At: D's Graffiti Concepts (HQ) 25 Kaki bt Road 4 #06-26 Synergy @ KB Singapore 417800
Estimated Period of Repair:	3.0 days	

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** Ho Zhao Tian

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Damaged	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER LOWER SPOILER	Cracked	0.00 F	*- F
4	1		*FRT RH HEADLAMP ASSY	Scratched	0.00 F	*- F
5	1		*FRT RH FENDER	Repair	0.00 F	*- F
6	1		*FRT RH FENDER PROTECTOR	Cracked	0.00 F	*- F
7	1		*FRT RH WHEEL RIM	Cut	0.00 F	*- F
8	1		*FRONT RH LOWER ARM	Distorted	0.00 F	*- F
9	1		*FRT RH KNUCKLE ARM	Distorted	0.00 F	*- F
10	1		*FRONT RH ABSORBER	Distorted	0.00 F	*- F
<b>Total Parts (\$\$)</b>					<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >