

22/03/2002

ASS. REC. BY:

REF:

CS/MSG18009402/U4d3d

Special Instruction:

Surveyor  
Menimen

Marcus

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time:

23/5/18 @ 4:11pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No:

SLK 3500D

Insured:

SLM 4467A

at Workshop m/s

Bluwel Automotive

Tel:

6745 2088

of

1 Kaki Bukit Ave 6 # 01-28

Policy No:

28929939ARW

Claim No:

559117

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/05/2018

CA / REV / REP. / REV 24 HRS

(up)

24/05/2018

H.O.D. Endorsement:

Date/Time:

4:23pm @ 23/5/18

Person Contacted:

Sally

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(X)

Estimate

SLK 3500D - X

SLM 4467A - X.

12/7/18

Dismantled.

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To inspect Vehicle No: SLK 35000  
at Workshop m/s 221  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 821c  
IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
Est. Repairs: 25 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLK 35000 Yr Regn: 6, 12  
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CA  
Make: BMW 320i coupe 1995  
Colour: white A/C: Insured / Std / NI / NA  
Sp. Reading: 102 052 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: WBADU320906 49/PP1  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Mod: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 225/40Z18  
R: 255/35Z18  
BS / DUN / EXNOVA / GY / FS / LIZA / MIP / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 15/5/18 D.O.I. 24/5/18  
Survey held at \_\_\_\_\_ 11.30 am.  
Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or  
MS body &  
The UP / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>no contact. LTA 66401 Rep 14k.</u>
	<u>15-18k.</u>
<u>24/7/18</u>	<u>Submit PRS Report</u>

Date/Time, File Pass to?

☐ : Prel. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

Photos

Others

TOTAL

120
50
10
180

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 May 2018		23 May 2018 16:11 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHUA PUAY KEOW, ID: S1465881E		
Main Claimant:	PANG ZHE LIANG, ID: S9013935E		
Vehicle Reg. No.:	SLK3500D	Date of Loss:	15/05/2018 22:00 - :59 [13 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 559117	Policy/Cover Note No.:	28929939AVW (Comprehensive) Coverage: 30/03/2018 - 29/03/2019
Vehicle Reg. No. (Insured):	SLM4467A	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/05/2018]		
Adj Asg. Remarks:	Liability is not clear. TP disagree with SJE list. Proceed to appoint LKK.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18009402/Uz4d3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 23-05-2018



Code : MSG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLM 4467A	Veh. Inspected	SLK 3500D
Policy No.		Coverage (\$)	0.00
Claim No.	559117	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	23/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	15/05/2018	Inspection Date
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883	

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MSME18066098 / SNE Motor Pte Ltd - Keri Bukit  
ENTRY DATE & TIME: 21/05/2018 16:17  
SUBMITTED BY: Chin Pei Ying

Your NCD will be affected due to late reporting  
Actual e-Filing Submission Date & Time: 21/05/2018 16:22

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon Application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report	21/05/2018 16:17
Date Of Accident	15/05/2018 22:45
Exact Location Of Accident	WOODLANDS AVE 6
Country/State of Loss	SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK3500D
Insured/Policyholder	
Name Of Registered Owner	PANG ZHE LIANG
NRIC No	S9013935E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96770781
Alternative Phone No	OFFICE-96770781
Vehicle Particulars	
Manufacturer	BMW
Model	320I
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29068665QMY
Cover Note Number	
Driver	
Name of Driver	PANG ZHE LIANG
NRIC No	S9013935E
Date Of Birth	03/05/1990
Occupation	INDOOR
Date Of Driving Pass	15/12/2009
Driving Experience	8 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96770781
Fax Number	
Contact Number	OFFICE-96770781
Email Address	NOEMAIL

Address BLK 718 WOODLANDS AVE 6 #08-660  
 Postcode 730718  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO HEAD  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name TRAFFIC POLICE DIVISION HQ  
 Police Station Address ROAD: 10 UBI AVENUE 3, POSTCODE: 408855, COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 65470000 - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO POLICE REPORT: T/20180516/7009.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLM4467A  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name PANG ZHE LIANG

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLK3500D

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

## Sketch Plan Pg. 1

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date &amp; Time: 21/5/18, 245 PM

Driver's Signature

(If driver is not the policyholder)

Date &amp; Time: 21/5/18, 245 PM

Reporting Centre Personnel's Signature

Name:


NRIC/FIN No.:

GIA/MS SketchPlanForm\_V5

BLWWS L

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*Refer to Police Report*

*I reported late because I was given 7 days MC and I was resting at home.*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 21/5/18 2:45 PM

GIARMC SketchPlanForm\_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time: 21/5/18 2:45 PM

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

2



**SINGAPORE  
POLICE FORCE**



T/20180516/7009

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20180516/7009

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 16/05/2018 16:26		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: PANG ZHE LIANG		Address: APT BLK 718 WOODLANDS AVENUE 6 #08-660 SINGAPORE 730718			
ID Type / ID No.: NRIC NO / S9013935E		Contact No.: Home/Office: Mobile: 96770781			
Nationality: SINGAPORE CITIZEN		Email: emailpzi@gmail.com			
Sex: Male	Age: 28	Date of Birth: 03/05/1990	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: INSURANCE AGENT		Driving Licence Information: Class: 3		Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 15/05/2018 22:45	Type of Location: X-Junction
Location:  WOODLANDS AVENUE 9  Cross junction				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 50 Km/h
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLK3500D	Car	BMW	320i	White	Seriously Damaged	0

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SLK3500D	MSIG INSURANCE (SINGAPORE) PTE. LTD.	29068665	26/12/2017	25/12/2018



**SINGAPORE  
POLICE FORCE**



T/20180516/7009

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20180516/7009

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	PANG ZHE LIANG	ID No.	S9013935E
Related Vehicle	SLK3500D (Car)	Contact No.	96770781
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	16/05/2018	Date Discharge	16/05/2018
No. of Days granted Medical Leave	07	Degree of Injury	Serious

**Brief Details.**

My car, SLK3500D was queuing at stationary at the right turn junction, awaiting for my turn to turn right. After I became the next vehicle to move off, I checked both left and right of my blindspot, as well as for ongoing traffic in the opposite direction. Once cleared, I made the right turn. Suddenly, I felt a huge impact coming from somewhere. The next thing that I was aware of, was that my car got hit from the left. I felt liquid coming off my eye and noticed that I was bleeding. I was in huge discomfort and was in the car. Fortunately, two off duty paramedic came to check on me. Shortly, ambulance came and conveyed me to Khoo Teck Phuat Hospital for treatment.



**SINGAPORE  
POLICE FORCE**



T/20180516/7009

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20180516/7009

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 16/05/2018 16:26
Officer In Charge Of Case: TP / TPHQ / SYED ZAYID MUHAMMAD BIN SYED ABDUL WAHID ALHINDUAN Contact No.: 65476394	Classification Of Case:
Authentication Stamp NP108	

- What Did You Makan Today Part 3!
- Mercedes Owners Thread
- Guide - Getting a preowned / 2nd hand c

**Post an Advertisement**

Sell it yourself! Advertise it at just

**\$58 until it's SOLD!**[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)**Aston Martin V8 Vantage 4.7 SMT ABS D/AB 2DR**

Very Low Mileage. Full Agent  
Servicing Records. Lowest Depre  
In Market.  
StarAd



Browse by Category ▼

Sort b

**19 vehicles**

bmw 320

Advan

Make Model Price Depreciation Reg Date Eng Cap Mil

**Search Selection****bmw 320**

Any

Any

**2012**

Any

**BMW 3 Series 320i Luxury****\$77,800**

\$13,890 /yr

05-Sep-2012

1,997 cc

54

Only 1 Owner With Low Mileage. Worried Free And Accident Free! In Flawless Condition, Trade In Welcomed. Bank/High View To Believe, Call Or Drop By Our Showroom.

Posted: 26-May-2018 Tags: 2012 BMW 320i, BMW 320i, BMW, 320i, Used BMW

**BMW 3 Series 320i Coupe Sunroof****\$77,800**

\$14,320 /yr

22-May-2012

1,995 cc

51

Ramadan Weekend Sale! High COE \$92k! Super Low Mileage! Only 51,000KM! Sporty Blue Coupe With Cream Interior! L High Paper Value For Min Losses! Guaranteed Best Condition In To...

Posted: 25-May-2018 Tags: 2012 BMW 320i, BMW 320i, BMW, 320i, Used BMW

**BMW 3 Series 320i M-Sport****\$63,800**

\$12,110 /yr

04-Jan-2012

1,995 cc

83

Immaculate Condition! Very Well Maintained By Previous Owner, Highest OMV Value. M-Sport Model With M-Sport Steeri Spec I-Drive With Navigation And Bluetooth. No Repair Needed....

Lay Auto Pte Ltd

Posted: 25-May-2018 Tags: 2012 BMW 320i, BMW 320i, BMW, 320i, Used BMW

**BMW 3 Series 320i****\$79,800**

\$13,770 /yr

22-Nov-2012

1,997 cc

70

New Arrival, Low Mileage Done, Tip Top Condition, Classy Pearl White, Well Groomed And Taken Care Off By Careful Owr House/Bank Loan Available With Flexible Downpayment, Buy Wi...

Benefit Auto Enterprise Pte Ltd

Posted: 24-May-2018 Tags: 2012 BMW 320i, BMW 320i, BMW, 320i, Used BMW

[Car Buying](#)[Car Selling](#)[Car Ownership](#)[Car Aftermarket](#)[On The Move](#)[Lifestyle](#)

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3935E
Vehicle Details	
Vehicle No.:	SLK3500D
Vehicle to be Exported:	No
Intended De-registration Date:	28 May 2018
Vehicle Make:	B.M.W.
Vehicle Model:	320I AT ABS D/AB 2WD 2DR GAS/D
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	A514J230N46B20BD
Chassis No.:	WBADV32090E491881
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$45,153.00
Original Registration Date:	28 Jun 2012
First Registration Date:	28 Jun 2012
Transfer Count:	1
Actual ARF Paid:	\$45,153.00 22576
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2022
PARF Rebate Amount:	\$31,607.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$85,216.00
COE Rebate Amount:	\$34,794.00
<b>Total Rebate Amount:</b>	<b>\$66,401.00</b>

The information contained herein is correct as at 28 May 2018

OK

### ...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 May 2018		23 May 2018 16:11 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































  



















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>CHUA PUAY KEOW</b> , ID: S1465881E									
Main Claimant: <b>PANG ZHE LIANG</b> , ID: S9013935E									
Vehicle Reg. No.: <b>SLK3500D</b>		Date of Loss:	15/05/2018 22:00 - :59 [70 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type: <b>TP / 559117</b>		Policy/Cover Note No.:	28929939AVW (Comprehensive) Coverage: 30/03/2018 - 29/03/2019						
Vehicle Reg. No. (Insured): <b>SLM4467A</b>		Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer: <b>Bluwel Automotive Service Pte Ltd (HQ)</b> 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... <b>[Imm.Advice due 24/05/2018]</b>									
Adj Asg. Remarks: Liability is not clear. TP disagree with SJE list. Proceed to appoint LKK.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


















































## Claim Documents




\*SLK3500D (559117)  
[SLM4467A]  
TP  
PANG ZHE LIANG  
May 15 2018 10:00PM  
[CHUA PUAY KEOW]  
Bluwel Automotive Service Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/05/18 12:36	<b>Accident Statement</b> From:OD - Reg. No: SLM4467A, Claimant: CHUA PUAY KEOW	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/05/18 16:18	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	25/05/18 16:18	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
30	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
31	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
32	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
33	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
35	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
36	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
37	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
38	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
39	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
40	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
41	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
42	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
43	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
44	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
45	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
46	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
47	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
48	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
49	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
50	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
51	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
52	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
53	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
54	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
55	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
56	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
57	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
58	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
59	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
60	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
61	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
62	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
63	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
64	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
65	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
66	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
67	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
68	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
69	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
70	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
71	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
72	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
73	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
74	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
75	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
76	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
77	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
78	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
79	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
80	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
81	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
82	25/05/18 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
83	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	12/07/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
134	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	12/07/18 17:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/05/18 09:07		PRI	 Load PDF	
2	23/05/18 09:10		Email correspondence with TP - TP reject SJE list & proceed to appoint LKK as SJE	 Load PDF	
3	23/05/18 12:36		TP GIA Report From: OD - Reg. No: SLM4467A, Claimant: CHUA PUAY KEOW	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18009402/UZ4D3E2

Date: 30/07/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28929939AVW

Claimant Vehicle No : SLK3500D

Insured Vehicle No : SLM4467A

Date of Loss: 15/05/2018

Nature of Claim: TP

Claim No: 559117

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLK3500D

Make &amp; Model: BMW 320I, 2.0 ABS D/AB 2WD 2DR GAS/D (A)

Engine No: A514J230N46B20BD

Reg. Date: 28/06/2012 (Man. Year: 2012)

Chassis No: WBADV32090E491881

Colour: White

Odometer: 102052 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size: 255/35Z R18

Front Left Side: Goodyear 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 23/05/2018

Date Inspected: 24/05/2018 Inspected At:

Bluwel Automotive Service Pte Ltd (HQ)  
1 Kaki Bukit Avenue 6, #01-28/37/53/55/56  
Autobay@Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$15,000.00 - \$18,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jul 2018)
<b>Parts:</b>	M1-COUPE	BMW 320I 2.0 ABS D/AB 2WD 2DR GAS/D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLK3500D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >