

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/05/2018 10:57
Date Of Accident	14/05/2018 10:15
Exact Location Of Accident	ALONG BKE TWDS PIE 1KM AFTER ECO BRIDGE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY8932T
Insured/Policyholder	
Name Of Registered Owner	M/S TIONG HUAT CONTRACTS PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98272443

Vehicle Particulars

Manufacturer	NISSAN
Model	-
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	DMCVSN3066121700
Cover Note Number	

Driver

Name of Driver	ISLAM NAZRUL
Passport No/FIN	F7556103L
Date Of Birth	08/05/1966
Occupation	OUTDOOR
Date Of Driving Pass	22/07/2017
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98272443
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 2 CANBERRA DRIVE #10-01 EIGHT COURTYARDS
Postcode	768138
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	KV7489B (COMMERCIAL VEHICLE)
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ISLAM SANTO GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI N.P.C
Police Station Address	ROAD: 20 CLEMENTI AVE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE POLICE REPORT: T/20180514/2088

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GU3113U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HOSSEN NAZMUL
NRIC/Passport Number	G6820115U
Contact Number	90777217

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GZ1200M
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver TAY QI HUA
NRIC/Passport Number S9322819G
Contact Number 91727501

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number KV7489B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver OOI BOON PIN
NRIC/Passport Number G7870581M
Contact Number 81276576

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any initial misrepresentation or withholding of material facts may allow insurance companies to renege on policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

		Vehicle:	
		A: GY8932T	
		B: GJ1215M	
		C: KZ1100M	
		D: KV7489B	

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT **ECO-Link Bridge**

as per police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Individual Statement



**SINGAPORE
POLICE FORCE**



T/20180514/2088

3 of 4

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

Report No. T/20180514/2088

CONTINUATION OF REPORT

Driver			
Name	OOI BOON PIN		ID No. G7870581M
Related Vehicle	KV7489B (Van)		Contact No. 81276576
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Brief Details.

On 14/05/2018 at about 1015hrs, I was driving my lorry bearing the registration plate number GY8932T at the 2nd lane of BKE. At the point of time it was drizzling and the road is wet. The traffic volume was heavy.

It was a slow moving traffic and I noticed that the vehicle in front of me stopped thus I slow down. At this point of time, I felt an impact coming from the rear and my vehicle inched forward and resulted that my vehicle collided into the rear of GZ1200M.

I alighted my vehicle and discovered that I am involved in a chain collision. I am the 2nd vehicle and there are three other vehicle involved. The following are the vehicle involved:

- 1st vehicle: GZ1200M
- 2nd vehicle: GY8932T
- 3rd vehicle: GU3113U
- 4th vehicle: KV7489B (Malaysian vehicle)

This is the first time such incident happened. I had exchanged particulars with the other drivers. Traffic Police and ambulance came and some of the passenger were conveyed by Ambulance. I do not have a in-car camera installed in my vehicle. There is scratches and dent at the front and rear of my vehicle. Both my front and rear headlight crack.

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



**SINGAPORE
POLICE FORCE**



T/20180514/2088

1 of 4

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

Report No. T/20180514/2088

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/05/2018 14:01		Vide Report No.: F/20180514/0095		Station Diary No.: 115	
Informant's Particulars					
Name of Informant: ISLAM NAZRUL			Address: APT BLK 2 CANBERRA DRIVE #10-01 EIGHT COURTYARDS SINGAPORE 768136		
ID Type / ID No.: NRIC NO / F7556103L			Contact No.: Home/Office:		Mobile: 98272443
Nationality: BANGLADESHI			Email:		
Sex: Male	Age: 52	Date of Birth: 08/05/1966	Type of Informant: Driver		
Race: Indian			Language:		Institution / School Name:
Occupation: Site Manager			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 14/05/2018 10:15	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY				
Along BKE towards PIE 1KM after Eco Bridge				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GU3113U	Lorry				Slightly Damaged	0
GY8932T	Lorry				Slightly Damaged	0
GZ1200M	Lorry				Slightly Damaged	0
KV7489B	Van				Slightly Damaged	0

Police Report



**SINGAPORE
POLICE FORCE**



T/20180614/2068

2 of 4

Police Station Of Origin:

Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8728999

Report No: T/20180614/2068

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	HOSSEN NAZMUL	ID No.	G8820115U
Related Vehicle	GU3113U (Lorry)	Contact No.	90777217
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ISLAM NAZRUL	ID No.	F7556103L
Related Vehicle	GY8932T (Lorry)	Contact No.	98272443
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAY QI HUA	ID No.	S9322B18G
Related Vehicle	GZ1200M (Lorry)	Contact No.	91727501
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Police Report



**SINGAPORE
POLICE FORCE**



T/20180514/2088

3 of 4

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

Report No. T/20180514/2088

CONTINUATION OF REPORT

Driver				
Name	OOI BOON PIN		ID No.	G7870581M
Related Vehicle	KV7489B (Van)		Contact No.	81276578
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 14/05/2018 at about 1015hrs, I was driving my lorry bearing the registration plate number GY8932T at the 2nd lane of BKE. At the point of time it was drizzling and the road is wet. The traffic volume was heavy.

It was a slow moving traffic and I noticed that the vehicle in front of me stopped thus I slow down. At this point of time, I felt an impact coming from the rear and my vehicle inched forward and resulted that my vehicle collided into the rear of GZ1200M.

I alighted my vehicle and discovered that I am involved in a chain collision. I am the 2nd vehicle and there are three other vehicle involved. The following are the vehicle involved:

- 1st vehicle: GZ1200M
- 2nd vehicle: GY8932T
- 3rd vehicle: GU3113U
- 4th vehicle: KV7489B (Malaysian vehicle)

This is the first time such incident happened. I had exchanged particulars with the other drivers. Traffic Police and ambulance came and some of the passenger were conveyed by Ambulance. I do not have a in-car camera installed in my vehicle. There is scratches and dent at the front and rear of my vehicle. Both my front and rear headlight crack.

Police Report



Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

1800 1000 1912000

4 of 4

Report No. T/20180514/2088

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 85474885 stating the report number as reference.

Signature Of Officer Recording The Report:
D /
Sgt 2 NG JIA HAO

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
14/05/2018 14:01


Officer In Charge Of Case:
TP / GIT /
SI THABAGESH JEYATHESH
Contact No.: 65476232

Classification Of Case:

Authentication Stamp
NP188



Police Report



Identification Card

