

08/11/14

Surveyor

REF: A19

9417 (u@)

### ASSIGNMENT

From:

Date: 13. 5. 19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 4K 1902L

at Workshop m/s Tan Lim motor

of 1 Dafu Lane 6

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh: After 10.00 am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS rwp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

YK1902L

Yr Regn:

9/99

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CM /

Make:

m.f Fuso FK617 75-45

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

277720

T/Radio: Insured / Std / NI / NA

Eng/No:

FK617JA00164

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

P-25 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Aeolus

Front

Rear

R/Bal.

6 mm

R/Bal.

6/6 mm

L/Bal.

6 mm

L/Bal.

6/6 mm

D.O.A.

26/4/18

D.O.I.

13/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MSH.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/5/18 2/5 3500 confirmed with willer.

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ )

Add Fee:



: Site Insp (\$ )



: Interview (\$ )



: Tech. Invs (\$ )



: Weekend (\$ )

**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	1589R
<b>Vehicle Details</b>	
Vehicle No.:	YK1902L
Vehicle to be Exported:	No
Intended De-registration Date:	30 Apr 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	FUSO FK617JJ
Primary Colour:	White
Manufacturing Year:	1999
Engine No.:	6D16932917
Chassis No.:	FK617JA00164
Maximum Power Output:	-
Open Market Value:	\$47,062.00
Original Registration Date:	21 Sep 1999
First Registration Date:	21 Sep 1999
Transfer Count:	1
Actual ARF Paid:	\$2,354.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	31 Mar 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$24,394.00
COE Rebate Amount:	\$19,108.00
<b>Total Rebate Amount:</b>	<b>\$19,108.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Apr 2018

OK