

ASS. REC. BY:

REF: CS3/AIG18009426/N240307

Final instruction

Surveyor

Meinen

From (Person)

ASSIGNMENT (Office)

of AIG

Date/Time: 24/5/18 @ 9:22am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No. _____

SIN 13652

Insured: SLN 2291V

at Workshop m/s

Motor Intel

Tel. 8838 3318

of 13 kaki Bukit Road 4 #01-20

Policy No.

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/05/2018

CA / REV / REP. / REV 24 HRS *lup*

Date/Time: 9:33am @ 24/5/18

Person Contacted

Wilson

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction	(X)	Estimate
1. Review the project schedule and identify critical path activities.		
2. Conduct a risk assessment for each activity.		
3. Develop a communication plan for stakeholders.		
4. Implement the project plan and monitor progress.		
5. Report project status to the steering committee.		
6. Close the project and conduct a post-mortem analysis.		

Estimate

81N13652-X

SIN 22914-X

DATE

MAZ

REF: AIG

ASSIGNMENT

From: _____ Date: 21/05/18

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SIN 13652

at Workshop m/s Motor Intel
of 13 kaki Bukit Rd 4 #01-20

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lwp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJN 13652 Yr Regn: 4 FEB 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI LANCER cc. 1584

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 119,487 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYSTC53A9U003108

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 24/5/18

Survey held at MOTOR INTEL

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 24/5/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S, O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/5/18 Submit DAR report.

RECEIVED 30 MAY 2018

Date/Time. File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time. File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

180

20

200

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SLN2291Y AND SJN1365Z ON 20/05/2018**

From: Chin, Lee-Ying
To: Admin A, 'assignments'
Cc: Fong, Andy-SY
Sent: 24/5/2018 9:22:18 AM
Attachments:  Fax232B.TIF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

ISLAND LAW LLC

Advocates & Solicitors

(UEN No. 200918269D)

(GST Reg No. 200918269D)

KIRPAL SINGH SHARMA
NG KWONG LOONGSUNITA CARMEL NETTO
SYAFIQAH AHMAD FU'AD

Our Ref : KS. 01365Z.18.PD (MIA).sq

Your Ref : SJN 22914

101 Upper Cross Street
#04-04 People's Park Centre
Singapore 058357
Tel: (65) 6221 3211
Fax: (65) 6225 3210
(65) 6225 3054

Date: 22 MAY 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.

(By Fax: 6835 7417)

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING SJN 1365Z AND SJN 22914 ALONG BEDOK
RESERVOIR ROAD (NEAR Eunos CC) ON 20/05/2018 @ 1330 HRS(NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)We act for IDRIVE AUTOMOBILE who has appointed the undermentioned
workshop to repair his/her motor vehicle no. SJN 1365Z.

Please be informed that the said vehicle can be inspected at:

Name : MOTOR INTEL AUTOMO PTE. LTD.
 Address : 13 EAKI BUKIT ROAD A
#01-20 BARTLEY BIZ CENTRE
SINGAPORE 417807
 Person to contact : WILSON ONG
 Tel : 8838 3318

If you failed to conduct the pre-repair inspection within the next 2 working days excluding any
intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter
without further reference to you.

Yours faithfully

For Surveyor
Please initial here after completion
of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

ISLAND LAW LLC

cc: Client (SJN 1365Z) (By email: sales@mia.com.sg)

By Fax: 6281 0187

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18009426/Nz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 24-05-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLN 2291Y	Veh. Inspected	SJN 1365Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	24/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/05/2018	Inspection Date	24/05/2018
Survey held at	-		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 22/05/2018 09:52
Date Of Accident 20/05/2018 13:30
Exact Location Of Accident BEDOK RESERVOIR ROAD (NEAR EUNOS CC)
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJN1365Z
Insured/Policyholder
Name Of Registered Owner IDRIVE AUTOMOBILE
Co Reg No 53364146B
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-90000000

Vehicle Particulars

Manufacturer MITSUBISHI
Model LANCER 1.6 CVT SPORTS GLX AIRBAG 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage THIRD PARTY
Fleet Policy YES
Policy Number 5100439017
Cover Note Number

Driver

Name of Driver ARIFIN BIN HANIS
NRIC No S8012134B
Date Of Birth 24/04/1980
Occupation OUTDOOR
Date Of Driving Pass 04/09/2009
Driving Experience 8 YEARS AND 8 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96663240
Fax Number
Contact Number NOEMAIL
Email Address

Address 68 BOUNDARY ROAD
Postcode 549983
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle
Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions DRIZZLING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name
Police Station Address
Police Station Contact
Was notice of intended Prosecution given? NO
If Yes, against whom?

BEDOK NORTH NEIGHBOURHOOD POLICE CENTRE
ROAD: 30 BEDOK NORTH ROAD, POSTCODE: 469676, COUNTRY: SINGAPORE
TEL NO: 1800-2449999 - FAX NO: 62447258

Circumstances of Accident

AS PER POLICE REPORT No.T/20180521/2052

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLN2291Y
Vehicle Make/Model/Colour MAZDA
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

ARIFIN BIN HANIS

Approximate Age

-3DAY MC-

Injuries Sustain

SJN1365Z

Injured person in which vehicle?

YES


Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Bedok Reservoir Rd on the left hand lane of a 3-lane road. Somewhere near Juncos C.L., as I was driving straight and in my lane, I suddenly felt an impact from the left hand portion of my vehicle. After the impact, I felt another impact from the rear portion of my vehicle. After the accident, I alighted to see that vehicle B had collided into my rear right hand portion on 1st impact and thereafter front portion collided into my rear portion on 2nd impact. Hence, I was involved in an accident of 2-vehicle.

Vehicle A: SJN 1365Z.
Vehicle B: SLN 2291Y.

DECLARATION
I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933
Tel: 67416697
Fax: 67492305

Reporting Centre Person's Signature
Name: Email: vackb@singnet.com.sg
NRIC/FIN NO:

MOTORCAR (Rear)

Vehicle No: SJN 1365Z

Rear Portion			CON	AC	Qty
NAC	INC	Item			
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DMG	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	BR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	R	
1171	991328	Bootlid Emblem	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

[illegible]

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2018 Edit Reg		24 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
[Created by adjuster]									
CLAIM SUBFOLDER DETAILS									
Insured:	LCRF Pte Ltd , Co. Reg. No.: 201624597K								
Main Claimant:	IDRIVE AUTOMOBILE , Co. Reg. No.: 53364146B								
Vehicle Reg. No.:	SJN1365Z	Date of Loss:	20/05/2018 13:00 - :59 [111 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9592932305SG	Policy/Cover Note No.:	0999994786 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLN2291Y	Policy No. (Claimant):							
		Excess:							
Repairer:	Motor Intel Automo Pte Ltd (HQ) Bartley Biz Centre, 13 Kakai Bukit Road 4, #01-20, 417807 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Hai-Chuan] Hai-Chuan.Ng@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 06/06/2018]								
			View All	Compose Case Mail					
ASSOCIATED MAIL RECEIVED									
AIG_SG (28/05/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJN1365Z (9592932305SG)
[SLN2291Y]
TP
IDRIVE AUTOMOBILE
May 20 2018 1:00PM
[LCRF Pte Ltd]
Motor Intel Automo Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print						
1	28/05/18 10:03	General View										1 Load JPG		☒						
2	28/05/18 10:03	General View										1 Load JPG		☒						
3	28/05/18 10:03	General View										1 Load JPG		☒						
4	28/05/18 10:03	General View										1 Load JPG		☒						
5	28/05/18 10:03	General View										1 Load JPG		☒						
6	28/05/18 10:03	General View										1 Load JPG		☒						
7	28/05/18 10:03	General View										1 Load JPG		☒						
8	28/05/18 10:03	General View										1 Load JPG		☒						
9	28/05/18 10:03	General View										1 Load JPG		☒						
10	28/05/18 10:03	General View										1 Load JPG		☒						
11	28/05/18 10:03	General View										1 Load JPG		☒						
12	28/05/18 10:03	General View										1 Load JPG		☒						
13	28/05/18 10:03	General View										1 Load JPG		☒						
14	28/05/18 10:03	General View										1 Load JPG		☒						
15	28/05/18 10:03	General View										1 Load JPG		☒						
16	28/05/18 10:03	General View										1 Load JPG		☒						
17	28/05/18 10:03	General View										1 Load JPG		☒						
18	28/05/18 10:03	General View										1 Load JPG		☒						
19	28/05/18 10:03	General View										1 Load JPG		☒						
20	28/05/18 10:03	General View										1 Load JPG		☒						
21	28/05/18 10:03	General View										1 Load JPG		☒						
22	28/05/18 10:03	General View										1 Load JPG		☒						
23	28/05/18 10:03	General View										1 Load JPG		☒						
24	28/05/18 10:03	General View										1 Load JPG		☒						
25	28/05/18 10:03	General View										1 Load JPG		☒						
															1 per page			☒		
Documentation															Thumbnail		Print			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										1 Load PDF								
1	28/05/18 10:01	OI GIA REPORT																		

Documents Checklist

	Reset	Save	Print
DOCUMENTS CHECKLIST			
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009426/NZ4D3E2
Date: 31/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994786
 Claimant Vehicle No: SJN1365Z Insured Vehicle No: SLN2291Y
 Date of Loss: 20/05/2018 Nature of Claim: TP Claim No: 9592932305SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN1365Z**
 Make & Model: MITSUBISHI LANCER, 1.6 GLX 5MT AIRBAG 2WD Engine No: 4G18KA9831
 Reg. Date: 04/02/2009 (Man. Year: 2008) Chassis No: JMYSTCS3A9U003108
 Colour: Black Odometer: 119487 km
 Engine Capacity: 1584 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/05/2018
 Date Inspected: 24/05/2018 Inspected At: Motor Intel Automo Pte Ltd (HQ)
 Bartley Biz Centre, 13 Kakai Bukit Road
 4, #01-20
 Singapore 417807

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Damaged	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR RH TAILLAMP	Broken	0.00 F	*- F
4	1		*BOOTLID	Repair	0.00 F	*- F
5	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
6	1		*REAR EXHAUST PIPE	Scratched	0.00 F	*- F
7	1		*REAR RH FENDER	Dented	0.00 F	*- F
8	1		*REAR RH WHEEL RIM	Scratched	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >