

22/03/2001

ASS. F. C. BY:

REF: 08/CTI1800928 / Afd3n2

Special instruction:

Surveyor:  
Meimen

ASSIGNMENT (Office)

From (Person): Elaine Cheong

of CTI

Date/Time: 23/5/18 @ 5pm

Estimated Cost:

Bill to:

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGV 9650R

Insured: SKU 5485K

at Workshop m/s MS Car Auto

Tel: 63851838

of 8 Kaki Bukit Ave 4 #01-07

Policy No: DMHCSN1717231700

Claim No: SNM18D02572C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19/05/2018

CA / REV / REP. / REV 24 HRS <sup>wp</sup>

H.O.D. Endorsement:

Date/Time: 5:22pm @ 23/5/18

Person Contacted: Desmond

Vehicle  IN  OUT

Date/Time	Action/Instruction (✓) Estimate	
	SGV 9650R - NA / AIG / 1800928 / h4	DOA: 19/5/2018
	SKU 5485K - NA / AIG / 1800928 / h4	DOA: 19/5/2018
	lump sum \$57007 (red: 1740440, 76%)	

5172100

REF: CTI

ASSIGNMENT

From: \_\_\_\_\_ Date: 25/05/18

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: SGV 9650R

at Workshop m/s MS Car Auto

of 8 Kaki Bukit Ave 4 #01-07

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: SGV9650R Yr Regn: 1 29/6/2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Audi TT c.c. 1984

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 38065 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: TRUZZE 8J271036085

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 225/50R17

R: 225/50R17

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 25/05/18

Survey held at MS

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS/wp

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

TP Chin

RECEIVED 3 FEB 2018

Date/Time. File Pass to?  : Preli. Report

1) 13/2 Typist  : Final Report

Date/Time. File Return to? \_\_\_\_\_

Days Of Repair: 5

Resurvey No. of Trip: -

Survey Fee:	
Transportation:	
_____ \$ + RS. _____ \$	
Photos	
Others	
TOTAL	<u>220</u>

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Report Format :

Lump Sum / I.B.I: (\$ 5200)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 May 2018		23 May 2018 17:00 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TW PREMIUM AUTOMOBILE PTE LTD, Co. Reg. No.: -								
Main Claimant:	RYUICHIRO SHIKANAI, ID: G5851785U								
Vehicle Reg. No.:	SGV9650R	Date of Loss:	19/05/2018 15:00 - :59						
Claim Type:	TP / SNM18D02572C02	Policy/Cover Note No.:	DMHCSN1717231700 (Third Party Only)						
Vehicle Reg. No. (Insured):	SKU5485K	Policy No. (Claimant):	2100036828-10000						
		Excess:	S\$0.00						
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/06/2018]								
Driver/Custodian (Insured):	SURAYANI (46 / Female), NRIC: S7182246Z, Tel: +6597826679								
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.								
<b>ASSOCIATED MAIL RECEIVED</b>									
			<a href="#">View All</a> <a href="#">Compose Case Mail</a>						
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
			<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/05/2018 14:37
Date Of Accident	19/05/2018 15:00
Exact Location Of Accident	VANDA LINK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGV9650R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	RYUICHIRO SHIKANAI
NRIC No	G5851785U
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83338222
Alternative Phone No	OFFICE-83338222

### Vehicle Particulars

Manufacturer	AUDI
Model	TT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100036828-10000
Cover Note Number	-

### Driver

Name of Driver	SHIKANAI NAHO
NRIC No	G5877315N
Date Of Birth	12/06/1975
Occupation	INDOOR
Date Of Driving Pass	16/09/2010
Driving Experience	7 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-83338222
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 1 COMMONWEALTH LANE #04-03  
 Postcode 149544  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured SPOUSE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - CHANGE/CROSS LANE  
 Weather Conditions AFTER RAINED  
 Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : UNKNOWN  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLEASE REFER TO ATTACHED STATEMENT.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKU5485K  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

Accident Sketch Plan

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(if driver is not the policyholder)  
Date & Time:




Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

Vanda Link



A - SGV 9050R

B - SKV 5485K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Due to the stated date & time, I was driving in my lane. Suddenly vehicle B did an illegal u-turn and hit the side of my car.

DECLARATION

(We declare the foregoing particulars are true in every respect.)



Policyholder's Signature  
Date & Time:



Driver's Signature  
(if driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NIC/FIN No.:

TRU 2778 J2 71036085  
 TP China. Device.

SJE : \_\_\_\_\_  
 Date of Survey : \_\_\_\_\_  
 Contacts : \_\_\_\_\_

Vehicle Nos : SGV 965QR  
 Model : Audi TT  
 Year : \_\_\_\_\_

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount: \_\_\_\_\_ Working Day: \_\_\_\_\_

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Side skirt LH <i>Rebond</i>	1	\$ 1,960.00	\$ 1,960.00
2	Rear fender LH <i>Repair</i>	1	\$ 3,896.00	\$ 3,896.00
3	Rear fender inner cowling LH <i>Not New</i>	1	\$ 289.00	\$ 289.00
4	Rear fender quarter glass with moulding <i>Not New</i>	1	\$ 846.00	\$ 846.00
5	Tail lamp LH <i>Cracked</i>	1	\$ 1,878.00	\$ 1,878.00
6	Rear bumper <i>Torn</i>	1	\$ 1,821.00	\$ 1,821.00
7	Rear bumper sensor <i>Not New</i>	1	\$ 665.00	\$ 665.00
8	Rear bumper side retainer <i>Cracked Not New</i>	1	\$ 187.00	\$ 187.00
9	Rear speed sensor(ABS sensor) <i>Not New</i>	1	\$ 563.00	\$ 563.00
10	Rear lower arm <i>Best</i>	1	\$ 964.00	\$ 964.00
11	Rear stabilizer link <i>Panel New</i>	1	\$ 241.00	\$ 241.00
12	Rear stabilizer link bar	1	\$ 689.00	\$ 689.00
13	Rear upper arm <i>Best</i>	1	\$ 895.00	\$ 895.00
14	Rear shock absorber <i>Not New</i>	1	\$ 2,144.00	\$ 2,144.00
15	Rear knuckle arm <i>Best</i>	1	\$ 2,245.00	\$ 2,245.00
16	Rear knuckle bearing with hub <i>Best</i>	1	\$ 689.00	\$ 689.00
Parts Sub Total :				\$ 14,116.00
Discount 5% :				\$ 1,411.60
<b>PARTS TOTAL :</b>				<b>\$ 12,704.40</b>

4627  
 4395.65

646  
 593  
 1503  
 493  
 498  
 672  
 302

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear bumper clip set <i>New</i>	1	\$ 60.00	\$ 60.00
2	Tail lamp clip set <i>New</i>	1	\$ 30.00	\$ 30.00
3	Rear wheel tyre LH <i>Not New</i>	1	\$ 850.00	\$ 850.00
4	Rear fender sealant <i>Not New</i>	1	\$ 120.00	\$ 120.00
5	Rear fender inner trim clip set <i>Not New</i>	1	\$ 60.00	\$ 60.00
6	Rear fender cowling clip set <i>Not New</i>	1	\$ 60.00	\$ 60.00
7	Rear quarter glass inner sealant <i>Not New</i>	1	\$ 60.00	\$ 60.00
8	Rear wheel Rim LH <i>Not New</i>	1	\$ 2,800.00	\$ 2,800.00
9	Rear quarter glass sealant <i>Not New</i>	1	\$ 60.00	\$ 60.00
<b>SPECIAL NETT TOTAL :</b>				<b>\$ 4,100.00</b>

790

30  
 10  
 750  
 X

Nos.	LABOUR	S\$
1	Panel beating, Removing and Replacing parts	\$ 2,200.00
2	Spray painting to affected area	\$ 1,500.00
4	To check wheel alignment	\$ 120.00
	To remove and refix rear seat and cushion upholstery	\$ 250.00
	To Remove and Refix reverse sensor and distance settings	\$ 80.00
	To remove and refix rear under carriage	\$ 1,200.00
5	Reset ABS Light	\$ 450.00
<b>LABOUR TOTAL :</b>		<b>\$ 5,800.00</b>

1390

400  
 600  
 80  
 40  
 50  
 220  
 X

PARTS TOTAL : \$ 12,704.40  
 SPECIAL NETT TOTAL : \$ 4,100.00  
 LABOUR TOTAL : \$ 5,800.00

total: 6575.65  
 n/s: 5.2k  
 OS Prays

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

28873.40

TOTAL :	\$	<u>22,604.40</u>
Deduct 20% :	\$	4,520.88
<b>GRAND TOTAL :</b>	<b>\$</b>	<b><u>18,083.52</u></b>

**KIM HOE TYRE & BATTERY**  
**KAKI BUKIT AUTOHUB**  
 01-10 SINGAPORE 417921  
 TEL:67472427

Customer

Vehicle ident no.

Repair order no.  
**R000112**

Technician

Date  
**22.5.18**

License plate no.  
**SGV9650R**

First reg. date

Model

Odometer reading: km/miles

**Audi : TT : 2007- : Front Wheel Drive : Standard  
 Suspension (1BA)**

**Complaints or reason for alignment check**

			Before	Target Data	Actual
Rear axle	Camber	left			-2°26' *
		right		-1°20' +/-0°30'	-1°33'
		cross		0°00' +/-0°30'	-0°53' *
	Toe	left			3°28' *
		right		0°13' +/-0°05'	0°12'
		total		0°25' +/-0°10'	3°40' *
Geometrical driving axis				0°00' +/-0°10'	1°38' *
Front axle	Camber	left			-1°04'
		right		-0°41' +/-0°30'	-0°59'
		cross		0°00' +/-0°30'	-0°05'
	Caster	left			
		right			
		cross		0°00'	
	SAI	left			
		right			
		cross		0°00'	
	Track differential angle	left			
		right		-1°18' +/-0°20'	
	Toe	left			-1°45' *
		right		0°05' +/-0°05'	1°40' *
		total		0°10' +/-0°10'	-0°05' *
	Setback				0°00'
Max steering lock	left steer	left		-36°48' +36°48' -0°00'	
		right		+36°48' -0°00'	
	right steer	left		+36°48' -0°00'	
		right		-36°48' +36°48' -0°00'	

\* This value is not within specification. Tire wear, handling and safety problems may result.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18009428/ATD3N2

Date: 13/02/2019

#### REFERENCE

<b>Handling Insurer:</b>	China Taiping Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b>	DMHCSN1717231700
<b>Claimant Vehicle No :</b>	SGV9650R	<b>Insured Vehicle No :</b>	SKU5485K
<b>Date of Loss:</b>	19/05/2018	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	SNM18D02572C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	SGV9650R	<b>Engine No:</b>	BWA141765
<b>Make &amp; Model:</b>	AUDI TT, 2.0 TFSI (A)	<b>Chassis No:</b>	TRUZZZ8J271036085
<b>Reg. Date:</b>	29/06/2007 (Man. Year: 2007)	<b>Odometer:</b>	38065 km
<b>Colour:</b>	Black		
<b>Engine Capacity:</b>	1984 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	

#### CONDITION OF TYRES

<b>Front Tyre Size:</b>	225/50R17	<b>Rear Tyre Size:</b>	225/50R17
<b>Front Left Side:</b>	Bridgestone 6 mm	<b>Rear Left Side:</b>	Bridgestone 6 mm
<b>Front Right Side:</b>	Bridgestone 6 mm	<b>Rear Right Side:</b>	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	23,073.40	5,185.65	17,887.75	77.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,800.00	1,390.00	4,410.00	76.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>28,873.40</b>	<b>6,575.65</b>	<b>22,297.75</b>	<b>77.23</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>28,873.40</b>	<b>5,200.00</b>	<b>23,673.40</b>	<b>81.99</b>

#### INSPECTION

<b>Date of Assignment:</b>	23/05/2018	
<b>Date Inspected:</b>	25/05/2018	<b>Inspected At:</b>
		Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875

**Estimated Period of Repair:** 5.0 days

**Adjuster:** ADRIAN LING

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Feb 2019)	
<b>Parts:</b> M1-COUPE	AUDI TT 2.0 TFSI (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SGV9650R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*SIDE SKIRT LH	Deformed	1,960.00 FL	*646.00 FL
2	1	*REAR FENDER LH	Repair	3,896.00 FL	*- FL
3	1	*REAR FENDER INNER COWLING LH	Not Necessary	289.00 FL	*- FL
4	1	*REAR FENDER QUARTER GLASS WITH MOULDING	Not Necessary	846.00 FL	*- FL
5	1	*TAIL LAMP LH	Cracked	1,878.00 FL	*593.00 FL
6	1	*REAR BUMPER	Torn	1,821.00 FL	*1,503.00 FL
7	1	*REAR BUMPER SENSOR	Not Necessary	665.00 FL	*- FL
8	1	*REAR BUMPER SIDE RETAINER	Not Necessary	187.00 FL	*- FL
9	1	*REAR SPEED SENSOR (ABS SENSOR)	Not Necessary	563.00 FL	*- FL
10	1	*REAR LOWER ARM	Bent	964.00 FL	*413.00 FL
11	1	*REAR STABILIZER LINK	Not Necessary	241.00 FL	*- FL
12	1	*REAR STABILIZER LINK BAR	Not Necessary	689.00 FL	*- FL
13	1	*REAR UPPER ARM	Bent	895.00 FL	*498.00 FL
14	1	*REAR SHOCK ABSORBER	Not Necessary	2,144.00 FL	*- FL
15	1	*REAR KNUCKLE ARM	Damaged	2,245.00 FL	*672.00 FL
16	1	*REAR KNUCKLE BEARING WITH HUB	Damaged	689.00 FL	*302.00 FL
17	1	*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
18	1	*SET TAIL LAMP CLIP	Necessary	30.00 FS	*10.00 FS
19	1	*REAR WHEEL TYRE LH	Not Necessary	850.00 FS	*- FS
20	1	*REAR FENDER SEALANT	Not Necessary	120.00 FS	*- FS
21	1	*SET REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
22	1	*SET REAR FENDER COWLING CLIP	Not Necessary	60.00 FS	*- FS
23	1	*REAR QUARTER GLASS INNER SEALANT	Not Necessary	60.00 FS	*- FS
24	1	*REAR WHEEL RIM LH	Cut	2,800.00 FS	*750.00 FS
25	1	*REAR QUARTER GLASS SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>24,072.00</b>	<b>5,417.00</b>
- List Item Discount on L Items 5.00/5.00% (S\$)	998.60	231.35
<b>Total Parts (S\$)</b>	<b>23,073.40</b>	<b>5,185.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING,REMOVING AND REPLACING PARTS	New	2,200.00	400.00
2	SPRAY PAINTING TO AFFECTED AREAS	New	1,500.00	600.00
3	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
4	TO REMOVE AND REFIX REAR SEAT AND CUSHION UPHOLSTERY	New	250.00	40.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTINGS	New	80.00	50.00
6	TO REMOVE AND REFIX REAR UNDER CARRIAGE	New	1,200.00	220.00
7	RESET ABS LIGHT	New	450.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>5,800.00</b>	<b>1,390.00</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;