

REF: NS/INC18009444/SH 2013

REF: NS/INC18009444/SH 2013

NS/INC18009444/SH 2013

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SKT 1790K
 Policy No: 900184044 2604208
 Claims No: MT/0997827-001
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 4382K Yr Regn: 20 / 12 / 2013
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /
 Truck / Trailer or
 Make: Toyota Prius C.C. 1798
 Colour: Maroon A/C Insured / Std / NI / NA
 Sp. Reading: 677979 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKN3C4705718962
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: M / S/Rim / STD A/Rim or
 Tyre Size: F: 175/65R15
 R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 19/5/18	D.O.I. 22/5/18

Survey held at SMRT.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC 4382K - NS/INC16011472/1160m2
	SKT 1790K - X
	US \$300 (led \$1149.70, 79%)
	DA: 29/07/16 TAX/65/18/2088
	LIK.
	NTUC.
	SKT 1790K.
	RECEIVED 11 JUN 2018

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
 13/08/16 transfer
 Date/Time, File Return to?

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation:

() S + PS St

() Photos

() Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech Invs (\$

☐ Weekend (\$

Report Format: 7P

Lump Sum / I.B.T: (\$ 300)

160

35

195



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18009444/Sqb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 24-05-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKT 1790K	Veh. Inspected	SHC 4382K
Policy No.	5100184044	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/05/2018	Inspection Date	22/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/0997402-002	COMFORT TRANSPORTATION PTE LTD	SHA 3102U	SIK 4437X	03/06/2018	\$ 2,431.58	\$ 450.00
2	MT/0996966-002	CITYCAB PTE LTD	SHA 8202G	SIF 5615T	01/06/2018	\$ 2,077.44	\$ 1,100.00
3	MT/0997824-001	CITYCAB PTE LTD	SHA 811B	SIH 5573X	30/05/2018	\$ 3,265.96	\$ 2,850.00
4	MT/0994720-002	SMRT TAXI PTE LTD	SHB 5571E	GU 5967J	15/05/2018	\$ 6,170.40	\$ 2,240.23
5	MT/0992549-002	SMRT TAXI PTE LTD	SHF 441J	SHB 8401T	01/05/2018	\$ 26,621.94	\$ 8,100.00
6	MT/0994278-002	SMRT TAXI PTE LTD	SHC 4212T	XE 565B	13/05/2018	\$ 21,016.42	\$ 4,600.00
7	MT/0997827-001	SMRT TAXI PTE LTD	SHC 4382K	SKT 1790K	19/05/2018	\$ 1,449.70	\$ 300.00
8	MT/0994682-002	SMRT TAXI PTE LTD	SHC 4536J	GBD 5726L	14/05/2018	\$ 5,555.30	\$ 950.00
9	MT/0997288-002	COMFORT TRANSPORTATION PTE LTD	SHD 3230S	SIN 6185T	02/06/2018	\$ 2,736.58	\$ 1,302.98
10	MT/0997833-001	COMFORT TRANSPORTATION PTE LTD	SHC 1781L	SIT 1714T	03/06/2018	\$ 5,712.98	\$ 2,300.00
11	MT/0997524-002	COMFORT TRANSPORTATION PTE LTD	SHA 3460K	GBG 4353U	05/06/2018	\$ 2,752.02	\$ 900.00
12	MT/0997717-002	COMFORT TRANSPORTATION PTE LTD	SHC 2931P	GBG 3789Z	05/06/2018	\$ 2,751.20	\$ 1,250.00
13	MT/0996973-002	COMFORT TRANSPORTATION PTE LTD	SHA 3075P	FBE 3401G	01/06/2018	\$ 1,087.44	\$ 508.00
14	MT/0997835-001	COMFORT TRANSPORTATION PTE LTD	SHA 3514P	SJA 2496R	04/06/2018	\$ 2,836.58	\$ 800.00

Claim received from LKK Auto

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5100184044	SM PARTNERS PTE LTD	201811126M	GFT	Third Party	SKT1790K	SKT1790K	26/04/2018	

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4382K
Vehicle to be Exported:	No
Intended De-registration Date:	24 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR1325006
Chassis No.:	JTDKN36U705718962
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	20 Dec 2013
First Registration Date:	20 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Dec 2021
PARF Rebate Amount:	\$6,276.00
Intended COE Rebate Details	
COE Expiry Date:	19 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$62,740.00
COE Rebate Amount:	\$27,980.00
Total Rebate Amount:	\$34,256.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 24 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2018 11:06
Date Of Accident	19/05/2018 14:55
Exact Location Of Accident	HENDERSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4382K
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	TAN GEOK ENG
NRIC No	S0567918D
Date Of Birth	06/03/1948
Occupation	OUTDOOR
Date Of Driving Pass	07/07/1970
Driving Experience	47 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	466
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	6
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 4	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 5	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG HENDERSON ROAD AT THE SECOND RIGHT LANE AND HAD SLOWED DOWN WHEN APPROACHING THE TRAFFIC JUNCTION. SUDDENLY THE VEHICLE SKT1790K FROM BEHIND OVERTOOK ME FROM MY LEFT AND RESULTED IT'S RIGHT REAR PORTION HIT ONTO THE LEFT FRONT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT1790K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	SYED MUHAMMAD NIZAM BIN MOHAMED ZAIN
NRIC/Passport Number	S8635493D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Jon Geok Eng
Driver's Signature
(If driver is not the policyholder)
Date & Time:

abu 21/5/20
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION D

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____
Date & Time: _____

Jan Geert Eng

Driver's Signature
(If driver is not the policyholder)
Date & Time:

21/5/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

CC14

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4382K
 Ref. No : TAX/05/18/2088
 Reg. Date : 20/12/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : TAN GEOK ENG
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 19/05/2018 02:56:00 PM
 Accident Reported Date / Time : 21/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 19/05/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096187
 Special Instruction to ARC, if any :
 TOWED \$60 / SKT1790K
 Prepared Date : 21/05/2018 02:12:01 PM



Sebastian.
 22/5/18.

- Long Sun Repair.
 - Photo After Paint


 28/5/18

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chassis No : JTDKN36U70-5718962

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 378.00	0.00
Total Material Charges	: 392.22	392.22
Other Charges	: 164.00	0.00
TOTAL	: 1,272.22	0.00
Lum Sum Total	: 1,250.00	0.00
No. of Repair Days	: 3.00	0.00
Prepared / Adjusted By	:	2 days
Arc / Surveyor Sign Off Date	: 21/05/2018 05:33:56 PM	01/01/1900 12:00:00 AM

[Handwritten signature]

Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/05/2018 05:29:20 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 5/21/2018 5:32:02 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	378.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	84.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
Total Other Costs	164.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	<i>R</i> No
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace	<i>X</i> No
TOTAL MATERIALS								490.28	490.27	
TOTAL MATERIALS(Discounted)								392.22	392.22	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4382K

Ref. No : TAX/05/18/2088

Reg. Date : 20/12/2013

Vehicle Type : TAXI

Make : TOYOTA PRIUS

Model : PRIUS

Name of Driver : TAN GEOK ENG

Type of Accident : SIDE SWIPE

Date / Time of Accident : 19/05/2018 02:56:00 PM

Accident Reported Date / Time : 21/05/2018 12:00:00 AM

Surveyor is Required? : Yes

Survey by : Sebastian

Vehicle is Towed Back? : Yes

Towed Back Date/Time : 19/05/2018

Replacement Vehicle issued? : No

Accident Repair Job Card No : 000024096187

Special Instruction to ARC, if any :

TOWED \$60 / SKT1790K NTAC HS
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121
LUMPSUM REPAIR

Prepared Date : 21/05/2018 02:12:01 PM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date 22-5-18

2nd witness

Date

E 1/2 F
KM 677979

Vehicle to Wega Date In: 22/5
Time In: 7:49
Wega Job No: 05/0322
Vehicle sent to SMRT Date In: 23-5-2018
Time In: 3:45
Received by (SMRT):

QC 23/5/18 17.00 PASS

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U70-5718962

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	200.00
Total Spray Painting Charges	: 378.00	200.00
Total Material Charges	: 0.00	0.00
Other Charges	: 80.00	-100.00
TOTAL	: 796.00	300.00
Lump Sum Total	: 0.00	0.00
No. of Repair Days	: 3.00	2.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 21/05/2018 05:33:56 PM	22/05/2018 11:45:28 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/05/2018 05:29:20 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1805-0609

Invoice No :

Quotation Date : 25/5

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 5/21/2018 5:32:02 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	338.00	200.00
Total Labour	338.00	200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00
Total Spray Painting & Panel Beating	378.00	200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-100.00
Total Other Costs	80.00	-100.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	100.00	0.00	Replace	Repair	No <i>R</i>
53876-47030		6505554	FENDER LINER FRT/LH	0	171.70	25.00	0.00	Replace	Not given	No <i>X</i>
TOTAL MATERIALS							0.00	0.00		
TOTAL MATERIALS(Discounted)							0.00	0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

0.00
 + 200.00 /
 + 200.00 /

 400.00 /
 - 20%

 320.00 /
 US \$ 300 /-

Sebastian
 7/6/18

1449.70

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18009444/Sqbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 18-06-2018
189556

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKT 1790K	Veh. Inspected	SHC 4382K
Policy No.	5100184044	Coverage (\$)	0.00
Claim No.	MT/0997827-001	Excess (\$)	0.00
Assign From		Assign Date	22/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTDKN36U705718962	Colour	MAROON
Odometer	677979	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/05/2018	Inspection Date	22/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4382K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FENDER LINER FRT / LH	NOT NECESSARY TO REPAIR	171.70	-
1	BUMPER FRT		482.00	-
			653.70	-
<u>LABOUR</u>				
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		418.00	200.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.	378.00	200.00	
		796.00	400.00	
GRAND TOTAL			1,449.70	400.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				300.00

Report Ref No. NS/INC18009444/Sqbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.