

ASS. REC. BY:

REF: CS3/FC18009450 / G24d3<sup>2</sup>

Surveyor

6R

ASSIGNMENT (Office)

CWS

From (Person):

Aini Bt Md Min

of

FCI

Date/Time: 24/5/18 @ 12:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 3571D

Insured:

84C 743D

at Workshop m/s:

Sunrise Auto Service

Tel:

9876 9154

of

BK 15 Defu June 10 # 01-392

Policy No:

Claim No:

D18001074MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A

20/05/2018

(Client's Record)

28/5/18 @ 9am

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

12:25pm @ 24/5/18

Person Contacted:

paul

Vehicle IN

OUT

Date/Time	Action/Instruction (X) Estimate	
	GBD 3571D - NA/1A/15021762/d2	DOA: 19/12/2015
	84C 743D - CC3/A1G08024106/KDN	DOA: 28/05/2018

PRS  
Xhe

REF: FCI


C4150E

ASSIGNMENT

From: \_\_\_\_\_ Date: 28/5/18  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To inspect Vehicle No: GBD 3571 D  
at Workshop m/s Sunrise Auto Service  
of Blk 15 Defu Lane 10 # 01-392  
Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: 9am  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: 41k - 42k  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS / w/p

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBD 3571 D Yr Regn: 19 Sep 2014  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Nissan Cabstar C.C. 2953  
Colour: Silver A/C: Insured / Std / NI / NA  
Sp. Reading: 116567 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: JNISC2F248.0856431  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Mod: M / S/Rim / STD A/Rim or  
Tyre Size: F: 195R15  
R: 155R13  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Westlake (near)  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 28-03-18  
Survey held at w/s 10:30Am  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 01 JUN 2018

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

### MOTOR SURVEY ASSIGNMENT

Date	22-05-2018	Our Ref No. D18004074MFSH
Accident Date	20-05-2018	Claim Type. Third Party
Insured Vehicle	SHC0743D	Third Party Vehicle. GBD3517D
Survey Location	BLK 15 DEFU LANE 10#01-392	
Contact Person.	PAUL	
Contact No.	0/ 98769154	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

Cc : Workshop	SUNRISE AUTO SERVICE	Attention. NIL
Cc : TP Solicitor	KSCGP JURIS LLP	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240624)



PRI Documents



Close



## PRI Header Details

Claim No	D18004074MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & KSCGP JU
Workshop Name	SUNRISE AUTO SERVICE (Contact Person : PAUL)	Survey Location & Contact Details	BLK 15 DEFU LANE 10#01-392 Mobile: 98769154 , Phone: 0 , Fax: 0 EmailId: ACCIDENT@KSCGP.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0743D	TP Vehicle No	GBD3517D
PRI Recieved Date	24-05-2018 02:51:12 PM	Surveyor Appointed Date	24-05-2018 02:54:02 PM	Surveyor Accept Date	24-05-2018 0

## Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	24-05-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--------------------------------------------

## Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
---------	----------------------	-------------------------------------

## Nivitha (LKK Auto)

---

**From:** Aini Binte Md Min <Aini@msfirstcapital.com.sg>  
**Sent:** Thursday, 24 May 2018 12:17 PM  
**To:** 'assignments@lkkauto.com'  
**Cc:** Sithara  
**Subject:** NEW ASSIGNMENT (ACCDT INVLVG SHC743D & GBD3571D ON 20.5.18 - O/REF: D18/4074)  
**Attachments:** WORKSHOP DETAILS.pdf

Dear Catherine

Refer to our telephone conversation of just.

Kindly attend to the PRI.

Thanks & Regards

Aini  
Motor Claims Department

**MS First Capital Insurance Ltd** | 36 Robinson Road, City House, #16-01 Singapore 068877 | TEL: 6507 3848  
Fax: 6507 3849 | Company Reg. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to [www.msfirstcapital.com.sg](http://www.msfirstcapital.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

Dep 6850/yr  
571 /with

111

41 - 42 K

Min

31/5/18

Your insured vehicle : SHC 743D  
Our client's vehicle / ref: GBD 3571D ; SN/sy/ms  
Date : 24 May 2018

First Capital Insurance Limited

By Email Only

Dear Sirs,

**DATE OF ACCIDENT: 20 MAY 2018**  
**NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS**

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our list of surveyors as appended below:-

S/N	Name of Surveyor	Company Name
1.	Foo Philip	Precision Appraisal Services
2.	Ronald Ng	Precision Appraisal Services
3.	Lee Kok Weng	Lee Automobile Appraisals Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which we will commence repairs thereafter without any further notice or reference to you. Please also let us know if you required a Post-Repair Survey/Inspection for our client's consideration. Please be informed that the said vehicle can be surveyed / inspected at:

Workshop : Sunrise Auto Service  
Address : Block 15 Defu Lane 10  
#01-392  
Singapore 539196  
Contact : Paul (h/p: 9876 9154)

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,



Your ref : SHC 743D  
Our client's vehicle / ref: GBD 3571D ; SN/sy/ms  
Date : 24 May 2018

**Acknowledgement**

This is to confirm that I \_\_\_\_\_ *[Full Name of Surveyor]* of  
\_\_\_\_\_ *[Surveyor's Company]* have completed as  
follows:-

(a) Pre- Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(b) Pre- Repair Survey/Inspection (after dismantling) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(c) Re-inspection of new replacement part (party by part) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(d) Post – Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:



Posted: 15-May-2018 Tags: 2014 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan



**Nissan Cabstar** **\$43,000** **\$6,850 /yr** **09-Sep-2014** **2,953 cc** **86,996 km** **Truck** **Available**  
**Fuel Type:** Diesel  
 1 Owner Only. Regular Servicing At Nissan Service Center. Can Call/Whatsapp If Interested.

**DIRECT OWNER**

Posted: 06-May-2018 Tags: 2014 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan



**Nissan Cabstar** **\$43,800** **\$7,250 /yr** **13-Jun-2014** **2,953 cc** **86,554 km** **Truck** **Available**  
**Fuel Type:** Diesel  
 Please Call To Arrange For Viewing, Thanks.

Posted: 30-Apr-2018 Tags: 2014 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan



**Nissan Cabstar** **\$48,800** **\$7,980 /yr** **10-Jul-2014** **2,953 cc** **95,311 km** **Truck** **Available**  
**Fuel Type:** Diesel  
 New Paint. Low Millage Done, Low Deposit, In House Loan Available.

**PREMIUM AD**

Posted: 23-Apr-2018 Tags: 2014 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan



#### Save on petrol with OCBC 365 credit card!

Enjoy huge petrol savings of up to 23%, attractive cashback on your monthly spend, and 2 years annual fee waiver. Apply now and start enjoying today.

Find out more!



**Nissan Cabstar** **\$46,800** **\$7,790 /yr** **02-Jun-2014** **2,953 cc** **102,580 km** **Truck** **Available**  
**Fuel Type:** Diesel  
 1 Owner, Original Paint Work, 100% Accident Free, 100% Loan Available.

Posted: 04-Apr-2018 Tags: 2014 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan

Save this search criteria, to get email alerts whenever a match is found.

Make  Model  Price  Depreciation  Reg Date  Eng Cap  Mileage  Veh Type  Status

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used NISSAN, NISSAN Singapore, used NISSAN Singapore, used NISSAN, used vehicles Singapore or even buy used NISSAN Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

Compare [ 2 ]

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

Select used cars to **Compare** or **Add to Alert**

**Shortlist [ 2 ]**



Mazda 3 1.6A SP  
Luxury (COE till  
28-Feb-2007)



Nissan Cabstar  
09-Sep-2014

To compare cars,  
select from the  
search results.

To compare cars,  
select from the  
search results.

Add to Shortlist

Compare Now

Clear All





**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
FIRST CAPITAL INSURANCE LTD		Ref:	CS3/FCI18009450/Gz4d3s2
36 ROBINSON ROAD		Date:	07-06-2018
#16-01 CITY HOUSESINGAPORE 068877			
		Code:	FCI2
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	SHC 743D	Veh. Inspected	GBD 3571D
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18004074MFSH	Excess (\$)	0.00
Assign From	AINI BT MD MIN	Assign Date	24/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JN1SC2F24Z0856431	Colour	SILVER
Odometer	116567 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195 R15	MICHELIN	6 mm
L/H Front Tyre	195 R15	MICHELIN	6 mm
R/H Rear Tyre	155 R13	WEST LAKE	6 mm
L/H Rear Tyre	155 R13	WEST LAKE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
<b>5. General Information</b>			
Accident Date	20/05/2018	Inspect Date / Time	28/03/2018 ( 10:30 AM )
Survey held at	SUNRISE AUTO SERVICES BLK 15 DEFU LANE 10 #01-392 SINGAPORE 539195		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) MARKET VALUE: \$43,000.00			

Report Ref No. CS3/FCI18009450/Gz4d3s2

Inspected By



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.