

ASS. REC. BY:

REF: CS/SMO18009473/Tlgd3/

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person): Grace TCO

of

SMO

Date/Time: 24/05/2018 @ 2:38pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 686E

Insured:

SGL 41534

at Workshop m/s

performance motor

Tel: 6319 0174

of

303 Alexandra Road

Policy No:

Claim No:

CMTD1802057/GPL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/05/2018

28/05/18 @ 10am - 12pm

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time:

2:50pm @ 24/5/2018

Person Contacted:

Caroline

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SKU 686E -X

SGL 41534 -X

31/5/18 @ 1:41pm revised to Grace Paul loop by email.

31/7/18 @ 3:30pm confirmed with Caroline that fig B15518.85, 9 days.

Cred \$ 4587.85, 73/107

Girvan

Taulpin

REF: SMO

ASSIGNMENT

From:

Date:

28/5/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKU 686E

at Workshop m/s

Performance

of

303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

16:30am - 12pm

Make of Veh:

Gary

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

9

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKU 686E

Yr Regn:

2015 June

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 520I

C.C.

1997

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

62962

T/Radio: Insured / Std / NI / NA

Eng/No.

C/No:

WBA5U320X0D 828399

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

28/5/18

Survey held at

PML

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 01 AUG 2018

Date/Time. File Pass to?

☐

: Preli. Report

1) 31/7 15:58

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

9

Resurvey No. of Trip:

1

Survey Fee:

Transportation

) S + RS)

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

15578.25

450

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 24 May 2018 2:38 PM
To: PBSP; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Gnoh, Pau Loong; Ye, Yong Kang Melvin
Subject: CMTD1802057/GPL - SUV(LKK)/ SGL4153U & SKU686E ACC ON 14/05/2018
Attachments: SKM_558e18051510150.tif; SKU686E.PDF

Our Claim Reference: CMTD1802057/GPL
Your Reference: SKU686E

Hi Caroline,

As agreed we have appointed **LKK AUTO** according to your request to conduct the survey.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for SKU686E on 28/05/18.

Please be informed that Gnoh Pau Loong the handler of this case

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Thursday, May 24, 2018 2:12 PM
To: Teo, Grace; Claims - Motor Survey
Subject: Re: CMTD1802057/GPL - LIA/ SGL4153U & SKU686E ACC ON 14/05/2018

Dear Sirs

Please arrange the survey on Monday, 28.05.2018, 10.30am - 12noon.

***Owner waiting.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 15 May 2018 2:42:30 PM
To: PBSP
Cc: Gnoh, Pau Loong; Ye, Yong Kang Melvin
Subject: CMTD1802057/GPL - LIA/ SGL4153U & SKU686E ACC ON 14/05/2018

Our Claim Reference: CMTD1802057/GPL
Your Reference: SKU686E

Hi Caroline,

We acknowledged receipt of your claim documents.

Kindly re-direct your future motor claims survey request to motorsurvey@sompo.com.sg

Please be informed that Gnoh Pau Loong is the handler of this case.

Kindly advise us when the vehicle is in for survey.

Aside to Pau Loong,

Please refer to the liability request from Performance Motors Limited.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: PBSP [mailto:pml-pbsp@sime-darby.com.sg]

Sent: Tuesday, May 15, 2018 10:19 AM

To: Henry, Irene James; claimsreport

Subject: REQ FOR DIRECT SETTLEMENT-SKU686E AND SGL4153U ON 14/05/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 31 July 2018 3:30 PM
To: PBSP; Taufikh (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SKU686E

Dear Caroline,

WITHOUT PREJUDICE

Confirm final fig \$15,518.25 before GST and 9 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, 23 July 2018 2:07 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SKU686E

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 10,134.00

Total Parts : 5,384.25

Total Labour & Parts : 15,518.25

Repair days: 9

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 31 May 2018 1:41 PM
To: 'Teo, Grace'; 'Gnoh, Pau Loong'
Cc: 'Ye, Yong Kang Melvin'; SUR; assignments
Subject: RE: CMTD1802057/GPL - SUV(LKK)/ SGL4153U & SKU686E ACC ON 14/05/2018
Attachments: CSSMO18009473T1qd3.pdf

Dear Mr Goh,

Enclosed herewith preliminary advice of SKU 686E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

Sent: Thursday, 24 May 2018 2:38 PM

To: PBSP <pml-pbsp@sinedarby.com.sg>; admin-d@lkkauto.com; assignments@lkkauto.com

Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD1802057/GPL - SUV(LKK)/ SGL4153U & SKU686E ACC ON 14/05/2018

Our Claim Reference: CMTD1802057/GPL

Your Reference: SKU686E

Hi Caroline,

As agreed we have appointed **LKK AUTO** according to your request to conduct the survey.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for SKU686E on 28/05/18.

Please be informed that Gnoh Pau Loong the handler of this case

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1802057/GPL

Date: 31st May 2018

Our Ref: CS/SMO18009473/T1qd3

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SKU 686E


We thank you for the instruction on 24/05/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/05/2018 at the premises of M/s PERFORMANCE MOTORS LIMITED and have the following to report:-

Workshop Estimate Amount	: S\$ <u>19,605.35</u>
Revised Estimate Amount	: S\$ <u>8,675.70</u>
"Check" Items Amount	: S\$ <u>5,280.20</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 6 days.

We have NOT authorized repair.

Yours faithfully

Taufikh
Automobile Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available: aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/05/2018 18:19
Date Of Accident	14/05/2018 06:50
Exact Location Of Accident	OLD HOLLAND RD OUTSIDE MGS SCHOOL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU686E
Insured/Policyholder	
Name Of Registered Owner	YOONG EE POW
NRIC No	S2576250I
Email Address	EPYO@CHEVLON.COM
Mobile Phone No	(LOCAL) +65-98355437
Alternative Phone No	OFFICE-98355437

Vehicle Particulars

Manufacturer	BMW
Model	520I
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA222000
Cover Note Number	

Driver

Name of Driver	YOONG EE POW
NRIC No	S2576250I
Date Of Birth	12/07/1965
Occupation	INDOOR
Date Of Driving Pass	14/04/1989
Driving Experience	29 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98355437
Fax Number	
Contact Number	OFFICE-98355437
Email Address	EPYO@CHEVLON.COM

Address	20 CHESNUT LANE
Postcode	679193
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGL4153U
Vehicle Make/Model/Colour	KIA GREY
Details Of Properties	MY CAR BUMPER & BOOTH WERE DAMAGED
Vehicle Category	PRIVATE CAR
Name of Driver	YEONG YUEN JOO
NRIC/Passport Number	S7436634A
Contact Number	
Address	BLK 110 SPOTTISWOODE PARK #05-89
Postcode	081110
Insurance Company Name	SOMPO INSURANCE SINGAPORE PTE. LTD.
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	3
Passenger 1	NAME: : GENDER: :

Passenger 2

NAME: ;

GENDER: ;

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

4:50pm
14 May '18


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


14/5/18
4:50pm

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Happened in a school zone, outside MGS School, on Old Holland Rd. I ~~was~~ waited My car stop because there is a long ~~long~~ queue of cars waiting to turn into the school to drop off their daughters. Then suddenly the car at ~~back~~ behind me ~~hit~~ hit the back of my car. My car camera capture the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 4:50 PM
14 May '18

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

14/5/18
4:50

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159942
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

15 MAY 2018

Estimate No. : b1 46923
Date Estimated : 14/05/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Yoong Ee Pow
20 Chestnut Lane

Singapore 679193

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU686E	D828399	29/06/2015	520iA	0

DESCRIPTION

To replace rear bumper, bootlid, tail panel and attachment
include knocking cause by the accident

1038 1058 243
Painting rear bumper, bootlid, tail panel, left rear fender
right rear, trunk floor

To carry out body cavity preservation.
(For cut panel).

To carry out body cavity preservation.
(Per panel).

To check electrical wiring systems and lightings at the
rear section for proper function.

Sundries.

VALUE

14675 2550 5,525.00

14608 2537 5,120.00

4517 531.00

100 118.00

150 177.00

mc 7 150.00

Total Labour 1: 11,621.00

DESCRIPTION

TAIL END PANEL
BOOTLID
SET MOUNTS PDC SENSOR REAR
RR BUMPER BOTTOM CENTRE GUIDE
RR BUMPER CARRIER
ADAPTOR
REAR BUMPER CENTRE GUIDE
RR LH MOUNT
RR RH MOUNT
REAR BUMPER PRIMED (PDC)
REAR BUMPER TOWING EYE COVER PRIMED
EMBLEM GROMMET
MODEL LETTERING 520i
BMW EMBLEM
BOOTLID SEALING

QTY PRICE

1 817.30
1 1,602.40
1 62.95
1 58.95
1 714.25
1 68.45
1 60.05
1 198.30
1 198.30
1 1,467.20
1 46.45
2 0.80
1 62.55
1 69.50
1 115.25

VALUE

bt 817.30
bt 1,602.40
? 62.95
? 58.95
bt 714.25
de 68.45
de 60.05
de 198.30
de 198.30
de 1,467.20
un x 46.45
re 1.60
re 62.55
re 69.50
re 115.25

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46923
Date Estimated : 14/05/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU686E	D828399	29/06/2015	520iA	0

DESCRIPTION

REAR LH REFLECTOR
RR LH LIGHT IN SIDE PANEL
RR LH LIGHT IN TRUNK LID
DECOUPLING RING PDC TORQUE CONVERTE
BUMPER PDC SENSOR (300 ALPINWEISS)

QTY	PRIC	VALUE
1	35.20	35.20
1	572.25	572.25
1	338.00	338.00
4	5.05	20.20
4	368.80	1,475.20

Total Parts : 7,984.35

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 30 / Uninsured losses / Direct Expenses

Regn No. _____ Date Recd. _____

Date/Time: 28/5/2015 _____

Surveyor's name: Taufik _____

Surveyor's Tel: 97495449 _____

Authorized Del: _____

RESURVEY: _____

Surveyor's Ext: _____

No. of Working Days: 9 days

Labour 1	:	11,621.00
Parts	:	7,984.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,372.37
Grand Total	:	20,977.72

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

2016/10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46923
Date Estimated : 14/05/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Yoong Ee Pow
20 Chestnut Lane

- ACCOUNT - 509
Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

Singapore 679193

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SKU686E	D828399	29/06/2015	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	1.00	8.00		8.00 <i>agree</i>
# PLUG *	1.05	10.00		10.50 <i>agree</i>
# PLUG BLACK D=5MM *	0.90	10.00		9.00 <i>agree</i>
# BLIND RIVET AVIBVLB *	0.55	60.00		33.00 <i>agree</i>
# SCREW (SF PLUS M5X15) *	0.55	10.00		5.50 <i>agree</i>
# (DG/SL) BODY ADHESIVE K5B (195ML) *	281.55	1.00		281.55 <i>agree</i>
# PUNCH RIVET N4 *	0.55	20.00		11.00 <i>agree</i>
# (DG) BODYWORK ADHESIVE K5A (50ML) *	118.35	1.00		118.35 <i>agree</i>
# (DG) CLEANER R1 (100ML) *	23.85	1.00		23.85 <i>agree</i>

Total Labour :	
Total Parts :	500.75
Total Labour & Parts :	500.75

Performance Motors Limited

A member of the Sino Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46923
Date Estimated : 14/05/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Yoong Ee Pow
20 Chestnut Lane

- ACCOUNT - 509
Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

Singapore 679193

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKU686E	D828399	29/06/2015	520iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid, tail end panel include making good the rear LH/RH fenders, trunk floor plate and knocking out dents caused by the accident	4675.00		4,675.00	
To spray paint rear bumper, boot lid, tail end panel, rear LH/RH fenders and trunk floor plate	4608.00		4,608.00	
* To carry out body cavity preservation. (For cut panel).	451.00		451.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
Sundries	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
TAIL END PANEL	817.30	1.00		817.30
BOOTLID	1,602.40	1.00		1,602.40
# EXPANDING NUT *	1.00	8.00		8.00
RR BUMPER CARRIER	714.25	1.00		714.25
ADAPTOR	68.45	1.00		68.45
REAR BUMPER CENTRE GUIDE	60.05	1.00		60.05
REAR BUMPER PRIMED (PDC)	1,467.20	1.00		1,467.20
EMBLEM GROMMET	0.80	2.00		1.60
MODEL LETTERING 520i	62.55	1.00		62.55
BMW EMBLEM	69.50	1.00		69.50
# PLUG *	1.05	10.00		10.50
# PLUG BLACK D=5MM *	0.90	10.00		9.00
DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00		20.20
# BLIND RIVET AVIBVLB *	0.55	60.00		33.00
# SCREW (SF PLUS M5X15) *	0.55	10.00		5.50
# (DG/SL) BODY ADHESIVE K5B (195ML) *	281.55	1.00		281.55
# PUNCH RIVET N4 *	0.55	20.00		11.00

Performance Motors Limited

A member of the Stone Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

(DG) BODYWORK ADHESIVE K5A (50ML) *
(DG) CLEANER R1 (100ML) *

118.35 1.00
23.85 1.00

118.35 *Up net*
23.85 *UP all*

SUPPLEMENTARY ITEMS

Total Labour :	10,134.00
Total Parts :	5,384.25
Total Labour & Parts :	15,518.25
Deduction for Excess :	
Total Repair Costs less Excess:	15,518.25
GST @7%:	1,086.28
Grand Total :	16,604.53

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18009473/T1qd3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 03-08-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGL 4153U	Veh. Inspected	SKU 686E
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802057/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	24/05/2018

2. Vehicle Particulars & Condition

Make & Model	BMW 520i	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WBA5A320X0D828399	Colour	BLACK
Odometer	62962	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	PIRELLI	6 mm
L/H Front Tyre	225/55 R17	PIRELLI	6 mm
R/H Rear Tyre	225/55 R17	PIRELLI	6 mm
L/H Rear Tyre	225/55 R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/05/2018	Inspection Date	28/05/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFV 833B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH WING MIRROR	CUT	2,079.00	2,079.00
1	RH WING MIRROR COVER	CRACKED	5,781.40	5,781.40
1	RH WING MIRROR SIGNAL LAMP	CUT	156.70	156.70
LESS 5% DISCOUNT			-400.86	-400.85
			7,616.24	7,616.25
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
<u>LABOUR</u>				
LABOUR FOR REPAIR ON AFFECTED AREA.			500.00	200.00
SPRAY PAINT ON AFFECTED AREA.			300.00	-
CHECK WIRING.			50.00	30.00
			850.00	230.00
GRAND TOTAL			8,516.24	7,866.25
RECOMMENDED COST OF REPAIRS				7,866.25

Report Ref No. CC6/EQ18003903/T1jb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 686E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	TAIL END PANEL (SN)	BENT	817.30	817.30
1	BOOTLID (SN)	BENT	1,602.40	1,602.40
1	SET MOUNTS PDC SENSOR REAR (SN)	NOT NECESSARY	62.95	-
1	RR BUMPER BOTTOM CENTRE GUIDE (SN)	NOT NECESSARY	58.95	-
1	RR BUMPER CARRIER (SN)	BENT	714.25	714.25
1	ADAPTOR (SN)	DEFORMED	68.45	68.45
1	REAR BUMPER CENTRE GUIDE (SN)	DEFORMED	60.05	60.05
1	RR LH MOUNT (SN)	NOT NECESSARY	198.30	-
1	RR RH MOUNT (SN)	NOT NECESSARY	198.30	-
1	REAR BUMPER PRIMED (PDC) (SN)	DEFORMED	1,467.20	1,467.20
1	REAR BUMPER TOWING EYE COVER PRIMED (SN)	NOT NECESSARY	46.45	-
2	EMBLEM GROMMET @\$0.80 (SN)	NECESSARY	1.60	1.60
1	MODEL LETTERING 520I (SN)	NECESSARY	62.55	62.55
1	BMW EMBLEM (SN)	NECESSARY	69.50	69.50
1	BOOTLID SEALING (SN)	NOT NECESSARY	115.25	-
1	REAR LH REFLECTOR (SN)	NOT NECESSARY	35.20	-
1	RR LH LIGHT IN SIDE PANEL (SN)	NOT NECESSARY	572.25	-
1	RR LH LIGHT IN TRUNK LID (SN)	NOT NECESSARY	338.00	-
4	DECOUPLING RING PDC TORQUE CONVERTE @\$5.05 (SN)	NECESSARY	20.20	20.20
4	BUMPER PDC SENSOR (300 ALPINWEISS) @\$368.80 (SN)	NOT NECESSARY	1,475.20	-
8	EXPANDING NUT @\$1.00 (SN) (ADDITIONAL)	NECESSARY	8.00	8.00
10	PLUG @\$1.05 (SN) (ADDITIONAL)	NECESSARY	10.50	10.50
10	PLUG BLACK D=5MM @\$0.90 (SN) (ADDITIONAL)	NECESSARY	9.00	9.00
60	BLIND RIVET AVIBVLB @\$0.55 (SN) (ADDITIONAL)	NECESSARY	33.00	33.00
10	SCREW (SF PLUS M5X15) @\$0.55 (SN) (ADDITIONAL)	NECESSARY	5.50	5.50
1	(DG/SL) BODY ADHESIVE K5B (195ML) (SN) (ADDITIONAL)	NECESSARY	281.55	281.55
20	PUNCH RIVET N4 @\$0.55 (SN) (ADDITIONAL)	NECESSARY	11.00	11.00
1	(DG) BODYWORK ADHESIVE K5A (50ML) (SN) (ADDITIONAL)	NECESSARY	118.35	118.35
1	(DG) CLEANER R1 (100ML) (SN) (ADDITIONAL)	NECESSARY	23.85	23.85
			8,635.10	5,534.25

Report Ref No. CS/SMO18009473/T1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPLACE REAR BUMPER, BOOTLID, TAIL PANEL AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT.		5,525.00	4,675.00
	PAINTING REAR BUMPER, BOOTLID, TAIL PANEL, LEFT REAR FENDER, RIGHT REAR, TRUNK FLOOR.		5,120.00	4,608.00
	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL).		531.00	451.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	100.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			11,471.00	9,984.00
	GRAND TOTAL		20,106.10	15,518.25
RECOMMENDED COST OF REPAIRS				15,518.25

Report Ref No. CS/SMO18009473/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.