

ASS. REC BY:

REF: CS3/ALG18009477/N 24d3/2

Special Instruction:

Surveyor  
member

Naz

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALG

Date/Time:

21/5/2018 @ 2.31pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 289 H

Insured:

GBC 2035Y

at Workshop m/s

Lush Automotive

Tel:

97 9 66 97 9

of

No. 8 kaki Bukit Ave 4 #03-47

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/05/2018

CA / REV / REP. / REV 24 HRS (wp)

25/05/2018

Date/Time:

2.44pm @ 21/5/18

Person Contacted:

Mr. Max

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction ( X ) Estimate

SJK 289H - CC4/ASM18005410/M/pb3

DOA: 20/03/18

GBC 2035Y - NA/ALG16001319/r3

DOA: 22/10/15

PRS

REF: AIG

## ASSIGNMENT

From: Date: 25/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJK 289H  
at Workshop m/s Lush Automotive  
of No. 8 Kaki Bukit Ave 4 #03-47

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

31/5/18 Submit DAR Report.

Veh No: SJK 289H Yr Regn: /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW C.C.

Colour: SILVER A/C: Insured / Std / NI / NA

Sp. Reading: 382, 115 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBAPF72000A143007

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 25/5/18

Survey held at LUSH AUTOMOTIVE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 01 JUN 2018

Date/Time: File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time: File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) )


Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Weekend (\$

180

20

200

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBC2035Y AND SJK289H ON 23/5/2018**

From: Chin, Lee-Ying  
To: 'assignments', Admin A  
Cc: Fong, Andy-SY  
Sent: 24/5/2018 2:31:21 PM  
Attachments:  180524-GIA report SJK289H(new).pdf

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Yvonne [<mailto:yvonne@ealc.com.sg>]  
**Sent:** Thursday, May 24, 2018 1:21 PM  
**To:** Chan, Yoke Shi  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene  
**Subject:** PRI AIG Insured GBC2035Y [EAL.2018.5684.MK.ya -SJK289H]

Our ref : 2018.5684.MK.ya -SJK289H  
Your ref : GBC2035Y

PLEASE REPLY VIA EMAIL ([yvonne@ealc.com.sg](mailto:yvonne@ealc.com.sg))

AIG Asia Pacific Insurance Pte Ltd  
No. 78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Motor Claims Department  
**2 DAYS' PRE-REPAIR NOTICE**

Surveyor from M/s AIG Asia Pacific Insurance Pte Ltd

Vehicle **SJK289H** inspected as follows by Name:

Before repair	Parts removed	After repair
_____	_____	_____
Signature	Signature	Signature
Date/ Time:	Date/ Time:	Date/ Time:

Dear Sir/Madam,

**NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE**

**CLAIMANT: SPEED ARRIVE**

**ACCIDENT INVOLVING SJK289H & GBC2035Y ON 23 MAY 2018 ALONG BALESTIER ROAD TOWARDS THOMSON ROAD AT ABOUT 1135 HOURS**

We refer to the above matter wherein we are instructed to act for **SPEED ARRIVE**, the owner of vehicle no. **SJK289H**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SJK289H** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Lush Automotive Pte Ltd  
No. 8 Kaki Bukit Avenue 4,  
#03-47 Premier@Kaki Bukit,  
Singapore 415875  
Tel: 97966979 (Mr Max)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,  
Yvonne Ang

East Asia Law Corporation  
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413  
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.


If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



**LKK Auto Consultants Pte Ltd**  
 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933  
 TEL: 6256 3561 FAX: 6256 4315  
 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CS3/AIG18009477/Nz4d3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 24-05-2018	
			Code : AIG	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	GBC 2035Y	Veh. Inspected	SJK 289H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	CHIN LEE YING	Assign Date	24/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	23/05/2018	Inspection Date		
Survey held at	LUSH AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-47 PREMIER @ KAKI BUKIT SINGAPORE 415875			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GlA Records Management Centre established by the General Insurance Association of Singapore (GlA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/05/2018 09:34
Date Of Accident	23/05/2018 11:35
Exact Location Of Accident	BALESTIER ROAD TOWARDS THOMSON ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK289H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SPEED ARRIVE
Co Reg No	53340525D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90215282

### Vehicle Particulars

Manufacturer	BMW
Model	318i
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMHCSN1741291700
Cover Note Number	

### Driver

Name of Driver	HAR CHAW KHEAN
NRIC No	S7678317I
Date Of Birth	15/10/1976
Occupation	OUTDOOR
Date Of Driving Pass	22/08/2009
Driving Experience	8 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90214943
Fax Number	
Contact Number	
EMail Address	CHAWKHEAN@GMAIL.COM

Address	483 YIO CHU KANG ROAD #05-07
Postcode	787057
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	MOULMEIN NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer to sketch plan / police report no: T/20180523/2092

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC2035Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHANDRASEKARAN VIVEKPANDIAN
NRIC/Passport Number	G6772374R
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	HAR CHAW KHEAN
------	----------------

Approximate Age	41
Injuries Sustain	NECK AND SHOULDER
Injured person in which vehicle?	SJK289H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	483 YIO CHU KANG ROAD #05-07
Postcode	787057



**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
 Policyholder's Signature  
 Date & Time:  
 24/05/08 9:35am

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:  
 24/05/08 9:35am

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.: Jenny Lim  
 S6927273H

## Sketch Plan Pg. 2

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

**SPEED ARRIVAL**

Policyholder's Signature \_\_\_\_\_  
Date & Time: ★ 9:35 am  
24-05-18  
GIAN MICHAEL P. TORRES JR.

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:  
24/05/18 9:35am

Reporting Centre Personnel's Signature  
Name: Jenny Lim  
NRIC/FIN No.: S6927273H



**SINGAPORE  
POLICE FORCE**



T/20180523/2092

Police Station Of Origin:  
Moulmein NPP  
101 Jalan Rajah #01-01 SINGAPORE  
321101  
Tel No: 1800-25089999

1 of 3

Report No. T/20180523/2092

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 23/05/2018 16:55		Vide Report No.:		Station Diary No.: 23	
<b>Informant's Particulars</b>					
Name of Informant: HAR CHAW KHEAN			Address: 483 YIO CHU KANG ROAD #05-07 SINGAPORE 787057		
ID Type / ID No.: NRIC NO / S76783171			Contact No.: Home/Office: Mobile: 90214943		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 41	Date of Birth: 15/10/1976	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: driver			Driving Licence Information: Class: Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 23/05/2018 11:35	Type of Location: Straight Road
Location: Along Road 1 BALESTIER ROAD				
Balestier Road towards Thomson Rd (Junction of Shan Rd and Balestier Rd)				
Weather: Raining		Road Surface: Wet	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBC2035Y	Lorry				Slightly Damaged	1
SJK289H	Car				Seriously Damaged	0

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

## Police Report Pg. 2



**SINGAPORE  
POLICE FORCE**



T/20180523/2092

Police Station Of Origin:  
Moulmein NPP  
101 Jalan Rajah #01-01 SINGAPORE  
321101  
Tel No: 1800-25089999

2 of 3

Report No. T/20180523/2092

## CONTINUATION OF REPORT

<b>Driver 1</b>			
Name	CHANDRASEKARAN VIVEKPANDIAN	ID No.	G6772374R
Related Vehicle	GBC2035Y (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver 2</b>			
Name	HAR CHAW KHEAN	ID No.	S7678317I
Related Vehicle	SJK289H (Car)	Contact No.	90214943
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	23/05/2018	Date Discharge	23/05/2018
No. of Days granted Medical Leave	03	Degree of Injury	Serious

**Brief Details.**

I was driving my vehicle along Balestier Rd towards Thomson Rd on the most right lane. I was approaching Shan Rd junction. All of a sudden a lorry hit me from the rear. I wish to state that I did not apply any brakes and I drive steadily. I stopped my car and alighted from my car. The driver of the lorry also stopped and we exchanged particulars. I felt pain at my neck area and shoulder. I went to Tan Tock Seng Hospital for a checkup and received 3 days Medical Leave.



**SINGAPORE  
POLICE FORCE**



T/20180523/2092

3 of 3

Police Station Of Origin:  
Moulmein NPP  
101 Jalan Rajah #01-01 SINGAPORE  
321101  
Tel No: 1800-25089999

Report No. T/20180523/2092

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
E /  
Sr Staff Sgt MOHAMMAD AZRI BIN JUMAHAT

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
23/05/2018 16:55

Officer In Charge Of Case:  
TP / AEIT /  
SSI 2 SITIMARSITA BINTE BOHARI  
Contact No.: 65476219.

Classification Of Case:

Authentication Stamp  
NP188



SINGAPORE  
POLICE FORCE

SN 080

SIGNATURE

# **MOTORCAR (Rear)**

## **Rear Portion**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DMG	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	DMG	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	MS	✓	
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	CRK	✓	
1149	993045	Rear Bumper Reinforcement	DT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	SC	✓	
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish	CRK	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	SCR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	SCR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DMG	✓	
1171	991328	Bootlid Emblem	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	DT	✓	
1178	990377	Bootlid Rubber	BT	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

## **Vehicle No: SJK 289 H**

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	CRK	✓	
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 May 2018 <a href="#">Edit Reg</a>		24 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	FOOD SPECTRUM TRADING, Co. Reg. No.: 53062665M		
Main Claimant:	SPEED ARRIVE, Co. Reg. No.: 53340525D		
Vehicle Reg. No.:	SJK289H	Date of Loss:	23/05/2018 11:00 - :59 [106 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6411190430SG	Policy/Cover Note No.:	1700042673 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC2035Y	Policy No. (Claimant):	
		Excess:	
Repairer:	LUSH AUTOMOTIVE PTE LTD (HQ) No. 8 Kaki Bukit Avenue 4,, #03-47 Premier@Kaki Bukit,, 415875 Kaki Bukit - Tel: 86662345		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 08/06/2018]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)






































- AIG\_SG (31/05/2018): Request To Upload TP GIA Report

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)




Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJK289H (6411190430SG)  
[GBC2035Y]  
TP  
SPEED ARRIVE  
May 23 2018 11:00AM  
[FOOD SPECTRUM TRADING]  
LUSH AUTOMOTIVE PTE LTD

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail		Print	
1	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
2	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
3	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
4	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
5	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
6	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
7	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
8	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
9	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
10	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
11	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
12	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
13	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
14	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
15	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
16	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
17	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
18	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
19	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
20	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
21	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
22	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
23	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
24	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
25	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
26	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
27	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
28	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
29	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
30	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
31	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
32	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
33	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
34	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
35	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
36	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	
37	31/05/18 17:41	General View									 Load JPG		<input checked="" type="checkbox"/>	



Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	31/05/18 17:41	General View		 Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	31/05/18 17:01	OI GIA REPORT		 Load PDF	
2	01/06/18 16:14	TP GIA		 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009477/NZ4D3E2

Date: 04/06/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700042673  
 Claimant Vehicle No: SJK289H Insured Vehicle No: GBC2035Y  
 Date of Loss: 23/05/2018 Nature of Claim: TP Claim No: 6411190430SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK289H  
 Make & Model: BMW 318i, 2.0 (A) Engine No: B094I438N46B20BZ  
 Reg. Date: 30/06/2009 (Man. Year: 2009) Chassis No: WBAPF72000A143007  
 Colour: Silver Odometer: 382115 km  
 Engine Capacity: 1995 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 24/05/2018  
 Date Inspected: 25/05/2018 Inspected At: LUSH AUTOMOTIVE PTE LTD (HQ)  
 No. 8 Kaki Bukit Avenue 4, #03-47  
 Premier@Kaki Bukit,  
 Singapore 415875  
 Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Damaged	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Damaged	0.00 F	*- F
3	1		*REAR BUMPER TOW COVER	Missing	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER	Cracked	0.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
7	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Scratched	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
11	1		*BOOTLID	Damaged	0.00 F	*- F
12	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID LOCK	Dented	0.00 F	*- F
14	1		*BOOTLID RUBBER	Bent	0.00 F	*- F
15	1		*REAR EXHAUST PIPE	Cut	0.00 F	*- F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >