

22/03/2002

ASS. REC. BY:

REF: CS3/ AIG18009478 / N24d3d2

Special Instruction:

Surveyor: N92

ASSIGNMENT (Office)

From (Person): chin lee ying

of AIG

Date/Time: 21/5/18 @ 2.56pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.: SGM 5551 S

Insured: ABC 3367H

at Workshop m/s Motor Intel

Tel: 88 38 3318

of 13 kaki Bukit Road 1 # 01-20

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 23/05/2018

CA / REV / REP. / REV 24 HRS 'wp'

25/05/2018

H.O.D. Endorsement:

Date/Time: 3.30pm @ 21/5/18

Person Contacted:

wilson

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	SGM 5551 S - NA   AIG18009375 / r3
	ABC 3367H - X

DOA: 23/5/18

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 25/05/2018  
 Estimated Cost: \_\_\_\_\_  
 OD  TP  WS  TP RES  OD RES  EVA  INV  MV   
 To Inspect Vehicle No: SGM 5551 S  
 at Workshop m/s Motor Intel  
 of 13 kaki bukit road 4 # 01-20  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SGM 5551 S Yr Regn: 6 OCT 12009  
 Type:  M.Car /  M.Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /  Truck /  Trailer or  
 Make: ANDI AT c.c. 1984  
 Colour: YELLOW A/C:  Insured /  Std /  NI /  NA  
 Sp. Reading: N/A (cant start) T/Radio:  Insured /  Std /  NI /  NA  
 Eng/No: \_\_\_\_\_  
 C/No: WAUZZ28TX9A047282  
 Gen. Cond:  Good /  Fair /  Poor /  Burnt  
 Steering:  Inorder /  Jammed /  Leaked /  Burnt or  
 Brake:  Inorder /  Jammed /  Leaked /  Burnt or  
 Modi:  Nil /  S/Rim /  STD A/Rim or RT RACING  
 Tyre Size: F: 275/60 R20  
 R: 11

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS lwp  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or PRACTICAL MAX HF  
 Front 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm Rear 6 mm  
 D.O.A. 23/05/18 D.O.I. 25/5/18  
 Survey held at MOTOR INTEL  
 Des. of Damages:  Frt /  Rear /  O/S /  N/S /  U/C /  Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>31/5/18</u>	<u>Submit DAR Report.</u>

RECEIVED 01 JUN 2018.

Date/Time. File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time. File Return to?  
 2) \_\_\_\_\_  
 Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: 3  
 Resurvey No. of Trip: \_\_\_\_\_ Survey Fee: 180  
 Transportation \_\_\_\_\_  
 Add Fee:  Site Insp (\$ \_\_\_\_\_)  S + RS \_\_\_\_\_ SI  
 Interview (\$ \_\_\_\_\_) Photos \_\_\_\_\_  
 Tech. Invs (\$ \_\_\_\_\_) Others 20  
 Weekend (\$ \_\_\_\_\_) TOTAL 200

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED  
VEHICLE GBC3367H AND SGM5551S ON 23/05/2018**

From: Chin, Lee-Ying  
To: 'assignments', Admin A  
Cc: Fong, Andy-SY  
Sent: 24/5/2018 2:56:06 PM  
Attachments:  FaxEBAB.TIF

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**ISLAND LAW LLC**  
**Advocates & Solicitors**

(UEN No. 200918269D)

(GST Reg No. 200918269D)

KIRPAL SINGH SHARMA  
NG KWONG LOONG

SUNITA CARMEL NETTO  
SYAFIQAH AHMAD FU'AD

Our Ref : KS-05551S-18-PD.MIA.WL

Your Ref : Vehicle GBC 3367H

Date: 24 May 2017

101 Upper Cross Street  
#04-04 People's Park Centre  
Singapore 058357  
Tel: (65) 6221 3211  
Fax: (65) 6225 3210  
(65) 6225 3054

AIG Asia Pacific Insurance Pte Ltd

( Fax 6835 7417 )

Attn: Motor Claims Department

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

( )

Dear Sirs,

ACCIDENT INVOLVING SGM5551S, GBC 3367H & SKN 1424A Along  
Bartley Viaduct On 23 May 2018 @ 0915 Hours

(NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS  
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We act for Yeo Chong Shan, Eugene who has appointed the undermentioned  
workshop to repair his/her motor vehicle no. SGM5551S.

Please be informed that the said vehicle can be inspected at:

Name : MOTOR INTEL AUTOMO PTE. LTD.  
Address : 13 KAKI BUKIT ROAD 4  
#01-20 BARTLEY BIZ CENTRE  
SINGAPORE 417807  
Person to contact : WILSON ONG  
Tel : 8838 3318

If you failed to conduct the pre-repair inspection within the next 2 working days excluding any  
intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter  
without further reference to you.

Yours faithfully

For Surveyor  
Please initial here after completion  
of pre-repair inspection. Thank you.

Appointed surveyor :  
(Name & Signature)

ISLAND LAW LLC By Fax: 6281 0187  
cc: Client (SGM5551S) (By email: sales@mia.com.sg)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18009478/Nz4d3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 24-05-2018



Code : AIG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBC 3367H	Veh. Inspected	SGM 5551S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	24/05/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	23/05/2018	Inspection Date	
Survey held at	-		

## 5a. Remarks

<p>A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.          B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.          THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.          C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.</p>
---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/05/2018 13:41
Date Of Accident	23/05/2018 09:15
Exact Location Of Accident	BARTLEY VIA SLIP RD TO KAKI BUKIT AVE 04
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGM5551S
-----------------------------	----------

### Insured/Policyholder

Name Of Registered Owner	YEO CHONG SHAN, EUGENE (YANG CONGSHAN)
NRIC No	S8629257B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90927943
Alternative Phone No	OTHERS-90927943

### Vehicle Particulars

Manufacturer	AUDI
Model	A5-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5073261752-02
Cover Note Number	

### Driver

Name of Driver	YEO CHONG SHAN, EUGENE (YANG CONGSHAN)
NRIC No	S8629257B
Date Of Birth	06/10/1986
Occupation	INDOOR
Date Of Driving Pass	13/11/2008
Driving Experience	9 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90927943
Fax Number	
Contact Number	OTHERS-90927943
EMail Address	NOEMAIL

Address	BLK 165 #02-307 TAMPINES STREET 12
Postcode	521165
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

### Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC3367H
Vehicle Make/Model/Colour	CITROEN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ADAM BIN MASDULLAH
NRIC/Passport Number	S1824266D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1


### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKN1424A
-----------------------------	----------



Vehicle Make/Model/Colour	AUDI A4-BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MAHALIL PURAM MOHAN
NRIC/Passport Number	S2668699G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3
Passenger 1	NAME: : GENDER: :
Passenger 2	NAME: : GENDER: :

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Bentley Viaduct towards Kaki Bukit from tangines on the left most lane of a 4-lane road. Somewhere before slip road into Kaki Bukit Ave 4, I saw vehicles ahead slowing down to a stop as such I also slowed down and managed to stop completely behind vehicles ahead of me. Moments after I stop, I suddenly felt a strong impact from the rear portion of my vehicle. The impact caused my vehicle to surge forward and hit into the rear portion of the vehicle ahead of me. After the accident, I managed to see that I am the center vehicle of a 3-car collision.

vehicle A SGW 5551S.  
 vehicle B GBC 3367H  
 vehicle C: SKN 1424A.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

23 MAY 2018

IDAC KAKI BUKIT (VAC)  
 23 KAKI BUKIT AVE 4  
 Singapore 415933

Reporting Centre Personnel's Signature  
 Name: [Signature]  
 Fax: 67492305  
 Email: vaakh@singnet.com.sg  
 NRIC/PIN No: [Blank]

Condition (CON):

(01)Best (2)Denied (3)Destroyed (4)Cracked (5)Cut (6)Scratched (07)Deformed  
 (08)Satisfied (09)Dunkled (10)Broken (11)Necessary (12)Missing (13)Torn  
 (14)Unconfirmed (15)Not Working

**MOTOR CAR (Frt)**

ACTION/AC

(1)Replace (✓) (2)Repair (X) (3)Check (✓)  
 (4)Not Consistent (N/C)

Aug 2005

Front Portion

Vehicle No: SGM 5551S

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	BR	✓	
1002	991887	Frt Number Plate Base	BR	✓	
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DMG	✓	
1005	992341	Frt Bumper Clips	NEC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement	DT	✓	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	CRK	✓	
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	BR	✓	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler Tow Cover	MS	✓	
1016	991438	Frt Bumper Sensor	SC	✓	
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem	BR	✓	
1023	991799	Frt Grille Chrome Moulding	BR	✓	
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	DT	✓	
1026	992025	Frt Support Panel Top Garnish Cover	CRK	✓	
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	BR	✓	
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	DT	✓	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock	DMG	✓	
1036	990285	Bonnet Insulator	NEC	✓	
1037	990273	Bonnet Hinge	DT	✓	
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass	CRK	✓	
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag	PUN	✓	
1128	994485	Steering Wheel Airbag Sensor	SC	✓	
1129	990749	Dashboard Airbag	PUN	✓	
1130	990750	Dashboard Airbag Sensor	SC	✓	
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_

ORIGINAL COPY

(01)Rear (2)Denied (3)Distorted (4)Cracked (5)Cut (6)Scratched  
 (7)Deformed (8)Shifted (9)Inhibited (10)Broken (11)Necessary  
 (12)Missing (13)True (14)Unconfirmed (15)Not Working

**MOTORCAR (Rear)**

AS, DNR, LAM)  
 (1)Replace (✓) (2)Repair(0) (3)Check (P)  
 (4)Not Consistent (NC)

**Rear Portion**

Vehicle No: **SGM 5551 S**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	MS	✓	
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DMG	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	DMG	✓	
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	CRK	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper <del>Under</del> Under Cover	CRK	✓	
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	SC	✓	
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DT	✓	
1171	991328	Bootlid Emblem	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge	DT	✓	
1180	993877	Bootlid Spoiler	NEC	✓	
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	SCR	✓	
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 May 2018 <a href="#">Edit Reg</a>		24 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>JNBK CORPORATION PTE LTD</b> , Co. Reg. No.: 200502810W								
Main Claimant:	<b>YEO CHONG SHAN, EUGENE (YANG CONGSHAN)</b> , ID: S8629257B								
Vehicle Reg. No.:	<b>SGM5551S</b>	Date of Loss:	23/05/2018 09:00 - :59 [103 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 1905683711SG</b>	Policy/Cover Note No.:	2100285306 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBC3367H</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Motor Intel Automo Pte Ltd (HQ)</b> Bartley Biz Centre,13 Kakai Bukit Road 4,#01-20, 417807 Kaki Bukit - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Wui, Shawn-KJ</b> ] Shawnkaijye.Wui@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Muhammad Nazril Bin Abdullah</b> ] ... [Final Rpt due 08/06/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (31/05/2018): <b>Request To Upload TP GIA Report</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

### Claim Documents

**\*SGM5551S (1905683711SG)**  
**[GBC3367H]**  
**TP**  
**YEO CHONG SHAN, EUGENE (YANG CONGSHAN)**  
**May 23 2018 9:00AM**  
**[JNBK CORPORATION PTE LTD]**  
**Motor Intel Automo Pte Ltd**

<a href="#">Upload Documents</a>	<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<a href="#">Upload Video</a>	<a href="#">Upload Audio</a>	<b>View</b> <input type="button" value="View in Browser"/>
<b>Photos/Images</b>					3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
2	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
3	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
4	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
5	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
6	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
7	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
8	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
9	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
10	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
11	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
12	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
13	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
14	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
15	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
16	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
17	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
18	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
19	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
20	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
21	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
22	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
23	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
24	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
25	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
26	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
27	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
28	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
29	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
30	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
31	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
32	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
33	31/05/18 17:34	General View		Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>					1 per page <input type="button" value="v"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	31/05/18 16:55	OI GIA REPORT		Load PDF	<input type="checkbox"/>

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG18009478/NZ4D3E2

**Date:** 05/06/2018

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100285306
<b>Claimant Vehicle No :</b> SGM5551S	<b>Insured Vehicle No :</b>	GBC3367H
Date of Loss: 23/05/2018	Nature of Claim:	TP Claim No: 1905683711SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SGM5551S</b>	Engine No: CDN032112
Make & Model: AUDI A5, 2.0 (A)	Chassis No: WAUZZZ8TX9A047282
Reg. Date: 06/10/2009 (Man. Year: 2009)	Odometer: 0 km
Colour: Yellow	
Engine Capacity: 1984 cc	
Market Value/New Car Price: N/A	
Sum Insured (\$\$): <b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size: 275/60 R20	Rear Tyre Size: 275/60 R20
Front Left Side: PRACTICAL MAX HP 6 mm	Rear Left Side: PRACTICAL MAX HP 6 mm
Front Right Side: PRACTICAL MAX HP 6 mm	Rear Right Side: PRACTICAL MAX HP 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	24/05/2018	
Date Inspected:	25/05/2018 Inspected At:	Motor Intel Automo Pte Ltd (HQ) Bartley Biz Centre, 13 Kakai Bukit Road 4, #01-20 Singapore 417807
Estimated Period of Repair:	3.0 days	

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT NUMBER PLATE	Broken	0.00 F	*- F	
2	1		*FRT NUMBER PLATE BASE	Broken	0.00 F	*- F	
3	1		*FRT BUMPER	Damaged	0.00 F	*- F	
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F	
5	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F	
6	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F	
7	1		*FRT BUMPER GRILLE	Broken	0.00 F	*- F	
8	1		*FRT BUMPER TOW COVER	Missing	0.00 F	*- F	
9	1		*FRT BUMPER SENSOR	Shorted	0.00 F	*- F	
10	1		*FRT GRILLE EMBLEM	Broken	0.00 F	*- F	
11	1		*FRT GRILLE CHROME MOULDING	Broken	0.00 F	*- F	
12	1		*FRT SUPPORT PANEL	Dented	0.00 F	*- F	
13	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Cracked	0.00 F	*- F	
14	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F	
15	1		*BONNET	Dented	0.00 F	*- F	
16	1		*BONNET LOCK	Damaged	0.00 F	*- F	
17	1		*BONNET INSULATOR	Necessary	0.00 F	*- F	
18	1		*BONNET HINGE	Dented	0.00 F	*- F	
19	1		*FRT LH FENDER	Repair	0.00 F	*- F	
20	1		*FRT WINDSCREEN GLASS	Cracked	0.00 F	*- F	
21	1		*STEERING WHEEL AIRBAG	Punctured	0.00 F	*- F	
22	1		*STEERING WHEEL AIRBAG SENSOR	Shorted	0.00 F	*- F	
23	1		*DASHBOARD AIRBAG	Punctured	0.00 F	*- F	
24	1		*DASHBOARD AIRBAG SENSOR	Shorted	0.00 F	*- F	
					<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >