



Your Ref: AEMD/105/009/2018/042B(PD)

Date: 01<sup>st</sup> June 2018

Our Ref: CS1/SPF18009485/K1qbs2

**M/s Automotive Engineering & MGT Division**

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SHB 8592A INSURED VEHICLE: TP 1121G ACCIDENT DATE: 10/03/2018**

We thank you for your instruction on 24/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHB 8592A from M/s KM Auto Assessors Pte. Ltd.
- b) Colour damaged vehicle photographs of SHB 8592A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SHB 8592A  
Make & Model : Kia Optima 1.7 Taxi Auto  
Year of Registration : 2013  
Chassis Number : KNAGM414ME5447103

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.