

ASS. REC. BY:

REP: CS/FCI18009511/K1sd3<sup>n2</sup>

Special Instruction:

Surveyor: Kalvin  
cus

ASSIGNMENT (Office)

From (Person): Lurene jaw

of FCI

Date/Time: 24/5/18 @ 7.51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 8943X

Insured: SHA 8729D

at Workshop m/s: Premier Automotive

Tel: 65446682

of 23 changi south Ave 2 #03-02

Policy No:

Claim No: D18064153 MFST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23/05/2018

CA / REV / REP. / REV 24 HRS cup

H.O.D. Endorsement:

Date/Time: 9:16am @ 25/5/18

Person Contacted:

Giang

Vehicle: IN / OUT

Date/Time

Action/Instruction (  ) Estimate

SHB 8943X-CC3 / III 7010354 / H1ea3q2

DOA: 24/5/2017

SHA 8729D-X

28/05/18 @ 17:07pm revised PA to Lurene via email..

01/06/18 ( \$ 2,764.20 - \$ 1,600.00 ) - Reduction = 42%

Summit Kalvin

REF: FCI

ASSIGNMENT

From: Date: 25/05/2018

Veh No: SHB 8943X Yr Regn: 31 Mar, 2014

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SHB 8943X

Make: KIA optima C.C. 1685

at Workshop m/s Premier Automotive

Colour: Silver A/C: Insured / Std / NI / NA

of 23 changi south Ave 2 #03-02

Sp. Reading: 555174 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.:

C/No: KNA 6M414ME 5462043

Claims No.:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD / Rim or

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 205/65R16

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Atilas

Bal. or Market Value:

Front Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 7 mm R/Bal. 7 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 7 mm L/Bal. 7 mm

Est. Repairs: days Res: Yes or No

D.O.A. 23/5/8 D.O.I. 25/5/8

Lum Sum: % 3 Val: Yes or No

Survey held at Premier

CA / REV / REP. / 24 HRS 1wp

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted: Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31/5/8 Returned 4541600/31/8

RECEIVED 01 JUN 2018

Date/Time: File Pass to? 01/06/18 Typist

: Preli. Report  : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Date/Time: File Return to?

Add Fee:  : Site Insp (\$)  : Interview (\$)  : Tech. Invs (\$)  : Weekend (\$)

Survey Fee:	110
Transportation	50
___S+RS___SI	50
Photos	18
Others	
TOTAL	228

Report Format : Lump Sum / I.B.I: (\$) 1,600/- 4/5



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004153MFSH

Date: 28 May 2018

Our Ref: CS/FCI18009511/K1sd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 8943X**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/05/2018 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 2,764.20</u>
Revised Estimate Amount	: <u>S\$ 2,028.10</u>
"Check" Items Amount	: <u>S\$</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

**Description of Damage:**

The vehicle sustained damages at the n/s rear portion.



**Comments/ Present Status:**

Damages Consistent.  
Repair days: 3 Days

Yours faithfully,  
Kalvin Ang  
Automotive Assessor

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 28 May 2018 5:07 PM  
**To:** 'Claim Workflow System'; LURENEJAW@MSFIRSTCAPITAL.COM.SG  
**Cc:** sur@lkkauto.com; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM  
**Subject:** RE: SURVEY ASSESSMENT - D18004153MFSH/1  
**Attachments:** SHB 8943X - Preli Advise.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SHB 8943X.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]  
**Sent:** Friday, 25 May 2018 9:20 AM  
**To:** 'Claim Workflow System' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** LURENEJAW@MSFIRSTCAPITAL.COM.SG; [sur@lkkauto.com](mailto:sur@lkkauto.com)  
**Subject:** RE: SURVEY ASSESSMENT - D18004153MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Thursday, 24 May 2018 7:50 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [LURENEJAW@MSFIRSTCAPITAL.COM.SG](mailto:LURENEJAW@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18004153MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	23-05-2018	<b>Our Ref No.</b> D18004153MFSH
<b>Accident Date</b>	23-05-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA8729D	<b>Third Party Vehicle.</b> SHB8943X
<b>Survey Location</b>	23 CHANGI SOUTH AVENUE 2 #03-02	
<b>Contact Person.</b>	GOH WEE DEK	
<b>Contact No.</b>	62148880/ 65446682	<b>Fax No.</b> 62141511
<b>Survey Type</b>	WITHOUT PREJUDICE: PENDING ID'S VF TO DETERMINE LIABILITY	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

## THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	PREMIER AUTOMOTIVE SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	LURENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240713)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18004153MFSH	<b>Policy No</b>	D-18088937MFSH	<b>Claimant S.No &amp; Name</b>	PREMIER
<b>Workshop Name</b>	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : GOH WEE DEK)	<b>Survey Location &amp; Contact Details</b>	23 CHANGI SOUTH AVENUE 2 #03-02 <b>Mobile:</b> 65446682 , <b>Phone:</b> 62148880 , <b>EmailId:</b> WEEDEK.GOH@PREMIERTAXI.C		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE: PENDING ID'S VER		
<b>Insured Name</b>	CITYCAB PTE LTD	<b>Insured Vehicle No</b>	SHA8729D	<b>TP Vehicle No</b>	
<b>PRI Recieved Date</b>	23-05-2018 10:19:23 PM	<b>Surveyor Appointed Date</b>	24-05-2018 07:50:44 PM	<b>Surveyor Accept Date</b>	2018 1

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	25-05-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Upload"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	---------------------------------------

## Vehicle Particulars

<b>Make</b>	Please Select Make ▼	<b>Model</b>	Please Select Model ▼	<b>Year</b>	
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18009511/K1sd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-05-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 8729D	Veh. Inspected	SHB 8943X
Policy No.		Coverage (\$)	0.00
Claim No.	D18004153MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	25/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/05/2018	Inspection Date	25/05/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Text size + -

### Enquire Transaction History

#### Transaction History Details

Log Date/Time:	31 Mar 2014 / 09:47:59	Receipt No.:	AACCK001-AX239-140331-000009
Asset Type:	Vehicle	Transaction Amount:	\$71,161.00
Asset ID:	SHB8943X	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140331094759027818		

Vehicle No.:	SHB8943X
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	31 Mar 2014
Original Registration Date:	31 Mar 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5462043
Engine No.:	D4FDDH308336
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,776.00
Minimum PARF Benefit:	\$7,365.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	31 Mar 2014 09:47:59
COE No.:	2014033101001233N
COE Expiry Date:	30 Mar 2022
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$58,745.00
Lifespan Expiry Date:	30 Mar 2022
Owner ID Type:	Company

Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

23-May-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8943 X

1 pc	Rear bumper	<i>Rebrand</i>	\$	696.00
1 pc	Rear bumper n/s side bracket	<i>X 300</i>	\$	29.00
1 pc	Rear n/s wheel cover	<i>knop</i>	\$	113.00
			\$	838.00
		Less 10%	\$	83.80
			\$	<u>754.20</u>

### S/NETT

1 set	n/s door sticker	<i>nc</i>	\$	100.00
1 pc	Rear n/s fender sticker	<i>nc</i>	\$	60.00
	Sundry	<i>nc</i>	\$	<del>50.00</del> <i>20</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	<del>180.00</del> <i>X 0.7</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door, rear n/s fender, rear bumper, n/s rocker panel garnish		\$	<del>700.00</del> <i>400</i>
	To putty and spray painting on rear n/s door, rear n/s fender, rear bumper, n/s rocker panel garnish		\$	<del>800.00</del> <i>720</i>
	To apply rustproofing on the repaired and replaced panels.		\$	<del>120.00</del> <i>X 0.7</i>
			\$	<u>2,764.20</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

*Ka/uh LKK*  
*25/5/8 1125hr*  
*3 Ryz*  
*4/5*  
*After Repair p Leds*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18009511/K1sd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-06-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8729D	Veh. Inspected	SHB 8943X	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18004153MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	24/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414ME5462043	Colour	SILVER	
Odometer	555174	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	7 mm	
L/H Front Tyre	205/65 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/05/2018	Inspection Date	25/05/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8943X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER N/S SIDE BRACKET	SERVICEABLE	29.00	-
1	REAR N/S WHEEL COVER	GRAZED	113.00	113.00
	LESS 10% DISCOUNT		-83.80	-80.90
			754.20	728.10
<b>SPECIAL NETT ITEMS</b>				
1	SET N/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			210.00	180.00
<b>LABOUR</b>				
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE REAR N/S DOOR, REAR N/S FENDER, REAR BUMPER, N/S ROCKER PANEL GARNISH.		700.00	400.00
	TO PUTTY AND SPRAY PAINTING ON REAR N/S DOOR, REAR N/S FENDER, REAR BUMPER, N/S ROCKER PANEL GARNISH.		800.00	720.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,800.00	1,120.00
<b>GRAND TOTAL</b>			<b>2,764.20</b>	<b>2,028.10</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,600.00</b>

Report Ref No. CS/FCI18009511/K1sd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.