

ASS. REC. BY: Morcos

REF:

CS/TP 18009512/urb n2

V

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SSK 4228Hat Workshop m/s 344

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 17800

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: u Consistent? : Yes or NoEst. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SSK 4228H Yr Regn: 10 / 08

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Subaru Exiga C/C: 1994Colour: white ACC: Insured / Std / NI / NASp. Reading: 176774 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YAS 009724

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front: _____ Rear: _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 22/5/18 D.O.I. 25/5/18

Survey held at: _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8/6/18 N/A Lorntem LT A 135-37 4 with plus. net 4263
1/5 3350 (Rec 3783.60, 519)

RECEIVED 08 JUN 2018

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 5

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2) 8/6 - typistAdd Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

150

50

50+50

36

80

416

Report Format: TPLump Sum / I.B.I. (\$) 3550

Ref. No :	CS/TP18009512/UVbn2		Res. Date: 28/5/18	Date Received:
Veh. No :	SJK 4228H		SP:	WKSP: <i>[Signature]</i>
C/No :				
Action/Instruction:				
1. File	2. Submit Photo?	YES / NO		
3. Indicate Res. Date On Photo Page?	YES / NO			Message:
If No, due to	a) No authorisation b) Days of repair			
others:				
Final Re-inspection or Progress Photos				Inspected By: <i>[Signature]</i>

WHAT IS YOUR BIG DATE?

subaru exiga

Price Range ▼

Depreciation ▼

Year Reg ▼

Vehicle Type ▼

Home » Used Cars » Eezy Solutions Pte Ltd » Subaru Exiga 2.0A

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Subaru Exiga 2.0A

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price \$28,000**Depreciation** \$8,890 /yr

View models with similar depreciation

Reg Date 30-Oct-2009

(1yr 5mths 1day COE left)

Manufactured 2008**Mileage** 118,388 km (13.8k /yr)**Transmission** Auto**Engine Cap** 1,994 cc**Road Tax** \$1,206 /yr**Power** 109.0 kW (146 bhp)

View specs of the Subaru Exiga (2008-2011)

Curb Weight 1,520 kg**Features** 2.0L Boxer Engine, Steptronic Auto Transmission, Sports/Eco Mode, AWD, ABS, EBD, Immobilizer, SRS Airbags, 4 Disc Brakes, 7 Seaters MPV.**Accessories** Audio System With Reverse Camera, Premium Leather Upholstery, Fog Lamps, Rear Sensors.**Description** Cheap And Affordable White Unit. Spacious 7 Seater Ideal For Family Usage. Excellent Exterior With Clean And Neat Interior, Well Kept And Maintained By Previous Owner, Tip Top Condition, Please Call To Arrange An Appointment For Viewing.**COE** \$19,629**OMV** \$30,709**ARF** \$30,709

Seller Infor

Company

Address

Location

Office No

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9305D
Vehicle Details	
Vehicle No.:	SJK4228H
Vehicle to be Exported:	No
Intended De-registration Date:	28 May 2018
Vehicle Make:	SUBARU
Vehicle Model:	EXIGA MPV 2.0i AWD 4AT ABS AIRBAG
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	EJ20D603697
Chassis No.:	YA5009724
Maximum Power Output:	109.0 kW (146 bhp)
Open Market Value:	\$25,968.00
Original Registration Date:	18 Oct 2008
First Registration Date:	18 Oct 2008
Transfer Count:	2
Actual ARF Paid:	\$25,968.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Oct 2018
PARF Rebate Amount:	\$12,984.00
Intended COE Rebate Details	
COE Expiry Date:	17 Oct 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$14,400.00
COE Rebate Amount:	\$553.00
Total Rebate Amount:	\$13,537.00

The information contained herein is correct as at 28 May 2018

OK

UAA118067068 / National Assessment Centre Services - Upl
 ENTRY DATE & TIME: 23/05/2018 13:48
 SUBMITTED BY: Krishnasamy a/o Gennadasamy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/05/2018 13:48
 Date Of Accident 22/05/2018 15:00
 Exact Location Of Accident 5 DEFU LANE 6 (INSIDE THE WAREHOUSE)
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJK4228H
Insured/Policyholder
 Name Of Registered Owner DRK CONSTRUCTION (S) PTE LTD
 Co Reg No 201409305D
 Email Address RAVI@DRKCONSTRUCTION.COM.SG
 Mobile Phone No (LOCAL) +65-81395291
 Alternative Phone No OFFICE-81395291
Vehicle Particulars
 Manufacturer SUBARU
 Model EXIGA MPV 2.0I AWD 4AT ABS AIRBAG
 Exact Purpose for which vehicle was being used at time of accident WORK
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
Insurance Company
 Name of Insurance Company DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy NO
 Policy Number MT/00474667
 Cover Note Number
Driver
 Name of Driver SIVASAMY RAVIGHANDRAN
 NRIC No S2729853B
 Date Of Birth 22/06/1967
 Occupation INDOOR
 Date Of Driving Pass 27/12/2003
 Driving Experience 14 YEARS AND 4 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-81395291
 Fax Number
 Contact Number OTHERS-81395291
 Email Address RAVI@DRKCONSTRUCTION.COM.SG

Address BLK 293B COMPASSVALE CRESCENT
 #12-65
 Postcode 542293
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP4506B
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver PARAMANANDAM BALASANKAR
 NRIC/Passport Number G7099935N
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, at knowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 23/5/18

Driver's Signature
(If driver is not the policyholder)
Date & Time: 23/5/18

Reporting Centre Personnel's Signature
Name:
NRIC/IN No:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was parked inside to Det. King's Warehouse.
 I was inside an office when I heard a loud bang.
 I ran out of the office and I saw a lorry doing
 reversing damaging my car. I shouted at the driver
 the driver stopped his lorry and alighted from the lorry.
 He appeared shock.

DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature
 Date & Time: 23/5/18

GLARAN, Seremban 14111 1/3

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 23/5/18.

Reporting Centre Personnel's Signature
 Name:
 NRIC/EPN No.:

BLUWEL AUTOMOTIVE SERVICE PTE LTD



WORKSHOP: 1 KAKI BUKIT AVE B (UNIT B) #01-28
(Unit C) #01-29-53/55 Singapore 417883
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
Co. Reg. No.: 200704951N
GST Reg. No.: 200704951N

not about
the
1/5 + 3500
Sch.

Rear door o/s	2	788.20	X
Rear door inner lock o/s	11	266.30	X
Rear fender o/s	Body 20	982.50	✓
Rear fender inner trim board o/s	11	365.40	X
Fuel lip	Best	80.60	✓
tail lamp o/s	11	319.60	✓
Rear bumper	Total	694.00	✓
Rear bumper side holder o/s	11	38.50	X
set Rear bumper clips	11	50.00	✓
Rear fender glass o/s	11	342.00	✓
Rear fender glass Dam rubber o/s	11	56.50	✓
Rear fender glass sealant o/s	11	50.00	✓
		4033.60	
	20/2		
To check wiring		50.00	30
To transfer Rear door mechanism	11	80.00	X
To spray rust proofing		100.00	50
To dismantle & ref. x seat cushion upholstery		150.00	100
To dismantle & refix petrol tank		100.00	80
To dismantle & replacing rear fender glass o/s		120.00	✓
Labour for panel beating - cut, weld, straighten & replacing parts		1200.00	1000
To putty & spray painting		1500.00	1000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$ 7333.60



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18009512/Uvbn2

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 14-06-2018



ON BEHALF OF DRK CONSTRUCTION (S) PTE
LTD

Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SJK 4228H
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	25/05/2018

2. Vehicle Particulars & Condition

Make & Model	SUBARU EXIGA (A)	c.c	1994
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	YA5009724	Colour	WHITE
Odometer	176774	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	KUMHO	8 mm
L/H Front Tyre	215/60 R16	KUMHO	8 mm
R/H Rear Tyre	215/60 R16	KUMHO	8 mm
L/H Rear Tyre	215/60 R16	KUMHO	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/05/2018	Inspection Date	25/05/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 4228H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR O/S	TO REPAIR SEE LABOUR	788.20	-
1	REAR DOOR INNER LOCK O/S	NOT NECESSARY	266.30	-
1	REAR FENDER O/S	BADLY DENTED	982.50	982.50
1	REAR FENDER INNER TRIM BOARD O/S	NOT NECESSARY	365.40	-
1	FUEL LIP	BENT	80.60	80.60
1	TAILLAMP O/S	CRACKED	319.60	319.60
1	REAR BUMPER	TORN	694.00	694.00
1	REAR BUMPER SIDE HOLDER O/S	NOT NECESSARY	38.50	-
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR FENDER GLASS O/S	NECESSARY	342.00	342.00
1	REAR FENDER GLASS DAM RUBBER O/S	NECESSARY	56.50	56.50
1	REAR FENDER GLASS SEALANT O/S	NECESSARY	50.00	50.00
	LESS 20% DISCOUNT		-	-515.04
			4,033.60	2,060.16
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	30.00
	TO TRANSFER REAR DOOR MECHANISM.	NOT NECESSARY	80.00	-
	TO SPRAY RUST PROOFING.		100.00	50.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	100.00
	TO DISMANTLE & REFIX PETROL TANK.		100.00	80.00
	TO DISMANTLE & REPLACING REAR FENDER GLASS O/S.		120.00	120.00
	LABOUR FOR PANEL BEATING,CUT,WELD STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR DOOR O/S.		1,200.00	1,000.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
	-		-	-
	-		-	-
	-		-	-
			3,300.00	2,380.00
	GRAND TOTAL		7,333.60	4,440.16
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,550.00



Report Ref No. CS/TP18009512/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.