

22/03/2002

ASS. REC. BY:

REF: CS/MSG18009533/ A sd3eb

Special Instruction:

Surveyor:

Menmen

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

21/5/18 @ 4:15pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 9365B

Insured:

YP 6443K

at Workshop m/s

N-51 Automotive

Tel:

68420051

of

Blk 2 Kaki Bukit # 01-17 / 18

Policy No:

21053077MKC

Claim No:

559205

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/05/2018

CA / REV / REP. / REV 24 HRS

25/05/2018

H.O.D. Endorsement:

Date/Time:

5:51pm @ 21/5/18

Person Contacted:

Melody

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

For this case wksp say got estimate.

SLR 9365B - X

YP 6443K - X

22/05/18 @ 13:18 pm.

revised to Katherine Wong providing Estimate v.i.s menmen.

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLR9365B Yr Regn: 2017, August
 Type: M:Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius Alpha c.c. 1797
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 71732 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ZVW400026003
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/60R16
 R: 205/60R16

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: **Yes** or **No**
 GIA / PR Seen: _____ Consistent?: **Yes** or **No**
 Est. Repairs: _____ days Res.: **Yes** or **No**
 Lum Sum: _____ % 3 Val.: **Yes** or **No**
CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: **IN** / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 25/05/18
 Survey held at N51
 Des. of Damages: **Frnt** / Rear / O/S / N/S / U/C / Rooftop or _____
 The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	<u>T? MSIG.</u>
<u>12/10/18</u>	<u>Confirmed P/P \$4,866.30 @ 4 days with Adrian (\$810.15 Red - 14%)</u>

Date/Time, File Pass to? 15/10/18
 1) Typist
 Date/Time, File Return to?
 2) _____

: Preli. Report
 : Final Report

Days Of Repair: 4
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Report Format : _____
 Lump Sum / I.B.I: (\$ 4,866.30 P/P)

Survey Fee: 150
 Transportation: _____
 Photos _____
 Others 10
 TOTAL 160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 May 2018		24 May 2018 16:18 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)
CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	AUTOWAY LOGISTIC PTE LTD, Co. Reg. No.: 200614599H		
Main Claimant:	DARWIN-51 CAR RENTAL PTE LTD, Co. Reg. No.: 201407909C		
Vehicle Reg. No.:	SLR9365B	Date of Loss:	23/05/2018 14:00 - :59 [8 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 559205	Policy/Cover Note No.:	29053077MKC (Comprehensive) Coverage: 02/12/2017 - 01/12/2018
Vehicle Reg. No. (Insured):	YP6443K	Policy No. (Claimant):	
		Excess:	
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/05/2018]		
Driver/Custodian (Insured):	MUHAMMAD AZMI BIN AHMAD (), NRIC: S8430733E, Tel: +6587429310		
Adj Asg. Remarks:	TP agree on SJE - Please appoint Adrian Ling of LKK Auto. Liability is 50/50. Contact Person/ Tel : Melody / 6842 0051 or 6744 0510. Thanks.		

ASSOCIATED MAIL RECEIVED
[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/05/2018 16:38
Date Of Accident	23/05/2018 13:05
Exact Location Of Accident	PIE -> CHANGI BEFORE PAYA LEBAR EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR9365B
Insured/Policyholder	
Name Of Registered Owner	DARWIN-51 CAR RENTAL PTE LTD
Co Reg No	201407909C
Email Address	SALES@N51.COM.SG
Mobile Phone No	(LOCAL) +65-83802233
Alternative Phone No	OFFICE-68420051
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS ALPHA HYBRID-1.8 S CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD17V08976/VPZ/R00
Cover Note Number	

Driver

Name of Driver	CHUA SOON YONG
NRIC No	S1616714B
Date Of Birth	07/09/1963
Occupation	OUTDOOR
Date Of Driving Pass	01/04/2006
Driving Experience	12 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-82859944
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 241 BUKIT BATOK EAST AVE 5 #01-279
Postcode	650241
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP6443K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

VEHICLE A - SLR 9365B
 VEHICLE B - SP6443K



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG THE TOWARDS CHANGE DIRECTION,
 I WAS ON THE THIRD LANE.

WHILE TRAVELLING FORWARD IN MY LANE, SUDDENLY I HEARD
 A LOUD SOUND AND FOLLOW WITH A IMPACT FROM THE RIGHT
 SIDE OF MY VEHICLE, AND REALIZED THE RIGHT SIDE MIRROR
 OF MY VEHICLE WAS TOTALLY DAMAGED.

ALIGHTED FROM MY VEHICLE AND REALIZED IT WAS A TRUCK
 BEARING (SP 6443K) THAT HIT ONTO THE RIGHT SIDE REGION
 OF MY VEHICLE WHEN HE CUTTED INTO MY LANE FROM
 SECOND LANE, (LANE 2).

VEHICLE A - SLR 9365B
 VEHICLE B - SP 6443K

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

(62257402)

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
 1 KAKI BUKIT ROAD 1 #01-09 ENTERPRISE
 ONE
 SINGAPORE 415934

TPMS 16
Shiley

ESTIMATE

Repair Code : CLM14170
 Date in : 23/05/2018
 Vehicle Num. : SLR9365B
 Model : TOYOTA PRIUS ALPHA 1.8S CVT
 Chassis/Eng# : ZVW400026003/2ZR1984730

Contact : 82859944

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR SIDE MIRROR <i>Missing</i>	1	1373.00	✓ 1,373.00
FRONT RH DOOR SIDE MIRROR COVER	1	90.40	✓ 90.40
FRONT RH FENDER <i>Dented</i>	1	933.10	✓ 933.10 <i>737.5</i>
FRONT RH FENDER 'HYBRID' EMBLEM <i>New</i>	1	65.00	✓ 65.00
FRONT RH FENDER INNER SHIELD <i>New</i>	1	165.00	✗ 165.00
FRONT RH HEADLAMP <i>cut</i>	1	1113.00	✓ 1,113.00 <i>944</i>
FRONT RH QUARTER GLASS <i>cut</i>	1	293.10	✓ 293.10
Subtotal before discount			4,032.60
Percentage discount 25%			1,008.15
Sub-total 1			3,024.45
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>New</i>	30	50.00	✗ 50.00
FRONT RH QUARTER GLASS SEALANT <i>New</i>	1	60.00	30 60.00
Subtotal before discount			110.00
Percentage discount 0%			0.00
Sub-total 2			110.00
Parts-total			3,134.45

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR) *30' 40.00*

To remove, reinstall fender glass *50' 100.00*

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
 1 KAKI BUKIT ROAD 1 #01-09 ENTERPRISE
 ONE
 SINGAPORE 415934

Contact : 82859944

ESTIMATE

Repair Code : CLM14170

Date in : 23/05/2018

Vehicle Num. : SLR9365B

Model : TOYOTA PRIUS ALPHA 1.8S CVT

Chassis/Eng# : ZVW400026003/2ZR1984730

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

	700	800.00
	300	500.00
	+	100.00
Labour Total		1,540.00
Parts & Labour Total		4,674.45

1080

5676.45

*** This is a computer-generated document which requires no signature.***

page 2

total ~~3745.65~~
 CP/P)
 total: ~~4676.47~~
 total: 4866.30 ✓
 04 hrs.

Adrian Lim,
 P/P 25/05/18
 03-04 hrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 May 2018		24 May 2018 16:18 Edit Adj Rpt	S\$4,866.30 Edit Estimates	S\$4,866.30 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	AUTOWAY LOGISTIC PTE LTD, Co. Reg. No.: 200614599H		
Main Claimant:	DARWIN-51 CAR RENTAL PTE LTD, Co. Reg. No.: 201407909C		
Vehicle Reg. No.:	SLR9365B	Date of Loss:	23/05/2018 14:00 - :59 [8 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 559205	Policy/Cover Note No.:	29053077MKC (Comprehensive) Coverage: 02/12/2017 - 01/12/2018
Vehicle Reg. No. (Insured):	YP6443K	Policy No. (Claimant):	
		Excess:	
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 25/05/2018]		
Driver/Custodian (Insured):	MUHAMMAD AZMI BIN AHMAD (), NRIC: S8430733E, Tel: +6587429310		
Adj Asg. Remarks:	TP agree on SJE - Please appoint Adrian Ling of LKK Auto. Liability is 50/50. Contact Person/ Tel : Melody / 6842 0051 or 6744 0510. Thanks.		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

***SLR9365B (559205)**
[YP6443K]
TP
DARWIN-51 CAR RENTAL PTE LTD
May 23 2018 2:00PM
[AUTOWAY LOGISTIC PTE LTD]
N-51 Automotive Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser
Video				1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/05/18 11:12	Video - Accident from SLR9365B	Load AVI	<input type="checkbox"/>
2	24/05/18 11:12	Video - Accident from SLR9365B(rear video)	Load MP4	<input type="checkbox"/>
Assessment Reports				1 per page <input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/05/18 08:20	Accident Statement Addm. #1 <small>From:SC - Reg. No: YP6443K, Claimant: AUTOWAY LOGISTIC PTE LTD</small>	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Adjuster Immediate Advice	(Protected)	<input type="checkbox"/>
Photos/Images				3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
2	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
3	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
4	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
5	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
6	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
7	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
8	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
9	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
10	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
11	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
12	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
13	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
14	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
15	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
16	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
17	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
18	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
19	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
20	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
21	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
22	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
23	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
24	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
25	11/10/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
26	11/10/18 17:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	11/10/18 17:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
28	11/10/18 17:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	11/10/18 17:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	11/10/18 17:48	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/05/18 08:20	SLR9365B E FILE REPORT From:SC - Reg. No: YP6443K, Claimant: AUTOWAY LOGISTIC PTE LTD	Load PDF	
2	24/05/18 10:23	TP agree on SJE & PRI details	Load PDF	
3	24/05/18 11:41	Liability - 50/50	Load PDF	
4	25/05/18 12:16	Estimate	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18009533/USD3E2

Date: 15/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29053077MKC
Claimant Vehicle No : SLR9365B	Insured Vehicle No :	YP6443K
Date of Loss: 23/05/2018	Nature of Claim:	TP
		Claim No: 559205

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR9365B	Engine No:	2ZR1984730
Make & Model:	TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)	Chassis No:	ZVW400026003
Reg. Date:	31/08/2017 (Man. Year: 2017)	Odometer:	71732 km
Colour:	Blue		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,136.45	3,786.30	350.15	8.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	1,080.00	460.00	29.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,676.45	4,866.30	810.15	14.27
+ GST 7.00/7.00% (S\$)	397.35	340.64	56.71	14.27
Nett Amount (S\$)	6,073.80	5,206.94	866.86	14.27

INSPECTION

Date of Assignment:	24/05/2018	
Date Inspected:	25/05/2018 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Oct 2018)	
Parts: 144	TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLR9365B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT RH DOOR SIDE MIRROR	Missing	1,373.00 FL	*1,373.00 FL	
2	1		*FRONT RH DOOR SIDE MIRROR COVER	Missing	90.40 FL	*90.40 FL	
3	1		*FRONT RH FENDER	Dented	933.10 FL	*737.90 FL	
4	1		*FRONT RH FENDER HYBRID EMBLEM	Necessary	65.00 FL	*65.00 FL	
5	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	165.00 FL	*- FL	
6	1		*FRONT RH HEADLAMP	Cut	2,449.00 FL	*2,449.00 FL	
7	1		*FRONT RH QUARTER GLASS	Cut	293.10 FL	*293.10 FL	
8	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS	
9	1		*FRONT RH QUARTER GLASS SEALANT	Necessary	60.00 FS	*30.00 FS	
					Sub Total (S\$)	5,478.60	5,038.40
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,342.15	1,252.10
					Total Parts (S\$)	4,136.45	3,786.30

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING.(TO FR)	New	40.00	30.00
2	TO REMOVE, REINSTALL FENDER GLASS	New	100.00	50.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	700.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	500.00	300.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	0.00
Gross Labour Cost (\$\$)			1,540.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >