

ASS. REC. BY:

REF: CS/FCI18009538/ Ggd3⁷² Special Instruction:

Surveyor

aws

From (Person):

GQ
Serene Ler

ASSIGNMENT (Office)

of

FCI

Date/Time:

25/5/18 @ 8:48am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 2312P

Insured:

SHA 3479H

at Workshop m/s

V8 motor Werkz

Tel:

944 2977 /

of

BLK 9 #01-44 Sin Ming Ind. Est & Co. C

Policy No:

Claim No:

D1800 4138 MFSH

Sum Insured:

Excess:

- Make of Veh:

(Client's Record)

D.O.A.

22/05/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

9:20am @ 25/5/18

Person Contacted:

Ah Qiang

Vehicle:

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 2312P - CS/TMI18009353/K/vb DOA: 22/05/2018
	SHA 3479H - CS/TMI18009353/K/vb DOA: 22/05/2018
13/8/18-	Perf prei advise via email
*	MV: \$12K (est); LTA: \$6178; NV: \$5824

QWY2008

xxl.

REF:

FLI

Co1406

ASSIGNMENT

(-2018)

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s: **V8 Motor werkz**
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **\$12k**
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: **4** days Res.: Yes or No
 Lum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLT2312P** Yr Regn: **12 Dec 2008**
 Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Toyota Vios** c.c. **1497**
 Colour: **Black** A/C: Insured / Std / NI / NA
 Sp. Reading: **197318** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **MR053HY 930 5086 442**
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: ☒ Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **185/60 R15**
 R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. 5 mm	L/Bal. 5 mm
D.O.A. _____	D.O.I. 08-08-18
Survey held at w/s	5:20 pm
Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or	

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Finalized, \$950 with Ah Gray. (Red to 2377, 71%)

RECEIVED 08 NOV 2018

Date/Time, File Pass to? ☐ : Preli. Report
 1) **08/11 transfer** ☐ : Final Report
 Date/Time, File Return to?

Days Of Repair: **4**
 Resurvey No. of Trip: _____

Report Format: **TP**
 Lump Sum / I.R.I.: (\$ **950**)

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:	130
Transportation:	50
) S + RS. SI	26
) Photos	
) Others	
TOTAL	206



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18009538/Gqd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 25-05-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3479H	Veh. Inspected	SLT 2312P
Policy No.		Coverage (\$)	0.00
Claim No.	D18004138MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	25/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/05/2018	Inspection Date	08/08/2018
Survey held at	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004138MFSH

Date: 13/8/2018

Our Ref: CS/FCI18009538/Gqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLT 2312P

Please be informed that we had conducted the inspection of the abovementioned vehicle
8/8/2018 at the premises of M/s V8 Motor Werkz and have the following to report: -

Workshop Estimate Amount	: S\$ <u>3,327.00</u>
Revised Estimate Amount	: S\$ <u>1,194.65</u>
"Check" Items Amount	: S\$ <u>0.00</u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
N/S portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Guo Qiang

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	23-05-2018	Our Ref No. D18004138MFSH
Accident Date	22-05-2018	Claim Type. Third Party
Insured Vehicle	SHA3479H	Third Party Vehicle. SLT2312P
Survey Location	blk 9 #01-44 Sin Ming Industrial Est sector c	
Contact Person.	AH QIANG	
Contact No.	91442977/ 88181666	Fax No. 0
Survey Type	WITHOUT PREJUDICE: NO EST. PROVIDED *	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	V8 MOTOR WERKZ PTE LTD	Attention. NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240698)



PRI Documents



Close



PRI Header Details

Claim No	D18004138MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & VISION L PTE LTD
Workshop Name	V8 MOTOR WERKZ PTE LTD (Contact Person : AH QIANG)	Survey Location & Contact Details	blk 9 #01-44 Sin Ming Industrial Est sector c Mobile: 88181666 , Phone: 91442977 , Fax: 0 EmailId: PRESTINAMOH@VISIONLAWLLC.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. PROVIDED *		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA3479H	TP Vehicle No	SLT2312P
PRI Recieved Date	24-05-2018 12:14:37 PM	Surveyor Appointed Date	25-05-2018 08:47:52 AM	Surveyor Accept Date	25-05-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	25-05-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 13 August 2018 11:10 AM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004138MFSH/1
Attachments: PRELI ADVISED SLT 2312P.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLT 2312P**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 25 May 2018 9:29 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004138MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 25 May 2018 8:48 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004138MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Tokio Marine Insurance Singapore Ltd.

(Company Reg. No.: 192300014M) (GST Reg. No.: M2-0000923-4)

20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046

T: (65) 6221 6111 / (65) 6221 4355 / (65) 8224 0895 E: LMS@tokiomarine.com.sg W: www.tokiomarine.com.sg

A sheet size of 100mm
Large format copy
TOKIO MARINE
 INSURANCE GROUP
 FORM MX1H

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: 17-MH000848-R01 (Private Motor Car)

- | | | |
|--|----------------------------|--------------------------------|
| 1. Index Mark and Registration Number of Vehicle | SLT2312P | Chassis No.: MR053HY9305086412 |
| 2. Name of Policyholder | FUSION CAR RENTALS PTE LTD | |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 01/03/2018 | |
| 4. Date of Expiry of Insurance | 25/07/2018 | |

5. Persons or Class of Persons entitled to drive*

Any person who is driving on the Policyholder's order or with their permission.

The hirer.

Any other person who is driving on the hirer's order or with his/ their permission.

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to use*

Use for the carriage of passengers or goods in connection with the Policyholder's business or the hirer's business.

Use for social domestic and pleasure purpose and business purposes of the Policyholder or of any person to whom the vehicle is hired.

The Policy does not cover:-

1) Use for racing, pace-making, reliability trial or speed-testing.

2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 96 of the Road Transport Act, 1987 (Malaysia): are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost/destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account: 0996DDA

Insurance Plan:	Third Party Cover Only
Policy Excess:	Excess-Third Party (Sect II) SGD 1,500

Tokio Marine Insurance Singapore Ltd.

Authorized Signature,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0140G
Vehicle Details	
Vehicle No.:	SLT2312P
Vehicle to be Exported:	No
Intended De-registration Date:	10 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	1NZX818856
Chassis No.:	MR053HY9305086442
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$11,834.00
Original Registration Date:	12 Dec 2008
First Registration Date:	12 Dec 2008
Transfer Count:	3
Actual ARF Paid:	\$11,834.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2018
PARF Rebate Amount:	\$5,917.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$7,721.00
COE Rebate Amount:	\$259.00
Total Rebate Amount:	\$6,176.00

The information contained herein is correct as at 10 Aug 2018

OK

V8 MOTOR WERKZ PRIVATE LIMITED

9 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644

TEL NO : 88181669 / 91442977

EMAIL : V8MOTORWERKZ@GMAIL.COM

ROC NO. :

DATE : 08/08/2018

MAKE / MODEL: TOYOTA VIOS

VEHICLE PLATE NUM : SLT2312P

ESTIMATED COST :

526.2
 25%: 394.65
 1194.65
 20%: 950

No.	Description	QTY	Amount
1	SIDE FENDER — Buc	1	\$385.00
3	SIDE FENDER MUD GUARD COVERING — R	1	\$180.00
4	DOOR BRACKET X { NN	2	\$240.00
5	DOOR CHECK X	1	\$170.00
6	PASSENGER DOOR Repair x	1	\$902.00
8	TO PUTTY AND SPRAY PAINT ON FRONT RIGHT SIDE PANEL INNER / OUTER, DOOR.	1 400	\$1000.00
9	TO DISMANTLE/REPLACE/REFIT/PANEL BEAT FRONT RIGHT SIDE SIDE PANEL, PANEL LINER, UNDER CARRIAGE, ETC.	1 400	\$450.00

(41.2

4 Days.

Unpssm repair.

After repair photos.

Gue Amp - 888 0212

08/08/18

3327

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18009538/Gqd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-11-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3479H	Veh. Inspected	SLT 2312P
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18004138MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	25/05/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053HY9305086442	Colour	BLACK
Odometer	197318	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	5 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	5 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	5 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/05/2018	Inspection Date	08/08/2018
Survey held at	V8 MOTOR WERKZ PTE. LTD. 9 SIN MING INDUSTRIAL EST SECTOR C #01-44 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 2312P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SIDE FENDER	BUCKLED	385.00	385.00
1	SIDE FENDER MUD GUARD COVERING	DEFORMED	180.00	141.20
2	DOOR BRACKET	NOT NECESSARY	240.00	-
1	DOOR CHECK	NOT NECESSARY	170.00	-
1	PASSENGER DOOR	TO REPAIR SEE LABOUR	902.00	-
	LESS 25% DISCOUNT		-	-131.55
			1,877.00	394.65
LABOUR				
	TO PUTTY AND SPRAY PAINT ON FRONT RIGHT SIDE PANEL INNER/OUTER, DOOR.		1,000.00	400.00
	TO DISMANTLE/REPLACE/REFIT/PANEL BEAT FRONT RIGHT SIDE SIDE PANEL, PANEL LINER, UNDER CARRIAGE, ETC. INCLUSIVE OF THE REPAIR OF PASSENGER DOOR.		450.00	400.00
			1,450.00	800.00
GRAND TOTAL			3,327.00	1,194.65
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				950.00

Report Ref No. CS/FCI18009538/Gqd3n2

MARKET VALUE: \$12,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$6,176.00=NETT VALUE: \$5,824.00

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.