

ASS. REC. BY:

REF: CS3/ALG18009540/N24d3⁵² Special Instruction:Surveyor:
Mummen

Nq2

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALG

Date/Time:

25/5/2018 @ 9.21am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 6051M

Insured:

SJT 7642C

at Workshop m/s

Avis Management

Tel:

9630 1281

of

8 kaki Bukit Ave 4 #05-01/02

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

21/05/2018

CA / REV / REP. / REV 24 HRS lwp

H.O.D. Endorsement:

Date/Time:

10.22am @ 25/5/18

Person Contacted:

Alex

Vehicle (IN) OUT

Date/Time	Action/Instruction (X) Estimate
	SGY 6051M - X
	SJT 7642C - X



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18009540/Nz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 25-05-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJT 7642C	Veh. Inspected	SJY 6051M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	25/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/05/2018	Inspection Date	25/05/2018
Survey held at	-		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SJT7642C AND SGY6051M ON 21/05/2018**

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 25/5/2018 9:21:01 AM
Attachments:  FaxC902.tif

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

ALT

ADVOCATES AND SOLICITORS

Your Ref: SJT 7642C
Our Ref: AL.INS.2018.SJY 6051M

22 May 2018

By Fax: 6835 7416

AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 Shenton Way
Tower 2 #07-16
Singapore 079120
Attention: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING SHD 16P, SGY 6051M, SJT 7642C, SJQ 4395B, SJK 9785H, SLD 5979E AND SLM 826Z ALONG SELETAR EXPRESSWAY TOWARDS BUKIT TIMAH EXPRESSWAY AFTER MANDAI EXIT ON 21 MAY AT ABOUT 0715 HOURS

1. We act for the owner of vehicle no. SGY 6051M.
2. We are instructed to claim damages against you in connection with the above accident.
3. Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop: -

Avis management Pte Ltd
8 Kaki Bukit Avenue 4
#05-01/02 Premier Building
Singapore 415875
Person In-Charge: Mr Alex Beh
Hp: 9630 1281

4. TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Yours faithfully


ALLISTER LIM

ALLISTER LIM & THIRUMURGAN

111 North Bridge Road, #11-04 Peninsula Plaza, Singapore 179098 UEN & GST Reg. No.: 53130941W
Tel: 6438 3303 Fax: 6438 1211 (Not for service of court documents) Email: mail@alt.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/05/2018 09:27
Date Of Accident	21/05/2018 07:15
Exact Location Of Accident	SLE> BKE AFTER MANDAI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY6051M
Insured/Policyholder	
Name Of Registered Owner	GAN SUN WEI(YAN SUNWEI)
NRIC No	S8612204I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91527540
Alternative Phone No	OTHERS-91527540
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	COLT RALLIART VERSION-R 1.5 M
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI18B01927/VPE/R001E00
Cover Note Number	

Driver

Name of Driver	GAN SUN WEI(YAN SUNWEI)
NRIC No	S8612204I
Date Of Birth	12/05/1986
Occupation	INDOOR
Date Of Driving Pass	05/07/2010
Driving Experience	7 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91527540
Fax Number	
Contact Number	OTHERS-91527540
Email Address	NOEMAIL

Address	BLK 129C CANBERRA ROAD #11-590
Postcode	753129
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	7
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SEMBAWANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 4 SEMBAWANG CRESCENT , POSTCODE: 757633 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5549999 - FAX NO: 68522499
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20180521/2044

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD16P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJK9785H
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJQ4395B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SJT7642C
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number SLD5979E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 6

Vehicle Registration Number

SLM826Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false statement may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if/when:
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (2) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (3) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
 - (4) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (5) the information so collected under (3) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulation, laws or court orders.

For Insurer's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)

Reporting Centre for Insurers' Signature
Name: Singapore 415933
NRIC/FIN No: Tel: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN

SLE TO SEE before
MANDA-1

A - CANE 051M
B - HTILP
C - HT-42
D - 1045018
E - STR 97894
F - SLIDE 14E
G - SIM 212

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

as per police report

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 413093
Tel: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180521/2044

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

1 of 3

Report No. T/20180521/2044

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/05/2018 11:18		Vide Report No.: J/20180521/0065		Station Diary No.: 44	
Informant's Particulars					
Name of Informant: GAN SUN WEI			Address: APT BLK 129C CANBERRA STREET #11-590 SINGAPORE 753129		
ID Type / ID No.: NRIC NO / S8612204I			Contact No.: Home/Office: Mobile: 91527540		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 32	Date of Birth: 12/05/1986	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: ASSISTANT MANAGER			Driving Licence Information: Class: 3,3A Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 21/05/2018 07:15	Type of Location: Straight Road
Location: Along Road 1 SELETAR EXPRESSWAY				
SLE TOWARDS BKE AFTER MANDAI EXIT				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: CHAIN COLLISION (7 VEHICLES)				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHD16P	TAXI					0
SJK9785H	Car					0
SJQ4395B	Car					0
SJT7642C	Car					0
SJY6051M	Car				Seriously Damaged	0

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180521/2044

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

2 of 3

Report No. T/20180521/2044

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Colour	Condition	No. of Passengers
SLD5979E	Car					0
SLM826Z	Car					0

Brief Details.

On 21/05/2018 at about 0715hrs, I was driving SJY6051M along SLE towards BKE after Mandai Exit. Infront of my vehicle was a Transcab Taxi SHD16P. Subsequently the SHD16P jammed break, as such I applied the break. After I applied the break, I felt an impact from the rear of my vehicle and it caused my vehicle to hit onto SHD16P. After the collision, I made a checked and discovered that it was a chain collision which involved 7 vehicles including my vehicle.

I was advised by the Traffic Police to lodge a Police report. No one was conveyed after the accident.



**SINGAPORE
POLICE FORCE**



T/20180521/2044

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

3 of 3

Report No. T/20180521/2044

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt ISZAD BIN ISHAK		Signature Of Informant: 	
Signature Of Interpreter: Not applicable		Date/Time: 21/05/2018 11:16	
Officer In Charge Of Case: TP / GIT /	Signature	Classification Of Case: TP / GIT	
Contact No.:			
Authentication Stamp NP168		Singapore Police Force	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8197F

Vehicle Details

Vehicle No.: SJT7642C
Vehicle to be Exported: Yes
Intended De-registration Date: 31 May 2018
Vehicle Make: KIA
Vehicle Model: CERATO FORTE 1.6 AT SX ABS D/AB 2WD 4DR
Primary Colour: White
Manufacturing Year: 2009
Engine No.: G4FC9H289709
Chassis No.: KNAFW411MA5121077
Maximum Power Output: 92.7 kW (124 bhp)
Open Market Value: \$13,822.00
Original Registration Date: 29 Oct 2009
First Registration Date: 29 Oct 2009
Transfer Count: 1
Actual ARF Paid: \$13,822.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Oct 2019
PARF Rebate Amount: \$7,602.00

Intended COE Rebate Details

COE Expiry Date: 28 Oct 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$18,899.00
COE Rebate Amount: \$2,662.00
Total Rebate Amount: \$10,264.00

The information contained herein is correct as at 30 May 2018

OK

Legend:

(01)New (02)Used (03)Discard (04)Cracked (05)Co (06)Strashed (07)Deformed
(08)Stiff (09)Buckled (10)Broken (11)Inaccuracy (12)Missing (13)Torn
(14)Unconfirmed (15)Not Working

MOTOR CAR (Frt)

ACTIVITY

(1)Repair (✓) (2)Repair (X) (3)Check (P)
(4)Not Connected (N/C)

Aug 2005

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	BR	✓	
1002	991887	Frt Number Plate Base	BR	✓	
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	CUT	✓	
1005	992341	Frt Bumper Clips	NEC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991497	Frt Bumper Lower Spoiler	BR	✓	
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem	CUT	✓	
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	DT	✓	
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	DT	R	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: **SJY6051M**

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	SCR	R	
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector	CAN	✓	
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Front Bumper Air intake Deflect		✓	

No of Items:

Accessories:

ORIGINAL COPY

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 May 2018 Edit Reg		25 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	ABDUL JALIL BIN MOHAMED YUSOF, ID: S1658197F		
Main Claimant:	GAN SUN WEI(YAN SUNWEI), ID: S86122041		
Vehicle Reg. No.:	SJY6051M	Date of Loss:	21/05/2018 07:00 - :59 [134 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5087424937SG	Policy/Cover Note No.:	1800058715 (Comprehensive)
Vehicle Reg. No. (Insured):	SJT7642C	Policy No. (Claimant):	
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 12/06/2018]		
Claimant's Solicitor:	ALLISTER LIM & THUMURGAN - Tel: 64383303		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (05/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJY6051M (5087424937SG)**
[SJT7642C]
TP
GAN SUN WEI(YAN SUNWEI)
May 21 2018 7:00AM
[ABDUL JALIL BIN MOHAMED YUSOF]

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View In Browser	
Photos/Images			3 per page	☒
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/06/18 14:57	General View	 Load JPG	☒
2	01/06/18 14:57	General View	 Load JPG	☒
3	01/06/18 14:57	General View	 Load JPG	☒
4	01/06/18 14:57	General View	 Load JPG	☒
5	01/06/18 14:57	General View	 Load JPG	☒
6	01/06/18 14:57	General View	 Load JPG	☒
7	01/06/18 14:57	General View	 Load JPG	☒
8	01/06/18 14:57	General View	 Load JPG	☒
9	01/06/18 14:57	General View	 Load JPG	☒
10	01/06/18 14:57	General View	 Load JPG	☒
11	01/06/18 14:57	General View	 Load JPG	☒
12	01/06/18 14:57	General View	 Load JPG	☒
13	01/06/18 14:57	General View	 Load JPG	☒
14	01/06/18 14:57	General View	 Load JPG	☒
15	01/06/18 14:57	General View	 Load JPG	☒
16	01/06/18 14:57	General View	 Load JPG	☒
17	01/06/18 14:57	General View	 Load JPG	☒
18	01/06/18 14:57	General View	 Load JPG	☒
19	01/06/18 14:57	General View	 Load JPG	☒
20	01/06/18 14:57	General View	 Load JPG	☒
21	01/06/18 14:57	General View	 Load JPG	☒
22	01/06/18 14:57	General View	 Load JPG	☒
23	01/06/18 14:57	General View	 Load JPG	☒
24	01/06/18 14:57	General View	 Load JPG	☒
25	01/06/18 14:57	General View	 Load JPG	☒
26	01/06/18 14:57	General View	 Load JPG	☒
27	01/06/18 14:57	General View	 Load JPG	☒
28	01/06/18 14:57	General View	 Load JPG	☒
29	01/06/18 14:57	General View	 Load JPG	☒
30	01/06/18 14:57	General View	 Load JPG	☒
31	01/06/18 14:57	General View	 Load JPG	☒
32	01/06/18 14:57	General View	 Load JPG	☒
33	01/06/18 14:57	General View	 Load JPG	☒
34	01/06/18 14:57	General View	 Load JPG	☒
35	01/06/18 14:57	General View	 Load JPG	☒
36	01/06/18 14:57	General View	 Load JPG	☒

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	01/06/18 14:57	General View	 Load JPG	✓
38	01/06/18 14:57	General View	 Load JPG	✓
39	01/06/18 14:57	General View	 Load JPG	✓
40	01/06/18 14:57	General View	 Load JPG	✓
41	01/06/18 14:57	General View	 Load JPG	✓
42	01/06/18 14:57	General View	 Load JPG	✓
43	01/06/18 14:57	General View	 Load JPG	✓
44	01/06/18 14:57	General View	 Load JPG	✓
45	01/06/18 14:57	General View	 Load JPG	✓
46	01/06/18 14:57	General View	 Load JPG	✓
47	01/06/18 14:57	General View	 Load JPG	✓
48	01/06/18 14:57	General View	 Load JPG	✓
49	01/06/18 14:57	General View	 Load JPG	✓
50	01/06/18 14:57	General View	 Load JPG	✓
51	01/06/18 14:57	General View	 Load JPG	✓
52	01/06/18 14:57	General View	 Load JPG	✓
53	01/06/18 14:57	General View	 Load JPG	✓
54	01/06/18 14:57	General View	 Load JPG	✓
55	01/06/18 14:57	General View	 Load JPG	✓
56	01/06/18 14:57	General View	 Load JPG	✓
57	01/06/18 14:57	General View	 Load JPG	✓
58	01/06/18 14:57	General View	 Load JPG	✓
59	01/06/18 14:57	General View	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/06/18 13:24	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009540/NZ4D3S2
Date: 06/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800058715
Claimant Vehicle No: SJY6051M Insured Vehicle No: SJT7642C
Date of Loss: 21/05/2018 Nature of Claim: TP Claim No: 5087424937SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY6051M**
Make & Model: MITSUBISHI COLT, 1.5 RALLIART VERSION-R (M) Engine No: 4G15HS7306
Reg. Date: 02/03/2007 (Man. Year: 2006) Chassis No: Z27A0400389
Colour: White Odometer: 278085 km
Engine Capacity: 1468 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45R16 Rear Tyre Size: 205/45R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/05/2018
Date Inspected: 30/05/2018 Inspected At: Avis Management
8 Kaki Bukit Ave 4 #05-01/02
Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Missing	0.00 F	*-F
2	1		*REAR NUMBER PLATE BASE	Missing	0.00 F	*-F
3	1		*REAR BUMPER	Damaged	0.00 F	*-F
4	1		*REAR BUMPER LOWER	Broken	0.00 F	*-F
5	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
6	1		*REAR BUMPER BRACKET	Dented	0.00 F	*-F
7	1		*REAR BUMPER PROTECTOR	Cut	0.00 F	*-F
8	1		*REAR BUMPER MOULDING	Broken	0.00 F	*-F
9	1		*REVERSE SENSOR	Short Circuit	0.00 F	*-F
10	1		*REAR END PANEL	Dented	0.00 F	*-F
11	1		*BOOTLID	Dented	0.00 F	*-F
12	1		*BOOTLID EMBLEM	Necessary	0.00 F	*-F
13	1		*BOOTLID HANDLE	Scratched	0.00 F	*-F
14	1		*REAR EXHAUST PIPE	Cut	0.00 F	*-F
15	1		*REAR RH FENDER PROTECTOR	Scratched	0.00 F	*-F
16	1		*FRT NUMBER PLATE	Broken	0.00 F	*-F
17	1		*FRT NUMBER PLATE BASE	Broken	0.00 F	*-F
18	1		*FRT BUMPER	Cut	0.00 F	*-F
19	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
20	1		*FRT BUMPER LOWER SPOILER	Broken	0.00 F	*-F
21	1		*FRT GRILLE EMBLEM	Cut	0.00 F	*-F
22	1		*FRT SUPPORT PANEL	Dented	0.00 F	*-F
23	1		*BONNET	Repair	0.00 F	*-F
24	1		*FRT LH FENDER	Repair	0.00 F	*-F
25	1		*FRT LH FENDER PROTECTOR	Cracked	0.00 F	*-F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >