

ASS. REC. BY:

REF:

CS3 / LPC18009545 / T1qbd3<sup>57</sup>

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

ERIC WOO

of

LPC

Date/Time:

25/5/18 @ 12:03pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 502M

Insured:

YJ 9221X

at Workshop m/s

Yee Keong Motor

Tel:

9780 8928 / 62620218

of

No. 14 Penjuru Road

Policy No:

Claim No:

17/18/18/VC00/020625

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/05/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

12:10pm @ 25/5/18

Person Contacted:

Vehicle

IN/OUT

Date/Time

Action/Instruction (X) Estimate

XD 502M-CS3 / FC115 614721 / T1qbd1

DOA: 25/08/2015

YJ 9221X-X.

disassemble survey - 06/6/18

after paint - 06/6/18

22/6/18 &amp; Submit PPS.

LPC

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:			
IDAC Accident Report		Consistent?	Yes or No
GLI - PR Seen		Consistent?	Yes or No
Est. Repairs	days	Res.	Yes or No
Lump Sum	%	3 Val	Yes or No

CA / REV / REP / 24 HRS

PKS

Vehicle: IN / OUT

Date	Person Contacted
------	------------------

Date	Time	Action	Instruction
------	------	--------	-------------

X D 502 M  
 M Car / V4 / Bus / Van / Lorry / Taxi / Private Motor  
 Truck / Trailer  
 Make FU 1792 P068 1945  
 Colour Blue  
 Sp Reading 388 b f s  
 Eng No  
 C No FV617PA00492  
 Gen Cond Good / Fair / Poor / Burnt  
 Steering In order / Jammed / Leaked / Burnt or  
 Brake In order / Jammed / Leaked / Burnt or  
 Mod NII / S/Rim / STD A/Rim or  
 Tyre Size E: 245 / R122.5  
 R: (O)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or *Chao Yang*

Front		Rear	
R/Bal	8 mm	R/Bal	8/8 mm
L/Bal	8 mm	L/Bal	8/8 mm
D.O.A		D.O.I	25/5/18017

Survey held at Yee Koon 14 Pajun

Des. of Damages: Frt / Rear / Q/S / N/S / U/C / Rooftop / 00

$$F_v + N/s$$

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 22 JUN 2018

22/6 1953

☐ : Prel. Report  
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip

Add Fee:  Enter \$

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

□  $0 \leq t \leq 1$   $\leq 23$

Figure 1. Schematic diagram of the experimental setup.

PR3



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC18009545/T1qd3

300 BEACH ROAD

#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 25-05-2018



Code : LPC2

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YJ 9221X	Veh. Inspected	XD 502M
Policy No.		Coverage (\$)	0.00
Claim No.	17/18/18/VC00/020625	Excess (\$)	0.00
Assign From	ERIC WOO	Assign Date	25/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	21/05/2018	Inspection Date	25/05/2018
Survey held at	YEE KEONG MOTOR ENGINEERING NO: 14 PENJURU ROAD SINGAPORE 609125		

5a. Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## Nivitha (LKK Auto)

---

**From:** ERIC WOO JUN KIAT <ericwoo@lonpac.com>  
**Sent:** Friday, 25 May 2018 12:03 PM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Notice of Accident /Notice to conduct pre-repair inspection;Accident involving XD 502M (our client) & YJ 9221X (your insured) along Jalan Buroh towards Pioneer Road on 21.05.18 Our Ref:17/18/18/VC00/020625  
**Attachments:** 25052018120035.pdf

Dear Catherine/Nivitha,

As spoken, please assist.

Thank you.

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

---

**From:** ERIC WOO JUN KIAT  
**Sent:** Wednesday, 23 May, 2018 10:16 AM  
**To:** 'motor@kscgp.com'  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Notice of Accident /Notice to conduct pre-repair inspection;Accident involving XD 502M (our client) & YJ 9221X (your insured) along Jalan Buroh towards Pioneer Road on 21.05.18 Our Ref:17/18/18/VC00/020625

Dear See Yee,

Thank you for your list of surveyors.

We regret we are not agreeable to your panel of surveyor as listed.

We shall be assigning LKK Auto Consultants Pte Ltd to conduct the survey on your client's vehicle No: XD 502M.

Dear Catherine/Nivitha,

FYA.

Thank you.

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

---

**From:** motor@kscgp.com [mailto:motor@kscgp.com]  
**Sent:** Tuesday, 22 May, 2018 8:00 PM

**To:** ERIC WOO JUN KIAT

**Cc:** MT\_Claim\_SG

**Subject:** RE: Notice of Accident /Notice to conduct pre-repair inspection;Accident involving XD 502M (our client) & YJ 9221X (your insured) alongJalan Buroh towards Pioneer Road on 21.05.18 Our Ref:17/18/18/VC00/020625

Dear Eric,

We are instructed to reply to your email as per the attached.

Please assist.

Thank you.

Regards,

See Yee

Executive

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0987 / Fax: 6538 3708

Email: [motor@kscgp.com](mailto:motor@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

**From:** ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]

**To:** [motor@kscgp.com](mailto:motor@kscgp.com)

**Cc:** [mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)

**Sent:** Tue, 22 May 2018 09:28:16 +0000

**Subject:**

Dear See Yee,

We refer to your email below.

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

---

**From:** [motor@kscgp.com](mailto:motor@kscgp.com) [mailto:[motor@kscgp.com](mailto:motor@kscgp.com)]

**Sent:** Tuesday, 22 May, 2018 2:50 PM

**To:** MT\_Claim\_SG

**Subject:** Notice of Accident /Notice to conduct pre-repair inspection; Accident involving XD 502M (our client) & YJ 9221X (your insured) along Jalan Buroh towards Pioneer Road on 21.05.18

Dear Sir/Mdm,

We are instructed to send you the attached Notice of Accident and our client's Accident Report.

Kindly assist.

Thank you.

Regards,  
See Yee  
Executive  
KSCGP Juris LLP  
10 Hoe Chiang Road  
#13-03A Keppel Towers  
Singapore 089315  
Tel: 6538 3611 / DID: 3152 0987 / Fax: 6538 3708  
Email: [motor@kscgp.com](mailto:motor@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

Your Insured's vehicle ; ref: YJ 9221X ; 17/18/18/VC00/020625

Our client's vehicle ; ref: XD 502M; YK/sy

Date : 22 May 2018

Lonpac Insurance Bhd

By Email Only

Dear Sirs,

**DATE OF ACCIDENT: 21 MAY 2018**

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS**

We refer to the above matter and your email dated 22 May 2018.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/N	Name of Surveyor	Company Name
1.	Foo Philip	Precision Appraisal Services
2.	Ronald Ng	Precision Appraisal Services
3.	Lee Kok Weng	Lee Automobile Appraisals Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which we will commence repairs thereafter without any further notice or reference to you. Please also let us know if you required a Post-Repair Survey/Inspection for our client's consideration. Please be informed that the said vehicle can be surveyed / inspected at:

Workshop : Yee Keong Motor Engineering  
Address : No. 14 Penjuru Road  
Singapore 609125  
Contact person/Hp/Fax : Mr. Hiew / 9780 8928 / 6262 0218

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,



## SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.**
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Date Of Report	21/05/2018 17:47
Date Of Accident	20/05/2018 15:00
Exact Location Of Accident	ALONG JLN BUROH TOWARDS PIONEER RD
Country/State Of Loss	SINGAPORE
Vehicle Registration Number	XD502M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THIAM YUN SERVICE
Co Reg No	53067456D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-98299269
<b>Vehicle Particulars</b>	
Manufacturer	MITSUBISHI
Model	FV517JD2RDEB-11.9 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
Claim: Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Is it Policy	NO
Policy Number	DMCV17S007632
Cover Note Number	
<b>Driver</b>	
Name of Driver	NG KWEE THIAM
NRIC No	S6945007E
Date Of Birth	27/12/1969
Occupation	OUTDOOR
Date Of Driving Pass	26/06/1996
Driving Experience	21 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98299269
Fax Number	
Contact Number	
Email Address	NOEMAIL
Address	NIL
Postcode	



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

### THIAM YUN SERVICE

BLK 183A BOON LAY AVENUE #11-700

SINGAPORE 641183

TEL : 98299269 ROC : 53067456D

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A **14 DAY TIMEFRAME** FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	7456D
<b>Vehicle Details</b>	
Vehicle No.:	XD502M
Vehicle to be Exported:	No
Intended De-registration Date:	22 Jun 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	FV517P2RDEB
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	6D24378406
Chassis No.:	FV517PA00492
Maximum Power Output:	-
Open Market Value:	\$70,297.00
Original Registration Date:	07 Jul 2006
First Registration Date:	07 Jul 2006
Transfer Count:	1
Actual ARF Paid:	\$3,515.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	06 Jul 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$44,493.00
COE Rebate Amount:	\$35,765.00
<b>Total Rebate Amount:</b>	<b>\$35,765.00</b>

The information contained herein is correct as at 22 Jun 2018

OK




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC18009545/T1qd3s2 Date: 27-06-2018 Code: LPC2	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
Insured Veh.	YJ 9221X	Veh. Inspected	XD 502M
Policy No.		Coverage (\$)	0.00
Claim No.	17/18/18/VC00/020625	Excess (\$)	0.00
Assign From	ERIC WOO	Assign Date	25/05/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MITSUBISHI FV517P2RDEB	c.c	11945
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	FV517PA00492	Colour	BLUE
Odometer	388698 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	CHAO YANG	8 mm
L/H Front Tyre	295/80 R22.5	CHAO YANG	8 mm
R/H Rear Tyre	295/80 R22.5 (D)	CHAO YANG	8/8 mm
L/H Rear Tyre	295/80 R22.5 (D)	CHAO YANG	8/8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.			
<b>5. General Information</b>			
Accident Date	21/05/2018	Inspect Date / Time	25/05/2018 ( 05:15 PM )
Survey held at	YEE KEONG MOTOR ENGINEERING NO. 14 PENJURU ROAD SINGAPORE 609125		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC18009545/T1qd3s2

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or not, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.