

22/03/2002

ASS. REG. BY:

REF: CS3/

A1G18009562/G24d3er

Special Instruction:

Surveyor:

Maimen

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

A1G

Date/Time:

25/5/18 @ 2.50pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 9532D

Insured:

SJT 9049C

at Workshop m/s

Len Wang Motor

Tel:

6748 2910

of

Blk 3007 ubi Rd 1 # 01-414

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/05/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

4.44pm @ 25/5/18

Person Contacted:

Alice

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SJS 9532D - CS / HSB10011003 / Rfgl

DOA: 29/05/2010

SJT 9049C - X.

1/6/18

Dismantled

5/6/18

After Repair

PRS  
Surrey xpl.

REF:

8474E

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s long wany  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: \$20k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJS9532D Yr Regn: 16 Sep 2009  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Volkswagen Jetta <sup>G.C</sup> 1390  
 Colour: Blue A/C: Insured / Std / M / NA  
 Sp. Reading: 74352 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WV WZEE 1KZ 94021307  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 205/55R18  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Continental  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 31-05-18  
 Survey held at w/s 5:50pm  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
d/s ft  
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time	Action / Instruction
1/6/18	Dismantled
1/6/18	Submit DAR Report

RECEIVED 01 JUN 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation: \_\_\_\_\_ \$ + RS. \_\_\_\_\_ \$

Photos

Others

TOTAL

180
20
200

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE  
SJT9049C AND SJS9532D ON 23/05/2018**

From: Chin, Lee-Ying  
To: 'assignments', Admin A  
Cc: Fong, Andy-SY  
Sent: 25/5/2018 2:50:28 PM  
Attachments:  SKMBT\_C364e18052411400.pdf

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

---

**From:** Cheonghoh Law [mailto:mail@cheonghoh.sg]  
**Sent:** Friday, May 25, 2018 2:19 PM  
**To:** Lim, Sheng Yang  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Supramaniam, Darshene; Chan, Yoke Shi  
**Subject:** Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJT9049C AND SJS9532D ON 23/05/2018

Dear Sirs,

We refer to the above matter and to your email of 24 May 2018.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your 10 appointed surveyors as stated in your aforesaid e-mail.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- (1) Kelvin Teo Hoon Tong
- (2) Chiang Fuh Keong Dave
- (3) Ho Joo Loong Danny
- (4) Lee Kok Weng
- (5) Hong Shiyuan
- (6) Lim Yong Tian Sebastian
- (7) Ong Ah Keng Kent
- (8) Ong Poh Meng

- (9) Philip Foo
- (10) Thor Teck Soon David

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre- repair survey and please contact our client's workshop, Leng Wang Motor, Blk 3007 Ubi Road 1 #01-414 Singapore 408701 to contact survey of the said vehicle SJS 9532 DB.

Contact Person : Ms Alice Yong  
Tel: 6748 2910 / 9817 2032

Kindly proceed to do the needful.

Thanks & regards  
Catherine  
CHEONGHOH LAW CORPORATION  
Blk 53 Chin Swee Road #03-05  
Singapore 160053  
T: 6337 8700 | F: 6337 3700 | E: [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/05/2018 09:31
Date Of Accident	23/05/2018 19:50
Exact Location Of Accident	JUNCTION OF SENGKANG WEST WAY & FERNVALE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS9532D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YANG BOWEI
NRIC No	S2708474E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96738909
Alternative Phone No	OTHERS-96738909

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA-1.4 TSI (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00446009
Cover Note Number	

### Driver

Name of Driver	YANG BOWEI
NRIC No	S2708474E
Date Of Birth	11/04/1963
Occupation	INDOOR
Date Of Driving Pass	26/06/2009
Driving Experience	8 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96738909
Fax Number	
Contact Number	OTHERS-96738909
EMail Address	NOEMAIL

Address	BLK 613D PUNGGOL DRIVE #17-817 SINGAPORE
Postcode	824613
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GWEN ONG GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336

#### Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJT9049C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I am driving on the way, in the junction of Seng Kang W'ay and Fernvale RD the direct green is on, whilst I passing the junction, Car B hit on my Car (A) right front.

## DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 24 day clause whereby the claim against own policy must be made within the stipulated time frame from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time: 9/20/21

Driver's Signature

Date & Time: 21/5/18

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Officer/Personnel's Signature

Name:

NRIC/PR No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	8474E

### Vehicle Details

Vehicle No.:	SJS9532D
Vehicle to be Exported:	No
Intended De-registration Date:	01 Jun 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AUTO 1K21Q5 7 SPD
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	CAV094876
Chassis No.:	WVWZZZ1KZ9U021307
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$21,661.00
Original Registration Date:	16 Sep 2009
First Registration Date:	16 Sep 2009
Transfer Count:	1
Actual ARF Paid:	\$21,661.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Sep 2019
PARF Rebate Amount:	\$11,913.00

### Intended COE Rebate Details

COE Expiry Date:	15 Sep 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$8,489.00
COE Rebate Amount:	\$1,094.00
<b>Total Rebate Amount:</b>	<b>\$13,007.00</b>

The information contained herein is correct as at 01 Jun 2018

OK



## ▶ Jetta Used Vehicle List (15 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
<b>Volkswagen Jetta Sport 1.4A TSI</b>	<b>\$24,800</b>	\$9,050 /yr	17-Dec-2009	1,390 cc	112,449 km	WM Car Pte Ltd	<b>Availat</b>
One Of The Powerful Volkswagen Unit On The Market. A Sporty Black To Attract All Users,Well Maintained Condition For Interior And Exterior.Call Our Friendly Sales Staff For More Information, Call Us N...							
Office No. - 64634936 Chris Ong - 91375618   Ivan Choo - 97629200   Peng Hee - 91761283							
<b>Volkswagen Jetta 1.6A</b>	<b>\$24,000</b>	\$10,830 /yr	02-Nov-2009	1,595 cc	116,500 km		<b>Availat</b>
Direct Selling By 1st Owner. Good Condition. Selling Due To Family Expansion. View At Your Convenience.							
Office No. - - GK - 92476511							
<b>Volkswagen Jetta 1.4A TSI</b>	<b>\$21,800</b>	\$8,790 /yr	01-Oct-2009	1,390 cc	172,000 km	Hua Yang Credit Pte Ltd	<b>Availat</b>
\$3K Drive Away! Low Depreciation! Excellent Fuel Consumption! New Paintwork! Call Now For A Test Drive Appointment!							
Office No. - 64635111 Benny - 84822999   Kamen - 88621923							
<b>Volkswagen Jetta 1.4A TSI</b>	<b>\$24,300</b>	\$10,240 /yr	25-Sep-2009	1,390 cc	170,000 km	Car Search	<b>Availat</b>
Recent Repair Mechantronics Unit In November Last Year. 6 Months Warranty Until April. Have Record On The Parts That Was Changed. Owner Well Maintain On Vehicle. View To Believe.							
Office No. - 62620728 Tan - 98001024   Daryl - 98186406							
<b>Volkswagen Jetta 1.4A TSI</b>	<b>\$22,800</b>	\$9,680 /yr	25-Sep-2009	1,390 cc	223,000 km	Carro	<b>Availat</b>
Mechantronics Done Last Year. New Roof Lining With 1 Year Warranty. 6 Months Old Tyres. Viewing Is Strictly By Appointment Only.							
Office No. - 67146652 Jace - 81394200							
<b>Volkswagen Jetta 1.4A TSI</b>	<b>\$19,800</b>	\$7,560 /yr	15-Sep-2009	1,390 cc	-	Passionate Cars Pte Ltd	<b>Availat</b>
Down Payment As Low As \$2500 Onwards. Welcome Old Car 1 To 1 Exchange Without Cash Top Up.							
Office No. - 66365001 Ivan - 81261954   Aaron - 97491191							
<b>Volkswagen Jetta 1.4A TSI</b>	<b>\$20,750</b>	\$7,800 /yr	09-Sep-2009	1,390 cc	12,283 km		<b>Availat</b>
Facelifted Model. Your Ideal Continental Sedan, Great Balance Between Comfort, Sportiness And Safety. Low Depreciation Unit. Exterior Condition 8/10. (Bumper And Side Are Scratched. Pictures Included)...							
Office No. - - Spotbarn - 96723555							
<b>Volkswagen Jetta 1.4A TSI</b>	<b>\$20,800</b>	\$9,310 /yr	27-Jul-2009	1,390 cc	169,956 km	Ritz Auto	<b>Availat</b>
Cheaper Than Rental! Only \$694 A Month! Non Smoker Unit, Very Well Maintained! No Repairs Needed! All Trade In Welcome, Major Bank And In House Loan Available! Night And Door Step Viewing Available! H...							
Office No. - 62556118 Han - 97284422   Krist - 97113211   Alex - 97740917							
<b>Volkswagen Jetta 1.4A TSI</b>	<b>\$22,300</b>	\$10,920 /yr	16-Jul-2009	1,390 cc	109,000 km		<b>Availat</b>
New Tyres. Head Lamps Converted To Sport Model With Smoked Reflector. No Repairs Needed.							
Office No. - - Vincent Lu - 96887977							
<b>Volkswagen Jetta 1.4A TSI</b>	<b>\$19,888</b>	\$8,460 /yr	26-Jun-2009	1,390 cc	150,000 km		<b>Availat</b>

## Conditions (CON)

(01)Item (2)Denied (3)Distorted (4)Cracked (5)Cut (6)Scratched  
 (07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary (12)Missing  
 (13)Torn (14)Unconfirmed (15)Not Working

## MOTOR CAR (RH)

## ACTION (AC)

(1)Replace (✓) (2)Repair (X) (3)Check (?)  
 (4)Not Consistent (NC)

Vehicle No: SJS 95320

## Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door	SCR	R	
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper	SCR	R	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector	NC	✓	2
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender	DT	✓	
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
		Frt RH Wheel Rim	CUT	✓	

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door			
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			
		Frt RH Shock Absorber ?			
		Frt RH Knuck Air Arm ?			
		Frt RH Knuck Arm Beat 1/4 NC			
		Frt RH Lower Arm ?			

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jun 2018 <a href="#">Edit Reg</a>		25 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

**CLAIM SUBFOLDER DETAILS**

Insured:

SIM POH CHYE, ID: S0200950A

Main Claimant:

YANG BOWEI, ID: S2708474E

Vehicle Reg. No.:

SJS9532D

Claim Type:

TP / 0765542199SG

Vehicle Reg. No. (Insured):

SJT9049C

Repairer:

Leng Wang Motor (HQ) Blk 3007 Ubi Road 1, #01-414, 408701 Ubi - Tel:

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Nivitha Govindasamy] ... [Final Rpt due 12/06/2018]

Claimant's Solicitor:

CHEONGHOH LAW CORPORATION - Tel: 63378700

Date of Loss:

23/05/2018 19:00 - :59  
[104 Months and 7 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

1800038129 (Comprehensive)

Policy No. (Claimant):

Excess:

[Created by adjuster]

**ASSOCIATED MAIL RECEIVED**

[View All](#)
[Compose Case Mail](#)

- AIG\_SG (05/06/2018): Request To Upload TP GIA Report






































**ALL ASSOCIATED TASKS**









[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJS9532D (0765542199SG)  
[SJT9049C]  
TP  
YANG BOWEI  
May 23 2018 7:00PM  
[SIM POH CHYE]  
Leng Wang Motor

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
2	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
3	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
4	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
5	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
6	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
7	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
8	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
9	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
10	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
11	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
12	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
13	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
14	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
15	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
16	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
17	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
18	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
19	01/06/18 16:21	General View														Load JPG	<input checked="" type="checkbox"/>	
20	07/06/18 12:18	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
21	07/06/18 12:18	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
22	07/06/18 12:18	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
23	07/06/18 12:18	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
24	07/06/18 12:18	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
25	07/06/18 12:18	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
26	07/06/18 12:18	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
27	07/06/18 12:18	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
28	07/06/18 12:18	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
29	07/06/18 12:18	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
30	07/06/18 12:18	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>	
31	07/06/18 12:19	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>	
32	07/06/18 12:19	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>	
33	07/06/18 12:19	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>	
34	07/06/18 12:19	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>	
35	07/06/18 12:19	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>	
36	07/06/18 12:19	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>	
37	07/06/18 12:19	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	07/06/18 12:19	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	07/06/18 12:19	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	07/06/18 12:19	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	07/06/18 12:19	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	07/06/18 12:19	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	07/06/18 12:19	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	07/06/18 12:19	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/06/18 12:39	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009562/GZ4D3E2

Date: 11/06/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800038129  
**Claimant Vehicle No :** SJS9532D **Insured Vehicle No :** SJT9049C  
 Date of Loss: 23/05/2018 Nature of Claim: TP Claim No: 0765542199SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJS9532D**  
 Make & Model: VOLKSWAGEN JETTA, 1.4 (A) Engine No: CAV094876  
 Reg. Date: 16/09/2009 (Man. Year: 2009) Chassis No: WWZZZ1KZ9U021307  
 Colour: Blue Odometer: 74352 km  
 Engine Capacity: 1390 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/55 R18 Rear Tyre Size: 205/55 R18  
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 25/05/2018  
 Date Inspected: 31/05/2018 Inspected At: Leng Wang Motor (HQ)  
 Blk 3007 Ubi Road 1, #01-414  
 Singapore 408701  
 Estimated Period of Repair: 4.0 days

Adjuster: Nivitha Govindasamy

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Repair	0.00 F	*- F
2	1		*FRT BUMPER	Repair	0.00 F	*- F
3	2		*FRT BUMPER PROTECTOR	Necessary	0.00 F	*- F
4	1		*FRT RH FENDER	Dented	0.00 F	*- F
5	1		*FRT RH WHEEL RIM	Cut	0.00 F	*- F
6	1		*FRT RH SHOCK ABSORBER	* Check	0.00 F	*- F
7	1		*FRT RH KNUCKLE ARM	* Check	0.00 F	*- F
8	1		*FRT RH KNUCKLE ARM BEARING	Necessary	0.00 F	*- F
9	1		*FRT RH LOWER ARM	* Check	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >