

2009/01/01

ASS. REC. BY:

REF: CS3 / FWD 18009570 / GZAD312

Instruction:

Surveyor: GQ
Murmen

ASSIGNMENT (Office)

From (Person): Josey Toh

of FWD

Date/Time: 25/5/18 @ 4:13pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 3379L

Insured: SJH 1289S

at Workshop no: Cadre Automobile

Tel: 6747 7618

of No. 1, Kaki Bukit Ave 6 #02-49

Policy No:

Claim No: 1201800006319

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/05/2018

CA / REV / REP. / REV 24 HRS (w/p)

H.O.D. Endorsement:

Date/Time: 25/5/18 @ 5:08pm

Person Contacted: Mr. Chen

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SLP 3379L - X</u>
	<u>SJH 1289S - X</u>
<u>30/5/18</u>	<u>Disman/led</u>

PRS
Xml.

ASSIGNMENT

From: _____ Date: 28/5/18

Estimated Cost: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 3379L

at Workshop n/s: Cadre Automobile

of: 1 Kaki Bukit Ave 6 #02-19 Autobay

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SLP3379L Yr Regn: _____

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Audi A5 CC

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 92369 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 245/40R18
R: "

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt. Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. _____ D.O.I. 28-03-18

Survey held at: w/s 3:50pm

Des. of Damages: Frt / Rear / O/S / UIC / Rooftop or _____

The Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate: S\$ 12,500 - 13,500

* 4 days

31/5/18 submit PRS report.

RECEIVED 01 JUN 2018

Date/Time: File Pass to? : Prel. Report : Final Report

Date/Time: File Return to? _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

1. _____ S + RS _____ S

1. Phone _____

1. Other _____

TOTAL _____

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech Insp (\$ _____)

Weekend (\$ _____)

Nivitha (LKK Auto)

From: josey.loh@fwd.com
Sent: Friday, 25 May 2018 4:13 PM
To: sur@lkkauto.com; assignments@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Subject: FW: Our client's vehicle no. SLP3379L (Cadre); Your insured's vehicle no. SJH1289S - PRI (Our Ref: 1201800006319)
Attachments: Cadre Automobile - Pre-Repair Notice (FWD)(SLP3379L).pdf

Hi LKK team,

Please refer to the attached and liaise with TP repairer for PRS.

Attached is the TP GIA report.

Please create the case in Merimen.

Thank you.

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind Regards

Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

From: Motor Claims SG - SG Common
Sent: Friday, 25 May, 2018 4:11 PM
To: 'Hui Ting'
Cc: Corene Chong
Subject: RE: Our client's vehicle no. SLP3379L (Cadre); Your insured's vehicle no. SJH1289S - PRI (Our Ref: 1201800006319)

WITHOUT PREJUDICE

Dear Huiting,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK Auto Consultants Pte Ltd, to conduct the pre-repair survey (PRS) on your client's vehicle, SLP3379L. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards

Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg



FWD Insurance
Endowment Plan
Get the biggest guaranteed return for a 3-year plan available online.
Limited time offer!
2.02% p.a.
fwd.com.sg
save now

From: Hui Ting [<mailto:huiting@crossbordersllc.com>]
Sent: Friday, 25 May, 2018 4:00 PM
To: Motor Claims SG - SG Common
Cc: Corene Chong
Subject: RE: Our client's vehicle no. SLP3379L (Cadre); Your insured's vehicle no. SJH12895 - PRI (Our Ref: 1201800006319)

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Sirs

1. We refer to your email dated 25 May 2018.
2. Our client objects appointing your surveyors as a single joint expert.
3. We propose one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:-
 - a) Dennis Yap PAL'S Appraiser Pte Ltd

- b) Yap Teck Lee LCW Appraiser Pte Ltd
- c) Yap Teck Chye MC-Coy Appraiser Pte Ltd
- d) Dixon Yeo Treasure Appraiser Pte Ltd
- e) Marc Ananda United Appraisal and Management Pte Ltd
- f) Andrew How Prominent Appraiser Services
- g) Alan Cheong K.H. C L Appraiser Pte Ltd
- h) T.T. Rajan ST Appraisal Services
- i) Sebastian Lim Constanct Appraiser Services
- j) Aeon Auto Consultants LLP

4. Please let us know within two (2) working days whether you are agreeable to the appointment of any of the above motor surveyors as a single joint expert.

Thank You.

Regards
Huiting
TEL: 6812 6873

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

From: motorclaims.sg@fwd.com <motorclaims.sg@fwd.com>
Sent: Friday, May 25, 2018 3:50 PM
To: Hui Ting <huiting@crossbordersllc.com>
Cc: Corene Chong <corene@crossbordersllc.com>
Subject: RE: Our client's vehicle no. SLP3379L (Cadre); Your insured's vehicle no. SJH1289S - PRI (Our Ref: 1201800006319)

WITHOUT PREJUDICE

Dear Huiting,

We refer to your letter dated 25 May 2018 of the PRI Notice of your client's vehicle SLP3379L.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD

2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards

Josey Loh
Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872
E josey.loh@fwd.com
W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
--	------------------------------------------------------------------------------------------------------------------------------	--	------------------------------------------------------------------------------------

From: Hui Ting [<mailto:huiting@crossbordersllc.com>]
Sent: Friday, 25 May, 2018 3:41 PM
To: Motor Claims SG - SG Common
Cc: Corene Chong
Subject: Our client's vehicle no. SLP3379L (Cadre); Your insured's vehicle no. SJH12895 - PRI

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Sirs

1. Please find attached our PRI notice dated 25 May 2018 for your kind attention.
2. Please reply email to corene@crossbordersllc.com & huiting@crossbordersllc.com

Thank You.

CROSSBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.CA (SLP3379L)
Your Ref: SJH1289S

25 May 2018

FWD SINGAPORE PTE. LTD.
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986

BY EMAIL ONLY
motorclaims.sg@fwd.com

Attn: Motor Claims Department

URGENT

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
CLAIMANT: LIM KIAN HENG
TRAFFIC ACCIDENT ON 22 MAY 2018 AT 19:25 HRS ALONG GUILLEMARD ROAD INVOLVING VEHICLES NO. SLP3379L & SJH1289S

We are instructed by Lim Kian Heng to notify you of a road accident on 22 May 2018 at about 19:25 hrs along Guillemard Road involving our client's vehicle registration number SLP3379L and vehicle registration number SJH1289S driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Cadre Automobile
Address: No. 1 Kaki Bukit Avenue 6 #02-49
Autobay @ Kaki Bukit Singapore 417883
Contact: Mr Victor @ 6747 7618

Please liaise with the above workshop directly.

Yours faithfully

Amerjeet Singh

Email: corene@crossbordersllc.com /
hulting@crossbordersllc.com

encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

CONFIDENTIALITY CAUTION

THIS DOCUMENT IS FOR THE ADDRESSEES ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR PLEASE CONTACT US IMMEDIATELY.

CROSSBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

VEHICLE NO: SLP 3379L

MAKE & MODEL: Audi A5

DATE OF ACCIDENT	22 / 05 / 2018
TIME OF ACCIDENT	7.25 AM PM
LOCATION OF ACCIDENT	Guilleward Road
Exact Purpose use during accident	
NAME OF OWNER	Lim Kian Heng
TELP NO	
NRIC	S7105295H
CLAIM TYPE	OD / <u>THIRD PARTY</u> / Reporting Only
INSURANCE CO.	
TYPE OF COVERAGE	<u>Comprehensive</u> / Third Party / Third Party Fire & Theft
POLICY NO.	GA 241646/1
NAME OF DRIVER	As above / If No:
NRIC	
DATE OF BIRTH	22 / 02 / 1971
OCCUPATION	<u>Outdoor</u> / Indoor
DATE OF DRIVING PASS	19 / 11 / 2011
GENDER	<u>Male</u> / Female
CONTACT NO.	91963354 Office: Home:
ADDRESS	Blk 555 Woodlands Dr 53 #02-39 (S) 730555
DRIVER HAVE ANY OWN Vehicle	NO / If yes: Reg No:
RELATIONSHIP	Employee / If No:
WEATHER CONDITION	<u>Clear</u> / Raining / Other:
ROAD SURFACE	<u>Dry</u> / Wet / Other:
ANY INJURIES	No / If yes: Who? (Myself/owner)
CONTACT NO.	As above
POLICE REPORT	No / If yes: Where? MacPherson Police Post
VEHICLE B NO.	SJH 1289S
NAME	Han Siew Fong
CONTACT NO.	97611848
VEHICLE C NO.	
VEHICLE D NO.	
VEHICLE E NO.	
VEHICLE F NO.	
ANY WITNESS	
WITNESS CONTACT NO.	
Have you been approach by unknown person soliciting (s) offering accident claims assistance?	NO
	YES <u>NO</u>
PARTICULAR WORKSHOP	Sinc Motor Pte Ltd CADRE AUTOMOTIVE.
TELP NO	1 Kaki bukit ave 6 #02-1119.
CONTACT PERSON	Autobay @ kaki bukit
FAX NO.	Singapore 417883
	Telp : 67476106 (6 lines) HP 86121774.
	Fax: 67442368

DECLARATION

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate police liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand and acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/ are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurer/lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;

investigating the accident and/or my claims;

(ii) carrying out and/ or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers/lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder)/ Date & Time

Witnessed by Reporting Centre Personal

Sketch Plan



Describe Circumstances of the Accident

Refer to Police:
 T20180523/2062
 dd: 23/5/2018

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personal

Insurance Co. _____
 Vehicle No. _____ Date of accident _____
 Reporting Only
 Own Damage Claim
 Third Party Claim



**SINGAPORE
POLICE FORCE**



T/20180523/2063

Police Station Of Origin:
MacPherson NPP
54 Phipit Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

2 of 3
Report No. T/20180523/2063

CONTINUATION OF REPORT

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	HAN SIEW FONG	ID No.	S2737180F
Related Vehicle	SJH1289S (Car)	Contact No.	97611848
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	LIM KIAN HENG	ID No.	S7105295H
Related Vehicle	SLP3379L (Car)	Contact No.	91963354
Hospital/Clinic	SINGAPORE BRAIN SPINE NERVES CENTER	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	23/05/2018	Date Discharge	23/05/2018
No. of Days granted Medical Leave	14	Degree of Injury	Serious

Brief Details.

On 22/05/2018 at about 1825hrs, I was driving my car, SLP3379L along Gullermard road behind City Plaza. I was driving toward Tanjong Katong Road direction and saw a car, SJH1289S on my left coming out from City plaza drop off point. The car did not stop and I turn slightly to the right to avoid the accident. The car then collided into the rear left of my car. Due to the accident, the left rear portion and my left rear rim were damaged. We exchange particulars, took pictures of the damages and left. No police or ambulance at scene.

On 23/05/2018, I woke up and felt pain on my spine area. I went to Singapore Brain Spine Nerves Centre and was given 14 days of hospitalization leave from 23/05/2018 - 05/06/2018.



**SINGAPORE
POLICE FORCE**



T/20180523/2063

Police Station Of Origin:
MacPherson NPP
54 Pipit Road #01-82/84 SINGAPORE
370054
Tel No: 1800-7449999

3 of 3

Report No. T/20180523/2063

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 ANG KAH LUN	
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No.: 65476151	
Authentication Stamp NP168	

Signature Of Informant:
Date/Time: 23/05/2018 15:10
Classification Of Case:

SINGAPORE POLICE FORCE

SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Jun 2018 Edit Reg		25 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by adjuster]
Insured:	Han Siew Fong, ID: S2737190F			
Main Claimant:	LIM KIAN HENG, ID: S7105295H			
Vehicle Reg. No.:	SLP3379L	Date of Loss:	22/05/2018 19:00 - :59 [105 Months and 15 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 1201800006319	Policy/Cover Note No.:	PNPV2017-00004770 (Comprehensive)	
Vehicle Reg. No. (Insured):	S3H1289S	Policy No. (Claimant):		
		Excess:		
Repairer:	Cadre Automobile (HQ) NO. 1 KAKI BUKIT AVENUE 6, #02-49 AUTOBAY, 417883 Kaki Bukit - Tel:			
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 11/06/2018]			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SLP3379L (1201800006319)
[SJH1289S]
TP
LIM KIAN HENG
May 22 2018 7:00PM
[Han Siew Fong]
Cadre Automobile

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="button" value="v"/>
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
2	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
3	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
4	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
5	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
6	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
7	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
8	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
9	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
10	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
11	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
12	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
13	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
14	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
15	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
16	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
17	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
18	31/05/18 17:44	General View	 Load JPG	<input checked="" type="checkbox"/>
19	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
20	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
21	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
22	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
23	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
24	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
25	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	31/05/18 17:46	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
39	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
40	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
41	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
42	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
43	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
44	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
45	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
46	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
47	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
48	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
49	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
50	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
51	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
52	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
53	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
54	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
55	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
56	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
57	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
58	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
59	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
60	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
61	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
62	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
63	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
64	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
65	31/05/18 17:46	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	01/06/18 09:07	Insured GIA Report		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18009570/GZ4D3E2

Date: 04/06/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00004770
 Claimant Vehicle No: SLP3379L Insured Vehicle No: SJH1289S
 Date of Loss: 22/05/2018 Nature of Claim: TP Claim No: 1201800006319

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP3379L
 Make & Model: AUDI A5, 3.0 (A) Engine No: CDN049005
 Reg. Date: 07/08/2009 (Man. Year: 2009) Chassis No: WAUZZZ8T3AA000969
 Colour: Black Odometer: 92369 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/05/2018
 Date Inspected: 28/05/2018 Inspected At: Cadre Automobile (HQ)
 NO. 1 KAKI BUKIT AVENUE 6, #02-49
 AUTOBAY
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$12,500.00 - \$13,500.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Jun 2018)
Parts: M1-COUPE	AUDI A5 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLP3379L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >