

Surveyor: 60 ASSIGNMENT (Office)From (Person): Yee Pei Li of EGI Date/Time: 25/5/18 @ 4:16pm

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLX 806SS Insured: SJH 8006Xat Workshop m/s: Wee Hue Auto Tel: 6858 0019of 19 Kimchuan terracePolicy No: _____ Claim No: SJH 8006X

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23/05/2018

(Client's Record) _____

CA / REV / REP. / REV 24 HRS 1up 28/05/2018 H.O.D. Endorsement _____Date/Time: 5:01pm @ 25/5/18 Person Contacted: Kiat Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SLX 806SS - NA/INC/8009449/r3 DOA: 23/5/18
	SJH 8006X - X
28/5/18	Dis mantled.

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Friday, 25 May 2018 4:16 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SJH8006X / TP : SLX8065S/LKK / DOA : 23/05/2018
Attachments: OI - 3RD VEH SJH8006X - SAS.pdf; 2ND VEH SLX8065S - SAS.pdf; 1ST VEH SLK1803T - SAS.pdf; 2ND VEH SLX8065S - PRI NOTICE.pdf

Dear Catherine,

We have rejected to their PRS list, please assist to conduct this survey **VISION LAW LLC**,

ADDRESS : **WEE HOE AUTO SERVICE**
19 KIM CHUAN TERRACE
SINGAPORE 537041

PERSON TO CONTACT : KIAT @ 6858 0019

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Try to obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please update the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

Company Registration No. 200721148H

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D/O MUNIANDY
SEGA PARAM
ONG BOCK KEE
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YINGXIAN SELWYN

Head Office:
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Branch:
490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

HEAD OFFICE:

TEL : 65342811 (Hunting)
FAX : 65356802 (General)

E-MAIL: annatan@visionlawllc.com

BRANCH

TEL : 63580703
FAX : 63580448(conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to **HEAD OFFICE** for this matter

OUR REF: AKN-atv-INS-W30-SLX8065S-2018 - [please reply to: annatan@visionlawllc.com](mailto:annatan@visionlawllc.com)
YOUR REF: SJH8006X

25 May 2018

ERGO INSURANCE PTE LTD
5 Temasek Boulevard
#04-01 Suntec Tower One
Singapore 038985
Attn: Motor Claims Department

BY FAX 68299248 & EMAIL
claims@ergo.com.sg

Dear Sirs

NAME OF CLAIMANT: AUTOHOME TRADING
VEHICLE NUMBER: SLX 8065 S
YOUR INSURED VEHICLE NUMBER: SJH 8006 X
ACCIDENT ALONG PIE (EUNOS FLYOVER) TOWARDS CHANGI AIRPORT ON 23 MAY 2018
AT ABOUT 2150HOURS

We refer to your email dated 25 May 2018 wherein there is no agreement to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

WEE HOE AUTO SERVICE
19 KIM CHUAN TERRACE
SINGAPORE 537041
Contact Person: **TEL: 6858-0019 (KIAT)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

(Head Office)

cc. **SLX 8065 S** - By fax 6858-0195 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature) :

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
ERGO INSURANCE PTE LTD		Ref: CS3/EGI18009571/Gz4d3e2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER		Date: 04-06-2018	
FIVE SINGAPORE 038985		Code: EGI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SJH 8006X	Veh. Inspected	SLX 8065S
Policy No.		Coverage (\$)	0.00
Claim No.	SJH8006X	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	25/05/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH	c.c	1798
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	JTDGG20W30J009151	Colour	SILVER
Odometer	7656 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	9 mm
L/H Front Tyre	195/65 R15	GOODYEAR	9 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	9 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.			
5. General Information			
Accident Date	23/05/2018	Inspect Date / Time	28/05/2018 (12:30 PM)
Survey held at	WEE HOE AUTO SERVICE 19 KIM CHUAN TERRACE SINGAPORE 537041		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,500-\$9,500			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

Report Ref No. CS3/EGI18009571/Gz4d3e2

Inspected By



XING GUO QIANG

M. MATAI, AMSAE-A

Automotive Assessor



K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.