

ASS. REC. BY: Adrian King

REF:

C03/MSH18009582/Avb 4/2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SKZ 5091L

Policy No. 28876292 Qmx

Claims No. 559245

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

PC 2328L Yr Regn: 2013/Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Mini Bus.

Make:

Nissan Urban. c.c. 2753.

Colour:

Silver. A/C: Insured / Std / NI / NA

Sp. Reading:

212334. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1TGFE2520/83872

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195 R15C

R: 195 R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kapsen.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

22/5/18

D.O.I.

25/05/18

Survey held at

Fastech.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 07516

PC 2328L - NM / C/L18009352/h4

DUA: 22052018

SKZ 5091L - Q3/AQ/L18009354/h13

DUA: 22052018

28/5/18 Email GIA to Iryani

12/6/18 Adrian confirmed LS \$6000 (Red 8197.55, 5773)

12/6/18 Send preli revised by merimen

RECEIVED 12 JUN 2018

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

12/6 - typist

Report Format:

merimen

Lump Sum / I.B.I: (\$

6000p

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

200

Transportation:

S + RS \$

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2018		28 May 2018 15:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

ANG SIEW ENG RACHEL, ID: S7020975F, Tel: +6597980030, Email: MOSHI2606@YAHOO.COM

Main Claimant:

BOON HONG TRANSPORT SERVICES, Co. Reg. No.: S29805508

Vehicle Reg. No.:

PC2328L

Claim Type:

TP / 559245

Vehicle Reg. No. (Insured):

SKZ5091L

Repairer:

Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pel - 6643 1307]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/05/2018]

Driver/Custodian (Insured):

ANG SIEW ENG RACHEL (47 / Female), NRIC: S7020975F, Tel: +6597980030

Adj Asg. Remarks:

DIRECT SURVEY DONE BY LKK AUTO ON 25.05.2018

Date of Loss:

22/05/2018 07:00 - :59
[52 Months and 29 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

28876292QMX (Comprehensive)
Coverage: 26/01/2018 - 25/01/2019

Policy No. (Claimant):

Excess:

S\$500.00

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Iryani Amin <iryani_amin@sg.msig-asia.com>
Sent: Monday, 28 May 2018 3:26 PM
To: Veron Chen (LKKAUTO)
Cc: SUR; KKLau; Accounts (LKKAUTO)
Subject: RE: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 22/5/18, PC 2328L (TP VEHICLE), SKZ 5091L (OI VEHICLE)

Dear Veron Chen ,

This is our claim reference number : M559245

Have a nice day

Iryani Binte Amin
Admin Officer, Claims Services (Motor)
Direct line +65 6594 2555 | Direct fax +65 6225 7402 | iryani_amin@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us



A member of **MS&AD** INSURANCE GROUP

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Monday, 28 May, 2018 10:20 AM
To: Iryani Amin <iryani_amin@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>; KKLau <kklau@lkkauto.com>; Accounts (LKKAUTO) <account@lkkauto.com>
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 22/5/18, PC 2328L (TP VEHICLE), SKZ 5091L (OI VEHICLE)

Dear Iryani,

Please be informed that we had inspected the vehicle PC 2328L at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 25/5/18.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 28 May 2018 10:20 AM
To: iryani_amin@sg.msig-asia.com
Cc: SUR; KKLau; Accounts (LKKAUTO)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 22/5/18, PC 2328L (TP VEHICLE), SKZ 5091L (OI VEHICLE)
Attachments: GIA.pdf

Dear Iryani,

Please be informed that we had inspected the vehicle PC 2328L at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 25/5/18.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 12 Jun 2018

Preliminary Advice

Insured Vehicle No	: SKZ5091L		
TP Vehicle No	: PC2328L	Accident Date	: 22/05/2018
Make	: NISSAN URVAN	Assignment Date	: 28/05/2018
Date of Inspection	: 25/05/2018	Est. Duration of Repair	: 6.00
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,197.55
Revised Amount (est)	:S\$	6,000.00 (Lump Sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/05/2018 11:14
Date Of Accident	22/05/2018 07:50
Exact Location Of Accident	ALONG THOMSON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC2328L
Insured/Policyholder	
Name Of Registered Owner	M/S BOON HONG TRANSPORT SERVICES
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91773881

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMB1SN3085001700
Cover Note Number	-

Driver

Name of Driver	TEO KIANG MENG
NRIC No	S0853922G
Date Of Birth	18/04/1950
Occupation	OUTDOOR
Date Of Driving Pass	18/11/1976
Driving Experience	41 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91773881
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 204 SERANGOON CENTRAL #05-120
Postcode	550204
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : KHONG HAR MUI
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ5091L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJZ6003Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TEO KIANG MENG
Approximate Age
Injuries Sustain BODY
Injured person in which vehicle? PC2328L
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name KHONG HAR MUI
Approximate Age
Injuries Sustain BODY
Injured person in which vehicle? PC2328L
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/5/2018 at 7.50am, I was driving my vehicle A along Thomson Road. I stop my car due to in front vehicle stop. Suddenly vehicle B hit on my rear portion. There were 3 cars involving in an accident. I felt double impact.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Fastech Auto Ptd Ltd

1 Kaki Bukit Avenue 6, #01-46/48/50, Autobay, Singapore 417883

H/P: 9487 7074

Tel: 6741 7244, 6746 5405

Fax: 6745 8520, 6746 5786

Email: general@fastechauto.com.sg

TPMS 19.
Veron

JN1764E2520793872

Vehicle No.: PC2328L

Vehicle made & model: NISSAN URVAN

Qty	List Items:	Amount \$
1	Tailgate <i>distorted</i>	2,264.60 ✓ <i>2101.40</i>
1	Tailgate logo <i>new</i>	59.70 ✓
1	Tailgate sticker "3.0 DTI" <i>new</i>	101.30 <i>55</i>
1	Tailgate sticker "URVAN" <i>new</i>	59.70
1	Tailgate outer moulding <i>cracked</i>	254.70 ✓
1	Tailgate wiper motor <i>not new</i>	431.60 X
1	Tailgate inner lock <i>damaged</i>	261.20 ✓
1	Tailgate inner lock actuator <i>not new</i>	241.60 X
1	Tailgate inner board <i>torn</i>	280.90 ✓
1	Tailgate lock striker <i>not new</i>	51.50 X
2	Tailgate hinges - L/R @ 62.20 <i>not new</i>	124.40 X
2	Tailgate dampers - L/R @ 189.90 <i>not new</i>	379.80 X
2	Tailgate side stoppers - L/R @ 42.20 <i>cracked</i>	84.40 X
2	Taillamps - L/R @ 209.80 <i>cracked</i>	419.60 ✓
1	Taillamp filler panel - LH <i>Repair</i>	504.60 X
1	Rear bumper <i>Distorted</i>	680.50 ✓
2	Rear bumper side holders - L/R @ 42.20 <i>new</i>	84.40 ✓
1	Rear end panel <i>Dented</i>	441.80 ✓
1	Rear end panel inner member <i>Repair</i>	512.60 X
1	Rear end panel top moulding <i>not new</i>	192.60 X
1	Rear exhaust silencer <i>Best</i>	876.90 ✓
1	Rear exhaust mounting <i>not new</i>	42.60 X
1	Rear fender - LH <i>Repair</i>	1,793.40 X
1	Rear step panel <i>Best</i>	280.60 ✓
1	Rear spare wheel carrier <i>not new</i>	286.90 X
1	Rear spare wheel carrier holder <i>not new</i>	82.60 X
Sub-total		10,794.50
Less 10%		1,079.45
Total List		9,715.05

5856.40.
5270.76

Vehicle No.: PC2328L

Vehicle made & model: NISSAN URVAN

Special Nett items:

1 set	Tailgate glass sealant	<i>{ New</i>	80.00 <i>60</i>
1 set	Tailgate glass foam tape		65.00 <i>30</i>
15	Tailgate inner board clips @ 3.50	<i>New</i>	67.50 <i>30</i>
1 set	Rear bumper clip	<i>New</i>	30.00 ✓
1 set	Rear reverse sensor	<i>Damaged</i>	280.00 <i>20</i>
1	Rear sticker "70 KM/H"	<i>{ New</i>	10.00 ✓
1 set	Rear sticker "8 PAX"		10.00 ✓
Total Special Nett			542.50

Labour Charges:

To check rear electrical wiring	<i>1930</i>	50.00 <i>30</i>
To remove, refix tailgate glass		180.00 <i>120</i>
To remove, refix rear interior trims		120.00 <i>40</i>
To remove, refix rear exhaust systems		100.00 <i>80</i>
To remove, refix rear reverse sensor		60.00 <i>40</i>
Transfer & install tailgate mechanical & electrical to new tailgate		180.00 <i>80</i>
To respray undercoating		150.00 <i>40</i>
To respray painting and etc		1,300.00 <i>700</i>
Panel beating, cut, weld, remove & replacing above parts		1,800.00 <i>800</i>
Total Labour		3,940.00

total: 7570.76
n/s. 6K
06 Days.

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 14,197.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sig *Page 2 of 2*

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 May 2018		28 May 2018 15:27 Edit Adj Rpt	S\$6,000.00 Edit Estimates	S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ANG SIEW ENG RACHEL , ID: S7020975F, Tel: +6597980030, Email: MOSHI2606@YAHOO.COM									
Main Claimant: BOON HONG TRANSPORT SERVICES , Co. Reg. No.: 52980550B									
Vehicle Reg. No.: PC2328L		Date of Loss: 22/05/2018 07:00 - :59	[52 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type: TP / 559245		Policy/Cover Note No.: 28876292QMX (Comprehensive)	Coverage: 26/01/2018 - 25/01/2019						
Vehicle Reg. No. (Insured): SKZ5091L		Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 27/06/2018]									
Driver/Custodian (Insured): ANG SIEW ENG RACHEL (47 / Female), NRIC: S7020975F, Tel: +6597980030									
Adj Asg. Remarks: DIRECT SURVEY DONE BY LKK AUTO ON 25.05.2018									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC2328L (559245)

[SKZ5091L]

TP

BOON HONG TRANSPORT SERVICES

May 22 2018 7:00AM

[ANG SIEW ENG RACHEL]

Fastech Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	28/05/18 15:23	Accident Statement From: SC - Reg. No: SKZ5091L, Claimant: ANG SIEW ENG RACHEL					Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	12/06/18 11:27	Adjuster Immediate Advice					Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
2	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
3	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
4	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
5	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
6	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
7	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
8	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
9	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
10	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
11	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
12	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
13	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
14	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
15	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
16	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
17	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
18	11/06/18 17:44	General View					Load JPG	<input checked="" type="checkbox"/>	
19	11/06/18 17:44	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
20	11/06/18 17:44	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
21	11/06/18 17:44	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
22	11/06/18 17:44	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
23	11/06/18 17:44	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
24	11/06/18 17:44	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
25	11/06/18 17:44	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
26	11/06/18 17:44	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
27	11/06/18 17:44	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
28	11/06/18 17:44	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
29	11/06/18 17:44	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
30	11/06/18 17:44	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
31	11/06/18 17:44	Reinspection Photo					Load JPG	<input checked="" type="checkbox"/>	
32	11/06/18 17:44	Reinspection Photo					Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
66	11/06/18 17:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/05/18 15:23	TPD PC2328L GIA REPORT From: SC - Reg. No: SK25091L, Claimant: ANG SIEW ENG RACHEL	Load PDF	
2	28/05/18 15:26	DIRECT SURVEY DONE BY LKK AUTO	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18009582/AVBQ2

Date: 13/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28876292QMX

Claimant Vehicle No : PC2328L

Insured Vehicle No : SKZ5091L

Date of Loss: 22/05/2018

Nature of Claim: TP

Claim No: 559245

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC2328L

Make & Model: NISSAN URVAN, 3.0 D MICROBUS 4DR 5MT ABS
AIRBAG (M)

Engine No: ZD30313882K

Reg. Date: 23/12/2013 (Man. Year: 2012)

Chassis No: JN1TG4E25Z0793872

Colour: Silver

Odometer: 212334 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: KAPSEN 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,257.55	5,640.76	4,616.79	45.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,940.00	1,930.00	2,010.00	51.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,197.55	7,570.76	6,626.79	46.68
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	14,197.55	6,000.00	8,197.55	57.74
+ GST 7.00/7.00% (S\$)	993.83	420.00	573.83	57.74
Nett Amount (S\$)	15,191.38	6,420.00	8,771.38	57.74

INSPECTION

Date of Assignment: 28/05/2018

Date Inspected: 25/05/2018 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Jun 2018)	
Parts:	N/A	NISSAN URVAN 3.0 D MICROBUS 4DR 5MT ABS AIRBAG (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC2328L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	2,264.60 FL	*2,101.40 FL
2	1		*TAILGATE LOGO	Necessary	59.70 FL	*59.70 FL
3	1		*TAILGATE STICKER 3.0 DTI	Necessary	101.30 FL	*55.00 FL
4	1		*TAILGATE STICKER URVAN	Necessary	59.70 FL	*59.70 FL
5	1		*TAILGATE OUTER MOULDING	Cracked	254.70 FL	*254.70 FL
6	1		*TAILGATE WIPER MOTOR	Not Necessary	431.60 FL	*- FL
7	1		*TAILGATE INNER LOCK	Damaged	261.20 FL	*261.20 FL
8	1		*TAILGATE INNER LOCK ACTUATOR	Not Necessary	241.60 FL	*- FL
9	1		*TAILGATE INNER BOARD	Torn	280.90 FL	*280.90 FL
10	1		*TAILGATE LOCK STRIKER	Not Necessary	51.50 FL	*- FL
11	2		*TAILGATE HINGES -L/R	Not Necessary	124.40 FL	*- FL
12	2		*TAILGATE DAMPERS -L/R	Not Necessary	379.80 FL	*- FL
13	2		*TAILGATE SIDE STOPPERS -L/R	Not Necessary	84.40 FL	*- FL
14	2		*TAILLAMP -L/R	Cracked	419.60 FL	*419.60 FL
15	1		*TAILLAMP FILLER PANEL -LH	Repair	504.60 FL	*- FL
16	1		*REAR BUMPER	Distorted	680.50 FL	*680.50 FL
17	2		*REAR BUMPER SIDE HOLDER -L/R	Necessary	84.40 FL	*84.40 FL
18	1		*REAR END PANEL	Dented	441.80 FL	*441.80 FL
19	1		*REAR END PANEL INNER MEMBER	Repair	512.60 FL	*- FL
20	1		*REAR END PANEL TOP MOULDING	Not Necessary	192.60 FL	*- FL
21	1		*REAR EXHAUST SILENCER	Bent	876.90 FL	*876.90 FL
22	1		*REAR EXHAUST MOUNTING	Not Necessary	42.60 FL	*- FL
23	1		*REAR FENDER -LH	Repair	1,793.40 FL	*- FL
24	1		*REAR STEP PANEL	Bent	280.60 FL	*280.60 FL
25	1		*REAR SPARE WHEEL CARRIER	Not Necessary	286.90 FL	*- FL
26	1		*REAR SPARE WHEEL CARRIER HOLDER	Not Necessary	82.60 FL	*- FL
27	1		*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
28	1		*SET TAILGATE GLASS FOAM TAPE	Necessary	65.00 FS	*30.00 FS
29	15		*TAILGATE INNER BOARD CLIPS	Necessary	67.50 FS	*30.00 FS
30	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
31	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
32	1		*REAR STICKER 70KM/H	Necessary	10.00 FS	*10.00 FS
33	1		*SET REAR STICKER 8 PAX	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,337.00	6,226.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,079.45	585.64
Total Parts (\$\$)	10,257.55	5,640.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE,REFIX TAILGATE GLASS	New	180.00	120.00
3	TO REMOVE,REFIX REAR INTERIOR TRIMS	New	120.00	40.00
4	TO REMOVE,REFIX REAR EXHAUST SYSTEMS	New	100.00	80.00
5	TO REMOVE,REFIX REAR REVERSE SENSOR	New	60.00	40.00
6	TRANSFER & INSTALL TAILGATE MECHANICAL & ELECTRICAL TO NEW TAILGATE	New	180.00	80.00
7	TO RESPRAY UNDERCOATING	New	150.00	40.00
8	TO RESPRAY PAINTING AND ETC	New	1,300.00	700.00
9	PANEL BEATING ,CUT,WELD ,REMOVE & REPLACING ABOVE PARTS	New	1,800.00	800.00
Gross Labour Cost (S\$)			3,940.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >