

Your Ref: SS/10289/117

Date: 27<sup>th</sup> June 2018

Our Ref: CS1/LAW18009584/Uqbs2

**M/s Alan Shankar & Lim LLC**151 Chin Swee Road  
#09-16 Manhattan House  
Singapore 169876

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SDS 182K INSURED VEHICLE: GBC 2795L ACCIDENT DATE: 24/11/2015**

We thank you for your instruction on 24/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SDS 182K from M/s Priority Services.
- b) Survey report by Delta-V Consultant with colour photographs.
- c) Singapore Accident Statement of Vehicles SDS 182K and GBC 2795L.
- d) Colour damaged vehicle photographs of SDS 182K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -  
Registration Number : SDS 182K  
Make & Model : BMW 523i  
Year of Registration : 2011  
Chassis Number : WBAFP32000C864286  
Engine Capacity : 2497 cc
2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.