

22/03/2018

ASS. REC. BY:

REF: CS3 / CTU8009611 / Tiz4ber Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

Merimen

From (Person):

Chong Boon Sen

of

CTU

Date/Time: 25052018 1257pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 7894M

Insured:

GZ 7701U

at Workshop m/s

TJ Car Care

Tel:

9757 5515

of

Blk 1010 Bukit Merah Lane 3 #01-115

Policy No:

DMCVSN 1657211701

Claim No:

SNM18D 02565002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21052018

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

25052018

1007am

Person Contacted:

Mr. Lim

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLU 7894M - NGA / HP18009474 / Y

DA: 21052018

GZ 7701U - X

Tanjin

CTI

From: _____
 Estimated by: _____
 UD ☒ WS / TP RES / OD RES / EVA / BIV / MV
 Insured / Not Insured
 Policy No. _____
 Claims No. _____
 Sign Insured _____
 Client's Period _____
 Make of Veh _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value _____
 IDAC Accident Report Consistent? Yes or No _____
 GLA / PRS Seen Consistent? Yes or No _____
 Est. Repairs days Res. Yes or No _____
 Lum. Sat. % 3 Val: Yes or No _____

CA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date _____ Person Contacted _____

SLU 7894M
 7017 Dec
 14 Cycles / Bus / Van / Lorry / Taxi / Prime Mover
 Truck / Trailer or _____

Make Mazda 3
 Colour white
 Sp. Reading 12489
 1496
 Insured / Std / NI / NA
 Insured / Std / NI / NA

Eng. No. _____
 C/T No. 3M6BN24A8J0192208
 Gen. Cond. Good / Fair / Poor / Burnt
 Steering Inorder / Jammed / Leaked / Burnt or
 Brake Inorder / Jammed / Leaked / Burnt or
 Mod. Nil / STD / STD A/Rim or
 Tyre Size F: 205/60R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front 6 R/Bal 6 mm
 L/Bal 6 mm
 D.O.A. 28/5/18 @ 1330

Survey held at BTTS Car Lane
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date-Time Action Instruction Arint GUA 06510

* Repair Estimate : S\$ 3500 - 4500

* 3 days

31/5/18 Submit PRS Report

RECEIVED 01 JUN 2018

Pre-Trip Check ☐ : Preli. Report
☐ : Final Report

Days Of Repair:
 Resurvey No. of Trip:

Survey Fee

Add Fee: ☐ \$
☐ \$
☐ \$
☐ \$

150
 150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 May 2018		25 May 2018 12:57 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	VANTAGE CONSTRUCTION PTE LTD, Co. Reg. No.: 199003845N		
Main Claimant:	KEE MEI TENG JASMINE, ID: S8133302E		
Vehicle Reg. No.:	SLU7894M	Date of Loss:	21/05/2018 12:00 - :59
Claim Type:	TP / SNM18D02565C02	Policy/Cover Note No.:	DMCVSN1657211701 (Third Party Only)
Vehicle Reg. No. (Insured):	GZ7701U	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	TJ Car Care Services (HQ) Blk 1010, #01-115, Bukit Merah Lane 3, 159724 Bukit Merah - Tel: 62768567		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/06/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Mr. Lim

9757 5515

Your ref : SNM18D02565C02
Our client's vehicle / ref: SLU 7894M ; GT/sy/ms
Date : 25 May 2018

China Taiping Insurance (Singapore) Pte Ltd

By Email Only

Dear Sirs,

DATE OF ACCIDENT: 21 MAY 2018
NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our list of surveyors as appended below:-

S/N	Name of Surveyor	Company Name
1.	Andrew How	Prominent Appraiser Services Pte Ltd
2.	Ananda Kumar	United Appraisal & Management Pte Ltd
3.	Tan Ee Cherng	United Appraisal & Management Pte Ltd
4.	T. Thiagarajan	ST Appraisal Services
5.	Francis Ng	Prestige Appraisal Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which we will commence repairs thereafter without any further notice or reference to you. Please also let us know if you required a Post-Repair Survey/Inspection for our client's consideration. Please be informed that the said vehicle can be surveyed / inspected at:

Workshop : TJ Car Care Services
Address : Block 1010 Bukit Merah Lane 3, #01-115, Singapore 159724
Contact : Mr Lim Boon Leong (h/p: 9757 5115)

Kindly acknowledge upon inspection in the acknowledgement box below.

Yours sincerely,



Acknowledgement

This is to confirm that I _____ [Full Name of Surveyor] of _____ [Surveyor's Company] have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date

(b) Pre- Repair Survey/Inspection (after dismantling) on _____ [Date] at _____ [Time].

Signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date

(c) Post - Repair Survey/Inspection on _____ [Date] at _____ [Time].

Signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/05/2018 15:58
Date Of Accident	21/05/2018 12:35
Exact Location Of Accident	ALONG MACPERSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU7894M
Insured/Policyholder	
Name Of Registered Owner	GOLOBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	JASMINE@PICODENSHI.COM.SG
Mobile Phone No	(LOCAL) +65-97527818
Alternative Phone No	OFFICE-97527818
Vehicle Particulars	
Manufacturer	MAZDA
Model	MAZDA3 HATCHBACK 1.5 AT DELUXE EU6
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18VC0034/VPZ/R03
Cover Note Number	

Driver

Name of Driver	KEE MEI TENG, JASMINE (JI MEITING, JASMINE)
NRIC No	S8133302E
Date Of Birth	02/11/1981
Occupation	OUTDOOR
Date Of Driving Pass	20/01/2003
Driving Experience	15 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97527818
Fax Number	
Contact Number	OTHERS-97527818
EMail Address	JASMINE@PICODENSHI.COM.SG

Address	BLK 121 PCTONG PASIR AVENUE 1 #10-285
Postcode	350121
Was driver an employee of the Insured's Company	NO
If No. Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ7701U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LEE WAI KONG
NRIC/Passport Number	S1740236F
Contact Number	94783055
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	KEE MEI TENG, JASMINE (JI MEITING, JASMINE)
------	---



Approximate Age	
Injuries Sustain	SLIGHT INJURY
Injured person in which vehicle?	SLU7894M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	


Accident Sketch Plan

IMPORTANT NOTICE

SKETCH PLAN

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be submitted by the Policyholder under the Accident Claim.
- Information provided must be as correct and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind the policy.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any Police Report will be collected by the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the QIA Records Management Centre maintained by the General Insurance Association of Singapore (QIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
- I consent under the Personal Data Protection Act (PDPA)
 - understand, acknowledge, agree and consent that
 - My insurer, my reinsurer and the General Insurance Association of Singapore ("QIA") may be permitted to collect, use, disclose and process my personal data (personal information set out in this form) and any other personal information provided by me or released by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' Insurance Brokers, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purposes of)
 - managing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - investigating the accident under my claim;
 - carrying out and/or dealing with my instructions or responding to any queries by me;
 - administering my claim (including the making of correspondence, statements, inquiries, reports or notices to me, which could involve disclosure of certain personal data about me to third parties delivery of the same as well as on the subject matter of any correspondence (packages), email;
 - complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - for purposes for "Purposes";
 - if I wish to who have insured vehicle(s) involved in this accident and the Insurers' Insurance Brokers, may be permitted to collect, use, disclose and process my Personal Information for one or more of the above Purposes; and
 - my Personal Information may be disclosed by any of the Insurers and/or QIA to their third party service providers or agents (including their Insurance Brokers), which may be used outside of Singapore, for one or more of the above Purposes.



Date of Submission of Form to the Insurer/Date of Issue

Sketch Plan

Along Macpherson Road

A = SLU 7894M

B = GZ 7701U

Traffic Light



Macpherson Road

Accident Sketch Plan

Describe Circumstance of the Accident *

I was driving on the extreme right 2nd lane, 2nd vehicle. When the 1st car move turn left, the green arrow change to red and I stop at the stop line. I look at my rear mirror and realised that the driver was not looking at the front traffic, he was meddling with his items at the passenger seat, the next minute I realised he had bang onto the back of my car.

Declaration


I hereby declare the foregoing particulars are true in every respect.


Police Officer's Signature



*

Driver's Signature of driver is as the undersigned / Date & Time


Witnessed by Reporting Person

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 May 2018		25 May 2018 12:57 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	VANTAGE CONSTRUCTION PTE LTD , Co. Reg. No.: 199003845N		
Main Claimant:	KEE MEI TENG JASMINE , ID: S8133302E		
Vehicle Reg. No.:	SLU7894M	Date of Loss:	21/05/2018 12:00 - :59 [5 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D02565C02	Policy/Cover Note No.:	DMCVSN1657211701 (Third Party Only)
Vehicle Reg. No. (Insured):	GZ7701U	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	TJ Car Care Services (HQ) Blk 1010, #01-115, Bukit Merah Lane 3, 159724 Bukit Merah - Tel: 62768567		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 06/06/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU7894M (SNM18D02565C02)
[GZ7701U]
TP
KEE MEI TENG JASMINE
May 21 2018 12:00PM
[VANTAGE CONSTRUCTION PTE LTD]
TJ Car Care Services

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print			
1	22/05/18 17:29	Accident Statement								Load HTM				
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print			
1	22/05/18 16:58	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
2	22/05/18 16:58	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
3	22/05/18 16:58	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
4	22/05/18 16:58	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
5	22/05/18 16:58	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
6	22/05/18 16:58	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
7	22/05/18 16:58	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
Documentation									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print			
1	22/05/18 17:28	Sketch Plan [Linked Accident Report Documents]								Load TIF				
2	22/05/18 17:29	Driver's NRIC + Driving License [Linked Accident Report Documents]								Load TIF				
3	22/05/18 17:29	Certificate of Insurance [Linked Accident Report Documents]								Load TIF				
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)								Thumbnail	Print			
1	25/05/18 12:56	PRS								Load PDF				
2	25/05/18 12:56	OI GIA REPORT								Load PDF				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	31/05/18 17:28	LKKPhotosIn6-1.pdf								Load PDF				

Linked Accident Report Documents

View

View in Browser

Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print
1	22/05/18 17:29	Accident Statement								Load HTM	

Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)								Thumbnail	Print
1	22/05/18 16:58	Accident Photo								Load JPG	<input checked="" type="checkbox"/>
2	22/05/18 16:58	Accident Photo								Load JPG	<input checked="" type="checkbox"/>
3	22/05/18 16:58	Accident Photo								Load JPG	<input checked="" type="checkbox"/>
4	22/05/18 16:58	Accident Photo								Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
5	22/05/18 16:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	22/05/18 16:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	22/05/18 16:58	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	22/05/18 17:28	Sketch Plan Sketch Plan	1	Load TIF	
2	22/05/18 17:29	Driver's NRIC + Driving License	1	Load TIF	
3	22/05/18 17:29	Certificate of Insurance	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118009611/T1Z4BE2

Date: 04/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1657211701

Claimant Vehicle
No: SLU7894MInsured Vehicle
No: GZ7701U

Date of Loss: 21/05/2018

Nature of Claim: TP

Claim
No: SNM18D02565C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU7894M

Make & Model: MAZDA 3, 1.5 HATCHBACK DELUXE EU6 (A)

Engine No: P520484441

Reg. Date: 14/12/2017 (Man. Year: 2017)

Chassis No: JM6BN24A8J0192268

Colour: White

Odometer: 12489 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/05/2018

Date Inspected: 28/05/2018 Inspected At:

TJ Car Care Services (HQ)
Blk 1010, #01-115, Bukit Merah Lane 3
Singapore 159724

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jun 2018)
Parts:	144	MAZDA 3 1.5 HATCHBACK DELUXE EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU7894M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >