

INS. CASE OWNER:

CC 6 /AIG1800LKK:
IDAC:

Surveyor:

Bryan

DOI:

ASSIGNMENT

27/5/18

Date / Time:

15/5/18

Registered in Merimen:

15/5/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHT 1213C

Name of Insured:

AHMAD DAMRI

Insured Tel No.:

HP:

87225874

Excess Sec II :SS

D.O.A.:

18/5/18

Is driver the owner?

(☒ YES / NO)

Nature of Accident:

Claim No.:

178096057756

Policy No.:

700485656-01

Make / Model:

MERLEDES

Place of Accident:

WOODMAN ST 8x UP

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: ☒ YES / NO)OI GIA REPORT: ☒ YES / NO : TP GIA REPORT: ☒ YES / NO

Insured Liability: %

Final ? Yes / No

GBF 8866K

INSRS:

WSP:

Tel:

Liability:

RMKS:

Tan
Lim

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:


Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
<u>16/5/18</u> <u>Ather</u>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

RECEIVED 31 MAY 2018



PRELIMINARY ADVICE		Date/Time:	Sent By:	
FINALIZATION		Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$S	() days	Reduction:	%
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 0	(Agreed / Assessed)	BOLA S/N No.:	24
Repair Cost:	\$S			If NO or B 28, Ass. Lia:
Loss of Rental (LOR):	\$S	() days		
Loss of Use (LOU):	\$S	(\$ x days)		
Loss of Income (LOI):	\$S	(\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]		
GIA/LTA Search:	\$S			
Medical:	\$S			
Disbursement:	\$S	(e.g. Tow/ Independent)		
Legal Cost:	\$S			
Total:	\$S	Global Sum \$S:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$S	Name 1:		
Payee 2: (Strike if N.A.):	\$S	Name 2:		
Payee 3: (Strike if N.A.):	\$S	Name 3:		

COPY SENT 17/6/18

1) Claim status: Normal/Reject/Private Settle
 2) Report Format: TP
 3) Survey fee: ¥320 T+20.

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: G3F 8866 K Yr Regn: 2016 / Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV200 C.G. 1461Colour: White A/C: Insured / Std / NI / NASp. Reading: 48200 T/Radio: Insured / Std / NI / NAEng/No: K9KC400D056154C/No: VSKYBAM2020135771Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 175 / 70 R14CR: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Goodyear

Front

Rear

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 18/05/2018 D.O.I. 25/05/2018Survey held at Tan Lim De Ju LaneDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>AIG 8611313C</u>
	<u>45: +650 (RBD: +64650 50%)</u>

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Add Fee: ☐ : Site Insp (\$

Transportation: _____

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

)

Report Format : _____

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18009613/Deb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 28-05-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGT 1313C	Veh. Inspected	GBF 8866K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/05/2018	Inspection Date	25/05/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SGT1313C
Date of Accident : 18 May 2018

Messrs Ten Dollar Salon Hub

Date : 23 May 2018

Estimate To Repair GBF8866K - NISSAN NV200 1.5L MT ABS AIRBAG 2WD 6
Chassis No : VSKYBAM20Z0135771

S/No	Quantity	Description	Amount
01	1 pc	<u>LIST ITEMS</u> rear bumper <i>deformed</i>	\$ 450.00 ✓
02	1 pc	n/s rear bumper reflector <i>NH</i>	\$ 45.00 X
			\$ 495.00
		Less 30 %	\$ 148.50
			\$ 346.50
		<u>LABOUR & MISC. CHARGES</u>	
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 450.00 300/-
02		Putty and spray painting of the affected portion.	\$ 500.00 300/-
			\$ 950.00
		Total	\$ 1,296.50

25/05/2018 @ 1100hrs

Not Actual
L/Smm

Tym 2 days

LKK Ando

[Signature]

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 0870B

Vehicle Details

Vehicle No.: GBF8866K

Vehicle to be Exported: Yes

Intended De-registration Date: 21 May 2018

Vehicle Make: NISSAN

Vehicle Model: NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC

Primary Colour: White

Manufacturing Year: 2016

Engine No.: K9KC400D056154

Chassis No.: VSKYBAM20Z0135771

Maximum Power Output: -

Open Market Value: \$20,261.00

Original Registration Date: 09 Dec 2016

First Registration Date: 09 Dec 2016

Transfer Count: 1

Actual ARF Paid: \$1,014.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 08 Dec 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$39,933.00

COE Rebate Amount: \$31,946.00

Total Rebate Amount: \$31,946.00

The information contained herein is correct as at 21 May 2018

OK

Asher Sng (LKKAuto)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Tuesday, 7 August 2018 4:22 PM
To: Asher Sng (LKKAuto)
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: RE: Your ref: 4780950537SG-003, ACCIDENT INVOLVING SGT 1313C (OI) & GBF 8866K (TP) ON 18/05/2018
Attachments: SGT1313C.MP4

Follow Up Flag: Follow up
Flag Status: Completed

Hi Asher

Reference to above OI video.

Pls proceed to reject TP claim since it is clear TP reversed into insured's stationary vehicle.

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718 | Fax +(65) 6835 7416

Bennie-WZ.Tan@aig.com | www.aig.com.sg

From: Asher Sng (LKKAuto) [mailto:AsherSng@lkkauto.com]
Sent: Tuesday, August 07, 2018 11:06 AM
To: Tan, Bennie-WZ
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: RE: Your ref: 4780950537SG-003, ACCIDENT INVOLVING SGT 1313C (OI) & GBF 8866K (TP) ON 18/05/2018

Hi Bennie,

We refer to the above matter.

Please kindly let us have your approval / instruction if any.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asher Sng (LKKAuto)

Sent: Tuesday, 31 July 2018 4:14 PM

To: 'Tan, Bennie-WZ' <Bennie-WZ.Tan@aig.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Subject: RE: Your ref: 4780950537SG-003, ACCIDENT INVOLVING SGT 1313C (OI) & GBF 8866K (TP) ON 18/05/2018

Hi Bennie,

We refer to the email below.

Enclosed insured video footage for your easy reference.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>

Sent: Tuesday, 26 June 2018 5:42 PM

To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Subject: RE: Your ref: 4780950537SG-003, ACCIDENT INVOLVING SGT 1313C (OI) & GBF 8866K (TP) ON 18/05/2018

Hi Asher

Before assessing further to this case, kindly advise if you have obtained OI's video footage mentioned in his GIA report for our consideration.

Best Regards

Bennie Tan

AIG

Senior Complex Claims Examiner

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1718 | Fax +(65) 6835 7416

From: Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]
Sent: Thursday, June 21, 2018 12:20 PM
To: Tan, Bennie-WZ
Cc: Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO)
Subject: Your ref: 4780950537SG, ACCIDENT INVOLVING SGT 1313C (OI) & GBF 8866K (TP) ON 18/05/2018

Your ref: **4780950537SG**
Our Ref: CC6/AIG18009613/Deb3

Dear Sir/Madam,

ACCIDENT INVOLVING SGT 1313C (OI) & GBF 8866K (TP) ON 18/05/2018

We refer to the above matter.

TP reported that OI move off from stationary while he was reversing out from the parking lot and hit his rear portion.

OI reported that TP reversed out of the parking lot and collided into his stationary vehicle.

Based on both party report third party vehicle reversed out of the parking lot, we are of the opinion that liability is not in third party favour.

In view of the above, we are intending to reject TP claim.

For your approval/ comments/ instruction.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is

received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 30 August 2018 10:57 AM
To: 'Johnson Chua'
Cc: caymen@tlmotor.com.sg
Subject: RE: Check Liability - TLM Ref: TP027052018; LKK Ref: TBA; Accident involving GBF8866K (TLM) & SGT1313C (AXA) on 18.05.2018
Attachments: SGT1313C.MP4; OI SKETCH PLAN.pdf

Without Prejudice

Hi Sir/Mdm,

We refer to the above matter.

We attached here with a copy of our insured's accident statement and video for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client reversed and hit into our insured stationary vehicle.

We are of the opinion that liability is not in your client's favor.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Johnson Chua <johnson.chua@tlmotor.com.sg>

Sent: Thursday, 30 August 2018 9:36 AM

To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>

Cc: caymen@tlmotor.com.sg

Subject: Check Liability - TLM Ref: TP027052018; LKK Ref: TBA; Accident involving GBF8866K (TLM) & SGT1313C (AXA) on 18.05.2018

Importance: High

Hi Asher,

We refer to your email below.

We update us on the status of this case.

Regards,



Johnson Chua
johnson.chua@tlmotor.com.sg

O. +65 6858 5151
F. +65 6858 0877

Tan Lim Motor Pte Ltd
51 Defu Lane 10
Singapore 539216
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Pte Ltd. Any use of the information (including but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Asher Sng (LKKAUTO) [<mailto:AsherSng@lkkauto.com>]
Sent: Tuesday, 31 July 2018 3:35 PM
To: Johnson Chua <johnson.chua@tlmotor.com.sg>; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: RE: Check Liability - TLM Ref: TP027052018; LKK Ref: TBA; Accident involving GBF8866K (TLM) & SGT1313C (AXA) on 18.05.2018

Without Prejudice

Hi Johnson,

We refer to the email below.

We are still pending for our insured video to revert the liability.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Johnson Chua <johnson.chua@tlmotor.com.sg>
Sent: Tuesday, 31 July 2018 2:11 PM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: Check Liability - TLM Ref: TP027052018; LKK Ref: TBA; Accident involving GBF8866K (TLM) & SGT1313C (AXA) on 18.05.2018
Importance: High

URGENT

Dear Asher,

We refer to our email below.

We have not received any reply from your office so far.

Please reply to us latest by **03.08.2018** (Fri). Otherwise, our client will take over the conduct of this matter through his solicitors.

Regards,



Johnson Chua
johnson.chua@tlmotor.com.sg

O: +65 6858 5151
F: +65 6858 0877

Tan Lim Motor Pte Ltd
51 Defu Lane 10
Singapore 539216
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

From: Johnson Chua [<mailto:johnson.chua@tlmotor.com.sg>]
Sent: Friday, 25 May 2018 4:07 PM
To: 'Hsiao Tong (LKKAuto)' <chewht@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>
Cc: 'Wei Shong' <wei.shong@tlmotor.com.sg>
Subject: Check Liability - TLM Ref: TP027052018; LKK Ref: TBA; Accident involving GBF8866K (TLM) & SGT1313C (AXA) on 18.05.2018
Importance: High

Dear LKK,

We refer to the above matter.

Survey has been conducted on 25.05.2018.

As such, please reply within **4 working days** whether you are agreeable to direct settle with us at 100% liability on this matter.

Regards,



Johnson Chua
johnson.chua@tlmotor.com.sg

O: +65 6858 5151
F: +65 6858 0877

Tan Lim Motor Pte Ltd
51 Defu Lane 10
Singapore 539216
<http://www.tlmotor.com.sg>

Confidentiality Notice: This email (including any attachments) is intended for the recipient(s) named above and may contain information that is confidential to Tan Lim Pte Ltd. Any use of the information (including, but not limited to, total or partial reproduction, distribution or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you are not an intended recipient of this email, please notify the sender immediately and delete it. While Tan Lim Motor has put in place anti-virus programs, we do not accept responsibility for any damage caused by viruses passed on unwittingly.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 May 2018 Edit Reg		25 May 2018 00:00 Edit Adj Rpt	S\$650.00 Edit Estimates	S\$650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: AHMAD DAHRI , ID: S26963071									
Main Claimant: TEN DOLLARS SALON HUB , Co. Reg. No.: 530508708									
Vehicle Reg. No.: GBF8866K		Date of Loss: 18/05/2018 12:00 - :59 [17 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4780950537SG		Policy/Cover Note No.: 2100485156 (Comprehensive)							
Vehicle Reg. No. (Insured): SGT1313C		Policy No. (Claimant): A29056024MKC							
		Excess:							
Repairer: Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com									
Claimant's Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 07/06/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBF8866K (4780950537SG)**
[SGT1313C]
TP
TEN DOLLARS SALON HUB
May 18 2018 12:00PM
[AHMAD DAHRI]
Tan Lim Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/08/18 16:08	OI Video - Accident	Load MP4	
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
2	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
3	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
4	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
5	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
6	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
7	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
8	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
9	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
10	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
11	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
12	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
13	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
14	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
15	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
16	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
17	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
18	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
19	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
20	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
21	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
22	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
23	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
24	30/08/18 11:11	General View	Load JPG	<input checked="" type="checkbox"/>
25	30/08/18 11:11	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
26	30/08/18 11:11	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
Documentation				
			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/05/18 09:01	TP ESTIMATE- MARKED	Load PDF	
2	30/05/18 09:01	TP GIA REPORT	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	31/05/18 10:33	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18009613/DEB3Q2

Date: 03/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100485156
Claimant Vehicle No : GBF8866K **Insured Vehicle No :** SGT1313C
 Date of Loss: 18/05/2018 Nature of Claim: TP Claim No: 4780950537SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF8866K**
 Make & Model: NISSAN NV200, 1.5 D ABS AIRBAG 2WD 6DR (M) Engine No: K9KC400D056154
 Reg. Date: 09/12/2016 (Man. Year: 2016) Chassis No: VSKYBAM20Z0135771
 Colour: White Odometer: 48200 km
 Engine Capacity: 1461 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14C Rear Tyre Size: 175/70 R14C
 Front Left Side: Goodyear 8 mm Rear Left Side: Goodyear 8 mm
 Front Right Side: Goodyear 8 mm Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	346.50	315.00	31.50	9.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	500.00	450.00	47.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,296.50	815.00	481.50	37.14
Approved Total (Overridden) (S\$)		650.00		
(S\$)	1,296.50	650.00	646.50	49.87
+ GST 7.00/7.00% (S\$)	90.76	45.50	45.26	49.87
Nett Amount (S\$)	1,387.26	695.50	691.76	49.87
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 25/05/2018
 Date Inspected: 25/05/2018 Inspected At: Tan Lim Motor Pte Ltd (Defu)
 51 Defu Lane 10
 Singapore 539216
 Estimated Period of Repair: 2.0 days

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	450.00 FL	*450.00 FL
2	1		*N/S REAR BUMPER REFLECTOR	Not Necessary	45.00 FL	*- FL
					Sub Total (\$\$)	495.00 450.00
					- List Item Discount on L Items 30.00/30.00% (\$\$)	148.50 135.00
					Total Parts (\$\$)	346.50 315.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	450.00	300.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	500.00	200.00
Gross Labour Cost (S\$)			950.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >