

ASS. REC. BY:

REF: CS/SMO18009630/719d31<sup>n2</sup> Special Instruction:Surveyor: Taukikh ASSIGNMENT (Office)From (Person): Grace Teo of SMO Date/Time: 28/5/18 @ 11:29 am

Estimated Cost: Bill to:

OD (TH) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XE 3716 M Insured: YN 2883Kat Workshop m/s Woon Meng Motor Tel: 6316 1131of 50 Bukit Bertok st 23 # 01-06Policy No: Claim No: CMTD1802248/NSW

Sum Insured: Excess:

Make of Veh:  
(Client's Record)D.O.A. 25/05/2018Insp: 42 Sungai Kadut AveCA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 12.11pmPerson Contacted: Ms. HengVehicle (IN) OUT

Date/Time Action/Instruction (✓) Estimate

XE 3716M-XYN 2883K-X01/6/18 @ 1.20pm informed Shann, we are pending estimate from repairer.27/5/18 @ 2.15pm revised to Shann by email.27/5/18 @ 7.43pm confirmed with Ms Heng LS \$2350, 3 days by email.  
(Red to 1329, 36%)

500000

Tamplin

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

Remark: The veh had commenced its repair at the time of inspection.

	N/S	O/S

Bal. or Market Value:			
IDAC Accident Rpt.:		Consistent? :	Yes or No
GIA / PR Seen:		Consistent? :	Yes or No
Est. Repairs:	3	days	Res.: Yes or No
Lum Sum:	%	3 Val.:	Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: XE 3716M Yr Regn: 2017, Dec  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Scania P400. C.C. 12742  
Colour: Green A/C: Insured / Std / NI / NA  
Sp. Reading: — T/Radio: Insured / Std / NI / NA  
Eng/No: YS2P4X20009224063  
C/No: 3  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Mod: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 315/80R22.5  
R: 2 ~ (D)  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front		Rear	
R/Bal.	8 mm	R/Bal.	8/8 mm
L/Bal.	8 mm	L/Bal.	8/8 mm
D.O.A.		D.O.I.	30/5/18 @ 1450
Survey held at	Woon Meng Seng Kafei		
Des. of Damages :	Frt / Rear / O/S / NS / U/C / Rooftop or N/S minor.		
The U/C / Chassis frame / Body Structure affected due to collision.			

Date / Time	Action / Instruction
	No Key.
	w/s will mail exp. mail of G.I. V.

RECEIVED 28 SEP 2018

Date/Time: File Pass to?

28/4 typisch

Date/Time: File Return to?

Report Format :

Lump Sum / I.B.T.: (\$)

: Preli. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:  : Site Insp (\$

☐ Interview (\$

☐ Tech Invs (\$

☐ Weekend (\$)

Survey Fee:

Transportation

$$S + P5 \rightarrow S1$$

250



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18009630/T1qd3		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 28-05-2018		
		Code : SMO		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YN 2883K	Veh. Inspected	XE 3716M	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1802248/NSW	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	28/05/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	25/05/2018	Inspection Date		
Survey held at	42 SUNGAI KADUT AVENUE			
Repairer	WOON MENG MOTOR PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1802248/NSW

Date: 27<sup>th</sup> September 2018

Our Ref: CS/SMO18009630/T1qd3

Without Prejudice

The Motor Claims Department  
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. XE 3716M.**


We thank you for the instruction on 28/05/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/05/2018 at the premises of M/s WOON MENG MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,679.00</u>
Revised Estimate Amount	: S\$ <u>3,179.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the n/s mirror.



Comments/ Present Status:

Damages consistent.

Days of repair: 3 days.

We have NOT authorized repair.

Yours faithfully

Taufikh  
Automobile Assessor

**Nivitha (LKK Auto)**

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Monday, 28 May 2018 11:29 AM  
**To:** admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** Heng Sew Sow; Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin  
**Subject:** CMTD1802248/NSW - SUV(LKK)/ Accident involving YN2883K & XE3716M ON 25.05.18  
**Attachments:** 20180526191738.pdf

Our Reference: CMTD1802248/NSW

Dear LKK AUTO/ MOHD TAUFIKH,

Please make arrangement to conduct the survey for XE3716M.

Please be informed that Shawn Ngo the handler of this case.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Heng Sew Sow [mailto:woonmeng@singnet.com.sg]  
**Sent:** Monday, May 28, 2018 11:17 AM  
**To:** Teo, Grace  
**Cc:** Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin  
**Subject:** RE: CMTD1802248/NSW - Accident involving YN2883K & XE3716M ON 25.05.18

Dear Taufikh

LKK Auto Consultants  
Mohd Taufikh (West area)

Best Regards,

Heng Sew Sow (Ms)  
Woon Meng Motor Pte Ltd  
Tel: 6316 1131/51  
Fax: 6316 7050

**From:** Teo, Grace [mailto:grace.teo@sompo.com.sg]  
**Sent:** Monday, 28 May 2018 11:06 AM  
**To:** Heng Sew Sow <woonmeng@singnet.com.sg>  
**Cc:** Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>  
**Subject:** CMTD1802248/NSW - Accident involving YN2883K & XE3716M ON 25.05.18

Our Reference : CMTD1802248/NSW  
Your Reference: XE3716M

**Without Prejudice**

Date: 28<sup>th</sup> May 2018

**Attention:**  
**M/S WOON MENG MOTOR**

Dear Ms. Heng,

**ACCIDENT INVOLVING YN2883K & XE3716M ON 25.05.2018**

We refer to your Notice of Accident dated 26/05/2018.

Kindly re-direct your future motor claims survey request to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

-----Original Message-----

From: Heng Sew Sow [<mailto:woonmeng@singnet.com.sg>]

Sent: Saturday, May 26, 2018 7:25 PM

To: claimsreport

Subject: Accident involving XE3716M & YN2883K ON 25.05.18

Dear Sir/Madam

We refer to the above accident

Kindly be advised that we will be assisting our client, owner of vehicle no: XE3716M, to submit a third party claim against your insured vehicle. We would like to proceed with direct settlement.

Please arrange for your surveyor to liaise with us for an inspection on our client's Vehicle at your earliest convenience.

Location : 50, Bukit Batok St 23 #01- 06 Midview Building ( S ) 659578 ( Vehicle in )

Thank you.

Woon Meng Motor Pte Ltd

Tel : 63161131

Fax : 63167050

## Shiau Chan (LKKAUTO)

---

**From:** Heng Sew Sow <woonmeng@singnet.com.sg>  
**Sent:** Thursday, 27 September 2018 7:43 PM  
**To:** Shiau Chan (LKKAUTO); Taufikh (LKKAUTO)  
**Cc:** SUR  
**Subject:** RE: Pending Finalised Offer for YP4262D & SJQ1925S & XE3716M & XD6898G

Accept your offer \$2350.00

Best Regards,  
Heng Sew Sow (Ms)  
Woon Meng Motor Pte Ltd  
Tel: 6316 1131/51  
Fax: 6316 7050

---

**From:** Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>  
**Sent:** Thursday, 27 September 2018 2:18 PM  
**To:** Woon Meng <woonmeng@singnet.com.sg>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: Pending Finalised Offer for YP4262D & SJQ1925S & XE3716M & XD6898G

Dear Ms Heng,

WITHOUT PREJUDICE

XE 3716M – Offer Lump Sum \$2,350.00 before GST and 3 repair days.

Kindly confirm.

Best Regards,  
**Shiau Chan (Ms) | Case Handler**  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Woon Meng <woonmeng@singnet.com.sg>  
**Sent:** Thursday, 6 September 2018 2:41 PM  
**To:** Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: Pending Finalised Offer for YP4262D & SJQ1925S & XE3716M & XD6898G

Dear Shiau Chan,

We refer to the matter below for your kind attention.

Please kindly be informed that we confirm acceptance of :

final fig \$700.00 before GST and 2 repair days.

Thanks & Warmest Regards,



## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 27 September 2018 2:15 PM  
**To:** Ngo, Sau Wei Shawn; Teo, Grace; assignments  
**Cc:** Ye, Yong Kang Melvin; SUR  
**Subject:** RE: CMTD1802248/NSW - SUV(LKK)/ Accident involving YN2883K & XE3716M ON 25.05.18  
**Attachments:** CSSMO18009630T1qd3.pdf

Dear Shawn,

Enclosed herewith preliminary advice of XE 3716M.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 2 August 2018 3:55 PM  
**To:** Ngo, Sau Wei Shawn <[Shawn.Ngo@sompo.com.sg](mailto:Shawn.Ngo@sompo.com.sg)>; Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CMTD1802248/NSW - SUV(LKK)/ Accident involving YN2883K & XE3716M ON 25.05.18

Dear Shawn,

Thank you for the email.

We will check and revert to you.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ngo, Sau Wei Shawn <[Shawn.Ngo@sompo.com.sg](mailto:Shawn.Ngo@sompo.com.sg)>  
**Sent:** Thursday, 2 August 2018 3:43 PM  
**To:** Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>; Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CMTD1802248/NSW - SUV(LKK)/ Accident involving YN2883K & XE3716M ON 25.05.18

Dear Shiau Chan,

Third party, M/s Woon Meng Motor had send in their letter of claims since 31.05.2018 but however till date we have yet to receive your surveyor report.

Please confirm.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 1 June 2018 1:20 PM  
**To:** 'Teo, Grace'; assignments; 'Shawn.Ngo@sompo.com.sg'  
**Cc:** 'Ye, Yong Kang Melvin'; SUR  
**Subject:** RE: CMTD1802248/NSW - SUV(LKK)/ Accident involving YN2883K & XE3716M ON 25.05.18

Dear Shawn,

Please be informed that we have inspected the vehicle XE 3716M on 30/05/2018.

We are pending for estimate from repairer.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Monday, 28 May 2018 12:15 PM  
**To:** 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Ngo, Sau Wei Shawn' <[Shawn.Ngo@sompo.com.sg](mailto:Shawn.Ngo@sompo.com.sg)>; 'Ye, Yong Kang Melvin' <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CMTD1802248/NSW - SUV(LKK)/ Accident involving YN2883K & XE3716M ON 25.05.18

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo, Grace [<mailto:grace.teo@sompo.com.sg>]  
**Sent:** Monday, 28 May 2018 11:29 AM  
**To:** [admin-d@lkkauto.com](mailto:admin-d@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** Heng Sew Sow <[woonmeng@singnet.com.sg](mailto:woonmeng@singnet.com.sg)>; Ngo, Sau Wei Shawn <[Shawn.Ngo@sompo.com.sg](mailto:Shawn.Ngo@sompo.com.sg)>; Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>  
**Subject:** CMTD1802248/NSW - SUV(LKK)/ Accident involving YN2883K & XE3716M ON 25.05.18

Our Reference: CMTD1802248/NSW

Dear LKK AUTO/ MOHD TAUFIKH,

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/05/2018 18:51
Date Of Accident	25/05/2018 08:40
Exact Location Of Accident	1 BUROH LANE ( LOADING BAY )
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE3716M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WENDY TRANSPORT ENTERPRISE CO
Co Reg No	0 2586 6300J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94305264

### Vehicle Particulars

Manufacturer	SCANIA
Model	P400LA-12.7 D 4X2 MSZ (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCV17S023183
Cover Note Number	

### Driver

Name of Driver	TOH LIANG HUAT
NRIC No	S7515269H
Date Of Birth	03/06/1975
Occupation	OUTDOOR
Date Of Driving Pass	03/04/1998
Driving Experience	20 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94305264
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 812A CHOA CHU KANG AVE 7 # 12- 673
Postcode	681812
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN2883K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:


Please note that you might be able to submit an Own Damage Claim under own policy within 14 days.

( ) Claim Own Damage ( ) Claim TP ( ) Reporting Only ( ) Claim OD/TP at other workshop

Workshop Name : \_\_\_\_\_

Sketch Plan Pg. 2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 25/5/12 @ 08:40hrs, my vehicle at loading bay waiting for unloading. a vehicle YN 2882K reversed and collided onto the front left of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

*[Signature]*  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

( Email Address : woonmeng@singnet.com.sg )

Co Reg No. 200603678M

GST Reg No. 20-0603678M

### Estimate

### TP CLAIM

To : Tenet Sampo Insurance Pte Ltd  
Motor Claims Dept

Date : 30 May 2018

Dear Sirs :

Fax : 6221 3147

### RE : ESTIMATE COST FOR SCANIA P400 - XE3716M ACCIDENT INVOLVING XE3716M & YN2883K ON 25/05/2018

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front side mirror mounting kit n/s.	1pc	\$ 893.00 <i>dis</i>
2	Front side mirror top n/s	1pc	\$ 620.00 <i>dis</i>
3	Front side mirror casing n/s.	1pc	\$ 786.00 <i>dis</i>
			\$ 2,299.00
			10% - 2069.10

### Labour Charge & Misc

To remove, repair, replace & install damaged \$ 600.00 *400*

To numbering " Wendy " logo. \$ 250.00 *150*

To R & R wiring. \$ 80.00 *30*

To putty & spray painting. \$ 450.00 *300*

**Total** \$ 3,679.00 *880.*

All prices quoted are subjected to 7% GST.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Tan Kah 97493744*  
*wp*  
*27/5/18*  
*Wong after repair.*  
*03 days.*  
*2949.10*  
*4/582350*  
*20/5/18*





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18009630/T1qd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 03-10-2018



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 2883K	Veh. Inspected	XE 3716M
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802248/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	28/05/2018

### 2. Vehicle Particulars & Condition

Make & Model	SCANIA P400	c.c	12742
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	YS2P4X20009224063	Colour	GREEN
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	315/80 R22.5	GOODYEAR	8 mm
L/H Front Tyre	315/80 R22.5	GOODYEAR	8 mm
R/H Rear Tyre	315/80 R22.5 (D)	GOODYEAR	8/8 mm
L/H Rear Tyre	315/80 R22.5 (D)	GOODYEAR	8/8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S MIRROR.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	25/05/2018	Inspection Date	30/05/2018
Survey held at	42 SUNGAI KADUT AVENUE		
Repairer	WOON MENG MOTOR PTE LTD		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 3716M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT SIDE MIRROR MOUNTING KIT N/S	DISTORTED	893.00	893.00
1	FRONT SIDE MIRROR TOP N/S	CRACKED	620.00	620.00
1	FRONT SIDE MIRROR CASING N/S	CRACKED	786.00	786.00
	LESS 10% DISCOUNT		-	-229.90
			2,299.00	2,069.10
<b>LABOUR</b>				
	TO REMOVE, REPAIR, REPLACE & INSTALL DAMAGED.		600.00	400.00
	TO NUMBERING "WENDY" LOGO.		250.00	150.00
	TO R&R WIRING.		80.00	30.00
	TO PUTTY & SPRAY PAINTING.		450.00	300.00
			1,380.00	880.00
<b>GRAND TOTAL</b>			<b>3,679.00</b>	<b>2,949.10</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,350.00</b>
---	--	--	-----------------

Report Ref No. CS/SMO18009630/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.