

ASS. REC. BY

REF CS3/AIG1800 9645/G243⁵² special instruction

Surveyor
MAMMEN

GQ

ASSIGNMENT (Office)

From (Person) chin lee ying

of AG

Date/Time: 28/5/18 @ 11:10am

Estimated Cost: Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJV1154Z Insured: SDM980E

at Workshop in/s EK52 AUTO Tel: 9373 5378

of 1 kaki Bukit Ave 6 #01-53 Autobay

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A 24/5/2018

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 11:35am @ 28/5/18 Person Contacted: KOEY Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate	
	SJV1154Z-NA AIG16017161/h1	DOA: 9/9/2016
	SDM980E-CC6/AIG15021308/Ung3q2	DOA: 12/12/2015
31/5/18	Dismantled	

**-PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SDM980E AND SJV1154Z ON 24/5/2018**

From: Fan, Winnie-LW

To:

Cc: Fong, Andy-SY, Chin, Lee-Ying

Sent: 28/5/2018 11:10:58 AM

Attachments:  [2nd PRS Letter to AIG 10052018.pdf](#)

Hi LKK,

Kindly assist to survey, car is in.

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Fax +(65) 6835 7416

winnie-lw.fan@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: elleen@satwantlaw.com [mailto:elleen@satwantlaw.com]

Sent: Monday, May 28, 2018 10:56 AM

To: Chan, Yoke Shi

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Fan, Winnie-LW; enquiry.ek52@gmail.com; Danny Lim; margaretlim@satwantlaw.com.sg

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDM980E AND SJV1154Z ON 24/5/2018

Importance: High

WITHOUT PREJUDICE

Dear Sir / Madam,

We have instructions to reject your surveyor and propose to engage MC-Coy Appraiser Pte Ltd (Michael)

Kindly see attached our letter and the workshop details as below:-

Workshop: EK52 Auto Pte Ltd

Address: 1 Kaki Bukit Ave 6 #01-53, Blk C, Autobay @ Kaki Bukit, Singapore 417883

Contact: Koey (9373 5378)

Kindly liaise directly with the workshop for the PRS on an urgent basis. Thank you.

Thank you & Best Regards
Elleen Lee (Branch Office)
Secretary

For and on behalf of

SATWANT & ASSOCIATES

Advocates & Solicitors | Notary Public | Commissioner for Oaths

Main Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 | fax: 6299 5541

Branch Office: 450 Lorong 6 Toa Payoh #02-03 Harsing Centre Singapore 319394 | tel: 6221 6114 | fax: 6266 6925

Email Confidentiality Warning:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that any unauthorised disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at elleen@satwantlaw.com and delete it from your system. Unless the contents of this email relate to matters within the scope of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should scan this email and any file attached for viruses. We take no responsibility for any loss or damage, whether caused by our own negligence or not, that results from a computer virus or a defect in the transmission of this email or any attached file.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Satwant Singh
Danny Teo Kim Soon
Pritam Singh
Khong Zi-Wei



CONVEYANCING OFFICE:
450 Lorong 6 Toa Payoh
#02-03 Herring Centre
Singapore 319304
Tel: 6221 6114
Fax: 6266 6925
www.satwantlaw.com.sg
(Fax not for service
of documents)

An Official Member of The Lawyer Network, an international network of law firms

(Please quote our Ref. when replying)

Your Ref : To be advised
Our Ref: PD/DL/1800867 (el) – Toa Payoh Office
(ellen@satwantlaw.com)

28 May 2018

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120

BY EMAIL ONLY

Attention: Motor Claims Department

Dear Sir/Mdm,

ACCIDENT INVOLVING SJV1154Z & SDM980E ALONG CTE/SLE AFTER ANG MO KIO AVE 1 EXIT ON 24/05/2018 @ 20:50

We refer to your email dated 28 May 2018 confirming your intention to conduct a pre-repair survey on our client's vehicle SJV1154Z.

Please be informed that said vehicle can be inspected at:

Workshop: EK52 Auto Pte Ltd

Location: 1 Kaki Bukit Ave 6 #01-53, Blk C, Autobay @ Kaki Bukit, Singapore 417883

Contact: Koey (9373 5378)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

SATWANT & ASSOCIATES
(Danny Teo)

cc client

For Surveyor: To initial after Completion

1st Inspection

Appointed surveyor
(Name & Signature)

Date & Time

2nd Inspection

Appointed surveyor
(Name & Signature)

Date & Time

3rd Inspection

Appointed surveyor
(Name & Signature)

Date & Time

NB: Any Settlement of offer is on the express condition that this settlement is in respect of our client's claim for property related damaged only and shall not preclude our client from claiming injury-related damages arising from this accident. This document is intended for the addressee(s) only and may contain confidential information and/or may be subject to legal privilege. If you have received this in error, please contact us immediately and destroy the original message.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/05/2018 11:21
Date Of Accident	24/05/2018 20:50
Exact Location Of Accident	CTE/ SLE AFTER ANG MO KIO AVE 1 EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV1154Z
Insured/Policyholder	
Name Of Registered Owner	TAN LOUIS VICTOR ROBOTH
NRIC No	S8114450H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81330064
Alternative Phone No	OFFICE-81330064

Vehicle Particulars

Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100327273-05
Cover Note Number	

Driver

Name of Driver	TAN LOUIS VICTOR ROBOTH
NRIC No	S8114450H
Date Of Birth	25/05/1981
Occupation	OUTDOOR
Date Of Driving Pass	07/04/2003
Driving Experience	15 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81330064
Fax Number	
Contact Number	OFFICE-81330064
EMail Address	NOEMAIL

Address	BLK 429B YISHUN AVE 11 #12-370
Postcode	762429
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE STATED DATE AND TIME, AT THE STATED VENUE, VEHICLE A (SJV1154Z) WAS TRAVELLING STRAIGHT ON MY RIGHTFUL LANE. THE VEHICLE IN FRONT OF ME SLOWED DOWN, SO, I FOLLOWED SUIT. SUDDENLY, I FELT A GREAT IMPACT ON MY REAR PORTION. VEHICLE B (SDM980E) HAD COLLIDED ONTO THE REAR PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDM980E
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time: 25/5/18
 1730hrs.


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:
 ERSD AUTO

SKETCH PLAN

CTE towards STE after Ang Mo Kio Ave1 Exit



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, at the stated venue, I vehicle 'A' SJV 1154Z was travelling straight on my rightful lane. The vehicle in front of me slowed down, so I followed suit. Suddenly I felt a great impact on my rear portion. Vehicle 'B' SDM 980E had collided onto the rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4450H
Vehicle Details	
Vehicle No.:	SJV1154Z
Vehicle to be Exported:	No
Intended De-registration Date:	30 May 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3L A
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	L13A4122984
Chassis No.:	GE61112186
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$13,130.00
Original Registration Date:	12 Jan 2010
First Registration Date:	12 Jan 2010
Transfer Count:	0
Actual ARF Paid:	\$13,130.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jan 2020
PARF Rebate Amount:	\$7,221.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jan 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$21,301.00
COE Rebate Amount:	\$2,617.00
Total Rebate Amount:	\$9,838.00

The information contained herein is correct as at 30 May 2018

OK

▶ Fit Used Vehicle List (5 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Honda Fit 1.3A G	\$22,800	\$9,450 /yr	04-Feb-2010	1,339 cc	85,000 km	SmartCars Boutique Pte Ltd	Availat

\$5k Down Payment. Beautiful Black Color. No Repair Needed Well Taken Care Of By Previous Owner. Super Low Mileage Done Please Call Our Sales Consultant For Viewing And Test Drive Before Its Gone. High...

Office No. - 67410182

Jimmy Choo - 97913903 | Des - 96835550

Honda Fit 1.3A GF (OPC)	\$19,800	\$7,100 /yr	09-Feb-2010	1,339 cc	109,899 km	Dickson Automobile	Availat
-------------------------	----------	-------------	-------------	----------	------------	--------------------	---------

Extended Warranty Available! Extremely Fuel Efficient! Very Affordable! Normal Plate Price At \$28500. Well Taken Care In Superb Condition, For You To Drive And Believe! Buy It From Us With A Peac...

Office No. - 68447667

Eric Lee - 91827304 | Ricky Eng - 91853390 | Jonathan Quah - 91901666

Honda Fit 1.3A G	\$22,500	\$9,470 /yr	25-Feb-2010	1,339 cc	-	Trust Motor Trading	Availat
------------------	----------	-------------	-------------	----------	---	---------------------	---------

Well Maintained Condition, Fuel Efficient And Reliable Model, Sporty Outlook With Spacious Interior Space. GST Included. Flexible Loan And Trade In Available, Call Now To Viewing The Car.

Office No. - 63384472

Alvin Chea - 90295022 | Benson Tan - 84187320 | Mr Lim - 96263081

Honda Fit 1.3A G	\$24,800	\$10,140 /yr	05-Mar-2010	1,339 cc	135,000 km	Hua Yang Credit Pte Ltd	Availat
------------------	----------	--------------	-------------	----------	------------	-------------------------	---------

In House Loan Available. Most Popular Honda Hatchback For Your Family And Daily Usage, Well Maintained By Previous Owner, Low Maintenance, Low Consumption, Buy With A Peace Of Mind. Trade In Available...

Office No. - 64635111

Alvin - 82645711 | Kamen - 88621923

Honda Fit 1.3A G	\$27,800	\$9,540 /yr	06-Aug-2010	1,339 cc	95,000 km	Hua Yang Credit Pte Ltd	Availat
------------------	----------	-------------	-------------	----------	-----------	-------------------------	---------

100% Loan, Most Popular Honda Hatchback For Your Family And Daily Usage, Well Maintained By Previous Owner, Low Maintenance, Low Consumption, With A Peace Of Mind. Trade In Available. Don't Miss I...


Office No. - 64658348

Teo - 96116191 | Michelle - 86063381 | Jackson - 84338996

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for C cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brand: carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & C results.

© 2004-2018 sgCarMart. All rights reserved.


Identification Card



Driving License



Driving License




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
07 Apr 2003

NP 428A



Licence No. S8114450R

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	BT	✓	
1138	993627	Rear Number Plate Base	RE	✓	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	RE	DMG	✓
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	BR	✓	
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket	DT	✓	
1148	993068	Rear Bumper Side Retainer	MC	✓	2
1149	993045	Rear Bumper Reinforcement	OT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel	DT	✓	
1160	993339	Rear End Panel Top Garnish	RE	✓	
1161	993333	Rear End Panel			
1162	990333	Boot Compartment Floor Panel	DT	✓	
1163	993851	Rear LH Taillamp	CRK	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRK	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DMG		
1171	991328	Bootlid Emblem	NEC	2	
1172	990356	Bootlid Handle	RE	✓	
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	DT	2	
1178	990377	Bootlid Rubber	DMG		
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	BUC	✓	
1182	991328	Tailgate Emblem	MC	✓	2
1183	994643	Tailgate Outer Handle	RE	✓	
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector Lower Trim Board	RE	✓	
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor	NW	✓	
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	MC	✓	
1196	994607	Tailgate Glass Sealant	MC	✓	
1197	994629	Tailgate Lock	BT	✓	
1198	994651	Tailgate Rubber	MC	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

Vehicle No: SJV 11543

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board	RE	✓	
1203	994328	Spare Tyre Panel	RE	✓	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	BT	✓	
1213	993357	Rear Exhaust Chrome Pipe mounting	BT	✓	2
1214	993361	Rear Exhaust Mounting Chromed	DT	✓	
1215	993358	Rear Exhaust Heat Shield	BUC	✓	
1216	995223	Rear LH Chassis Member	REPAIR	✓	
1217	993165	Rear RH Chassis Member	REPAIR	✓	
1218	993436	Rear LH Fender	BUC	✓	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim	RE	✓	
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield	RE	✓	
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	BUC	✓	
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim	RE	✓	
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield	RE	✓	
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			
		Wiper Motor			
		Speaker Board	RE	✓	

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 May 2018 Edit Reg		28 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	HAH CHING YOONG (XIA QINGYUN) , ID: S7202756F		
Main Claimant:	TAN LOUIS VICTOR ROBOTH , ID: S8114450H		
Vehicle Reg. No.:	SJV1154Z	Date of Loss:	24/05/2018 20:00 - :59 [100 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3009087657SG	Policy/Cover Note No.:	2100488908 (Comprehensive) Coverage: 31/10/2017 - 30/10/2018
Vehicle Reg. No. (Insured):	SDM980E	Policy No. (Claimant):	
		Excess:	
Repairer:	Ek52 Auto Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6, #01-53 BLK C AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 9373 5378		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/06/2018]		
Claimant's Solicitor:	SATWANT & ASSOCIATES - Tel: 62216114		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (05/06/2018): **No OI GIA Report (SDM980E VS SJV1154Z)**
- AIG_SG (05/06/2018): **Request To Upload TP GIA Report**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJV1154Z (3009087657SG)
[SDM980E]**

TP

TAN LOUIS VICTOR ROBOTH

May 24 2018 8:00PM

[HAH CHING YOONG (XIA QINGYUN)]

Ek52 Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
2	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
3	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
4	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
5	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
6	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
7	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
8	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
9	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
10	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
11	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
12	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
13	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
14	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
15	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
16	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
17	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
18	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
19	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
20	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
21	01/06/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
22	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
23	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
24	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
25	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
26	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
27	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
28	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
29	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
30	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
31	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
32	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
33	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
34	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
35	01/06/18 11:52	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images					
No	Relabel/Reorder	LKK Auto Consultants Pta Ltd (HQ)		Thumbnail	Print
36	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
37	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
38	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
39	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
40	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
41	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
42	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
43	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
44	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
45	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
46	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
47	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
48	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
49	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
50	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
51	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
52	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
53	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
54	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
55	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
56	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
57	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
58	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
59	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
60	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
61	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
62	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
63	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
64	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
65	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
66	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
67	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
68	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
69	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
70	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
71	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
72	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
73	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
74	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
75	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
76	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
77	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
78	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
79	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
80	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
81	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
82	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
83	01/06/18 11:52	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>

Photos/Images				✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
84	29/06/18 11:29	Photo After Spray	1	Load JPG ✓
85	29/06/18 11:29	Photo After Spray	1	Load JPG ✓
86	29/06/18 11:29	Photo After Spray	1	Load JPG ✓
87	29/06/18 11:29	Photo After Spray	1	Load JPG ✓
88	29/06/18 11:29	Photo After Spray	1	Load JPG ✓
89	29/06/18 11:29	Photo After Spray	1	Load JPG ✓
90	29/06/18 11:29	Photo After Spray	1	Load JPG ✓
91	29/06/18 11:29	Photo After Spray	1	Load JPG ✓
92	29/06/18 11:29	Photo After Spray	1	Load JPG ✓
93	29/06/18 11:29	Photo After Spray	1	Load JPG ✓
94	29/06/18 11:29	Photo After Spray	1	Load JPG ✓
95	29/06/18 11:29	Photo After Spray	1	Load JPG ✓
Documentation			1 per page	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	05/06/18 14:48	OI GIA REPORT	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009645/GZ4D3S2
Date: 02/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100488908
Claimant Vehicle No : SJV1154Z **Insured Vehicle No :** SDM980E
 Date of Loss: 24/05/2018 Nature of Claim: TP Claim No: 3009087657SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV1154Z**
 Make & Model: HONDA FIT, 1.3 (A) Engine No: L13A4122984
 Reg. Date: 12/01/2010 (Man. Year: 2008) Chassis No: GE61112186
 Colour: Red Odometer: 263809 km
 Engine Capacity: 1339 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50R15 Rear Tyre Size: 195/50R15
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/05/2018
 Date Inspected: 28/05/2018 Inspected At: Ek52 Auto Pte Ltd (HQ)
 1 KAKI BUKIT AVENUE 6, #01-53 BLK C AUTOBAY @
 KAKI BUKIT
 Singapore 417883
 Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*-F
2	1		*REAR NUMBER PLATE BASE	Deformed	0.00 F	*-F
3	1		*REAR BUMPER	Deformed	0.00 F	*-F
4	1		*REAR BUMPER TOW COVER	Broken	0.00 F	*-F
5	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
6	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*-F
7	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*-F
8	1		*REVERSE SENSOR	Damaged	0.00 F	*-F
9	1		*REAR END PANEL	Dented	0.00 F	*-F
10	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*-F
11	1		*REAR LH TAILLAMP	Cracked	0.00 F	*-F
12	1		*REAR RH TAILLAMP	Cracked	0.00 F	*-F
13	1		*TAILGATE	Buckled	0.00 F	*-F
14	2		*TAILGATE EMBLEM	Necessary	0.00 F	*-F
15	1		*TAILGATE OUTER HANDLE	Deformed	0.00 F	*-F
16	1		*TAILGATE INNER TRIM BOARD	Deformed	0.00 F	*-F
17	1		*TAILGATE WIPER MOTOR	Not Working	0.00 F	*-F
18	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*-F
19	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*-F
20	1		*TAILGATE LOCK	Bent	0.00 F	*-F
21	1		*TAILGATE RUBBER	Twisted	0.00 F	*-F
22	1		*SPARE TYRE BOARD	Deformed	0.00 F	*-F
23	1		*SPARE TYRE PANEL	Distorted	0.00 F	*-F
24	1		*REAR EXHAUST PIPE	Bent	0.00 F	*-F
25	2		*REAR EXHAUST MOUNTING	Bent	0.00 F	*-F
26	1		*REAR EXHAUST HEAT SHIELD	Buckled	0.00 F	*-F
27	1		*REAR LH CHASSIS MEMBER	Repair	0.00 F	*-F
28	1		*REAR RH CHASSIS MEMBER	Repair	0.00 F	*-F
29	1		*REAR LH FENDER	Buckled	0.00 F	*-F
30	1		*REAR LH FENDER INNER TRIM	Deformed	0.00 F	*-F
31	1		*REAR LH FENDER INNER SHIELD	Deformed	0.00 F	*-F
32	1		*REAR RH FENDER	Buckled	0.00 F	*-F
33	1		*REAR RH FENDER INNER TRIM	Deformed	0.00 F	*-F
34	1		*REAR RH FENDER INNER SHIELD	Deformed	0.00 F	*-F
35	1		*SPEAKER BOARD	Deformed	0.00 F	*-F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >