

Surveyor

## ASSIGNMENT (Office)

From (Person): Janice Gwh of ECICS Date/Time: 28/5/18 @ 4:21pm

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 4448 R Insured: SJQ 19255

at Workshop m/s: Comfort delgro Tel: 6214 8316

of: SQ Loyang Way

Policy No: Claim No: DMPCL800213H

Sum Insured: Excess:

Make of Veh: D.O.A. 25/05/2018

(Client's Record) 30/05/18

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 4:38 pm @ 28/5/18 Person Contacted: Jerry Vehicle: IN OUT

Date/Time	Action/Instruction ( ) Estimate
	SHA 4448A -x
	SJQ 19255-CCG / EQ 116005657 / KwB3S2 DOA: 25/3/16



**Veron Chen (LKKAUTO)**

---

**From:** Phoebe Jay Xie (ECICS, Claims) <PhoebeJay\_Xie@ecics.com.sg>  
**Sent:** Friday, 1 June 2018 5:40 PM  
**To:** Veron Chen (LKKAUTO); motorsurvey  
**Cc:** SUR  
**Subject:** RE: SHA4448A VS SJQ1925S (ECICS) DOA: 25.05.2018 \*\* 2nd email \*\*

Dear Veron,

Our claims ref is DMPC1800213H.

Thank you.

Best Regards,

Phoebe Jay Xie

**ECICS Limited**

DID: +65 6303 0180

FAX: +65 6338 9267

Email: [phoebejay\\_xie@ecics.com.sg](mailto:phoebejay_xie@ecics.com.sg)

---

**From:** Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]  
**Sent:** Friday, 1 June, 2018 4:57 PM  
**To:** motorsurvey  
**Cc:** SUR  
**Subject:** RE: SHA4448A VS SJQ1925S (ECICS) DOA: 25.05.2018 \*\* 2nd email \*\*

Dear Janice,

Please provides us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Monday, 28 May 2018 4:39 PM  
**To:** 'motorsurvey' <[motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SHA4448A VS SJQ1925S (ECICS) DOA: 25.05.2018 \*\* 2nd email \*\*

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** motorsurvey [<mailto:motorsurvey@ecics.com.sg>]

**Sent:** Monday, 28 May 2018 4:21 PM

**To:** Ng Nyuk Phin <[ngnp@cdge.com.sg](mailto:ngnp@cdge.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** Lim Kwok Eng <[limke@cdge.com.sg](mailto:limke@cdge.com.sg)>; Roger How Keen Meng <[rogerhow@cdge.com.sg](mailto:rogerhow@cdge.com.sg)>; motorsurvey <[motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg)>

**Subject:** RE: SHA4448A VS SJQ1925S (ECICS) DOA: 25.05.2018 \*\* 2nd email \*\*

Without Prejudice

Dear Larry

Thank you for your email.  
We will appoint LKK for the survey.

Aside to LKK

Please assist to arrange TP PRI.

Thank you.

Regards,

Janice Goh

**Claims Division**

DID: +65 6303 0182

FAX: +65 6338 9267

**ECICS Limited**

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY**, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

**From:** Ng Nyuk Phin [<mailto:ngnp@cdge.com.sg>]

**Sent:** Monday, 28 May, 2018 4:04 PM

**To:** motorsurvey

**Cc:** Lim Kwok Eng; Roger How Keen Meng

**Subject:** SHA4448A VS SJQ1925S (ECICS) DOA: 25.05.2018 \*\* 2nd email \*\*

**Importance:** High

Dear Motor Claims,

We are still waiting for your appointed surveyor.

Kindly arrange to survey the taxi at 59 Loyang Drive, level 4, rooftop carpark as soon as possible.

Regards,

Larry Ng

ComfortDelgro Engineering Pte Ltd

Loyang Taxi Crash Repair  
6214 8316

-----Forwarded by Ng Nyuk Phin/cdge/delgronotes on 05/28/2018 04:01PM -----  
To: [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg)  
From: Ng Nyuk Phin/cdge/delgronotes  
Date: 05/25/2018 03:44PM  
Subject: SHA4448A VS SJQ1925S (ECICS) DOA: 25.05.2018

Dear Motor Claims,

Please see attached repair estimate and SAS.

Kindly arrange to survey the taxi at 59 Loyang Drive, level 4, rooftop carpark as soon as possible.

Regards,  
Larry Ng  
ComfortDelGro Engineering Pte Ltd  
Loyang Taxi Crash Repair  
6214 8316

-----Forwarded by Ng Nyuk Phin/cdge/delgronotes on 05/25/2018 03:43PM -----  
To: [ngnp@cdge.com.sg](mailto:ngnp@cdge.com.sg)  
From: "ApeosPort-IV C5570 "<[sbs-singnalling@sbstransit.com.sg](mailto:sbs-singnalling@sbstransit.com.sg)>  
Date: 05/25/2018 03:42PM  
Subject: Scan Data from CDG\_LO\_AW\_A5570

(See attached file: *img-525154113-0001.pdf*)

Number of Images: 7  
Attachment File Type: PDF

Device Name: ApeosPort-IV C5570  
Device Location:

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
-------------------------------------	-------------------------------------	-------------------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

**Nivitha (LKK Auto)**

---

**From:** motorsurvey <motorsurvey@ecics.com.sg>  
**Sent:** Monday, 28 May 2018 4:21 PM  
**To:** Ng Nyuk Phin; assignments  
**Cc:** Lim Kwok Eng; Roger How Keen Meng; motorsurvey  
**Subject:** RE: SHA4448A VS SJQ1925S (ECICS) DOA: 25.05.2018 \*\* 2nd email \*\*  
**Attachments:** img-525154113-0001.pdf

Without Prejudice

Dear Larry

Thank you for your email.  
We will appoint LKK for the survey.

Aside to LKK

Please assist to arrange TP PRI.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.**

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

**From:** Ng Nyuk Phin [mailto:ngnp@cdge.com.sg]  
**Sent:** Monday, 28 May, 2018 4:04 PM  
**To:** motorsurvey  
**Cc:** Lim Kwok Eng; Roger How Keen Meng  
**Subject:** SHA4448A VS SJQ1925S (ECICS) DOA: 25.05.2018 \*\* 2nd email \*\*  
**Importance:** High

Dear Motor Claims,

We are still waiting for your appointed surveyor.

Kindly arrange to survey the taxi at 59 Loyang Drive, level 4, rooftop carpark as soon as possible.

Regards,  
Larry Ng  
ComfortDelgro Engineering Pte Ltd  
Loyang Taxi Crash Repair  
6214 8316

-----Forwarded by Ng Nyuk Phin/cdge/delgronotes on 05/28/2018 04:01PM -----

To: [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg)

From: Ng Nyuk Phin/cdge/delgronotes

Date: 05/25/2018 03:44PM

Subject: SHA4448A VS SJQ1925S (ECICS) DOA: 25.05.2018

Dear Motor Claims,

Please see attached repair estimate and SAS.

Kindly arrange to survey the taxi at 59 Loyang Drive, level 4, rooftop carpark as soon as possible.

Regards,

Larry Ng

ComfortDelgro Engineering Pte Ltd

Loyang Taxi Crash Repair

6214 8316

-----Forwarded by Ng Nyuk Phin/cdge/delgronotes on 05/25/2018 03:43PM -----

To: [ngnp@cdge.com.sg](mailto:ngnp@cdge.com.sg)

From: "ApeosPort-IV C5570" <[sbs-singnalling@sbstransit.com.sg](mailto:sbs-singnalling@sbstransit.com.sg)>

Date: 05/25/2018 03:42PM

Subject: Scan Data from CDG\_LO\_AW\_A5570

(See attached file: *img-525154113-0001.pdf*)

Number of Images: 7

Attachment File Type: PDF

Device Name: ApeosPort-IV C5570

Device Location:

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed.

Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

follow us on  follow us on  visit our website  **ecics.com.sg**

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/05/2018 14:17
Date Of Accident	25/05/2018 10:40
Exact Location Of Accident	PIE TWDS CHANGI AIRPORT BEFORE LORNIE RD EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA4448R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	TAN KIAN WEE
NRIC No	S1479028D
Date Of Birth	22/03/1961
Occupation	OUTDOOR
Date Of Driving Pass	27/10/1980
Driving Experience	37 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98183319
Fax Number	
Contact Number	
EMail Address	PAGULTAN@GMAIL.COM

Address	81 21-122 STRATHMORE AVENUE
Postcode	141081
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJQ1925S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMAD FAIZ BIN MATNAWI
NRIC/Passport Number	S9007008H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT

No. Of Passenger (Including Driver)

# SKETCH PLAN

A = SHAHRIK	PIC Tuds C/Airport
B = STQ 19255	before Lane Rd
Muhammad faiz	Exit
B. Matnawii	
SQ00700814	


## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 25/5/18 @ 1040am, I was driving along PIC Tuds C/Airport on lane 1. In front a motorcycle collided onto the rear portion of the other car. Upon seeing this, I immediately braked and stopped to avoid the collision. After a split second, I felt an impact from behind. Shortly after that I found a car STQ 19255 front portion collided onto the rear portion of my taxi. 1 Male passenger on board my taxi. No one was injured at the point of accident.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CC-REG NO. 19930382-3  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Teo Yen Yee  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




COMFORT TRANSPORTATION PTE. LTD.  
CO. REG. NO. 199303821R



Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Teo Yen Yee





**From:** motorsurvey <motorsurvey@ecics.com.sg>  
**To:** Ng Nyuk Phin <ngnp@cdge.com.sg>, assignments <assignments@lkkauto.com>  
**Cc:** Lim Kwok Eng <limke@cdge.com.sg>, Roger How Keen Meng  
<rogerhow@cdge.com.sg>, motorsurvey <motorsurvey@ecics.com.sg>

---

**Date:** Monday, May 28, 2018 04:17PM

**Subject:** RE: SHA4448A VS SJQ1925S (ECICS) DOA: 25.05.2018 \*\* 2nd email \*\*

---

Without Prejudice

Dear Larry

Thank you for your email.

We will appoint LKK for the survey.

Aside to LKK

Please assist to arrange TP PRI.

Thank you.

Regards,

Janice Goh

**Claims Division**

DID: +65 6303 0182

FAX: +65 6338 9267

**ECICS Limited**

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

Team: ARC Repair TP(CLSO)1	JOB CARD Sales Order:	JC NO305164522
CUSTOMER	REGN NO: SHA4448R	MILEAGE
R/MS COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL
CUSTOMER NO 7010045	MODEL I-40	E.....1/2.....F
ADDRESS 383 SIN MING DRIVE	YR OF MANU 26.05.2016	DATE/TIME IN 25.05.2018 12:20
Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMGU089997	TARGET DATE
65508755 (O)		COMPLETION DATE/TIME:
L (R) (P)		
SCOUT CARD NO.		

Accident Date: 25.05.2018  
NATURE: 3P 25.05.2018

JOB DESCRIPTION

Q / NO	LABOR CODE	DESCRIPTION
	2C1CS	- taxi rear damage

CHECKED & PASSED OUT BY: _____	
SERVICE ADVISOR	CUSTOMER'S SIGNATURE
Acknowledgement Slip	Exit Pass
Vehicle No.: SHA4448R	Vehicle No.: SHA4448R
Signature/Date	Name of Service Advisor
Date	Date
To be kept by Security Guard	

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA 4448R

DATE 25/5/2018 14:59

MAKE :

MODEL : HYUNDAI i40

DUA: 25.05.18

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 603.60	
	Rear Bumper Reinforcement			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket		\$ 49.00	\$ 98.00	
	Rear Bumper Clips			\$ 22.00	
	Rear Bumper Sponge			\$ 143.40	
	Rear Bumper Under Cover			\$ 225.00	
	Exhaust Pipe Insulator		\$ 58.55	\$ 117.10	
	Exhaust Silencer		\$ 954.00	\$ 1,908.00	
	Exhaust Pipe Hanger		\$ 58.55	\$ 117.10	
	Exhaust Pipe Centre			\$ 1,150.30	
	<b>SUB TOTAL</b>			<b>\$ 5,248.85</b>	
	<b>LESS 20%</b>			<b>\$ 1,049.77</b>	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 4,199.08</b>	
	Rear Bumper Reverse Sensor			\$ 135.70	Nett
	Rear Bumper Rubber Mat			\$ 50.00	Nett
				<b>\$ 185.70</b>	
	<b>Labour Charge</b>			<b>200</b>	
	Panel Beating			\$ <del>280.00</del>	
	Spray Painting Charge			\$ <del>250.00</del>	200
	Wiring Charge			\$ <del>50.00</del>	X 11
	Remove/Refix Reverse Sensor			\$ <del>120.00</del>	20
	Remove/Refix Exhaust Pipe			\$ <del>360.00</del>	X 11
	<b>TOTAL LABOUR</b>			<b>\$ 1,060.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 5,444.78</b>	
<p>Ka la 10/11/14</p> <p>30/5/18 1125hs</p> <p>2 Pys</p> <p>P/P</p> <p>Be the Part phh</p>					<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party surveys on a "Without Prejudice" basis</li> <li>No illegal modification is allowed</li> <li>Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 30.05.2018  
Time: 17:02:04  
Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS: COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305164522  
REGN NO : SHA4448R  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 26.05.2016  
DATE/TIME IN : 25.05.2018 12:20  
ACCIDENT DATE : 25.05.2018

JOB/PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	603.60	20.00	482.88
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0003 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	225.00	20.00	180.00
0004 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	135.70		135.70
0005 04-01-0103-1150-A	I40VC PROTECTOR MAT	1	50.00		50.00

SUB-TOTAL : 866.18

JOB NATURE

0000 L	PANEL BEATING	200.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00
0002 L	REMOVE/REFIX REVERSE SENSOR	20.00

SUB-TOTAL : 420.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 30.05.2018

Time: 17:02:04

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS: COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305164522  
REGN NO : SHA4448R  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 26.05.2016  
DATE/TIME IN : 25.05.2018 12:20  
ACCIDENT DATE : 25.05.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,286.18

AUTHORISED : YES / NO

MVA NAME & SIGNATURE  
DATE :

SURVEYOR NAME & SIGNATURE  
DATE :

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305164522

Date : 30. May. 2018

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHA4448R

Date of Accident: 25.05.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: ECICS SJQ1925S

2. The finalized amount shall be:

(a) Spare Parts after List discount \$866.18

(b) Labour Charges \$420.00

Total for Part-By-Part Repair Cost \$1,286.18

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: \_\_\_\_\_

Final Lumpsum Repair cost \_\_\_\_\_

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : Larry Ng

Name : Kalvin

Tel : 6214 8316

Date : 30/5/18

Fax : 6546 8156

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18009659/K1VD3N2

Date: 05/06/2018

## REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SHA4448R	Insured Vehicle No :	SJQ1925S
Date of Loss:	25/05/2018	Nature of Claim:	TP
		Claim No:	DMPC1800213H

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHA4448R	Engine No:	D4FDGU625898
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMGU089997
Reg. Date:	26/05/2016 (Man. Year: 2016)	Odometer:	284291 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,384.78	866.18	3,518.60	80.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	420.00	640.00	60.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,444.78</b>	<b>1,286.18</b>	<b>4,158.60</b>	<b>76.38</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>381.13</b>	<b>90.03</b>	<b>291.10</b>	<b>76.38</b>
<b>Nett Amount (S\$)</b>	<b>5,825.91</b>	<b>1,376.21</b>	<b>4,449.70</b>	<b>76.38</b>

## INSPECTION

Date of Assignment:	28/05/2018	
Date Inspected:	30/05/2018	Inspected At:
		ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2018)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA4448R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	603.60 FL	*603.60 FL
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	504.35 FL	*- FL
3	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Serviceable	360.00 FL	*- FL
4	2		*REAR BUMPER SIDE BRACKET	Serviceable	98.00 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*REAR BUMPER SPONGE	Serviceable	143.40 FL	*- FL
7	1		*REAR BUMPER UNDER COVER	Cut	225.00 FL	*225.00 FL
8	2		*EXHAUST PIPE INSULATOR	Serviceable	117.10 FL	*- FL
9	2		*EXHAUST SILENCER	Serviceable	1,908.00 FL	*- FL
10	2		*EXHAUST PIPE HANGER	Serviceable	117.10 FL	*- FL
11	1		*EXHAUST PIPE CENTRE	Serviceable	1,150.30 FL	*- FL
12	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS
13	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,434.55</b>	<b>1,036.30</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,049.77</b>	<b>170.12</b>
<b>Total Parts (\$\$)</b>	<b>4,384.78</b>	<b>866.18</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	280.00	200.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
3	WIRING CHARGE	New	50.00	-
4	REMOVE/REFIX REVERSE SENSOR	New	120.00	20.00
5	REMOVE/REFIX EXHAUST PIPE	New	360.00	-
Gross Labour Cost (S\$)			1,060.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >