

ASS. REC. BY:

REF: CS/FCI 18009664/Knd3/72
Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person): Eileen Lee of FCI Date/Time: 28/5/18 @ 4:33pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKR 2468X Insured: SHA 1848P

at Workshop in/s: Cheng Hoe Motor Tel: 67556142

of Blk 1019 Yishun Ind. Park A# 01-374

Policy No: Claim No: D1800419/MPSH

Sum Insured: Excess:

Make of Veh: D.O.A. 24/5/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS lwp

H.O.D. Endorsement:

Date/Time: 4:35pm 28/5/18 Person Contacted: e fcedn

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SKR 2468X-X
	SHA 1848P - CS/FCI 18001415/Avd 3m2 D.O.A: 19/01/18
1/6/18	Email preli revised to FCI
16/10	82673.20 Confirm E fcedn (Red 1015.80, 28/10) (NO LS)

ASS. REC. BY:

REF:

1621

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 04 days

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

31/5 13k pass to Catherine

RECEIVED 17 OCT 2010

16/10/2018

Veh No:

SKR 2468

Yr Regn: 01, 15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Forte K3 c.c. 1591

Colour:

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

79437

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAF8411 MF5331420

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F: 215/45ZR17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

24/3/18

D.O.I.

30/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

13/10 - typist

Report Format:

Lump Sum / I.B.I. (\$) CWS

2673.20

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

130

50

50+50

24

304



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18004191MFSH

Our ref: CS/FCI18009664/Kvd3

Date : 1/6/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKR 2468X


We thank for your instruction on 28/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/5/2018 at the premises of M/s CHENG HOE MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$3,689.00
Revised Estimate Amount	: S\$2,235.80
"Check" Items Amount	: S\$437.40
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	25-05-2018	Our Ref No. D18004191MFSH
Accident Date	24-05-2018	Claim Type. Third Party
Insured Vehicle	SHA1848P	Third Party Vehicle. SKR2468X
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	EFEEDA	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240763)



PRI Documents



Close



PRI Header Details

Claim No	D18004191MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CHENG H
Workshop Name	CHENG HOE MOTOR PTE LTD (Contact Person : EFEEEDA)	Survey Location & Contact Details	BLK 1019 YISHUN IND. PARK A #01-374 Mobile: 0 , Phone: 67556142 , Fax: 67557719 EmailId: CHMOTOR@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA1848P	TP Vehicle No	SKR2468X
PRI Recieved Date	25-05-2018 04:27:29 PM	Surveyor Appointed Date	28-05-2018 04:32:37 PM	Surveyor Accept Date	28-05-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-05-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 1 June 2018 8:01 AM
To: 'Claim Workflow System'
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004191MFSH/1, SKR 2468X
Attachments: SKR 2468X PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKR 2468X
Date of survey: 30/5/2018
Number of days:4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 28 May 2018 4:42 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004191MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 28 May 2018 4:32 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004191MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6498I
Vehicle Details	
Vehicle No.:	SKR2468X
Vehicle to be Exported:	No
Intended De-registration Date:	30 May 2018
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	G4FGEH741099
Chassis No.:	KNAFZ411MF5331420
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$18,093.00
Original Registration Date:	28 Jan 2015
First Registration Date:	28 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$13,093.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jan 2025
PARF Rebate Amount:	\$9,819.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jan 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,010.00
COE Rebate Amount:	\$43,953.00
Total Rebate Amount:	\$53,772.00

The information contained herein is correct as at 30 May 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/AMK

Claim Type: Third Party

Accident Date: 24/05/2018

TP Veh Reg No: SHA1848P

Estimate No: ES1890593/YISHUN

Date: 30 May 2018

Policy No: 5076530012-02

Veh Reg No: SKR2468X

Make/Model: KIA FORTE K3-1.6 (A)

Chassis No: KNAFZ411MF5331420

Engine No: G4FGEH741099

Reg. Date: 28/01/2015

Estimate Repair Cost to Vehicle No :SKR2468X

Description	U/Price	Quantity	List Price SS	Amount SS
List Price				
1 REAR BUMPER	601.00	1 PC	601.00	✓
2 REAR BUMPER REINFORCEMENT	309.00	1 PC	309.00	✓
3 REAR BUMPER SIDE RETAINERS	28.00	2 PCS	56.00	X
4 REAR BUMPER REFLECTORS	114.00	2 PCS	228.00	✓
5 REAR BUMPER INNER LEFT CENTRE PARKING SENSOR	214.00	1 PC	214.00	✓
6 REAR BUMPER LOWER PROTECTOR	202.00	1 PC	202.00	✓
7 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
8 REAR BUMPER LOWER BRACKETS	22.00	2 PCS	44.00	✓
9 BOOTLID (LOGO)	35.00	1 PC	35.00	✓
10 REAR BOOTLID EMBLEM 'K3'	28.00	1 PC	28.00	✓
11 REAR BOOTLID EMBLEM 'FORTE'	26.00	1 PC	26.00	✓
12 REAR PANEL	506.00	1 PC	506.00	X
13 REAR LH LOWER UNDER COVER	40.00	1 PC	40.00	✓
			2,310.00	
		Less 10%	231.00	2,079.00
Labour				
14 REMOVE & REFIX REAR BUMPER & LOWER PROTECTOR, TAIL LAMPS, CUT, WELD & RENEW REAR END PANEL & REALIGN BOOTLID THE SAME	750.00	1 LA	750.00	500
15 PUTTY & RESPRAY REAR BUMPER, BOOTLID, REAR END PANEL & ALL AFFECTED AREAS	800.00	1 LA	800.00	600
16 RUSTPROOFING	60.00	1 LA	60.00	X
			1,610.00	1,610.00
			Total	SS 3,689.00

Add GST @ 7% 258.23

Total Amount Payable SS 3,947.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

For Cheng Hoe Motor Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009664/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1848P	Veh. Inspected	SKR 2468X	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004191MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	28/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA FORTE K3 (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAFZ411MF5331420	Colour	METALLIC BLUE	
Odometer	79437	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 ZR17	MICHELIN	6 mm	
L/H Front Tyre	215/45 ZR17	MICHELIN	6 mm	
R/H Rear Tyre	215/45 ZR17	MICHELIN	6 mm	
L/H Rear Tyre	215/45 ZR17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/05/2018	Inspection Date	30/05/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 2468X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	601.00	601.00
1	REAR BUMPER REINFORCEMENT	CRACKED	309.00	309.00
2	REAR BUMPER SIDE RETAINERS @\$28.00	SERVICEABLE	56.00	-
2	REAR BUMPER REFLECTORS @\$114.00	MTG CRACKED	228.00	228.00
1	REAR BUMPER INNER LEFT CENTRE PARKING SENSOR	SHORTED	214.00	214.00
1	REAR BUMPER LOWER PROTECTOR	DENTED	202.00	202.00
6	REAR BUMPER CLIPS @\$3.50	NECESSARY	21.00	21.00
2	REAR BUMPER LOWER BRACKETS @\$22.00	CRACKED	44.00	44.00
1	BOOTLID (LOGO)	NECESSARY	35.00	35.00
1	REAR BOOTLID EMBLEM "K3"	NECESSARY	28.00	28.00
1	REAR BOOTLID EMBLEM "FORTE"	NECESSARY	26.00	26.00
1	REAR PANEL	TO REPAIR SEE LABOUR	506.00	-
1	REAR LH LOWER UNDER COVER	DISTORTED	40.00	40.00
	LESS 10% DISCOUNT		-231.00	-174.80
			2,079.00	1,573.20
LABOUR				
	REMOVE & REFIX REAR BUMPER & LOWER PROTECTOR, TAILLAMPS, CUT, WELD & RENEW REAR END PANEL & REALIGN BOOTLID THE SAME. INCLUSIVE OF THE REPAIR OF REAR PANEL.		750.00	500.00
	PUTTY & RESPRAY REAR BUMPER, BOOTLID, REAR END PANEL & ALL AFFECTED AREAS.		800.00	600.00
	RUSTPROOFING.	NOT NECESSARY	60.00	-
			1,610.00	1,100.00
GRAND TOTAL			3,689.00	2,673.20
RECOMMENDED COST OF REPAIRS				2,673.20

Report Ref No. CS/FCI18009664/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.