

ATTN.:

# **EUROKARS HABITAT PTE LTD** NO:12 SUNGEI KADUT, SINGAPORE 729648



ESTIMATE COST OF REPAIRS

**AXA INSURANCE PTE LTD** NAME: MR SEOH KENG CHYE WIP: 19062

64 WEST COAST RD 8 SHENTON WAY ADDRESS: **EXCESS:** 

#02-84 #24-01 AXA TOWER DATE: 25-May-18

SINGAPORE 126832 SINGAPORE 068811

TEL:

MOTOR CLAIMS

90301770 FAX: VEH NO: SKC1770H DATE IN: CONTACT PERSON: JOBI THOMAS 6360 2446

CHASSIS NO: WMWXS520102F21218 MILEAGE: TYPE OF CLAIM: THIRD PARTY CLAIM

MODEL: DATE REG.: POLICY NO. : MINI COOPER F55 22-Feb-17

		NATURE OF	WORKS		
s/NO		Parts Description			
		QTY		REVISED	PRICES
1	FRONT FENDER LH	1	M41.00.7.374.521		\$ 492.63
2	FRONT DOOR LH	1	M41.00.7.327.445		\$ 1,136.19
3	FRONT DOOR CHECKER	1	M51.21.7.328.595		\$ 84.19
4	FRONT DOOR GASKET	1	M51.21.7.297.263		\$ 18.13
5	FRONT DOOR BOLT	2	B07.14.7.248.303		\$ 6.50
6	REAR DOOR LH	1	M41.00.7.327.449		\$ 1,136.19
7	REAR DOOR CHECKER	1	M51.22.7.322.423		\$ 84.19
8	REAR DOOR GASKET	11	M51.22.7.322.411		\$ 18.63
9	DOOR SOUND INSULATOR	1	M51.48.8.165.271		\$ 128.69
10	WING MIRROR COVER LH	1	M51.16.7.375.965		\$ 74.75
11	WING MIRROR ASSY LH	1	M51.16.7.401.095		\$ 680.56
12	FRONT WHEEL ARCH LH	1	M51.77.7.300.819		\$ 169.63
13	SIDE SKIRT LH	1	M51.77.7.315.523		\$ 258.00
14	FRONT ADHESIVE PAD	1	M51.77.7.403.246		\$ 22.25
15	REAR ADHESIVE PAD	1	M51.77.7.403.247		\$ 17.25
16	FRONT ENTRANCE	1	M51.77.7.453.185		\$ 103.31
17	REAR ENTRANCE	1	M51.77.7.453.186		\$ 81.91
18	SIDE SKIRT RIVET	12	M07.13.0.702.966		\$ 20.28
19	SIDE SKIRT EXPANDING RIVET	2	M07.14.7.422.322		\$ 9.12
20	SIDE SKIRT C-CLIP	4	B07.14.7.311.312		\$ 5.00
21	SIDE SKIRT GROMMET	4	B51.43.7.001.491		\$ 4.00
22	SIDE SKIRT CLIP BLACK	14	M07.13.1.480.419		\$ 36.82
23	SIDE SKIRT FASTENER	8	M51.71.1.496.621		\$ 10.48
24	REAR DOOR ARCH GARNISH LH	1	M51.77.7.329.031		\$ 85.69
25	REAR FENDER WHEEL ARCH LH	1	M51.77.7.318.829		\$ 101.81
26	FRONT DOOR HANDLE LH	1	M51.21.7.327.343		\$ 167.63
27	FRONT DOOR HANDLE SEAL LH	2	M51.21.7.405.768		\$ 26.00
28	FRONT DOOR QUARTER GARNISH LH	1	M51.47.7.322.509		\$ 30.38
29	FRONT DOOR OUTER STRIP LH	1	M51.33.7.322.513		\$ 90.00
30	FRONT DOOR SEAL LH	1	M51.76.7.322.455		\$ 59.13
31	DOOR TRIM RIVET	16	M65.13.8.387.414		\$ 20.00
32	DOOR TRIM GROMMET	4	M51.41.8.146.797		\$ 14.76
33	DOOR TRIM EXPANDING CLIP	6	B07.14.7.265.039		\$ 17.64
34	DOOR TRIM CLIP W/WASHER WHITE	10	851.41.8.224.768		\$ 15.60

		GRAND TOTAL	\$	٠	\$	
		GST 7%	\$		\$	
		TOTAL AFTER EXCESS	\$	*		
		LESS EXCESS	\$		\$	5-6:
		TOTAL	\$	149	\$	15,166.39
		TOTAL PARTS	\$	129	\$	5,716.3
		TOTAL LABOUR	\$	(E)	\$	9,450.0
SUNDRIES.			NETT		\$	100.0
TO REPROGRAMME AFTER THE ACCIDENT REPAIR WO				٦	350.0	
	2016				4	350.0
TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIO	NING				\$	250.0
TO TRANSFER THE FRONT & REAR DOOR LH MECHAN	ISM.				\$	1,000.0
TO CHECK STEERING GEOMETRY & COMPOCYTOLE W						
TO CHECK STEERING GEOMETRY & CONDUCT FULL W	HEEL ALIGNMENT.		NETT		\$	560.0
TO CARRY-OUT BODY CAVITY PRESERVATION.	TO CARRY-OUT BODY CAVITY PRESERVATION.					250.0
MIRROR COVER LH.						
TO RESPRAY FRONT FENDER LH, FRONT DOOR LH, REA	AR DOOR LH, REAR F	ENDER LH AND WING			\$	4,000.0
REAR FEINDER AND ALE AREAS ATTECTED STATES.						
	I AND REAR DOOR LH. TO REPAIR			3	2,340.0	
		LAND DEAD COOR HE TO BEDAIR			ć	2,940.0
<u>Labour Des</u>	cription					
		TOTAL PARTS COST			\$	5,716.39
					\$	
		TOTAL PARTS			\$	5,716.39
FRONT FENDER INDICATOR COVER LH	1	M51.13.7.448.599			\$	199.50
DOOR SEAL CLIP	10	M51.76.7.412.895	-			16.9
REAR DOOR SEAL LH	1	M51.76.7.322.457			\$	64.3
REAR DOOR QUARTER GARNISH LH	1	M51.35.7.322.445			\$	54.7
REAR DOOR HANDLE LH	1	M51.21.7.327.339			\$	134.1
	REAR DOOR QUARTER GARNISH LH REAR DOOR SEAL LH DOOR SEAL CLIP FRONT FENDER INDICATOR COVER LH  Labour Des  TO REPLACE WING MIRROR ASSY LH, FRONT FENDER I REAR FENDER AND ALL AREAS AFFECTED BY THE ACCI  TO RESPRAY FRONT FENDER LH, FRONT DOOR LH, REA MIRROR COVER LH.  TO CARRY-OUT BODY CAVITY PRESERVATION.  TO CHECK STEERING GEOMETRY & CONDUCT FULL WI TO TRANSFER THE FRONT & REAR DOOR LH MECHAN  TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIO  TO REPROGRAMME AFTER THE ACCIDENT REPAIR WO	REAR DOOR HANDLE LH  REAR DOOR QUARTER GARNISH LH  REAR DOOR SEAL LH  DOOR SEAL CLIP  10  FRONT FENDER INDICATOR COVER LH  1  Labour Description  TO REPLACE WING MIRROR ASSY LH, FRONT FENDER LH, FORNT DOOR LH REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.  TO RESPRAY FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR FMIRROR COVER LH.  TO CARRY-OUT BODY CAVITY PRESERVATION.  TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.  TO TRANSFER THE FRONT & REAR DOOR LH MECHANISM.  TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.  TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	REAR DOOR HANDLE LH  REAR DOOR QUARTER GARNISH LH  REAR DOOR QUARTER GARNISH LH  REAR DOOR SEAL CHP  REAR SEAL CHP  REAR SEAL CHP  REAR SEAL CHP  REAR SEAL CHP  TOTAL PARTS  TOTAL PARTS  TOTAL PARTS COST  Labour Description  Labour Description  TO REPLACE WING MIRROR ASSY LH, FRONT FENDER LH, FORNT DOOR LH AND REAR DOOR LH. TO REPAIR REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.  TO RESPRAY FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH AND WING MIRROR COVER LH.  TO CARRY-OUT BODY CAVITY PRESERVATION.  TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.  TO TRANSFER THE FRONT & REAR DOOR LH MECHANISM.  TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.  TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.  SUNDRIES.  TOTAL LABOUR TOTAL PARTS TOTAL LESS EXCESS TOTAL AFTER EXCESS GST 7%6	REAR DOOR HANDLE LH  REAR DOOR MANDLE LH  REAR DOOR QUARTER GARNISH LH  REAR DOOR SEAL CHP  REAR SEAD CHE SEAR SEAL CHP  REAR SEAL CHP  REAR SEAL CHP  REAR SEAL CHP  REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.  TO RESPRAY FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH AND WING  MIRROR COVER LH.  TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.  TO TRANSFER THE FRONT & REAR DOOR LH MECHANISM.  TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.  TO TRANSFER THE FRONT & REAR DOOR LH MECHANISM.  TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.  TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.  SUNDRIES.  TOTAL LABOUR  S TOTAL LABOUR  S TOTAL LABOUR  S TOTAL LAFTER EXCESS  S TOTAL AFTER EXCESS  S TOTAL PARTY  THE	REAR DOOR HANDLE LH  1	REAR DOOR HANDLE LH  1 M51.21.7.327.339  \$ REAR DOOR QUARTER GARNISH LH  1 M51.27.7.327.339  \$ REAR DOOR SEAL LH  1 M51.76.7.412.895  \$ DOOR SEAL CLIP  10 M51.13.7.448.599  \$ \$ TOTAL PARTS  \$ \$ \$ TOTAL PARTS COST  \$ \$ \$ TOTAL PARTS COST  \$ \$ \$ TO TAL PARTS COST  \$ \$ \$ TO TAL PARTS COST  \$ \$ \$ REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.  TO RESPRAY FRONT FENDER LH, FRONT DOOR LH, REAR FENDER LH AND WING  \$ \$ \$ TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.  TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.  TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.  TO CHECK STEERING AFFER THE ACCIDENT REPAIR WORKS.  \$ \$ \$ \$ \$ \$ TOTAL LABOUR  \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$

#### REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

#### SINGAPORE ACCIDENT STATEMENT

### **IMPORTANT NOTICE**

Contact Number

**EMail Address** 

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible, Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT
Date Of Report	24/05/2018 11:40
Date Of Accident	23/05/2018 18:05
Exact Location Of Accident	ALONG WEST COAST RD TOWARDS PASIR PANJANG
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKC1770H
Insured/Policyholder	
Name Of Registered Owner	SEOH KENG CHYE
NRIC No	S1532237C
Email Address	SEOHKENG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90301770
Alternative Phone No	OFFICE-90301770
Vehicle Particulars	
Manufacturer	MINI
Model	COOPER 5DR FWD LED ABS
Exact Purpose for which vehicle was being used at ime of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
f No, Please state action to be taken	THIRD PARTY
/ehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Гуре Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01003815
Cover Note Number	N.A.
Driver	
Name of Driver	SEOH KENG CHYE
NRIC No	S1532237C
Date Of Birth	18/09/1962
Occupation	INDOOR
Date Of Driving Pass	14/05/1985
Priving Experience	33 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90301770
ax Number	

OFFICE-90301770

SEOHKENG@GMAIL.COM

Address NIL

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

12-

Insurance Company of Driver's Own Vehicle

-

#### **General Information of the Accident**

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO 2 Number of vehicles involved in the accident Was any body injured in the Accident? NO Was any injured conveyed to hospital by NO ambulance? Was any other material or property damaged? YES I have been approached by unknown person(s) NO soliciting/offering accident claims assistance. Number of Passengers (Including Driver) 1

#### **Details of Police Action**

Was the accident reported to the police?

If Yes, Please state which Police Station

Police Station Name CLEMENTI N.P.C

Police Station Address ROAD: 20 CLEMENTI AVE 5 , POSTCODE: 129858 , COUNTRY:

**SINGAPORE** 

YES

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### **Circumstances of Accident**

Brief Details. On the 23rd of May 2018 at about 1803 hrs, I was driving my car SKC 1770 H along West Coast Road on the first lane, heading towards Pasir Panjang Road negotiating a S-bend when a car SKR 174 G which was travelling on the left lane hit the left side of my car causing dent and serious damage to the left side of my car. I did not stop my car and headed straight home. The other car followed me back to my condominium basement carpark. There, she scolded me and we did not exchange our particulars at that time. I reported the accident to my insurance via phone and was told to bring my car in for damage evaluations. No one was injured and no ambulance was called to the scene. 2. After the accident, I went for a medical check-up at Silvercross Healthcare Pte Ltd located along Cheong Chin Nam Road as I felt spraint on my neck. I was given a day MC for 24th May 2018. The medical fee for the check-up is at \$55.25/-.

#### Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING FROM INSURED

Was there any audio recorded?

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKR174G

Vehicle Make/Model/Colour TOYOTA/ ALTIS/ SILVER

Details Of Properties NA

Vehicle Category PRIVATE CAR

Name of Driver UNKNOWN DRIVER

NRIC/Passport Number

Contact Number NA
Address NA
Postcode
Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authroised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 8. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties
- 7. By the loggement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Concent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) proceeding, hendling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) Investigating the accident and/or my claims:

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

- (hr) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

24/x/18 110x0m


VERIFIED BY AJAX MARS REPORTING OFFICER THOMAS NG CHIN CHUN

Policyholi

er's Signature / Date & Time Oriver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan







Police Station Of Origin: Clementi N.P.C 20 Clementi Avenue 5 SINGAPORE 129858 Tel No: 1800-8729999 1 of 3 Report No. T/20180523/2155

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/05/2018 22:16			Vide Report No.:	Station Diary No.:		
Informant	's Particul	ars				
Name of Informant: SEOH KENG CHYE JIMMY			Address: 64 WEST COAST ROAD #02-84 SINGAPORE 126832			
ID Type / ID No.: NRIC NO / S1532237C			Contact No.: Home/Office:	Mobile: 90301770		
Nationality SINGAPO		N	Email:			
Sex:         Age:         Date of Birth:           Male         55         18/09/1962			Type of Informant: Driver			
Race: Chinese			Language: English	Institution / School Name:		
Occupation: PROCESS SUPERVISOR			Driving Licence Informatio Class: 2B,3	n: Date of Expiry:		

General Informat	ion of the Accider	nt		
Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 23/05/2018 18:09	Type of Location: S-bend
Location:	54			8.
WEST COAST R	OAD		e	
Along West Coa		ir Panjang, just after C	Clementi Bible Church	h at the S-bend. I was
Weather:	5 5 12 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Road Surface:		Road Speed Limit:
Clear		Dry		50 Km/h
Traffic Flow:		Traffic Control:		Traffic Volume:
One Way				Moderate *
Type of Collision:	41	11	15	Anyone conveyed by
Between Moving	ambulance:			
	027			No

Details of Vehicle Involved								
Vehicle No.	Туре	Make	Model	Color		Condition	No of Passenger	
SKC1770H	Car	MINI	COOPER 5DR FWD LED ABS	Blue		Seriously Damaged	0	
SKR174G	Car					Seriously Damaged	0 (4)	

Details of Vehicle Insurance					
Vehicle No. Insurance Company	Insurance No	Effective	Expiry Date		





0 -40

2 of 3 Report No. T/20180523/2155

Police Station Of Origin: Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999

**CONTINUATION OF REPORT** 

Details of Vehicle Insurance							
Vehicle No. Insurance Company		Insurance No	Effective	Expiry Date			
SKC1770H	TENET SOMPO INSURANCE PTE.	D18MTPV0100381	22/02/2018	21/02/2019			
	LTD.	5					

<b>Details of Perso</b>	n involved					
Any Pedestrian Ir	nvolved: No					
No. of Pedestrian	s Injured: NIL		Use of Peo	destriar	Cross	sing: NA
Driver		JAS STREET				是自己的"自己的"。
Name	JIMMY		ID No.		S1532237C	
Related Vehicle	SKC1770H (Car) SILVER CROSS HEALTHCARE PTE LTD			Class of Driving Licence & Expiry Date		9030177 <b>0</b>
Hospital/Clinic						Class: 2B,3 Date of Expiry: NIL
Date Treatment.		Date Disc	harge	23/05	5/2018	
No. of Days granted Medical Leave 01			Degree of	Injury	NIL	

## Brief Details.

On the 23rd of May 2018 at about 1803 hrs, I was driving my car SKC 1770 H along West Coast Road on the first lane, heading towards Pasir Panjang Road negotiating a S-bend when a car SKR 174 G which was travelling on the left lane hit the left side of my car causing dent and serious damage to the left side of my car. I did not stop my car and headed straight home. The other car followed me back to my condominium basement carpark. There, she scolded me and we did not exchange our particulars at that time. I reported the accident to my insurance via phone and was told to bring my car in for damage evaluations. No one was injured and no ambulance was called to the scene.

2. After the accident, I went for a medical check-up at Silvercross Healthcare Pte Ltd located along Cheong Chin Nam Road as I felt spraint on my neck. I was given a day MC for 24th May 2018. The medical fee for the check-up is at \$55.25/-.





3 of 3

Report No. T/20180523/2155

Police Station Of Origin: Clementi N.P.C 20 Clementi Avenue 5 SINGAPORE 129858 Tel No: 1800-8729999 **CONTINUATION OF REPORT** 

## Sketch Plan

NP168

SINGAPORE

POLICE FORCE

STEMATURE

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D / SI FADIL BIN MASIRAN	Signature Of Informant:
Signature Of Interpreter  Not applicable	Date/Time: 23/05/2018 22:16
Officer In Charge Of Case: TP / GIA / Staff Sgt TANG SIEW PING Contact No.: 65476430	Classification Of Case:

SN 37



## Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Tel: 6461 6555 1 Fax: 6221 3302 1 Website: www.sompo.com.sg Co. Reg. No.: 198905490E / GST Reg. No.: M200903196

#### PRIVATE CAR POLICY SCHEDULE

Intermediary Code: 11V02903

Policy No.: D18MTPV01003815

1,717.00

(858.50)

(42.93)

S\$ 774,79

S\$ 54.24

S\$ 829.03

(40.78)

This Schedule is issued in accordance and should be read in conjunction with the terms, conditions and exceptions of the PRIVATE CAR Policy wordings, ref. MTP.27

Insured

: SEOH KENG CHYE

Address

: 64 WEST COAST ROAD

#02-84

VARSITY PARK SINGAPORE 126832

Business/Profession

: SUPERVISOR

INSURED DETAILS

Date of Birth & Age : 18 SEP 1962 & 55 years old

Martial Status: MARRIED

Driving Experience in 16 years

Gender: Male

Singapore

Identification Type : NRIC(Singaporean)

Identification No.: S1532237C

PREMIUM DETAILS

Less No Claim Discount (50%)

Less Loyalty Discount(5%)

Premium (incl. GST)

Less Offence free Discount (5%)

Premium

Total **GST** 

Add others :

Period of Insurance

: 22 FEBRUARY 2018 00:00 TO 21 FEBRUARY 2019 23:59

Persons or Classes of Persons entitled to drive: Refer to Certificate of Insurance

Limitations as to use

: Refer to Certificate of Insurance

٧	E.	Н	IC	LE	: D	E	T/	١	L	3
	_					_			_	

Vehicle Registration No. : SKC1770H

Chassis No.

WMWXS520102F21218

Engine No.

32399842B38A15A

Vehicle Make & Model

MINI COOPER 5 DR

Engine Capacity/Tonnage

1499 : HATCHBACK

Type of Body

Year of Registration

2017

Seating Capacity (including driver)

: 4

Estimated value of Vehicle

Market value at time of loss

Hire Purchase Owner

DBS

Coverage

Comprehensive - ExcelDrive PRESTIGE

Excess

\$ 500 - Section I

(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy

vear)

Voluntary Excess

N.A

Additional Excess

Young and/or Inexperienced Drivers or Elderly Drivers - \$1,500

Un-named Young and/or Inexperienced Drivers or Elderly Drivers - \$3,000

Un-named All Other Drivers

The terms shall be defined as follows:

'Young Drivers' shall be defined as drivers (including the Insured) who are below 25 years old.

'Inexperienced Drivers' shall be defined as drivers (including the Insured) who have less than 2 years of

driving experience in Singapore

'Elderly Drivers' shall be defined as drivers (including the Insured) who are above 70 years old.

Paragraph 2 of Endorsement E in the policy will not apply to insured's spouse provided he/she is 25 years

old & above but less than 70 years old &/or has 2 or more years driving experience.

Windscreen Excess

\$\$100,00 - Waived if Repair at ExcelDrive Workshop

**Endorsements Applicable** 

Endorsement D - Young and/or Inexperienced or Elderly Drivers Excess

Endorsement E - Excess Clause Endorsement H - Total Loss Endorsement L - Hire Purchase

Endorsement M - Inclusion Of Special Perils Endorsement P6 - Riot And Strike Endorsement Endorsement V - No Claim Discount Protection



## REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$1532237C





SEOH KENG CHYE JIMMY

建 才

CHINESE Date of birth 18-09-1962

S15322370

Country/Place of both SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES! PASS DATE Class 2B Motorcycles not exceeding 200 cc Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 killograms NP 428A

5803403



21-09-2017

Address

64 WEST COAST ROAD #02-84 SINGAPORE 126832



# GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

## Third Party Insurer Enquiry

Our Ref No:

GR-18-079283

Date of Request:

24/05/2018

Your Ref No:

Online Purchase

SKC1770H CMimi)

Eurokars Habitat Pte Ltd 12 Sungei Kadut Avenue Singapore 729648

Dear Sir/Madam,

**Enquiry Date** 

24/05/2018

Enquiry By

Jessica Harry Shastri

TP Vehicle No.

SKR174G

Accident Date

23/05/2018

**Enquiry Result** 

Enquiry Result							
TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.				
SKR174G	AXA Insurance Pte Ltd	13/01/2018-12/01/2019	6338 7288				

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.