

INS. CASE OWNER:

CC 4, AXA 1800 9705 / 6 jasyd

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

EOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

VIDEO EVIDENCE
FROM TP

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 350

COPY SENT
29/6/18

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s Jack Cars
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GlA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ1885 L Yr Regn: 30 Nov 2016
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Honda Vezel 1.5X cc 1496
 Colour: white A/C Insured / Std / NI / NA
 Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: RU 31209513

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16
 R: 11

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm

D.O.A. _____ D.O.I. 31-05-18
 Survey held at w/s 5:10pm

Des. of Damages: Frt / Rear ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

101 \$4,898

R (\$ 8,765.90 / 64%)

Date/Time, File Pass to? ☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

) \$ - RS - SI

) Photos

) Other:

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

ESTIMATE

DATE OF ACCIDENT : 24/05/2018
VEHICLE : SLJ1885L
MAKE & MODEL : HONDA VEZEL
INSURANCE : AXA INSURANCE
SURVEYOR : LKK AUTO

PARTS		CONDITION	COST
1.	FRONT RIGHT DOOR / <i>gone</i>		\$ 1580
2.	REAR RIGHT DOOR / <i>gone</i>		\$ 1430
3.	REAR RIGHT DOOR WEATHERSTRIP / <i>Tw</i>		\$ 280
4.	CENTRE WEATHERSTRIP / <i>TN</i>		\$ 420
5.	RIGHT SIDE SKIRT / <i>cut</i>		\$ 420
6.	RIGHT ROCKER PANEL x <i>repair</i>		\$ 780
7.	REAR RIGHT WHEELARCH / <i>scr</i>		\$ 280
8.	REAR RIGHT POWER WINDOW MOTOR ?		\$ 680
9.	REAR RIGHT DOOR POWER WINDOW FRAME ?		\$ 530
SPECIAL NETT			
1.	REAR RIGHT TYRE / <i>cut</i>		\$ 350
2.	FRONT RIGHT RIM x <i>NN</i>		\$ 620
3.	SILICON SEALANT / <i>gone</i>		\$ 200
4.	CLIPS / <i>gone</i>		\$ 100
LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	<i>400.</i>	\$ 2000
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	<i>400.</i>	\$ 3200
3.	TO CHECK WIRING & REWIRE	<i>NN X</i>	\$ 180

150



JACK CARS

4.	TO REMOVE AND REINSTALL DOORS	120	\$ 500
5.	TO REMOVE & INSTALL POWER WINDOW MECHANICAL & ELECTRICAL PARTS	NP X	\$ 250
6.	TO REMOVE AND REINSTALL WINDOWS	X	\$ 250
	PARTS - 20% :		\$ 5,120
	SPECIAL NETT :		\$ 1,270
	LABOUR :		\$ 6,380
	TOTAL :		\$ 12,770
	7% GST :		\$ 893.90
	GRAND TOTAL :		\$ 13,663.90

4 Days .

part by part .

before paint photos .

Guo Qian - 82880282

31/5/18

LKK Auto Centre Ltd. hereby notify the repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(New Assignment)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	25 May 2018		25 May 2018 17:37 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	TRANS-CAB SERVICES PTE LTD		
Main Claimant:	NOUVEAUX ARRIVANTS SERVICES		
Vehicle Reg. No.:	SLJ1885L	Date of Loss:	24/05/2018 17:00 - :59
Claim Type:	TP / C0473778	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHD9990S	Policy No. (Claimant):	
Repairer:	- Not Applicable - (-)	Excess:	S\$5,000.00
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/06/2018]		
Driver/Custodian (Insured):	LEE KHENG HUAT (63 / Male), NRIC: S1105365C, Tel: +6583142673		

ASSOCIATED MAIL RECEIVED

- AXA_SG (25/05/2018): C0473778/P1680520
- AXA_SG (25/05/2018): New TP Assignment - C0473778/P1680520

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

11:05am @ 28/05/2018
vehicle not in
person @ amber

KUMAR Shailendra

From: Thanaletchumi Santerashigaram <thana@jackcars.com.sg>
Sent: Friday, May 25, 2018 2:10 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey; SG AXA Insurance SM Claims Service Team
Subject: PRI of SLJ1885L
Attachments: PRI FORM.pdf
Categories: Shailendra

Greetings ,

Attached would be the PRI of SLJ1885L for your kind perusal.

Kindly revert.

Thank You.

*Best Regards ,
S.Thanaletchumi (Ms)
JACK CARS ENTERPRISE PTE LTD
Office : 67488824
Mobile : 92206746
Fax : 67488834
Email : thana@jackcars.com.sg*

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Wednesday, 20 June 2018 1:22 PM
To: 'Thanaletchumi Santerashigaram'
Cc: Admin A
Subject: SLJ1885L on 24.05.2018 *** LKK REF: CC4/AXA18009705/ja3 (AXA SHD 99905)

WITHOUT PREJUDICE

Dear Madam,

We refer to the subject.

We have reviewed the provided evidence (video footage) and we are of the view that your client is more liable of this incident.

Video showed your client driver cut/crossed lanes from the leftmost lane to turn right causing the collision with our insured driver who was travelling straight.

In view of this, regret to inform you that we are unable to look into your claim.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Thanaletchumi Santerashigaram [mailto:thana@jackcars.com.sg]
Sent: Thursday, 31 May 2018 4:33 PM
To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Subject: Re: PRI of SLJ1885L *** LKK REF: CC4/AXA18009705/ja3

Greetings Ms. Joy ,

Kindly revert on the liability of my client SLJ1885L.

Thank You.

Best Regards ,
S.Thanaletchumi (Ms)
JACK CARS ENTERPRISE PTE LTD
Office : 67488824
Mobile : 92206746
Fax : 67488834
Email : thana@jackcars.com.sg

Print Received Message

This mail is associated with :

***SLJ1885L (C0473778)
[SHD9990S]**

TP

NOUVEAUX ARRIVANTS SERVICES

May 24 2018 5:00PM

[TRANS-CAB SERVICES PTE LTD]

Jack Cars Enterprise Pte Ltd - Ubi

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 13/06/2018 10:14 AM.
To LKK_HQ
Subject Re: C0473778 / ACC INVLG SHD9990S (INSD) & SLJ1885L ON 24.05.18



AXA INSURANCE PTE LTD
8 Shenton Way, #24-01 AXA Tower
Singapore 068811
Customer Centre #01-01
☎ (65) 6881 8888
✉ (65) 6888 2422
🌐 www.axa.com.sg
GST Reg No.: S98053612M
Co. Reg No.: 198805012M

Dear LKK

Please proceed to reject third party claim.

Regards

Saw Theng

Dear LKK,

ID counter claim TP.

TP admitted in GIA report that he switched lane.

Please obtain evidence and liaise with OI before any settlement.

Thanks & Regards,
Cynthia Loh

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 May 2018		25 May 2018 17:37 Edit Adj Rpt	S\$4,898.00 Edit Estimates	S\$4,898.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Main Claimant:	NOUVEAUX ARRIVANTS SERVICES, Co. Reg. No.: 53312026L		
Vehicle Reg. No.:	SLJ1885L	Date of Loss:	24/05/2018 17:00 - :59 [17 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0473778	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHD9990S	Policy No. (Claimant):	5086502637-01
		Excess:	S\$5,000.00
Repairer:	Jack Cars Enterprise Pte Ltd - Ubi (HQ) BLK 3007 UBI ROAD 1 #01-450, 408701 Ubi - Tel:		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 06/06/2018]		
Driver/Custodian (Insured):	LEE KHENG HUAT (63 / Male), NRIC: S1105365C, Tel: +6583142673		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AXA_SG (13/06/2018): Re: C0473778 / ACC INVLG SHD9990S (INSD) & SLJ1885L ON 24.05.18
- AXA_SG (05/06/2018): C0473778 / ACC INVLG SHD9990S (INSD) & SLJ1885L ON 24.05.18
- AXA_SG (25/05/2018): C0473778/P1680520
- AXA_SG (25/05/2018): New TP Assignment - C0473778/P1680520

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLJ1885L (C0473778)**
[SHD99905]
TP
NOUVEAUX ARRIVANTS SERVICES
May 24 2018 5:00PM
[TRANS-CAB SERVICES PTE LTD]
Jack Cars Enterprise Pte Ltd - Ubi

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser v		
Video															1 per page v		☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)										Thumbnail		Print			
1	13/06/18 10:10	SCENE VIDEO											Load MP4				
Photos/Images															3 per page v		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	20/06/18 13:24	REJECTION EMAIL											Load PDF				
2	20/06/18 13:25	General View											Load JPG	☒			
3	20/06/18 13:25	General View											Load JPG	☒			
4	20/06/18 13:25	General View											Load JPG	☒			
5	20/06/18 13:25	General View											Load JPG	☒			
6	20/06/18 13:25	General View											Load JPG	☒			
7	20/06/18 13:25	General View											Load JPG	☒			
8	20/06/18 13:25	General View											Load JPG	☒			
9	20/06/18 13:25	General View											Load JPG	☒			
10	20/06/18 13:25	General View											Load JPG	☒			
11	20/06/18 13:25	General View											Load JPG	☒			
12	20/06/18 13:25	General View											Load JPG	☒			
13	20/06/18 13:25	General View											Load JPG	☒			
14	20/06/18 13:25	General View											Load JPG	☒			
15	20/06/18 13:25	General View											Load JPG	☒			
16	20/06/18 13:25	General View											Load JPG	☒			
17	20/06/18 13:25	General View											Load JPG	☒			
18	20/06/18 13:25	General View											Load JPG	☒			
19	20/06/18 13:25	General View											Load JPG	☒			
20	20/06/18 13:25	General View											Load JPG	☒			
21	20/06/18 13:25	General View											Load JPG	☒			
22	20/06/18 13:25	General View											Load JPG	☒			
23	20/06/18 13:25	General View											Load JPG	☒			
Documentation															1 per page v		☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)										Thumbnail		Print			
1	25/05/18 14:26	EMAIL											Load PDF				
2	25/05/18 14:26	SHD99905 INS GIA											Load PDF				
3	25/05/18 14:26	SLJ1885L TP GIA											Load PDF				
4	25/05/18 14:29	CO CLAIMANT TP											Load PDF				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	03/06/18 17:24	Immediate Advice											Load PDF				
2	05/06/18 10:10	TP ESTIMATE - MARKED											Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18009705/GJA3Q2

Date: 25/06/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No: P1680520

Claimant Vehicle No : SLJ1885L

Insured Vehicle No : SHD9990S

Date of Loss: 24/05/2018

Nature of Claim: TP

Claim No: C0473778

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ1885L

Make & Model: HONDA VEZEL, 1.5 X HYBRID CVT (A)

Engine No: LEB5909524

Reg. Date: 30/11/2016 (Man. Year: 2016)

Chassis No: RU31209513

Colour: White

Odometer: 0 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,390.00	3,978.00	2,412.00	37.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,380.00	920.00	5,460.00	85.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,770.00	4,898.00	7,872.00	61.64
+ GST 7.00/7.00% (S\$)	893.90	342.86	551.04	61.64
Nett Amount (S\$)	13,663.90	5,240.86	8,423.04	61.64
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 25/05/2018

Date Inspected: 31/05/2018 Inspected At:

Jack Cars Enterprise Pte Ltd - Ubi (HQ)

BLK 3007 UBI ROAD 1 #01-450

Singapore 408701

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 X HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ1885L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT DOOR (CONSISTENT)	Buckled	1,580.00 FL	*1,580.00 FL
2	1		*REAR RIGHT DOOR (CONSISTENT)	Buckled	1,430.00 FL	*1,430.00 FL
3	1		*REAR RIGHT DOOR WEATHERSTRIP (CONSISTENT)	Twisted	280.00 FL	*280.00 FL
4	1		*CENTRE WEATHERSTRIP (CONSISTENT)	Torn	420.00 FL	*420.00 FL
5	1		*RIGHT SIDE SKIRT (CONSISTENT)	Cut	420.00 FL	*420.00 FL
6	1		*RIGHT ROCKER PANEL (CONSISTENT)	Repair	780.00 FL	*- FL
7	1		*REAR RIGHT WHEELARCH (CONSISTENT)	Scratched	280.00 FL	*280.00 FL
8	1		*REAR RIGHT POWER WINDOW MOTOR (CONSISTENT)	*Check	680.00 FL	*- FL
9	1		*REAR RIGHT DOOR POWER WINDOW FRAME (CONSISTENT)	*Check	530.00 FL	*- FL
10	1		*REAR RIGHT TYRE (CONSISTENT)	Cut	350.00 FS	*150.00 FS
11	1		*FRONT RIGHT RIM (CONSISTENT)	Not Necessary	620.00 FS	*- FS
12	1		*SILICON SEALANT (CONSISTENT)	Necessary	200.00 FS	*200.00 FS
13	1		*CLIPS (CONSISTENT)	Necessary	100.00 FS	*100.00 FS
					Sub Total (\$\$)	7,670.00 4,860.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,280.00 882.00
					Total Parts (\$\$)	6,390.00 3,978.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	2,000.00	400.00
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	3,200.00	400.00
3	TO CHECK WIRING & REWIRE	New	180.00	0.00
4	TO REMOVE AND REINSTALL DOORS	New	500.00	120.00
5	TO REMOVE & INSTALL POWER WINDOW MECHANICAL & ELECTRICAL PARTS	New	250.00	0.00
6	TO REMOVE AND REINSTALL WINDOWS	New	250.00	0.00
Gross Labour Cost (S\$)			6,380.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >