


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1477L
 Ref. No : BUS/05/18/5037
 Reg. Date : 01/01/1900
 Vehicle Type : BUS -12M
 Make : MAN
 Model : MAN
 Name of Driver : Shen Pengtao
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 17/05/2018 11:54:00 AM
 Accident Reported Date / Time : 22/05/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : AIG
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 damages to the rear portion of bus
 Prepared Date : 22/05/2018 02:02:07 PM



Sebastian
 24/5/18

- Imp Sum Repair.
 - Photo After Paint.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 2,650.00	0.00
Total Spray Painting Charges	: 1,480.00	0.00
Total Material Charges	: 0.00	0.00
Other Charges	: 0.00	0.00
TOTAL	: 4,130.00	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	0.00
Prepared / Adjusted By	: Sim Kim Bock	4 days
Arc / Surveyor Sign Off Date	: 01/01/1900 12:00:00 AM	01/01/1900 12:00:00 AM


Prepared / Adjusted Date :

Remarks :

Prepared Date : 22/05/2018 04:08:46 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :



Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	2,650.00	0.00 2120
Total Labour	2,650.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,480.00	0.00 1338
Total Spray Painting & Panel Beating	1,480.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
F01001-CW274		6010064	REAR BUMPER CENTER	1	1,868.80	10.00	1,681.92	Replace	Replace <i>✓</i>	No
F01001-CW272		6010061	REAR ENGINE DOOR	1	1,868.80	10.00	1,681.92	Replace	Replace <i>✓</i>	No
F01001-CW273		6010062	REAR TAIL LAMP COVER RH	1	974.70	10.00	877.23	Replace	Replace <i>✓</i>	No
F01001-CW271		6010060	REAR TAIL LAMP COVER LH	1	974.70	10.00	877.23	Replace	Replace <i>✓</i>	No
S01001-CW002		6010464	ATTACHMENT BRACKET	1	569.30	10.00	512.37	Replace	Replace <i>✓</i>	No
4001G01-GSP438	REAR	6010412	GAS SPRING 500N	2	241.50	10.00	434.70	Replace	Replace <i>✓</i>	No
S01001-CW006		6010463	FRAME REAR BUMPER	1	1,423.20	10.00	1,280.88	Replace	Replace <i>✓</i>	No
		4	60KM/H STICKER	1	15.00	0.00	15.00	Replace	Replace <i>✓</i>	No
	COMMO N		SMRT LOGO	1	35.00	0.00	35.00	Replace	Replace <i>✓</i>	No
TOTAL MATERIALS								7,396.25	7,396.25	
TOTAL MATERIALS(Discounted)								0.00	0.00	
Added Spare Parts / Material Usage After Surveyor Signed off										

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									