

22/03/2002

ASS. REC. BY:

REF: CS/ICS18009735/TI sd36 Special Instruction:

Surveyor:
Merimer

ASSIGNMENT (Office)

From (Person): Janice Goh of EC/CS Date/Time: 30/5/18 @ 3:16pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No: S1Q 1925S Insured:

at Workshop m/s Woon Meng Motor Tel: 6316 1131

of 50 Bukit Batok St. 23

Policy No: MPC18A00091102 Claim No: DMPC1800213H

Sum Insured: Excess: \$500.00

Make of Veh: D.O.A. 25/05/2018
(Client's Record)CA / REV / REP. / REV 24 HRS 31/05/2018 @ Morning
H.O.D. Endorsement:

Date/Time: 3:37pm @ 30/5/18 Person Contacted: Ms. Heng Vehicle: IN/OUT

Date/Time Action/Instruction (✓) Estimate Inp of bukit batok.

S1Q1925S - CS/ICS18009659/vd3 - 25/05/2018

01/06/18 @ 15:26 p.m. revised IA to Janice Goh via merimer.

01/06/18 @ 15:30 p.m. mandate requested authorization to Janice Goh via merimer.

07/06/18 @ 10:52 a.m. mandate approved by Janice Goh.

07/06/18 @ 10:57 a.m. sent the mandate to Mr. Heng (Surveyor) via email.

Surrender

Taufan

REF: ECICS

ASSIGNMENT

From: Date: 31/5/18

Estimated Cost:

(OD) TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJQ 1925S
at Workshop m/s Woon Meng Motor
of 50 Bukit Batok St. 23

Insured:

Policy No.

Claims No.


Sum Insured: Excess: \$500

(Client's Record)

Morning

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$11K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / (REV) / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Woon Meng

Veh No: SJQ 1925S Yr Regn: 2009, April.
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Woon Meng Motor Co. 1399

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 14/103 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNADE2 41296523945

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Woon Meng

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I.

31/5/18 @ 11/20

Survey held at

Woon Meng Motor BR

Des. of Damages: (Prt) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rebate 6152

L/S \$1,935.00 Red - 40%

L/S \$1,300, 7 days

RECEIVED 17 JUL 2018

Date/Time. File Pass to?

17/07/18

1) Typist

Date/Time. File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 3,300.00 4/5

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation

) S + RS SI

) Photos

) Others

TOTAL

290

10

260

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2018 14:33 Sendback Est	28 May 2018 14:56 S\$5,235.00	30 May 2018 15:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	MOHD SUYUTI BIN ABDULLAH, ID: S1676966E, Email: muhdfaiz.matnawi@gmail.com			
Vehicle Reg. No.:	SJQ1925S	Date of Loss:	25/05/2018 10:00 - :59 [108 Months and 27 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / DMPC1800213H	Policy/Cover Note No.:	MPC18A00091102 (Comprehensive)	
		Excess:	S\$500.00	
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131			
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/06/2018]			
Driver/Custodian:	MUHAMMAD FAIZ BIN MATNAWI (28 / Male), NRIC: S9007008H, Tel: +6586662620			
Adj Asg. Remarks:	PLEASE BE INFORMED THAT THIS CASE IS HANDLE BY DESMOND LEE.			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Heng Sew Sow <woonmeng@singnet.com.sg>
Sent: Tuesday, 17 July 2018 12:59 PM
To: 'Shirley Hiew (LKK Auto)'
Cc: 'Taufikh (LKK Auto)'; sur@lkkauto.com
Subject: RE: after photo of SJQ1925S

Dear Shirley

Accept your offer \$3300.00

Thank you.

Best Regards,
Heng Sew Sow (Ms)
Woon Meng Motor Pte Ltd
Tel: 6316 1131/51
Fax: 6316 7050

-----Original Message-----

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, 17 July 2018 9:57 AM
To: 'Heng Sew Sow' <woonmeng@singnet.com.sg>
Cc: 'Taufikh (LKK Auto)' <taufikh@lkkauto.com>; sur@lkkauto.com
Subject: RE: after photo of SJQ1925S

Hi Ms Heng,

Re-confirmed COR I/s \$3300 , 7 days.

Thank you.

Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, 13 July 2018 3:42 PM
To: 'Heng Sew Sow' <woonmeng@singnet.com.sg>
Cc: 'Taufikh (LKK Auto)' <taufikh@lkkauto.com>
Subject: RE: after photo of SJQ1925S

Hi Ms. Heng,

Enclosed marking estimate for SJQ 1925S.

Thank you.
Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]

Sent: Friday, 13 July 2018 9:09 AM

To: 'Heng Sew Sow' <woonmeng@singnet.com.sg>

Cc: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>

Subject: RE: after photo of SJQ1925S

Hi Ms Heng,

COR I/s \$3050 , 7 days.

Regards

Taufikh

Lkk Auto

-----Original Message-----

From: Heng Sew Sow [mailto:woonmeng@singnet.com.sg]

Sent: Thursday, 12 July 2018 2:02 PM

To: 'Taufikh (LKKAuto)'; 'SUR'

Subject: after photo of SJQ1925S

Your message is ready to be sent with the following file or link
attachments:

IMG_8717

IMG_8718

IMG_8714

IMG_8715

IMG_8716

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

View Received Message

This mail is associated with :

SJQ1925S (DMPC1800213H)

OD

May 25 2018 10:00AM

[MOHD SUYUTI BIN ABDULLAH]

Woon Meng Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 07/06/2018 10:52 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4597.40) - SJQ1925S - Claim Handler: Janice Goh

Approved:4597.40.

DOCUMENTS SUMMARY

There are no documents.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 7 June 2018 10:57 AM
To: 'Heng Sew Sow'
Cc: sur@lkkauto.com
Subject: SJQ 1925S OD (ECICS)

Dear Ms. Heng,

As instructed by our client, please proceed to repair the insured vehicle **SJQ 1925S (Excess \$ 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Janice Goh

Date: 01 Jun 2018

Preliminary Advice

Vehicle No	: SJQ1925S	Accident Date	: 25/05/2018
Make	: KIA RIO	Policy No.	: MPC18A00091102
Assignment Date	: 30/05/2018	Excess	: S\$500.00
Date of Inspection	: 31/05/2018	Est. Duration of Repair	: 7 days
Inspection At	: Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building Singapore 659578		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,235.00
Revised Amount	:S\$	3,376.40
Check Items (Estimated)	:S\$	1,221.00
Total	:S\$	4,597.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	11,000.00
COE / PARF Rebate	:S\$	6,130.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,870.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/05/2018 14:34
Date Of Accident	25/05/2018 10:45
Exact Location Of Accident	PIE TOWARDS CHANGI (BEFORE LORNIE EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ1925S
Insured/Policyholder	
Name Of Registered Owner	MOHD SUYUTI BIN ABDULLAH
NRIC No	S1676966E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91540609
Alternative Phone No	OFFICE-91540609

Vehicle Particulars

Manufacturer	KIA
Model	RIO 1.4L M/T ABS AIRBAG 2WD 5DR

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00091102
Cover Note Number	

Driver

Name of Driver	MUHAMMAD FAIZ BIN MATNAWI
NRIC No	S9007008H
Date Of Birth	26/02/1990
Occupation	OUTDOOR
Date Of Driving Pass	17/02/2011
Driving Experience	7 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86662620
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 693, JURONG WEST CENTRAL 1, #04-93
Postcode	640693
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA4448R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN KIAN WEE
NRIC/Passport Number	S1479028D
Contact Number	98183319
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 25/5/18 @ 1425

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Please note that you might be able to submit an Own Damage Claim under own policy within 14 days.

☒ Claim Own Damage ☐ Claim TP ☐ Reporting Only ☐ Claim OD/TP at other workshop

Workshop Name : _____

SKETCH PLAN

A-SJG1925S
B-SHA4448R

A B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25 May 2018 at about 1045hrs, I was travelling ~~towards~~ along PIE towards Changi near Lornia Exit. Upon nearing the speed camera, the vehicle in front, one Comfort delgro Taxi, SHA4448R, jammed brake. As I was not able to brake in time, I hit onto the rear of the Taxi.

When I exited my vehicle, the driver namely Tan Kian Wee, claimed there is an accident in front of him. About 15 metres in front of his vehicle, there is one motorcycle, FW4374G, one car, SFP3361H.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 25/5/18 1425

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Woon Meng Motor Pte Ltd (Co.Reg.No:200603678M)
 50 Bukit Batok Street 23., #01-06 Midview Building
 Singapore 659578
 Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg

INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
 Policy No: MPC18A00091102
 Vehicle Reg. No.: **SJQ1925S**
 Driver Age/Info: 28 / MALE
 TP Injury Involved? NO
 Insured/Claimant: MOHD SUYUTI BIN ABDULLAH
 Driver: MUHAMMAD FAIZ BIN MATNAWI

Ref. No:
 Date of Loss: 25/05/2018
 Driveable?
 Party At Fault: UNKNOWN
 Third Party Involved? YES

Make/Model: KIA RIO, 1.4 5DR
 Vehicle Colour: SILVER
 Engine No: G4EE9H214980
 Odometer: 141102 KM

Vehicle Reg. Date: 28/04/2009
 Chassis No: KNADE241296523945

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair (day) 12

Description of Accident/Loss: REFER TO ATTACHED SKETCH PLAN.
 Present Location: WOON MENG MOTOR PTE LTD (BUKIT BATOK)

*Tanpin 97495749
 Ex \$500
 Not Authorise
 31/5/18 @ 1120
 Resurvey after repair
 Lumpsum
 sub @ 1kkanato.com
 7 days*

COST OF CLAIMS

	Amount
Parts	2,970.00
Miscellaneous Items	35.00
Labour	1,230.00
Paintwork Labour	1,000.00
Towing	0.00

Gross Total (S\$) 5,235.00
+ GST 7.00% (S\$) 366.45
Nett Amount (S\$) 5,601.45

This claim is handled by: **HENG SEW SOW**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE	35.00
Sub Total (S\$)			35.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO PUTTY & SPRAY PAINTING.	New	1,000.00
<u>Labour Items</u>			
2	TO REMOVE, REPLACE, WELD & INSTALL FRONT DAMAGED PARTS	New	900.00
3	TO R & R FRONT RADIATOR	New	120.00
4	TO R & R AIR CON SYSTEM. TOP UP AIR CON GAS	New	150.00
5	TO R & R WIRING	New	60.00
Gross Labour Cost (S\$)			2,230.00

Woon Meng Motor Pte Ltd/SJQ1925S/28/05/2018 14:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

4137.60
4/5\$ 3300 *
7 days

3840.60
4/5\$ 3050
7 days

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 May 2018 14:33 Sendback Est	28 May 2018 14:56 S\$5,235.00	30 May 2018 15:16 Edit Adj Rpt	S\$3,300.00 Edit Estimates	S\$3,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	MOHD SUYUTI BIN ABDULLAH, ID: S1676966E, Email: muhdfaiz.matnawi@gmail.com								
Vehicle Reg. No.:	SJQ1925S	Date of Loss:	25/05/2018 10:00 - :59 [108 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / DMPC1800213H	Policy/Cover Note No.:	MPC18A00091102 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131								
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/06/2018]								
Driver/Custodian:	MUHAMMAD FAIZ BIN MATNAWI (28 / Male), NRIC: S9007008H, Tel: +6586662620								
Adj Asg. Remarks:	PLEASE BE INFORMED THAT THIS CASE IS HANDLE BY DESMOND LEE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> ECICS (07/06/2018): Alert - Adj Mandate Approved (S\$4597.40) - SJQ1925S - Claim Handler: Janice Goh 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJQ1925S (DMPC1800213H)
OD
May 25 2018 10:00AM
[MOHD SUYUTI BIN ABDULLAH]
Woon Meng Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter		View View in Browser <input type="button" value="v"/>		
Assessment Reports		1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>		
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)	Thumbnail	Print
1	28/05/18 14:56	Repairer Estimates	1 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/06/18 15:26	Adjuster Immediate Advice	1 Load HTM	
Photos/Images		3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/06/18 15:33	Odometer Reading	1 Load JPG	<input checked="" type="checkbox"/>
2	01/06/18 15:33	Chassis Number	1 Load JPG	<input checked="" type="checkbox"/>
3	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
4	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
5	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
6	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
7	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
8	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
9	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
10	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
11	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
12	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
13	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
14	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
15	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
16	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
17	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
18	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
19	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
20	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
21	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
22	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
23	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
24	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
25	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
26	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
27	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
28	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
29	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
30	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
31	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
32	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
33	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>
34	01/06/18 15:33	General View	1 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
36	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
37	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
38	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
39	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
40	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
41	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
42	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
43	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
44	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
45	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
46	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
47	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
48	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
49	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
50	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
51	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
52	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
53	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
54	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
55	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
56	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
57	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
58	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
59	01/06/18 15:33	General View	 Load JPG	<input checked="" type="checkbox"/>
60	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	13/07/18 09:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)		Thumbnail	Print
84	13/07/18 09:44	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
85	13/07/18 09:44	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
86	13/07/18 09:44	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
87	13/07/18 09:44	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
88	17/07/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
89	17/07/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
90	17/07/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
91	17/07/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
92	17/07/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
93	17/07/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
94	17/07/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
95	17/07/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
96	17/07/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
97	17/07/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
98	17/07/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
99	17/07/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
100	17/07/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
101	17/07/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
102	17/07/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
103	17/07/18 09:52	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/06/18 15:32	ESTIMATE		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)		Thumbnail	Print
1	25/05/18 17:38	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)		Thumbnail	Print
1	25/05/18 17:37	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	25/05/18 17:37	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	25/05/18 17:37	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	25/05/18 17:37	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	25/05/18 17:37	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	25/05/18 17:37	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	25/05/18 17:37	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	25/05/18 17:37	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	25/05/18 17:37	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Woon Meng Motor Pte Ltd (Bukit Batok)		Thumbnail	Print
1	25/05/18 17:35	Sketch Plan		Load TIF	
2	25/05/18 17:35	Driver's Driving License/ NRIC		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One
Singapore 038987

Our File No: CS/ICS18009735/T1SD3E2

Date: 26/07/2018

REFERENCE

Insured/Claimant: MOHD SUYUTI BIN ABDULLAH Policy No: MPC18A00091102
Date of Loss: 25/05/2018 Nature of Claim: OD Claim No: DMPC1800213H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJQ1925S**
Make & Model: KIA RIO, 1.4 5DR Engine No: G4EE9H214980
Reg. Date: 28/04/2009 (Man. Year: 2009) Chassis No: KNADE241296523945
Colour: Silver Odometer: 141103 km
Engine Capacity: 1399 cc
Market Value/New Car Price: S\$11,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,970.00	2,272.60	697.40	23.48
Miscellaneous Items	35.00	35.00	0.00	0.00
Labour	1,230.00	1,030.00	200.00	16.26
Paintwork Labour	1,000.00	800.00	200.00	20.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,235.00	4,137.60	1,097.40	20.96
Approved Total (Overridden) (S\$)		3,300.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	5,235.00	2,800.00	2,435.00	46.51
+ GST 7.00/7.00% (S\$)	366.45	196.00	170.45	46.51
Nett Amount (S\$)	5,601.45	2,996.00	2,605.45	46.51

INSPECTION

Date of Assignment: 30/05/2018 Present Location: Woon Meng Motor Pte Ltd (Bukit Batok)
Date Inspected: 31/05/2018 Inspected At: Woon Meng Motor Pte Ltd (Bukit Batok)
50 Bukit Batok Street 23,, #01-06 Midview Building
Singapore 659578
Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2018)
Parts: 144	KIA RIO 1.4 5DR (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ1925S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Deformed	160.00 F	*160.00 F
2	2		*FRONT BUMPER RETAINER (WCP)	Necessary	30.00 F	*30.00 F
3	1		*FRONT BUMPER LOWER LIP (WCP)	Necessary	35.00 F	*35.00 F
4	1		*FRONT BUMPER LOWER GRILLE (WCP)	Deformed	40.00 F	*40.00 F
5	2		*FRONT BUMPER FOG LAMP (WCP)	Not Necessary	116.00 F	*- F
6	1		*FRONT BUMPER REFORCEMENT (WCP)	Bent	80.00 F	*80.00 F
7	1		*FRONT BUMPER SPONGE (WCP)	Deformed	42.00 F	*42.00 F
8	1		*FRONT CENTER GRILLE (WCP)	Cracked	35.00 F	*35.00 F
9	1		*EMBLEM (WCP)	Necessary	28.00 F	*28.00 F
10	2		*FRONT HEADLAMP (WCP)	Cracked	340.00 F	*340.00 F
11	1		*HORN (WCP)	Not Necessary	50.00 F	*- F
12	1		*FRONT SUPPORT PANEL (WCP)	Cracked	195.00 F	*195.00 F
13	1		*FRONT RADIATOR (WCP)	Bent	270.00 F	*270.00 F
14	1		*AIR CON CONDENSOR (WCP)	Bent	300.00 F	*300.00 F
15	1		*FAN MOTOR ASSY (WCP)	Not Necessary	220.00 F	*- F
16	1		*TOP HOSE (RAD TO ENGINE) (WCP)	Twisted	16.00 F	*16.00 F
17	1		*FRONT FENDER O/S (WCP)	Bent	130.00 F	*130.00 F
18	1		*FRONT FENDER INNER GARNISH O/S (WCP)	Not Necessary	32.00 F	*- F
19	1		*FRONT FENDER MOULDING O/S (WCP)	Missing	10.00 F	*10.00 F
20	1		*WHEEL HOUSE O/S (WCP)	Repair	180.00 F	*- F
21	1		*FRONT BONNET (WCP)	Bent	330.00 F	*330.00 F
22	1		*FRONT BONNET LOCK (WCP)	Bent	25.00 F	*25.00 F
23	2		*FRONT BONNET HINGE (WCP)	Repair	36.00 F	*- F

F=Franchise part.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	2,700.00	2,066.00
				+ Margin on L,N Items 10.00/10.00% (S\$)	270.00	206.60
				Total Parts (S\$)	2,970.00	2,272.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	FRONT NUMBER PLATE (BENT)	35.00	35.00
Sub Total (S\$)			35.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO PUTTY & SPRAY PAINTING.	New	1,000.00	800.00
<u>Labour Items</u>				
2	TO REMOVE, REPLACE, WELD & INSTALL FRONT DAMAGED PARTS	New	900.00	800.00
3	TO R & R FRONT RADIATOR	New	120.00	100.00
4	TO R & R AIR CON SYSTEM. TOP UP AIR CON GAS	New	150.00	100.00
5	TO R & R WIRING	New	60.00	30.00
Gross Labour Cost (S\$)			2,230.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >