

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPIL/BTTR%	DISC QUANTY	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	43	1			REAR KNUCKLE ARM RH			Bent	650				850	Reviewing	
	44	1			REAR WHEEL BEARING RH			Bent	160				160	Reviewing	
	45	1			REAR WHEEL HUB RH			Bent	180				180	Reviewing	
	46	1			REAR LOWER TRAILING ARM RH			Bent	220				220	Reviewing	
	47	1			REAR CROSSMEMBER			Servicable	0				0	Reviewing	
	48	1			REAR SPORT RIM RH			Cut	650				650	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		LABOUR TO FACILITATE REPAIR	1200	0	0	Reviewing		
	2		TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.	30	0	0	Reviewing		
	3		TO SPRAY PAINTING ON AFFECTED AREAS.	1000	0	0	Reviewing		
	4		TO REMOVE & RENEW ALL RH/R DOOR COMPONENTS TO ASSIST REPAIR.	60	0	0	Reviewing		
	5		TO REMOVE & INSTALL REAR WINDSCREEN GLASS.	120	0	0	Reviewing		
	6		TO REMOVE & REFIT ALL NECESSARY TRIM BOARDS, GARNISH, CARPET, FLOOR MATS & SEAT.	60	0	0	Reviewing		
	7		TO REMOVE & RENEW ALL RH/R UNDERCARRIAGE COMPONENTS TO FACILITATE REPAIR.	120	0	0	Reviewing		
	8		TO REMOVE & RENEW REAR CROSSMEMBER TO ASSIST REPAIR.	150	0	0	Reviewing		

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	12	1			REAR DOOR HANDLE OUTER RH			Damaged	110				110	Reviewing	
	13	1			REAR DOOR LOCK CAP RH			Serviceable	0				0	Reviewing	
	14	1			REAR DOOR HANDLE BRACKET RH			Serviceable	0				0	Reviewing	
	15	1			REAR DOOR LOCK RH			Bent	240				240	Reviewing	
	16	1			REAR DOOR RUBBER RH (OUTER)			Cut	200				200	Reviewing	
	17	1			REAR DOOR RUBBER RH (INNER)			Cut	200				200	Reviewing	
	18	1			REAR DOOR GLASS REGULATOR RH			Serviceable	0				0	Reviewing	
	19	1			REAR DOOR GLASS REGULATOR MOTOR RH			Serviceable	0				0	Reviewing	
	20	20			REAR DOOR RIVET			Necessary	2				40	Reviewing	
	21	1			REAR DOOR TRIMBOARD			Deformed	1650				1650	Reviewing	
	22	1			REAR SIDE STEP GARNISH RH			Deformed	240				240	Reviewing	
	23	1			REAR FENDER RH			Buckled	1850				1850	Reviewing	
	24	1			REAR FENDER INNER SHIELD RH			Damaged	100				100	Reviewing	
	25	10			REAR FENDER INNER SHIELD CLIP			Necessary	1.5				15	Reviewing	
	26	1			REAR FENDER INNER PANEL RH (NPA)			Repair	0				0	Reviewing	

POST SURVEY
INFORMATION

FNOL INFORMATION

CATEGORY

ASSESSMENT INFORMATION

POLICY INFORMATION

CATEGORY

License Type

Sum Insured 0

License Issue Date

Market Value 0

January 1, 2014

License Expiration Date

Address
28 BUKIT BATOK STREET 52 #07-01
SINGAPORE 659248, Singapore

Address type
Personal Correspondence

Gender
Female

Marital status
Unknown

Identification #
574897501

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	9/25/18 1:39 PM	10500	10500	Open	Share	Clone
ANG Richard	5/30/18 2:27 PM	15341	15341	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
SKN 9137B INSPECTION PHOTO 1.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	September 7, 2018
SKN 9137B INSPECTION PHOTO 2.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	September 7, 2018
SKN 9137B RE-INSPECTION PHOTO 2.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	September 7, 2018
SKN 9137B RE-INSPECTION PHOTO 1.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	September 7, 2018
SKN 9137B ESTIMATE.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	June 1, 2018
SKN 9137B IA.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	June 1, 2018
SKN 9137B UNDERTAKING LETTER.pdf	Forms / Claim Documents	Letter of undertaking	LKK AUTO CONSULTANTS PTE LTD (OD)	June 1, 2018
SKN 9137B IA.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	June 1, 2018
TP GIA Report (FBL9219R).pdf	Reports & Statement	GIA Report	CHEN Xinyou	May 29, 2018
GA073076-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	CHEN Xinyou	May 29, 2018
GA073076-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	CHEN Xinyou	May 29, 2018