

2000000

ASS. REC. BY:

REF: CS3/CTI18009758/Rizal

Surveyor

ASSIGNMENT (Office)

From (Person): Elaine Cheong of CTI Date/Time: 30/5/18 @ 1:53pm

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKR 9669L Insured:

at Workshop n/s: Hwa peng Auto Tel: 9688 5655

of Blk 70 woodlands Ind-park E

Policy No: Claim No: 8NM1ED02634C02/5

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A.

CA / REV / REP. / REV 24 HRS lup 31/5/2018 @ Morning H.O.D. Endorsement

Date/Time: 2:52pm @ 30/5/18 Person Contacted: Francis Vehicle: (IN) OUT

Date/Time	Action/Instruction (X) Estimate
	SKR 9669L - X
5/6/18	Dismantle d

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Wednesday, 30 May 2018 1:53 PM
To: assignments@lkkauto.com
Cc: admin-d@lkkauto.com
Subject: FW: PRE-REPAIR SURVEY - SLR9669L (CLAIM REF: SNM18D02634C02/5); Our ref: Our ref: LCH.my/W1HP-80469.18

Importance: High

Dear All,

Please refer to the email below.

For your urgent attention pls.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6225 5879

Email: elaine.cheong@sg.cntaiping.com

Website: www.sg.cntaiping.com



From: Elaine Cheong
Sent: Monday, 28 May, 2018 5:49 PM
To: 'Cheong Hoh Lee' <mail@cheonghoh.sg>; 'admin-a@lkkauto.com' <admin-a@lkkauto.com>
Subject: RE: PRE-REPAIR SURVEY - SLR9669L (CLAIM REF: SNM18D02634C02/5); Our ref: Our ref: LCH.my/W1HP-80469.18
Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Melody,

We refer to your email of 28.05.18.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6225 5879
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com



From: Cheong Hoh Lee [<mailto:mail@cheonghoh.sg>]

Sent: Monday, 28 May, 2018 5:01 PM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Subject: Re: PRE-REPAIR SURVEY - SLR9669L (CLAIM REF: SNM18D02634C02/5); Our ref: Our ref: LCH.my/W1HP-80469.18

Dear Elaine,

We refer to the above matter and to your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors as stated in your aforesaid letter.

We are further instructed to append below our client's 10 proposed surveyors as follows :-

- (1) Jeffery Ong Leng Kiat
- (2) Fong Kok Heng

- (3) Chang Fuh Keong
- (4) T Rajan
- (5) Ng Soon Chuan Louis
- (6) Ng Soon Aik Francis
- (7) Jayson Liaw Leong San
- (8) Lee Kok Weng
- (9) Loi Boon Juan
- (10) How Andrew

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre-repair survey ("PRS") of our client's vehicle no. SLR 9669 L at our client's repairer workshop as follows :-

Hwa Peng Auto Service (1996)
Blk 70 Woodlands Industrial Park E
Singapore 757836

Person to contact : Francis (mobile no. 9688 5655)

Regards,
Melody
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

On May 28, 2018, at 4:42 PM, Elaine Cheong <elaine.cheong@sg.cntaiping.com> wrote:

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

Dear Sir / Madam,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.
You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6225 5879

Email: elaine.cheong@sg.cntaiping.com

Website: www.sg.cntaiping.com

<image003.png>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/05/2018 10:46
Date Of Accident	24/05/2018 22:00
Exact Location Of Accident	ALONG UPPER THOMSON RD (NEAR TO CALTEX)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR9669L
Insured/Policyholder	
Name Of Registered Owner	LIM AH SUAY
NRIC No	S2199622Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90901855
Alternative Phone No	OFFICE-90901855

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3028681703
Cover Note Number	

Driver

Name of Driver	LIM AH SUAY
NRIC No	S2199622Z
Date Of Birth	15/05/1961
Occupation	INDOOR
Date Of Driving Pass	26/02/1980
Driving Experience	38 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90901855
Fax Number	
Contact Number	OFFICE-90901855
Email Address	NOEMAIL

Address -
 Postcode -
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name WOODLANDS WEST NPC
 Police Station Address ROAD: 9 MARSILING LANE , POSTCODE: 739146 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

refer attached police report.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GV4025D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver YAP TAI MENG
 NRIC/Passport Number S1161451E
 Contact Number 91002928
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLQ2290J
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver TAY MING SENG JARED
NRIC/Passport Number S8028026B
Contact Number 98259471
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LIM AH SUAY
Approximate Age
Injuries Sustain
Injured person in which vehicle? SKR9669L
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180525/2124

1 of 4

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

Report No. T/20180525/2124

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/05/2018 16:56	Video Report No.:	Station Diary No.: 85
--	-------------------	--------------------------

Informant's Particulars

Name of Informant: LIM AH SUAY		Address: APT BLK 846 WOODLANDS AVENUE 4 #02-614 SINGAPORE 730846	
ID Type / ID No.: NRIC NO / S2199622Z		Contact No.:	Mobile: 90901855
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 57	Date of Birth: 15/05/1961	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Cook		Driving Licence Information: Class:	Date of Expiry:

General information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 24/05/2018 22:00	Type of Location: Straight Road
Location: Along Road 1 UPPER THOMSON ROAD ANG MO KIO AVENUE 1 Upper Thompson Road towards Ang Mo Kio Avenue 1 (Near to Callex)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GV4025D	Lorry				Seriously Damaged	0
SLQ2290J	Car	PORSCHE			Seriously Damaged	0
SLR9669L	Car	MERCEDES BENZ		Silver	Seriously Damaged	0

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



T/20180525/2124

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

2 of 4
Report No. T/20180525/2124

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	YAP TAI MENG	ID No.	S1161451E
Related Vehicle	GV4025D (Lorry)	Contact No.	91002928
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAY MING SENG JARED	ID No.	S8028026B
Related Vehicle	SLQ2290J (Car)	Contact No.	98259471
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LIM AH SUAY	ID No.	S2199622Z
Related Vehicle	SLR9669L (Car)	Contact No.	90901855
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	25/05/2018	Date Discharge	25/05/2018
No. of Days granted Medical Leave	07	Degree of Injury	NIL

Brief Details.

On 24/05/2018 at about 2200hrs to 2230hrs, I was driving along Upper Thompson Road towards Ang Mo Kio Avenue 1 on the most left lane with my Car(SLR9669L) travelling in front of me was another car(SLQ2290J) which slowed down and subsequently came to a stop. I followed and my vehicle managed to come to a stop. Out of sudden, I felt an impact coming from the back of my vehicle which causes my car(SLR9669L) to move forward and collide onto the rear of car(SLQ2290J). I then made a check and discovered that a lorry(GV4025D) had collided onto the rear of my vehicle. My vehicle is seriously damaged to the front and back. Car(SLQ2290J) had damages to the back portion of the vehicle. Lorry(GV4025D) had damages to the front portion.

Sketch Plan #5



**SINGAPORE
POLICE FORCE**



T/20180525/2124

3 of 4

Report No. T/20180525/2124

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

CONTINUATION OF REPORT

I went to the doctor at Khoo Teck Puat hospital and was given Seven(7) days of MC due to the injuries on my back.

Sketch Plan #6



**SINGAPORE
POLICE FORCE**



T/20180525/2124

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

4 of 4




Report No. T/20180525/2124

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J/ Staff Sgt GOH ZHONG SHENG, JOHNSON 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 25/05/2018 16:56
Officer In Charge Of Case: TP / AEIT / SSI 2 YEO GEAK ENG CECILIA Contact No : 65478404	Classification Of Case:
Authentication Stamp 	

Accident Sketch Plan

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2199622Z



LIM AN SUAY
Name
林 安 瑞
Citizenship
Date of Birth
15-05-1981
Country/Place of Birth
INDONESIA

Sex M
21-05-2022




3199622Z

Doc No. S2199622Z

Date of Issue
28-08-2013

Address
APT B.K. 848 WOODLANDS AVENUE 4
#02-814
SINGAPORE 738848

REPUBLIC OF SINGAPORE DRIVING LICENCE



15 SEP 2013
15 SEP 2013




YOU ARE CATEGORISED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 3 Motor Cycle (200kg with or without sidecar), sidecar, or of the driver, and other motor vehicles of 200kg or less, and motor vehicles of any kind or passenger and the maximum weight of 200kg.
12 Oct 1982

Class 4 For motor vehicles which are not being pushed or towed and the maximum weight of 1720kg.
12 Oct 1982

Class 5 Motor vehicles not constructed to carry any load and the maximum weight of 1720kg.
12 Oct 1982

License No. S2199622Z



SP 429A

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 May 2018		07 Jun 2018 14:40 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	-, Co. Reg. No.: -	
Main Claimant:	LIM AH SUAY , ID: S21996222	
Vehicle Reg. No.:	SKR9669L	Date of Loss: 24/05/2018 22:00 - :59 [94 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D02634C02	Policy/Cover Note No.: DMCVSN1755551700
Vehicle Reg. No. (Insured):	GV4025D	Policy No. (Claimant): DMPCSN3028681703
		Excess: S\$0.00
Repairer:	Hwa Peng Auto Service (1996) (HQ) 70 WOODLANDS INDUSTRIAL PARK E9, 757836 Woodlands - Tel:	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]	
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/06/2018]	
Adj Asg. Remarks:	Assignment via email on earlier date	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SKR9669L (SNM18D02634C02)**
[GV4025D]
TP
LIM AH SUAY
May 24 2018 10:00PM
[-]
Hwa Peng Auto Service (1996)

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	26/05/18 13:24	Accident Statement	 Load HTM	<input type="checkbox"/>
2	04/06/18 11:07	Addendum Sheet	 Load TIF	<input type="checkbox"/>
3	04/06/18 11:18	Accident Statement Addm. #1	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	26/05/18 11:56	Accident Photo <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
2	26/05/18 11:56	Accident Photo <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
3	26/05/18 11:56	Accident Photo <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
4	26/05/18 11:56	Accident Photo <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
5	26/05/18 11:56	Accident Photo <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
6	26/05/18 11:56	Accident Photo <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
7	26/05/18 11:56	Accident Photo <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
2	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
3	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
4	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
5	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
6	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
7	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
8	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
9	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
10	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
11	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
12	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
13	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
14	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
15	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
16	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
17	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
18	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
19	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
20	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
21	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
22	12/06/18 17:04	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
23	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
24	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
25	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
26	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
27	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
28	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
29	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
30	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
31	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
32	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
33	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
34	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
35	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
36	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
37	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
38	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
39	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
40	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
41	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
42	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
43	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
44	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
45	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
46	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
47	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
48	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
49	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
50	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
51	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
52	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
53	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
54	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
55	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
56	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
57	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
58	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
59	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
60	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
61	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
62	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
63	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
64	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
65	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
66	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
67	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
68	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
69	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
70	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
71	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
72	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
73	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
74	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
75	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
76	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
77	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
78	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
79	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
80	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
81	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
82	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
83	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
84	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
85	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
86	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
87	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
88	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
89	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
90	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
91	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
92	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
93	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
94	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
95	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
96	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
97	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
98	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
99	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
100	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
101	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
102	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
103	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
104	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
105	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
106	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
107	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
108	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
109	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
110	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
111	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
112	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
113	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
114	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
115	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
116	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
117	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
118	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
119	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
120	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
121	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
122	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
123	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
124	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
125	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
126	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
127	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
128	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
129	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
130	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
131	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
132	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
133	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
134	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
135	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
136	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
137	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
138	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
139	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
140	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
141	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
142	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
143	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
144	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
145	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
146	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
147	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
148	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
149	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
150	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
151	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
152	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
153	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
154	12/06/18 17:04	Dismantled Parts		<input checked="" type="checkbox"/>
155	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
156	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
157	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
158	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
159	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
160	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
161	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
162	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
163	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
164	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
165	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
166	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
167	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
168	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
169	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
170	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
171	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>
172	12/06/18 17:05	Dismantled Parts		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
173	12/06/18 17:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
174	12/06/18 17:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
175	12/06/18 17:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
176	12/06/18 17:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
177	12/06/18 17:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
178	12/06/18 17:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
179	12/06/18 17:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
180	12/06/18 17:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
181	12/06/18 17:05	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/06/18 14:44	E-filed GIA report	 Load PDF	
2	08/06/18 10:08	Pre-Repair Survey ASSIGNMENT SENT EARLIER VIA EMAIL	 Load PDF	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	26/05/18 12:00	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	26/05/18 12:00	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	26/05/18 12:00	Sketch Plan #3 [Linked Accident Report Documents]	 Load TIF	
4	26/05/18 12:00	Sketch Plan #4 [Linked Accident Report Documents]	 Load TIF	
5	26/05/18 12:00	Sketch Plan #5 [Linked Accident Report Documents]	 Load TIF	
6	26/05/18 12:00	Sketch Plan #6 [Linked Accident Report Documents]	 Load TIF	
7	26/05/18 12:00	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
8	04/06/18 11:08	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
9	04/06/18 11:08	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
10	04/06/18 11:08	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
11	04/06/18 11:08	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/18 10:00	LKKPhotosIn6-1.pdf	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	26/05/18 13:24	Accident Statement	 Load HTM	
2	04/06/18 11:07	Addendum Sheet	 Load TIF	
3	04/06/18 11:18	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	26/05/18 11:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	26/05/18 11:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	26/05/18 11:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	26/05/18 11:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	26/05/18 11:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	26/05/18 11:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	26/05/18 11:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	26/05/18 12:00	Sketch Plan	 Load TIF	
2	26/05/18 12:00	Sketch Plan #2	 Load TIF	
3	26/05/18 12:00	Sketch Plan #3	 Load TIF	
4	26/05/18 12:00	Sketch Plan #4	 Load TIF	
5	26/05/18 12:00	Sketch Plan #5	 Load TIF	
6	26/05/18 12:00	Sketch Plan #6	 Load TIF	
7	26/05/18 12:00	Accident Sketch Plan	 Load TIF	
8	04/06/18 11:08	Accident Sketch Plan	 Load TIF	
9	04/06/18 11:08	Accident Sketch Plan	 Load TIF	
10	04/06/18 11:08	Accident Sketch Plan	 Load TIF	
11	04/06/18 11:08	Accident Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118009758/R1Z4D3E2

Date: 14/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN1755551700
 Claimant Vehicle No: SKR9669L Insured Vehicle No: GV4025D
 Date of Loss: 24/05/2018 Nature of Claim: TP Claim No: SNM18D02634C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR9669L**
 Make & Model: MERCEDES-BENZ 250S, 2.5 (A) Engine No: 27186030071153
 Reg. Date: 09/07/2010 (Man. Year: 2010) Chassis No: WDD2120472A230704
 Colour: Grey Odometer: 337188 km
 Engine Capacity: 1796 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18 Rear Tyre Size: 245/40Z R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/06/2018
 Date Inspected: 31/05/2018 Inspected At: Hwa Peng Auto Service (1996) (HQ)
 70 WOODLANDS INDUSTRIAL PARK E9
 Singapore 757836
 Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$19,800.00 - \$20,800.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2018)
Parts: 143	MERCEDES-BENZ 250S 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKR9669L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >