

Surveyor:

GR

ASSIGNMENT (Office)

From (Person):

Chin Iee Ying

of

ALG

Date/Time:

30/5/18 @ 11:12am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 2937H

Insured:

SKM 5501P

at Workshop n/s:

A-Tec Automotive

Tel:

63845206

of

8 kaki Bukit Ave 4 # 05-27

Policy No:

J100367667

Claim No:

4392665952G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/05/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

12:33pm @ 30/5/18

Person Contacted:

peeyie

Vehicle:

IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJK 2937H - X
	SKM 5501P - X
	Dismantle: 31/5/2018
	After repair: 4/6/2018

PAS xnl. REF: AIG C6878m (2018)

ASSIGNMENT

From: _____ Date: 30/5/2018 Veh No: SJK 2937H Yr Regn: 15 Oct 2008
 Estimated Cost: _____ Type: ☒ M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or
 To Inspect Vehicle No: SJK 2937H Make: Hyundai Avante c.c. 1591
 at Workshop m/s: A-Tec Automotive Colour: Silver A/C: Insured / Std / NI / NA
 of 8/cedi Bukit Ave 4 # 05-27 Sp. Reading: 285018 T/Radio: Insured / Std / NI / NA
 Insured: _____ Eng/No: _____
 Policy No: _____ C/No: KMH1DU41BR-94589554
 Claims No: _____ Gen. Cond: Good / Fair / Poor / Burnt
 Sum Insured: _____ Excess: _____ Steering: Inorder / Jammed / Leaked / Burnt or
 (Client's Record) Brake: Inorder / Jammed / Leaked / Burnt or
 Make of Veh: _____ Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/65 R 15
 R: _____
 (Policy Condition) BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
 Remark: The veh had commenced its TOYO / YOKO or
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR - Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS ^{1wp}
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT
 The U/C / Chassis frame / Body Structure affected due to collision.

Survey held at w/s 4:30pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 o/s tot

Date / Time Action / Instruction

DAR

Range 3500/2 - 4,000/2
 Repair days 4 days

T/Cum
 3/8/18

Date/Time: File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: DAR

Lump Sum / I.B.I: (\$

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SKM5501P AND SJK2937H ON 25/5/2018**

From: Chin, Lee-Ying
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY
Sent: 30/5/2018 11:12:19 AM
Attachments:  20180528092106676.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : SJK 2937H (wk)
Your Ref :

28 May 2018

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120

BY EMAIL ONLY

Dear Sir,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : COVE RENTALS P/L
ACCIDENT INVOLVING SJK 2937H & SKM 5501P ALONG BLK 270
SENGKANG CENTRAL MSCP ON 25 MAY 2018
PRE-REPAIR INSPECTION NOTICE

1. We act for Cove Rentals P/L, the owner of motor vehicle no. SJK 2937H, which was involved in the aforesaid accident.
2. We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. SKM 5501P for damages, costs and disbursements as a result of your insured driver's negligence.
3. Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s A-TEC Automotive at 8 Kaki Bukit Avenue 4 #05 - 27 Premier Singapore 415875 and kindly arrange with Ms. Peggie at 6384 5206.
4. If we do not hear from you within the next **two (2) working days**, we shall advise our client to proceed with their own inspection and repairs.
5. Please reply either by fax at 6733 8183 or by email to wengkit@chiaarul.com.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09
MANHATTAN HOUSE • SINGAPORE 169876
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)
EMAIL : info@chiaarul.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/05/2018 15:48
Date Of Accident	25/05/2018 12:10
Exact Location Of Accident	BLK 270 SENGKANG CENTRAL MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK2937H
Insured/Policyholder	
Name Of Registered Owner	COVE RENTALS PTE LTD
Co Reg No	201626878M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90000000
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	AVANTE-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5099639349
Cover Note Number	
Driver	
Name of Driver	JOSHUA KARTHIK KRISHNA
NRIC No	S9527860D
Date Of Birth	24/07/1995
Occupation	OUTDOOR
Date Of Driving Pass	14/09/2015
Driving Experience	2 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92318302
Fax Number	
Contact Number	
Email Address	NOEMAIL


No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	JOSHUA KARTHIK KRISHNA
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJK2937H
Were seat belts worn?	YES
Was this Injured conveyed to hospital by ambulance?	
Address	
Postcode	

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to the Notice of Reporting.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time.

Driver's Signature
(If driver is not the policyholder)
Date & Time.

26 MAY 2010

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6878M
Vehicle Details	
Vehicle No.:	SJK2937H
Vehicle to be Exported:	No
Intended De-registration Date:	31 Jul 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	G4FC8U511839
Chassis No.:	KMH DU41BR9U589554
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,390.00
Original Registration Date:	15 Oct 2008
First Registration Date:	15 Oct 2008
Transfer Count:	1
Actual ARF Paid:	\$11,390.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Oct 2018
PARF Rebate Amount:	\$5,695.00
Intended COE Rebate Details	
COE Expiry Date:	14 Oct 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$9,501.00
COE Rebate Amount:	\$194.00
Total Rebate Amount:	\$5,889.00

The information contained herein is correct as at 31 Jul 2018

OK

(01) Bent (02) Dented (03) Distorted (04) Cracked (05) Cut (06) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing
(13) Torn (14) Unconfirmed (15) Not Working

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

MOTOR CAR (RH)

Vehicle No: **SJK 2937H**

Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror	SCR	R	X
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper	460.00	CUT	✓
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	LR 74.00	NEC	✓ 2
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy	450.00	BR	✓
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender	670.20	DD	✓
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
		Frt RH fender 'vvt' lamp	28.00	NEC	✓

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door			
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			

No of Items: _____

Assessor: _____

2367 parts

400 point
600 labour

MOTOR CAR (Frt)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990131	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: **SJK 29374**

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jun 2018 Edit Reg		30 May 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	ASSOCIATE MACHINERY ENGINEERING SUPPLY PTE LTD , Co. Reg. No.: 201102616E		
Main Claimant:	-		
Vehicle Reg. No.:	SJK2937H	Date of Loss:	25/05/2018 00:00 - :59 [115 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4392665957SG	Policy/Cover Note No.:	2100367667 (Comprehensive)
Vehicle Reg. No. (Insured):	SKM5501P	Policy No. (Claimant):	
		Excess:	
Repairer:	A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier, 415875 Kaki Bukit - Tel: (1) 90626929 , (2) 97103383		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 04/07/2018]		
Claimant's Solicitor:	CHIA S ARUL & LLC - Tel: 67334647		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (26/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

***SJK2937H (4392665957SG)**
[SKM5501P]
TP

2

[ASSOCIATE MACHINERY ENGINEERING SUPPLY PTE LTD]
A-Tec Automotive Pte Ltd

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&objid=719512&extid=275788&corole=4&... 1/3

Photos/Images				☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
37	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
38	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
39	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
40	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
41	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
42	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
43	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
44	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
45	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
46	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
47	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
48	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
49	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
50	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
51	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
52	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
53	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
54	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
55	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
56	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
57	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
58	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
59	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
60	16/07/18 17:33	Photographs of Damaged Parts	 Load JPG	☒
61	31/07/18 11:15	Photo After Spray	 Load JPG	☒
62	31/07/18 11:15	Photo After Spray	 Load JPG	☒
63	31/07/18 11:15	Photo After Spray	 Load JPG	☒
64	31/07/18 11:15	Photo After Spray	 Load JPG	☒
65	31/07/18 11:15	Photo After Spray	 Load JPG	☒
66	31/07/18 11:15	Photo After Spray	 Load JPG	☒
67	31/07/18 11:15	Photo After Spray	 Load JPG	☒
68	31/07/18 11:15	Photo After Spray	 Load JPG	☒
69	31/07/18 11:15	Photo After Spray	 Load JPG	☒
70	31/07/18 11:15	Photo After Spray	 Load JPG	☒
71	31/07/18 11:15	Photo After Spray	 Load JPG	☒
72	31/07/18 11:15	Photo After Spray	 Load JPG	☒
73	31/07/18 11:15	Photo After Spray	 Load JPG	☒
74	31/07/18 11:15	Photo After Spray	 Load JPG	☒
75	31/07/18 11:15	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/06/18 12:00	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18009762/GZ4D3S2

Date: 13/08/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100367667
Claimant Vehicle No :	SJK2937H	Insured Vehicle No :	SKM5501P
Date of Loss:	25/05/2018	Nature of Claim:	TP
		Claim No:	4392665957SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK2937H	Engine No:	G4FC8U511839
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMH DU41BR9U589554
Reg. Date:	15/10/2008 (Man. Year: 2008)	Odometer:	285018 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	30/05/2018		
Date Inspected:	30/05/2018	Inspected At:	A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier Singapore 415875
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR WING MIRROR	Repair	0.00 F	*-F
2	1		*FRT BUMPER	Cut	0.00 F	*-F
3	2		*FRT BUMPER SIDE RETAINER L/R	Necessary	0.00 F	*-F
4	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*-F
5	1		*FRT RH FENDER	Dented	0.00 F	*-F
6	1		*FRT RH FENDER VVT LOGO	Necessary	0.00 F	*-F
7	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
8	1		*FRT RH BUMPER FOG LAMP RH	Broken	0.00 F	*-F
9	1		*FRT RH WHEEL RIM	Cut	0.00 F	*-F
F=Franchise part.						
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >