

ASS. REC. BY: Taufik

REF: CS/CTI18009792/T1+d3/

Special Instruction:

Surveyor:
Mennen

From (Person):

Suzy Tay

ASSIGNMENT (Office)

of CTI

Date/Time: 28/5/18 @ 3:07pm

Estimated Cost:

Bill to:

①

S/TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No:

SGH 1100M

Insured:

at Workshop w/s:

cycle & Carriage Industries
188 penden loop

Tel:

91865300

of

Policy No:

DMPCSN 1767841700

Claim No:

SNM18D02553C01

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/5/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:12pm @ 30/5/18

Person Contacted:

Alan

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGH 1100M - X

31/5 -

revert via mennen

1/6 @ 16:50pm

authorise repair by Alfred

1/6 @ 17:45

- email to workshop authorise repair excess \$0

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2018		28 May 2018 15:07 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																																				
<div style="display: flex; justify-content: space-between;"> <div> CLAIM SUBFOLDER DETAILS </div> <div> [Created by insurer] </div> </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Insured:</td> <td colspan="3">TAY JENNY (ZHENG JENNY), ID: S7224498B</td> </tr> <tr> <td>Vehicle Reg. No.:</td> <td>SGH1100M</td> <td>Date of Loss:</td> <td>22/05/2018 00:00 - :59</td> </tr> <tr> <td>Claim Type:</td> <td>OD / SNM18D02553C01</td> <td>Policy/Cover Note No.:</td> <td>DMPCSN1767841700 (Comprehensive) Coverage: 24/11/2017 - 15/11/2018</td> </tr> <tr> <td></td> <td></td> <td>Excess:</td> <td>S\$0.00</td> </tr> <tr> <td>Repairer:</td> <td colspan="3">Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300</td> </tr> <tr> <td>Handling Insurer:</td> <td colspan="3">China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]</td> </tr> <tr> <td>Adjuster:</td> <td colspan="3">LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/06/2018]</td> </tr> <tr> <td>Driver/Custodian:</td> <td colspan="3">SAMUEL TEO TECK ANN (59 / Male), NRIC: S1374496C, Tel: +6592222103</td> </tr> <tr> <td>Adj Asg. Remarks:</td> <td colspan="3">PLEASE PROCEED TO SURVEY & REVERT. NO EXCESS FOR THIS ACCIDENT.</td> </tr> </table> <div style="display: flex; justify-content: flex-end; margin-top: 5px;"> View All Compose Case Mail </div>					Insured:	TAY JENNY (ZHENG JENNY), ID: S7224498B			Vehicle Reg. No.:	SGH1100M	Date of Loss:	22/05/2018 00:00 - :59	Claim Type:	OD / SNM18D02553C01	Policy/Cover Note No.:	DMPCSN1767841700 (Comprehensive) Coverage: 24/11/2017 - 15/11/2018			Excess:	S\$0.00	Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300			Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]			Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/06/2018]			Driver/Custodian:	SAMUEL TEO TECK ANN (59 / Male), NRIC: S1374496C, Tel: +6592222103			Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY & REVERT. NO EXCESS FOR THIS ACCIDENT.		
Insured:	TAY JENNY (ZHENG JENNY), ID: S7224498B																																							
Vehicle Reg. No.:	SGH1100M	Date of Loss:	22/05/2018 00:00 - :59																																					
Claim Type:	OD / SNM18D02553C01	Policy/Cover Note No.:	DMPCSN1767841700 (Comprehensive) Coverage: 24/11/2017 - 15/11/2018																																					
		Excess:	S\$0.00																																					
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300																																							
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]																																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/06/2018]																																							
Driver/Custodian:	SAMUEL TEO TECK ANN (59 / Male), NRIC: S1374496C, Tel: +6592222103																																							
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY & REVERT. NO EXCESS FOR THIS ACCIDENT.																																							
ASSOCIATED MAIL RECEIVED																																								
There are no mail for this case.																																								
ALL ASSOCIATED TASKS <div style="display: flex; justify-content: flex-end; margin-top: 5px;"> View All Search Tasks Create New Task Complete </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.																									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?																															
No results.																																								

In



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18009792/T1td3

3 ANSON ROAD #16-00

SPRINGLEAF TOWERS SINGAPORE 079909

Date : 31-05-2018

Code : CTI



1.

Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SGH 1100M
Policy No.	DMPCSN1767841700	Coverage (\$)	0.00
Claim No.	SNM18D02553C01	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	31/05/2018

2.

Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

Description of Damages

--

5.

General Information

Accident Date	22/05/2018	Inspection Date	31/05/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a.

Remarks

- A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 1 June 2018 5:45 PM
To: Alan Quek Ai Lun
Cc: SUR
Subject: RE: SGH1100M Own policy claim (REF: SNM18D02553/C01/0)

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGH1100M (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alan Quek Ai Lun [mailto:alan.quek@cyclecarriage.com.sg]
Sent: Monday, 28 May 2018 3:18 PM
To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Thin Thin (LKKAUTO) <thinthin@lkkauto.com>; Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>; Zayyer (LKKAUTO) <zayyer@lkkauto.com>
Subject: FW: SGH1100M Own policy claim (REF: SNM18D02553/C01/0)
Importance: High

Dear Officer,

Car is in 188 Pandan Loop Cycle & Carriage, kindly arrange for survey urgently. Thank you.

Your Sincerely

Alan Quek
Service Advisor
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Tel: 6771 4377 | DID: 9186 5112 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

View Received Message

This mail is associated with :

***SGH1100M (SNM18D02553C01)**

OD

May 22 2018 12:00AM

[TAY JENNY (ZHENG JENNY)]

Cycle & Carriage Industries Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **01/06/2018 16:56 PM.**

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$6223.93) - SGH1100M - Claim Handler: Jowyn Tay

Approved:6223.93:PLEASE PROCEED TO AUTHORIZE REPAIRS UP TO \$6,223.93.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay

Date: 31 May 2018

Preliminary Advice

Vehicle No	: SGH1100M	Accident Date	: 22/05/2018
Make	: MERCEDES-BENZ GLA180	Policy No.	: DMPCSN1767841700
Assignment Date	: 28/05/2018	Excess	: S\$0.00
Date of Inspection	: 30/05/2018	Est. Duration of Repair	: 3.00
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,823.93
Revised Amount	:S\$	4,132.31
Check Items (Estimated)	:S\$	2,091.62
Total	:S\$	6,223.93
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	127,000.00
COE / PARF Rebate	:S\$	62,544.00
Salvage Value	:S\$	
Margin for Repair	:S\$	64,456.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4498B
Vehicle Details	
Vehicle No.:	SGH1100M
Vehicle to be Exported:	No
Intended De-registration Date:	31 May 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLA180 (R18 BI)
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	27091030995265
Chassis No.:	WDC1569422J269613
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$28,574.00
Original Registration Date:	16 Nov 2016
First Registration Date:	16 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$27,004.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Nov 2026
PARF Rebate Amount:	\$20,253.00
Intended COE Rebate Details	
COE Expiry Date:	15 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,000.00
COE Rebate Amount:	\$42,291.00
Total Rebate Amount:	\$62,544.00

The information contained herein is correct as at 31 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/05/2018 13:51
Date Of Accident	22/05/2018 00:10
Exact Location Of Accident	MEYER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGH1100M
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	TAY JENNY (ZHENG JENNY)
NRIC No	S7224498B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92220199
Alternative Phone No	OFFICE-92220199

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	GLA180

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1767841700
Cover Note Number	

Driver

Name of Driver	SAMUEL TEO TECK ANN
NRIC No	S1374496C
Date Of Birth	03/04/1959
Occupation	INDOOR
Date Of Driving Pass	22/02/1980
Driving Experience	38 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92222103
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	179 MEYER ROAD
Postcode	437963
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MARINE PARADE NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 300 MARINE PARADE ROAD , POSTCODE: 449296 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4428999 - FAX NO: 62447678
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT NO: T/20180522/2034.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNWON
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me; which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's
Name: Alan Quek
NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Ref police report for detail.

DECLARATION

We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's
Name: Alan Quek
NRIC/FIN No.:

22/05/18

TO: Cycle + Carriage
Accident Report Dept.

DATE: 22 MAY 2018

Dear Sir,

I, TAY Jenny the owner of vehicle number
SAH-1100M Mercedes GLA-180 authorised my
husband Samuel TOO TOO ANN, NRIC. S1374496C
to file an accident report on my behalf.
Kindly assist him.

Thank-you + Yours sincerely,

TAY JENNY

I/C: S7224498B

TEL: 92220199





Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No. T/20180522/2034

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/05/2018 11:14	Vide Report No.:	Station Diary No.: 34
--	------------------	--------------------------

Informant's Particulars

Name of Informant: SAMUEL TEO TECK ANN			Address: 179 MEYER ROAD SINGAPORE 437963		
ID Type / ID No.: NRIC NO / S1374496C			Contact No.: Home/Office: Mobile: 92222103		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 59	Date of Birth: 03/04/1959	Type of Informant: Vehicle Owner		
Race: Chinese			Language:		Institution / School Name:
Occupation: SELF EMPLOYED			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 22/05/2018 00:10	Type of Location:
Location: MEYER ROAD				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGH1100M	Car	MERCEDES BENZ	GLA180	Grey	Slightly Damaged	0



Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No. T/20180522/2034

CONTINUATION OF REPORT

Brief Details.

On 21/05/2018 at about 1200hrs, I parked my car outside my unit along Meyer Road.

Subsequently, on 22/05/2018 at about 0010hrs, my son came home and noticed that my car front bumper was dented. My son then alerted me about this incident. I then asked around my neighbors and was informed they did not see anything. I then called police and was attended by traffic police. Subsequently, I was given a case card.

I wish to state that on 21/05/2018 at about 1730hrs, I noticed one car parked in front of my car with a lady driver inside. She seemed very suspicious. She drove one white Volkswagen Pasat, bearing plate number SKK5677B

I wish to state that I have an in-car camera however it stops recording once I park my car. I am lodging this report for insurance claim.



Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

Report No. T/20180522/2034

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 MUHAMMAD IDRIS BIN MOHD ISMAIL

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

22/05/2018 11:14

Officer In Charge Of Case:

TP / GIT /

Classification Of Case:

Contact No.:

Authentication Stamp

NP 68

SIGNATURE

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DMPCSN1767841700	Engine No : 27091030995265 Chassis No: WDC1569422J269613
1. Index Mark and Registration Number of Vehicle	SGH1100M	
2. Name of Policy Holder	MDM TAY JENNY (ZHENG JENNY) @YEO JENNY (YANG JENNY)	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	24 NOVEMBER 2017 (10:54 HOURS)	NAMED DRIVERS EX SECT. I ADDITIONAL EX OTHER THAN NAMED DRIVERS: EX SECT. I - AGE <= 25.....\$53,000.00 EX SECT. I - AGE >= 26.....\$4500.00 * AGE AS AT DATE OF ACCIDENT
4. Date of Expiry of Insurance	15 NOVEMBER 2018	EX ON WINDSCREEN\$9100.00
5. Persons or Classes of Persons entitled to drive *		

(A) THE POLICYHOLDER.

(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use: *

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS.
THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD TUITION DRIVING TEST RACING PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS/THEFT) WILL BE DOUBLED.

ONE TIME WAIVER OF EXCESS FOR THE FIRST \$91,000 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT OF OWN DAMAGE CLAIM AT OUR AUTHORISED WORKSHOPS FOR EACH POLICY YEAR.

HIRE PURCHASE CO.: MERCEDES-BENZ FINANCIAL SERVICES SINGAPORE LTD

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).
Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Countersigned By:


Authorised Officer


Authorised Signatory

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S1374496C**

Name:

SAMUEL TEO TECK ANN

Birth Date: **03 Apr 1959**

Issue Date: **08 Apr 2015**



002405701F

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1374496C**



Name

SAMUEL TEO TECK ANN

張 德 安

Race

CHINESE

Date of birth

03-04-1959

Sex

M

S1374496C

Country of birth

SINGAPORE

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		EFFECTIVE DATE
Class 2B	Motorcycles <= 200 cc	29 Dec 1976
Class 2A	Motorcycles between 201 cc and 400 cc	29 Dec 1976
Class 2	Motorcycles > 400 cc	29 Dec 1976
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	22 Feb 1980

FOR C&C USE ONLY



NRIC No: **S1374496C**



Date of issue

04-06-2012



Licence No: **S1374496C**

NP 429A

179 MEYER ROAD
SINGAPORE 437963
NRIC No: **S1374496C**

Date: **10/05/2018**



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGH1100M

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 23880
Reg No/Reg Date SGH1100M / 16/11/2016
Date In/Mileage / 0
Chassis No WDC1569422J269613
Engine No 27091030995265
Make/Model MB/GLA 180 (X156) "URBAN"
Colour/Trim 027 787 Mountain Gr/ 043 368 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	23/05/2018/ 10:52	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :DMPCSN1767841700 // 22-05-2018 DRIVE IN/EXCESS :22-05-2018 // TBA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
S BPNSUB SUPPLY 1 PC REG. PLATE WITH HOUSING.NETT				60.00
A BPILAB REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.				1440.00
A BPIRES RESPRAY FRONT BUMPER				720.00
M FRT BUMPER	1.00	1290.69	00.00	1290.69
M CT/F BUMPER TRIM	1.00	62.94	00.00	62.94
M CT/F BOTTOM CHROME	1.00	592.53	00.00	592.53
M RH/F BOTTOM CHROME	1.00	71.49	00.00	71.49
M LH/F BOTTOM CHROME	1.00	71.49	00.00	71.49
M CT/F BOTTOM GRILLE	1.00	124.32	00.00	124.32
M LICENSE PLATE BASE	1.00	61.83	00.00	61.83
M CT/F IMPACT ABSORBER	1.00	123.37	00.00	123.37
M CT/F BASIC MOUNTING FOR BUMPER	1.00	122.16	00.00	122.16
M CT/F PARKING SENSOR	4.00	172.07	00.00	688.28
M CT/F PARKING SENSOR SEAL	4.00	6.42	00.00	25.68
M RADIATOR GRILLE SUPPORT	1.00	290.86	00.00	290.86
M RADIATOR GRILLE GARNISH SUPPORT	1.00	185.04	00.00	185.04
M RADIATOR GRILLE STAR HOLDER	1.00	72.06	00.00	72.06
M RADIATOR GRILLE STAR	1.00	130.65	00.00	130.65
M FRT CROSS MEMBER	1.00	310.54	00.00	310.54

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Alan Quek

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6777 4771 HP: 5186 5112 Fax: 6872 1272

Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by
Not Authorise

Ex 9D

Resurvey before paint
See @ 1/6/2018

Authorized signatory and company stamp

Nett 8,823.93
7% GST on 8823.93 477.68
Total Payable 7,301.61

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-9500111-X

ESTIMATE FOR SGH1100M

Finalization

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Taufikh

Vehicle & Document Information

WIP No 23880
Reg No/Reg Date SGH1100M / 16/11/2016
Date in/Mileage 30/05/2018 / 21750
Chassis No S WDC1569422J269613
Engine No 27091030995265
Make/Model MB/GLA 180 (X156) "URBAN"
Colour/Trim 027 787 Mountain Gr/ 043 36B ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator			
WC000668	Credit	04/06/2018/ 16:29	AQ	305 / Alan Quek Al Lun			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M. BPNSUN
POLICY NO/ACC DATE : DMPCSN1767841700V // 22-05-2018
DRIVE IN/EXCESS : 22-05-2018 // NIL
DATE IN/DATE SURVEY: 30-05-2018 // LKK TAUFIKH
BY/AUTHORIZED ON : LKK TAUFIKH // 30-05-2018

OFFICIAL TAX INVOICE

A BPILAB	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
S BPNSUB	SUPPLY 1 PC NO PLATE				60.00
A BPILAB	REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.				960.00
A BPIRES	RESPRAY FRONT BUMPER				600.00
X FRT BUMPER		1.00	1290.69	00.00	1290.69
X CT/F BUMPER TRIM		1.00	62.94	00.00	62.94
X CT/F BOTTOM CHROME		1.00	592.53	00.00	592.53
X CT/F BOTTOM GRILLE		1.00	124.32	00.00	124.32
X LICENSE PLATE BASE		1.00	61.83	00.00	61.83

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 4,132.31
7% GST on 4132.31 289.26
Total Payable 4,421.57

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally work or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of removing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)
















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2018		28 May 2018 15:07 Edit Adj Rpt	S\$4,132.31 Edit Estimates	S\$4,132.31 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TAY JENNY (ZHENG JENNY) , ID: S7224498B									
Vehicle Reg. No.: SGH1100M		Date of Loss:	22/05/2018 00:00 - :59 [18 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type: OD / SNM18D02553C01		Policy/Cover Note No.:	DMPCSN1767841700 (Comprehensive) Coverage: 24/11/2017 - 15/11/2018						
		Excess:	S\$0.00						
Repairer: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 07/06/2018]									
Driver/Customer: SAMUEL TEO TECK ANN (59 / Male), NRIC: S1374496C, Tel: +6592222103									
Adj Asp. Remarks: PLEASE PROCEED TO SURVEY & REVERT. NO EXCESS FOR THIS ACCIDENT.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> CHINA_TAIPING (01/06/2018): Alert - Adj Mandate Approved (S\$6223.93) - SGH1100M - Claim Handler: Jowyn Tay CHINA_TAIPING (01/06/2018): Alert - Adj Mandate Approved (S\$6223.93) - SGH1100M - Claim Handler: Jowyn Tay 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

















Claim Documents

*SGH1100M (SNM18D02553C01)
OD
May 22 2018 12:00AM
[TAY JENNY (ZHENG JENNY)]
Cycle & Carriage Industries Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	31/05/18 13:55	Adjuster Immediate Advice				Load HTM	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	31/05/18 14:13	General View Photo				Load PDF	
2	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
3	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
4	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
5	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
6	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
7	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
8	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
9	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
10	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
11	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
12	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
13	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
14	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
15	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
16	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
17	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
18	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
19	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
20	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
21	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
22	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
23	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
24	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
25	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
26	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
27	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
28	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
29	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
30	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
31	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
32	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
33	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
34	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
35	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
36	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
37	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
38	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
39	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
40	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>
41	20/06/18 18:53	General View				Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
42	20/06/18 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/06/18 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/06/18 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/06/18 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
46	20/06/18 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
47	20/06/18 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
48	20/06/18 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
49	20/06/18 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
50	20/06/18 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
51	20/06/18 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
52	20/06/18 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
53	20/06/18 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
54	20/06/18 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/05/18 15:00	Quotation/Replacement/Repair invoice	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/05/18 14:09	estimate	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	22/05/18 13:56	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	22/05/18 13:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	22/05/18 13:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	22/05/18 13:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	22/05/18 13:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	22/05/18 13:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	22/05/18 13:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	22/05/18 13:56	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	22/05/18 13:55	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	22/05/18 13:55	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	22/05/18 13:55	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
4	22/05/18 13:55	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
5	22/05/18 13:56	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
6	22/05/18 13:56	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
7	22/05/18 13:56	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
8	22/05/18 13:56	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118009792/T1TD3Q2

Date: 29/06/2018

REFERENCE

Insured/Claimant: TAY JENNY (ZHENG JENNY) Policy No: DMPCSN1767841700

Date of Loss: 22/05/2018

Nature of Claim: OD

Claim No: SNM18D02553C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGH1100M	Engine No:	27091030995265
Make & Model:	MERCEDES-BENZ GLA180, 1.6 (A)	Chassis No:	WDC1569422J269613
Reg. Date:	16/11/2016 (Man. Year: 2016)	Odometer:	21750 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$127,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,283.93	2,192.31	2,091.62	48.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,940.00	600.00	23.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,823.93	4,132.31	2,691.62	39.44
+ GST 7.00/7.00% (S\$)	477.68	289.26	188.42	39.44
Nett Amount (S\$)	7,301.61	4,421.57	2,880.04	39.44

INSPECTION

Date of Assignment: 28/05/2018

Date Inspected: 30/05/2018 Inspected At:

Cycle & Carriage Industries Pte Ltd
(Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2018)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGH1100M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	1,290.69 FS	*1,290.69 FS
2	1		*CT/F BUMPER TRIM	Cut	62.94 FS	*62.94 FS
3	1		*CT/F BOTTOM CHROME	Cut	592.53 FS	*592.53 FS
4	1		*RH/F BOTTOM CHROME	Not Necessary	71.49 FS	*- FS
5	1		*LH/F BOTTOM CHROME	Not Necessary	71.49 FS	*- FS
6	1		*CT/F BOTTOM CHROME	Cracked	124.32 FS	*124.32 FS
7	1		*LICENSE PLATE BASE	Deformed	61.83 FS	*61.83 FS
8	1		*CT/F IMPACT ABSORBER	Not Necessary	123.37 FS	*- FS
9	1		*CT/F BASIC MOUNTING FOR BUMPER	Not Necessary	122.16 FS	*- FS
10	4		*CT/F PARKING SENSOR	Not Necessary	688.28 FS	*- FS
11	4		*CT/F PARKING SENSOR SEAL	Not Necessary	25.68 FS	*- FS
12	1		*RADIATOR GRILLE SUPPORT	Not Necessary	290.86 FS	*- FS
13	1		*RADIATOR GRILLE GARNISH SUPPORT	Not Necessary	185.04 FS	*- FS
14	1		*RADIATOR GRILLE STAR HOLDER	Not Necessary	72.06 FS	*- FS
15	1		*RADIATOR GRILLE STAR	Not Necessary	130.65 FS	*- FS
16	1		*FRT CROSS MEMBER	Not Necessary	310.54 FS	*- FS
17	1		*PLATE WITH HOUSING	Bent	60.00 FS	*60.00 FS
					Total Parts (S\$)	4,283.93 2,192.31

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
2	REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH	New	1,440.00	960.00
3	RESPRAY FRONT BUMPER	New	720.00	600.00
Gross Labour Cost (S\$)			2,540.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >