

ASS. REC. BY:

REF:

CS3/CTI18009798/G2403²

Special Instruction:

Surveyor

Maximer

From (Person):

GQ
Jung Tay

ASSIGNMENT (Office)

of CTI

Date/Time:

25/5/18 @ 2:20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBA 8814

Insured:

GBF 8433B

at Workshop in/s

Sheng Li Lei

Tel:

91119222

of

NO. 2 Kaki Bukit Ave 2 # 01-36

Policy No:

DMCVSN1811751800

Claim No:

SNM18D02598C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

2:30pm @ 30/5/18

Person Contacted:

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

GBA 8814-X

GBF 8433B-X

Dismantle: 1/6/2018

After Repair: 7/6/2018

Range

2000 - 2500/2

Repair days

4

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **GBA 8814**

at Workshop m/s **Sheng Li Lai**

of **No. 2 Kaki Bukit Ave 2 #01-36**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **\$28 K.**

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: **4** days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT



Veh No: **GBA 8814** Yr Regn: **12 Feb 2007** (2022)

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Merce VITO 1116** c.c. **248**

Colour: **White** A/C: Insured / Std / NI / NA

Sp. Reading: **319238** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **WDF 639603 23 28 7673**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **225/60 R 16**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Nexen**

Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. 5 mm	L/Bal. 5 mm
D.O.A. _____	D.O.I. 20-05-18
Survey held at w/s	5:10pm
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or	
O/S Rear	
The U/C / Chassis frame / Body Structure affected due to collision:	

Date / Time	Action / Instruction
1/8	Submit PRE report.
RECEIVED 01 AUG 2010	

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?
2)

Report Format : **PRE**

Lump Sum / I.B.I. (\$)

Days Of Repair: **4**

Resurvey No. of Trip: **2**

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

☐ S + RS
☐ Photos
☐ Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CTI18009798/Gz4d3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 31-05-2018	
		Code : CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBF 8433B	Veh. Inspected	GBA 881U
Policy No.	DMCVSN1811751800	Coverage (\$)	0.00
Claim No.	SNM18D02598C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	31/05/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/05/2018	Inspection Date	30/05/2018
Survey held at	SHENG LI LAI 2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 May 2018		25 May 2018 14:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CRAB HOUSE, Co. Reg. No.: 53169005M		
Main Claimant:	CHARTERED ASIA TECHNOLOGY ENTERPRISE PTE LTD, Co. Reg. No.: 200003210H		
Vehicle Reg. No.:	GBA881U	Date of Loss:	23/05/2018 17:00 - :59
Claim Type:	TP / SNM18D02598C02	Policy/Cover Note No.:	DMCVSN1811751800 (Comprehensive) Coverage: 04/04/2018 - 03/04/2019
Vehicle Reg. No. (Insured):	GBF8433B	Policy No. (Claimant):	VCC/P1912424
		Excess:	S\$0.00
Repairer:	Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/06/2018]		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS AND LET US HAVE YOUR RECOMMENDATION ON COST OF REPAIRS.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

in

not extracted.

XGB

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/05/2018 11:20
Date Of Accident	23/05/2018 17:35
Exact Location Of Accident	CARAPRK OF BLK 87 CIRCUIT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBA881U
Insured/Policyholder	
Name Of Registered Owner	CHARTERED ASIA TECHNOLOGY ENTERPRISE PTE LTD
Co Reg No	200003210H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67893179

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	VITO 111-2.1 D L (M)

Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
--	----------------

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	VCC/P1912424
Cover Note Number	

Driver

Name of Driver	KOH KANG SHENG
NRIC No	S8609674I
Date Of Birth	10/04/1986
Occupation	OUTDOOR
Date Of Driving Pass	27/04/2005
Driving Experience	13 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98457416
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 451B SENGKANG WEST WAY #13-375
Postcode	792451
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TANG YONG WAH GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


REFER TO POLICE REPORT NO: T/20180523/7015 STATEMENT RECORDED BY SOO - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF8433B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN WEE KIAT
NRIC/Passport Number	S7811254I
Contact Number	



Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

Vehicle No
A - GBA 881 4
B - GRF 84338



Legend

Vehicle A

Bike B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report no. T/20180525/7015

DECLARATION

I/We declare the foregoing particulars are true in every respect.
Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180523/7015

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20180523/7015

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/05/2018 20:16	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: KOH KANG SHENG			Address: APT BLK 451B SENGKANG WEST WAY #13-375 SINGAPORE 792451		
ID Type / ID No.: NRIC NO / S8609674I			Contact No.: Home/Office:		

General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 23/05/2018 17:37	Type of Location: Car Park
Location: CIRCUIT ROAD Block 87 circuit road carpark				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBA881U	Van	MERCEDES BENZ	VITO 111L M	White	Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
GBA881U	AXA INSURANCE SINGAPORE PTE LTD	VCC/P1912424	12/02/2018	11/02/2019



**SINGAPORE
POLICE FORCE**



T/20180523/7015

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180523/7015

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	TANG YONG WAH	ID No.	F8251572X
Related Vehicle	GBA881U (Van)	Contact No.	93892032
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	KOH KANG SHENG	ID No.	S86096741
Related Vehicle	GBA881U (Van)	Contact No.	98457416
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

Hi Officer, this is a report against the driver of GBF8433B.

The driver drove in the carpark against the traffic direction when I was parking and did a fast reversing.

when I see the driver reversing into my vehicle, I sounded the horn. However the driver did not stop and ram into my company vehicle.

Resulting in the damage of my company vehicle GBA881U. (I have a video of the incident)

Driver did not provide any solution and walked off in a rush after giving me his NRIC detail.



**SINGAPORE
POLICE FORCE**



T/20180523/7015

3 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180523/7015

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
KALESWARI PALANI
Contact No.: 65476902

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
23/05/2018 20:16

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3210H
Vehicle Details	
Vehicle No.:	GBA881U
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jul 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	VITO 111L M
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	64698051282683
Chassis No.:	WDF63960323297673
Maximum Power Output:	-
Open Market Value:	\$39,265.00
Original Registration Date:	12 Feb 2007
First Registration Date:	12 Feb 2007
Transfer Count:	2
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Feb 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$24,252.00
COE Rebate Amount:	\$17,291.00
Total Rebate Amount:	\$17,291.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 19 Jul 2018

OK

(01) Bent (2) Cracked (3) Distorted (4) Rusted (5) Spun (6) Scratched
(07) Deformed (08) Dilated (09) Enframed (10) Stretched (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

ACTION (AC)
(1) Replace (✓) (2) Repair (R) (3) Check (C)
(4) Not Corrosive (NC)

Vehicle No: GBA 881U

Rear Portion			CON	AC	Qty
NAC	INC	Item			
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	S	R	X
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate			
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

Vehicle No: GBA 881U

[illegible]

No. of Items: _____ Assessor: _____

Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 May 2018		25 May 2018 14:20 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CRAB HOUSE , Co. Reg. No.: 53169005M		
Main Claimant:	CHARTERED ASIA TECHNOLOGY ENTERPRISE PTE LTD , Co. Reg. No.: 200003210H		
Vehicle Reg. No.:	GBA881U	Date of Loss:	23/05/2018 17:00 - :59 [135 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D02598C02	Policy/Cover Note No.:	DMCVSN1811751800 (Comprehensive) Coverage: 04/04/2018 - 03/04/2019
Vehicle Reg. No. (Insured):	GBF8433B	Policy No. (Claimant):	VCC/P1912424
		Excess:	\$0.00
Repairer:	Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 06/06/2018]		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS AND LET US HAVE YOUR RECOMMENDATION ON COST OF REPAIRS.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBA881U (SNM18D02598C02)
[GBF8433B]
TP

CHARTERED ASIA TECHNOLOGY ENTERPRISE PTE LTD
May 23 2018 5:00PM
[CRAB HOUSE]
Sheng Li Lai

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Video			1 per page ▼	✓
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 11:26	Video - Accident [Linked Accident Report Documents]	Load MP4	
Assessment Reports			1 per page ▼	✓
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 11:27	Accident Statement	Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 11:26	Accident Photo [Linked Accident Report Documents]	Load JPG	✓
2	24/05/18 11:26	Accident Photo [Linked Accident Report Documents]	Load JPG	✓
3	24/05/18 11:26	Accident Photo [Linked Accident Report Documents]	Load JPG	✓
4	24/05/18 11:26	Accident Photo [Linked Accident Report Documents]	Load JPG	✓
5	24/05/18 11:26	Accident Photo [Linked Accident Report Documents]	Load JPG	✓
6	24/05/18 11:26	Accident Photo [Linked Accident Report Documents]	Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/07/18 15:36	General View	Load PDF	
2	19/07/18 15:37	Photographs of Damaged Parts	Load PDF	
3	19/07/18 15:37	Photo After Spray	Load PDF	
Documentation			1 per page ▼	✓
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 11:26	Sketch Plan [Linked Accident Report Documents]	Load JPG	✓
2	24/05/18 11:26	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	✓
3	24/05/18 11:27	POLICE REPORT [Linked Accident Report Documents]	Load TIF	
4	24/05/18 11:27	POLICE REPORT [Linked Accident Report Documents]	Load TIF	
5	24/05/18 11:27	POLICE REPORT [Linked Accident Report Documents]	Load TIF	
6	24/05/18 11:27	Common Statement [Linked Accident Report Documents]	Load JPG	✓
7	24/05/18 11:27	Individual Statement [Linked Accident Report Documents]	Load JPG	✓
8	24/05/18 11:27	CI [Linked Accident Report Documents]	Load TIF	
9	24/05/18 11:27	DRIVER IC/DL [Linked Accident Report Documents]	Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/05/18 14:21	E-filed GIA report	Load PDF	
2	25/05/18 14:30	PRE REPAIR NOTIFICATION	Load PDF	

Linked Accident Report Documents

			View	View in Browser ▼
Video			1 per page ▼	✓
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 11:26	Video - Accident	 Load MP4	
Assessment Reports			1 per page ▼	✓
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 11:27	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 11:26	Accident Photo	 Load JPG	✓
2	24/05/18 11:26	Accident Photo	 Load JPG	✓
3	24/05/18 11:26	Accident Photo	 Load JPG	✓
4	24/05/18 11:26	Accident Photo	 Load JPG	✓
5	24/05/18 11:26	Accident Photo	 Load JPG	✓
6	24/05/18 11:26	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 11:26	Sketch Plan	 Load JPG	✓
2	24/05/18 11:26	Sketch Plan #2	 Load JPG	✓
3	24/05/18 11:27	POLICE REPORT	 Load TIF	
4	24/05/18 11:27	POLICE REPORT	 Load TIF	
5	24/05/18 11:27	POLICE REPORT	 Load TIF	
6	24/05/18 11:27	Common Statement	 Load JPG	✓
7	24/05/18 11:27	Individual Statement	 Load JPG	✓
8	24/05/18 11:27	CI	 Load TIF	
9	24/05/18 11:27	DRIVER IC/DL	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118009798/GZ4D3S2
Date: 01/08/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN1811751800
 Claimant Vehicle No: GBA881U Insured Vehicle No: GBF8433B
 Date of Loss: 23/05/2018 Nature of Claim: TP Claim No: SNM18D02598C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA881U**
 Make & Model: MERCEDES-BENZ VITO 111, 2.1 D L (M) Engine No: 64698051282683
 Reg. Date: 12/02/2007 (Man. Year: 2006) Chassis No: WDF63960323297673
 Colour: White Odometer: 319238 km
 Engine Capacity: 2148 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60R16 Rear Tyre Size: 225/60R16
 Front Left Side: Nexen 5 mm Rear Left Side: Nexen 5 mm
 Front Right Side: Nexen 5 mm Rear Right Side: Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/05/2018
 Date Inspected: 30/05/2018 Inspected At: Sheng Li Lai (KAKI BUKIT)
 NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT
 Singapore 417921
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$2,500.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 01 Aug 2018)	
Parts:	N/A	MERCEDES-BENZ VITO 111 2.1 D L (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA881U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >