

ASS. REC. BY:

REF:

CS3/MSG18009799/71240302

Instruction:

Surveyor

Manireh

Tuchik

ASSIGNMENT (Office)

From (Person):

Mund Ashik

of

MSIG

Date/Time:

28/5/18 @ 4:22pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No:

SLF 7347E

Insured:

SKP 979L

at Workshop m/s

TJ Car Care

Tel:

62 768567

of

Blk 1010, # 01-115 Bkt merah lane 3

Policy No:

B29 080481MCX

Claim No:

559348

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/05/2018

CA / REV / REP. / REV 24 HRS ^{1 up}

H.O.D. Endorsement:

Date/Time:

4:27pm @ 30/5/18

Person Contacted:

Vehicle

☒ IN ☐ OUT

Date/Time	Action/Instruction	Estimate
	SLF 7347E - NBA 11P18009494/Y	DOA: 23/5/18
	SKP 979L - NBA 11P18009494/Y	DOA: 23/5/18
31/5/18	Disassembled	

Signature: Tan Jiah

REF:


MS16

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

PRS.

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLF7347E Yr Regn: 2016 Sep.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Altis C.C. 1598
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 30031 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR053REH104054755
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55 R16
 R: 27
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 30/5/18
 Survey held at TO Car
 Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction mt 617
1/4/18 Submit PRS Repy.

* Repair Estimate : S\$ 10,500 - 11,500

* 5 days

RECEIVED 01 JUN 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) _____
 Date/Time, File Return to?

☐ : Final Report

2) _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Invs (\$ _____)

☐ Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

120
50
10
180

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 May 2018		28 May 2018 16:22 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PREMIER RENT A CAR PTE LTD , Co. Reg. No.: 200612929E		
Main Claimant:	GOLDBELL CAR RENTAL PTE LTD , Co. Reg. No.: 200710651D		
Vehicle Reg. No.:	SLF7347E	Date of Loss:	23/05/2018 18:00 - :59 [20 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 559348	Policy/Cover Note No.:	B29080481MCX (TP, Fire & Theft) Coverage: 01/05/2018 - 30/04/2019
Vehicle Reg. No. (Insured):	SKP979L	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	TJ Car Care Services (HQ) Blk 1010, #01-115, Bukit Merah Lane 3, 159724 Bukit Merah - Tel: 62768567		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/05/2018]		
Driver/Custodian (Insured):	CHA KWANGSIK (/ Male), NRIC: M40903976, Tel: +6588666280		
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK LIABILITY: 100% BOLA S28 APPLICABLE CONTACT : MR LIM BOON LEONG 9757 5155		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

In

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/05/2018 15:27
Date Of Accident	23/05/2018 19:00
Exact Location Of Accident	SLIP RD TOWARDS FORT RD INSIDE MCE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF7347E
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	PANG.DESMOND@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-93682523
Alternative Phone No	OFFICE-93682523

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	ON THE WAY HOME AFTER WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V00034/VPZ/R03
Cover Note Number	

Driver

Name of Driver	PANG CHEE WAI (FENG ZHIWEI)
NRIC No	S7304568A
Date Of Birth	27/01/1973
Occupation	INDOOR
Date Of Driving Pass	05/08/1998
Driving Experience	19 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93682523
Fax Number	
Contact Number	OTHERS-93682523
Email Address	PANG.DESMOND@YAHOO.COM.SG

Address	BLK 690E WOODLANDS DRIVE 75 #08-202
Postcode	735690
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP979L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SGB1178X
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

PANG CHEE WAI (FENG ZHIWEI)

Approximate Age

Injuries Sustain

SLIGHT INJURY

Injured person in which vehicle?

SLF7347E

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my work shop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/meal packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirement under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 24/05/2018
Reporting Centre Person's Signature
Name:
NIC/FIN No: *[Signature]*

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ACCIDENT HAPPENED AT APPROX. 7pm ON 23RD MAY '18
WHILE TRAVELLING IN THE MCE EXTENDING FORT ROAD
TOWARDS CHANIER AIRPORT. A PASSENGER CAR KNOCKED
AT MY REAR CAUSING A CHAIN COLLISION WITH A CAR
IN FRONT OF ME. PARTICULARS OF DRIVERS BEING EXCHANGED.

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PPN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 May 2018		28 May 2018 16:22 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PREMIER RENT A CAR PTE LTD , Co. Reg. No.: 200612929E								
Main Claimant:	GOLDBELL CAR RENTAL PTE LTD , Co. Reg. No.: 200710651D								
Vehicle Reg. No.:	SLF7347E	Date of Loss:	23/05/2018 18:00 - :59 [20 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 559348	Policy/Cover Note No.:	B29080481MCX (TP, Fire & Theft) Coverage: 01/05/2018 - 30/04/2019						
Vehicle Reg. No. (Insured):	SKP979L	Policy No. (Claimant):							
		Excess:	S\$750.00						
Repairer:	TJ Car Care Services (HQ) Blk 1010, #01-115, Bukit Merah Lane 3, 159724 Bukit Merah - Tel: 62768567								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 29/05/2018]								
Driver/Custodian (Insured):	CHA KWANGSIK (/ Male), NRIC: M40903976, Tel: +6588666280								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK LIABILITY: 100% BOLA S28 APPLICABLE CONTACT : MR LIM BOON LEONG 9757 5155								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLF7347E (559348)
[SKP979L]
TP
GOLDBELL CAR RENTAL PTE LTD
May 23 2018 6:00PM
[PREMIER RENT A CAR PTE LTD]
TJ Car Care Services

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail		Print	
1	28/05/18 10:31	Accident Statement From: SC - Reg. No: SKP979L, Claimant: PREMIER RENT A CAR PTE LTD				1 Load HTM			
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
2	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
3	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
4	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
5	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
6	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
7	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
8	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
9	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
10	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
11	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
12	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
13	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
14	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
15	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
16	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
17	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
18	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
19	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
20	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
21	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
22	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
23	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
24	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
25	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
26	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
27	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
28	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
29	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
30	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
31	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
32	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	
33	01/06/18 16:25	General View				1 Load JPG		<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
35	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
36	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
37	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
38	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
39	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
40	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
41	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
42	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
43	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
44	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
45	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
46	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
47	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
48	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
49	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
50	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
51	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
52	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
53	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
54	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
55	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
56	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
57	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
58	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
59	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
60	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
61	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
62	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
63	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
64	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
65	01/06/18 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
66	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
88	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
96	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	01/06/18 16:26	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/05/18 10:31	SGB1178X E-FILE REPORT (1st vehicle) From: SC - Reg. No: SKP979L, Claimant: PREMIER RENT A CAR PTE LTD	 Load PDF	
2	28/05/18 10:31	SLF7347E E-FILE REPORT (2nd vehicle) From: SC - Reg. No: SKP979L, Claimant: PREMIER RENT A CAR PTE LTD	 Load PDF	
3	28/05/18 11:03	PRI - KSCGP JURIS LLP	 Load PDF	
4	28/05/18 11:01	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18009799/T1Z4D3E2

Date: 04/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B29080481MCX
 Claimant Vehicle No: SLF7347E Insured Vehicle No: SKP979L
 Date of Loss: 23/05/2018 Nature of Claim: TP Claim No: 559348

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF7347E**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRX586761
 Reg. Date: 07/09/2016 (Man. Year: 2016) Chassis No: MR053REH104554755
 Colour: Blue Odometer: 30031 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/05/2018
 Date Inspected: 30/05/2018 Inspected At: TJ Car Care Services (HQ)
 Blk 1010, #01-115, Bukit Merah Lane 3
 Singapore 159724
 Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,500.00 - \$11,500.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF7347E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >