

Tanph 97495749

Exit to be advise

Resent, Not Andward PDI TUAS

Recovery before paint

sw @ the auto. u m

5 days

30/5/18 @ 11am

MS16

WINNER

OD

OW7

PDI TUAS

TAN CHEE KIANG (CHEN ZHIJIAN) @ 9698 8594
6 BISHAN STREET 25
#28-10
Singapore, 573975
Singapore

Phone No.

Fax No.

E-Mail

VAT Registration No. M20098505-2

Tax No. 199101494Z

Service Quote

Customer No. CV009788
Quote No. SER/QUO/1800847
QuoteDate 24/05/18
Salesperson Eric Tan
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

SURVEY EMAIL: 24/05/2018

28/5/2018

APPT: 30/5, 1100, 247, ✓

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Sharan GP 2.0 TSI HL LOW	0	
License No.	VIN	Initial Registration	Sales Advisor
SJX7228U	WVWZZZ7NZJV006049	15/11/17	Eric Tan
Engine Code	Labor Type	Engine No.	Model Code
	10	DED 016371	7N24MY

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	4	UNIT		1160 2,320.00
P B&P ALEX PAINT	SPRAY PAINT	4	UNIT		1000 2,000.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		bt 80.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		✓ 360.00
P B&P MECH	COMPULSORY TO DO AFTER AC				
	CHECK WIRE HARNESS, ECU, S	1	Time Un		✓ 200.00
	Nett				
	Sum Labor				4,960.00
P 1S0919275C GRU	SENSOR	1	Pieces		? 202.03
	Predecessor 1S0919275C				
P 1T0919133C 9B9	PARKING SENSOR O RING	1	Pieces		net 0.75
P 7N0121283C	AIR GUIDE LH	1	Pieces		? 55.29
P 7N0121284C	AIR GUIDE RH	1	Pieces		? 51.85
P 7N0805567B	SUPPORT LOCK CARRIER	1	Pieces		? 117.06
P 7N0805931	H/LAMP TOP PANEL LH	1	Pieces		? 43.68
P 7N0805932	H/LAMP TOP PANEL RH	1	Pieces		? 58.54
P 7N0807109D	REINFORCEMENT	1	Pieces		? 843.21
	Predecessor 7N0807109B				
P 7N0807183A	BUMPER SIDE BRACKET LH	1	Pieces		net 24.88
P 7N0807184A	BUMPER SIDE BRACKET RH	1	Pieces		? 24.88
P 7N0807192	BUMPER CENTRE BRACKET	1	Pieces		? 141.27
P 7N0807217J GRU	FRT BUMPER	1	Pieces		del 1,479.91
P 7N0823031A	FRT BONNET	1	Pieces		bt 1,662.19
P 7N0853101 2ZZ	CENTRE LOWER GRILLE CHRO	1	Pieces		cut 208.84
P 7N0853600A FOD	VW SIGN	1	Pieces		net 133.03
Sum carried forward					10,007.41

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TAN CHEE KIANG (CHEN ZHIJIAN)
6 BISHAN STREET 25
#28-10
Singapore, 573975
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV009788
Quote No. SER/QUO/1800847
QuoteDate 24/05/18
Salesperson Eric Tan
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Sharan GP 2.0 TSI HL LOW	0	
License No.	VIN	Initial Registration	Sales Advisor
SJX7228U	WVWZZZ7NZJV006049	15/11/17	Eric Tan
Engine Code	Labor Type	Engine No.	Model Code
	10	DED 016371	7N24MY

		Continued	10,007.41
P 7N0853651F 9B9	RADIATOR GRILLE	1 Pieces	ant 664.98
P 7N0853677 9B9	CENTRE LOWER GRILLE	1 Pieces	cur 179.37
P 7N2941754B	HEADLAMP RH	1 Pieces	7 3,002.55
	Use Predecessor 7N2941754A		
	Sum Item		8,894.31
		Sum Labor	4,960.00
		Sum Item	8,894.31
		Total SGD	13,854.31
		7% GST	13,854.31 969.80
		Total SGD Incl. GST	14,824.11

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to: - BBN: - Acc.-No..