

23/9/2007

ASS. REC. BY:

REF: CS/FCI18009816/Ktd3ⁿ²

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Gilen Lee

of

FCI

Date/Time: 30/5/18 @ 4:40pm

Estimated Cost:

Bill to:

OD / (FP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 7650D

Insured:

SHC 3788E

at Workshop n/s

Compute VMS

Tel:

6455 0012

of

176 Sin Ming Drive #03-14

Policy No:

Claim No:

DU8004252MP8H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24/5/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up,

H.O.D. Endorsement:

Date/Time:

11:33am @ 31/5/18

Person Contacted:

Lithui

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SJT 7650D ~x

SHC 3788E - NS / INC 1701 9/70 / K/rbe2

DoA: 3/10/17

14/6-

Parent preli advise.

18/110

81225.9, email & cabinet (Red: 180180: 59%)

REF: FCI

ASSIGNMENT

From:

Date: 12/6/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

~~S20 9154H~~

at Workshop m/s

~~Lim Jan Motor Complete~~

of

Blk 176, Sin Ming Drive # 03-09

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

~~After 10-30am~~

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

819k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{ups}

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

13/6 15h pgs to Catherine

Veh No:

SJT7650h Yr Regn: 10, 09

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS Lario

C.C.

1498

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

112733

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1BAAE1180021632

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD ☒ R/Rim or

Tyre Size:

F:

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

3

mm

L/Bal.

4

mm

L/Bal.

3

mm

D.O.A.

24/5/18

D.O.I.

12/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

- RECEIVED 19 OCT 2018

Date/Time: File Pass to?



Preli. Report

1) 19/10 Typist



Final Report

Date/Time: File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation

) S + RS) SI

Photos

Others

TOTAL

130

50

50

13

243

Report Format:

TP

Lump Sum / 15: (\$)

1225.91



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18009816/Ktd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 31-05-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3788E	Veh. Inspected	SJT 7650D
Policy No.		Coverage (\$)	0.00
Claim No.	D18004252MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/05/2018	Inspection Date
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004252MFSH

Date: 14/6/2018

Our Ref: CS/FCI18009816/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJT 7650D.

Please be informed that we had conducted the inspection of the abovementioned vehicle
12/06/2018 at the premises of M/s Complete VMS and have the following to report: -

Workshop Estimate Amount	: S\$ <u>3,027.71</u>
Revised Estimate Amount	: S\$ <u>1,225.91</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
o/s rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	28-05-2018	Our Ref No. D18004252MFSH
Accident Date	24-05-2018	Claim Type. Third Party
Insured Vehicle	SHC3788E	Third Party Vehicle. SJT7650D
Survey Location	176 SIN MING DRIVE #03-14SIN MING AUTOCARE COMPLEX	
Contact Person.	LILY/LI HUI (TEL: 64539622)	
Contact No.	64550012/ 0	Fax No. 65540012
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	COMPLETE VMS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 14 June 2018 3:43 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004252MFSH/1
Attachments: PRELI ADVISED SJT 7650D.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJT 7650D**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 31 May 2018 11:34 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004252MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 30 May 2018 4:39 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004252MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHUA PUAH KENG
BLK 422 ANG MO KIO AVE 3 #10-2508
SINGAPORE 560422

Attention : THE OWNER
Contact : 98009904

Estimate : ES006362

Date : 28/05/2018
Vehicle Num. : SJT7650D
Make/Model : NISSAN LATIO 1.5L A-2009
Chassis/Eng# : JN1BAAC11Z0021632/HR15116772B
Accident Date : 24/05/2018
Claim No. :
Reference :
Policy No. :

*Not Not have
Running After Rain
3 days
\$ 1225.91*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS : REAR BUMPER	<i>n</i> 629.00	<i>X</i>
List Total S\$:			629.00	
30.00% Discount S\$:			188.70	
			440.30	

1.	1	NETT ITEMS : TAIL LAMP R/H	<i>Gu</i> 339.90	<i>✓</i>
2.	1	REAR BUMPER LOWER LIP	<i>n</i> 785.00	<i>X</i>
Nett Total S\$:			1,124.90	
10.00% Discount S\$:			112.49	
			1,012.41	

LABOUR :
SPRAY PAINT DAMAGED AREA AFFECTED
CHANGE TAIL LAMP AND CHECK WIRING
RUST PROOFING TREATMENT
KNOCK OUT DENT ON REAR FENDER AND CHANGE ALL NECESSARY PARTS

Labour Total S\$:

3000
800.00
nn 65.00 *200*
60.00 *X*
650.00 *600*
1,575.00

SingDollars : Three Thousand Twenty-Seven & Cents Seventy-One Only

Total S\$: 3,027.71

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18009816/Ktd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-10-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3788E	Veh. Inspected	SJT 7650D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004252MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	30/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN LATIO (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JN1BAAC11Z0021632	Colour	WHITE	
Odometer	112733	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	TOYO	4 mm	
L/H Front Tyre	185/60 R15	TOYO	4 mm	
R/H Rear Tyre	185/60 R15	TOYO	3 mm	
L/H Rear Tyre	185/60 R15	TOYO	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/05/2018	Inspection Date	12/06/2018	
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 7650D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	629.00	-
	LESS 30% DISCOUNT		-188.70	-
			440.30	-
	NETT ITEMS			
1	TAIL LAMP R/H (N)	CUT	339.90	339.90
1	REAR BUMPER LOWER LIP (N)	TO REPAIR SEE LABOUR	785.00	-
	LESS 10% DISCOUNT		-112.49	-33.99
			1,012.41	305.91
	LABOUR			
	SPRAY PAINT DAMAGED AREA AFFECTED.		800.00	300.00
	CHANGE TAIL LAMP AND CHECK WIRING.		65.00	20.00
	RUST PROOFING TREATMENT.	NOT NECESSARY	60.00	-
	KNOCK OUT DENT ON REAR FENDER AND CHANGE ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BUMPER LOWER LIP.		650.00	600.00
			1,575.00	920.00
	GRAND TOTAL		3,027.71	1,225.91
	RECOMMENDED COST OF REPAIRS			1,225.91

Report Ref No. CS/FCI18009816/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.