



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
 Sin Ming Autocare Complex
 Singapore 575721
 Tel : (65) 6455 0600
 Fax : (65) 6455 6192
 Website: www.autocare.com.sg
 GST Reg. No: 20-0210033-N

AXA INSURANCE (SINGAPORE) PTE LTD
 8 SHENTON WAY #27-01 AXA TOWER
 SINGAPORE 068811

Estimate : E18/2440

Attention : Motor Claim Department
 Contact : 18008804741 Fax No. : 6880 4740

Date : 22/05/2018
 Vehicle Num. : SJM9780K
 Make/Model : MITSUBISHI COLT PLUS-2009
 Chassis/Eng# : JMYLTZ23W8Z000870/4A910116223
 Accident Date : 19/05/2018
 Claim No. : BFG
 Reference : TP CLAIM
 Policy No. : 5097023049

*Not available
 L1 Sur & ?
 Resurvey After Paint 4 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1PC	REAR BUMPER		602.00 ✓
2.	1PC	TAILGATE		825.00 ✓
3.	2PCS	REAR BUMPER BRACKET	25.00	50.00 ✓
4.	1PC	REAR END PANEL		374.00 ✓
5.	3PCS	TAIL GATE EMBLEM		162.00 ✓
6.	1SET	POWER TAILGATE LOCK		1,209.00 ✓
List TotalS\$:				3,222.00
10.00% Discount S\$:				322.20
				2,899.80

SPECIAL NETT ITEMS :				
1.	4PCS	BUMPER CLIPS	3.00	12.00 ✓
2.	1SET	REVERSE SENSOR		250.00 ✓
Special Nett Total S\$:				262.00

LABOUR :				
TO PANEL BEATING ON REAR DAMAGED AREAS			400	800.00
TO PUTTY & SPRAY PAINTING ON REAR DAMAGED AREAS			400	1,000.00
TO APPLY ANTI-RUST				80.00 ✓
TO CHECK WIRING				80.00 ✓
TO CHECK TAILGATE WATER SEEPAGE			60	60.00 ✓
TO REMOVE & REFIX TAILGATE INTERIOR UPHOLSTERY				100.00 ✓
TO REMOVE & INSTALL NEW SET REVERSE SENSOR				80.00 ✓
TO CHECK TAILGATE AUTO LOCK SYSTEM FOR PROPER FUNCTION				80.00 ✓
Labour Total S\$:				2,280.00


 for Sin Ming Autocare BFG Pte Ltd

E. & O.E. Total S\$: 5,441.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: