

ASS. REC. BY

REF:

es/FCI18009852/Ardb3/12

Special Instruction:

Surveyor's
CWS

Adrian

ASSIGNMENT (Office)

From (Person)

Joanne Young

of

FCI

Date/Time:

31/5/2018 @ 12.06pm

Estimated Cost

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV?CS

To Inspect Vehicle No:

SBX 9188H

Insured:

SH 9197P

at Workshop m/s

J-Mart Motor

Tel:

6343 0934

of

Blk 5 Defu Lane 10 # 01-578

Policy No:

Claim No:

D1800 4316 MP8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/5/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

2.35pm 07/5/18

Person Contacted:

Tregie

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SBX 9188H-X

SH 9197P- es/FCI14009367/Rgbd1

DOA: 9/5/14

1/6/18

Informed FCI pending workshop est by email

18/9/18

Adrian confirmed LS \$1200 (Red 3051.37, 7275)

18/9/18

Email preli revised to FCI

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SBX9188H Yr Regn: 2009 1 MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Sylphy c.c. 1498Colour: Purple A/C: Insured / Std / NI / NASp. Reading: 127763 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN13AAG1120107536Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 31/05/18Survey held at J-Mart.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

TP 1st Cap.

Note:

MV: 17K (EST)PV: 10.9KNett: 7.9K 6.1K

RECEIVED 19 SEP 2010

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 18/9 - typistReport Format: CWSLump Sum / I.B.I: (\$) 1200/2Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

135505014249



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18009852/Avd3

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 31-05-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9197P	Veh. Inspected	SBX 9188H
Policy No.		Coverage (\$)	0.00
Claim No.	D18004316MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/05/2018	Inspection Date	31/05/2018
Survey held at	J-MART MOTOR PTE LTD BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18004316MFSH
Our ref: CS/FCI18009852/Avd3

Date : 18/9/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SBX 9188X


We thank you for your instruction on 31/5/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 31/5/2018 at the premises of M/s J-MART MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,251.37
Revised Estimate Amount	: S\$1,200.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A.M.MATAI

Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	30-05-2018	Our Ref No. D18004316MFSH
Accident Date	24-05-2018	Claim Type. Third Party
Insured Vehicle	SH9197P	Third Party Vehicle. SBX9188H
Survey Location	BLOCK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C	
Contact Person.	ANGIE	
Contact No.	63430934/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	J-MART MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 18 September 2018 4:39 PM
To: 'Claim Workflow System'
Cc: 'JOANNEYONG@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18004316MFSH/1, SBX 9188H
Attachments: SBX 9188H PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SBX 9188H
Date of survey: 31/5/2018
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 1 June 2018 5:21 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004316MFSH/1, SBX 9188H

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SBX 9188H on 31/5/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 31 May 2018 2:39 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004316MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Thursday, 31 May 2018 12:06 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18004316MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 1 June 2018 5:21 PM
To: 'Claim Workflow System'
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004316MFSH/1, SBX 9188H

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SBX 9188H on 31/5/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 31 May 2018 2:39 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004316MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 31 May 2018 12:06 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004316MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

**Free Car Valuation**

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) | [Advertiser Login](#) | [i Ways of Selling](#)
New 5 Years Coe Renewal Toyota Vios 1.5A

\$2500 Downpayment Monthly
From \$580 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd



**CERTIFIED PRE-OWNED
MERCEDES-BENZ**

[View our cars](#)

Browse by Category

[Save Search](#)[Print](#)

Sort by Date Posted

20 results/page

5 vehicles

Search Sylphy[Advanced Search](#)[Search](#)[View All](#)

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Sylphy

Any

Any

2009

Any

Any

Any

Available

☐ Nissan Sylphy 1.5A**\$13,800**

\$7,910 /yr

15-Jan-2009

1,498 cc

-

Sedan

Available

Well Taken Care And Maintained By Owner. Very Spacious Sedan With Low Maintenance Cost. Highly Recommended For Daily Usage Or Family User. Loan Available. Trade In Welcome. Please Call Our Friendly Sa...

SKL Automobile Pte Ltd

★ Posted: 28-Mar-2018 Tags: 2009 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan

☐ Nissan Sylphy 1.5A**\$17,288**

\$9,870 /yr

05-Feb-2009

1,498 cc

110,000 km

Sedan

Available

1 Owner Only. Original Paintwork. STA/Vicom Inspection Welcome. No Repairs Needed. Flexible Bank And In-House High Loan Available At Low Interest Rate. 6 Months Certified Pre Owned Car Warranty Will B...

★ Posted: 23-Apr-2018 Tags: 2009 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan

☐ Nissan Sylphy 1.5A**\$15,800**

\$6,990 /yr

27-Feb-2009

1,498 cc

166,000 km

Sedan

Available

10% Downpayment. \$1,375/mth. Good Condition. Flexible Loan Package. Instant Approval. Ex Bankrupt Welcome. High Trade In.

★ Posted: 31-May-2018 Tags: 2009 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan

☐ Nissan Sylphy 1.5A**\$18,500**

\$7,870 /yr

21-Jul-2009

1,498 cc

-

Sedan

Available

Careful Owner With Full Agent Serviced Record, Original Paintwork, 6 Months Free Servicing By Reputable Workshop With 40 Years Experience In The Market For A Peace Of Mind, STA/Vicom Inspection Welcome...

★ Posted: 26-May-2018 Tags: 2009 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan


PREMIUM AD



Car Buying



Car Selling



Car Ownership



Car Aftermarket



On The Move



Lifestyle

**Buying a pre-owned car, but
Unsure of its Condition?**
Get, STA Car Evaluation

☐ Nissan Sylphy 1.5A**\$24,800**

\$10,680 /yr

25-Nov-2009

1,498 cc

100,316 km

Sedan

Available

Beautiful Well Kept Interior With Wood Trimmings, One Of The Most Popular Affordable Sedan With Luxury Looks, 100% Accident Free! Verified By STA! Immaculate Condition, Reluctant Sale By Owner But Nee...

Prem Roy Motoring

★ Posted: 15-May-2018 Tags: 2009 Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Used Nissan

CONFIRMED

Save this search criteria, to get email alerts whenever a match is found.

[Save Search](#)

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1561Z
Vehicle Details	
Vehicle No.:	SBX9188H
Vehicle to be Exported:	Yes
Intended De-registration Date:	31 May 2018
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.5 4AT
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	HR15101631B
Chassis No.:	JN1BAAG11Z0107536
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$20,131.00
Original Registration Date:	15 May 2009
First Registration Date:	15 May 2009
Transfer Count:	1
Actual ARF Paid:	\$20,131.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 May 2019
PARF Rebate Amount:	\$10,065.00
Intended COE Rebate Details	
COE Expiry Date:	14 May 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$8,489.00
COE Rebate Amount:	\$810.00
Total Rebate Amount:	\$10,875.00

The information contained herein is correct as at 31 May 2018

OK

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

30-May-18

Our ref : TP/4515/18

Loke Guat Bee

RE : estimate cost for vehicle no : SBX 9188H

1 pc	frt bumper	\$	808.45	nett	-
1 pc	frt bumper rh retainer		112.45	-	-
1 pc	frt bumper rh fog lamp		397.10	+	-
1 pc	frt bumper rh fog lamp cover		85.90	+	-
2 pcs	frt bumper chrome		228.40	-	-
1 pc	frt bumper reinforcement		397.10	+	-
1 pc	headlamp		1020.45	X	-
10 pcs	frt bumper clips		50.00	30	-
1 pc	frt grille		435.00	X	-
			3,534.85		-
		less 10%	353.49		-
			3,181.37		-

1 pc	frt no plate	40.00	nett	✓	-
	Panel beating.	500.00	200	-	-
	Spray painting.	500.00	200	-	-
	Wiring.	30.00	-	-	-
		4,251.37		-	-
		Plus 7% GST	297.60		-
			4,548.96		-

SD : four thousand five hundred forty-eight & cents ninety-six only.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King
h/s 31/05/18.
03 days.
total 1531.37.
h/s 12K




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18009852/Avd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9197P	Veh. Inspected	SBX 9188H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004316MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	31/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JN1BAAG11Z0107536	Colour	PURPLE	
Odometer	127763	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	6 mm	
L/H Front Tyre	195/65 R15	MICHELIN	6 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/05/2018	Inspection Date	31/05/2018	
Survey held at	J-MART MOTOR PTE LTD BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBX 9188H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER (N)	DEFORMED	808.45	808.45
1	FRT BUMPER RH RETAINER (N)	NECESSARY	112.45	112.45
1	FRT BUMPER RH FOG LAMP (N)	NOT NECESSARY	397.10	-
1	FRT BUMPER RH FOG LAMP COVER (N)	NOT NECESSARY	85.90	-
2	FRT BUMPER CHROME (N)	NECESSARY	228.40	228.40
1	FRT BUMPER REINFORCEMENT (N)	NOT NECESSARY	397.10	-
1	HEADLAMP (N)	NOT NECESSARY	1,020.45	-
10	FRT BUMPER CLIPS (N)	NECESSARY	50.00	30.00
1	FRT GRILLE (N)	NOT NECESSARY	435.00	-
	LESS 10% DISCOUNT		-353.48	-117.93
			3,181.37	1,061.37
	<u>SPECIAL NETT ITEMS</u>			
1	FRT NO PLATE (SN)	BENT	40.00	40.00
			40.00	40.00
	<u>LABOUR</u>			
	PANEL BEATING.		500.00	200.00
	SPRAY PAINTING.		500.00	200.00
	WIRING.		30.00	30.00
			1,030.00	430.00
	GRAND TOTAL		4,251.37	1,531.37
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00

Report Ref No. CS/FC118009852/Avd3n2

MARKET VALUE: \$17,000.00 (EST)-PAPER VALUE: \$10,900.00=NETT VALUE: \$6,100.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.