

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Julie mengubut of AGI

Date/Time: 3/5/18 @ 3pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJG 2099Y

Insured: SGB 6523A

at Workshop m/s: Wei Lee Motor Works

Tel: 6456 9830

of Blk 9 Sin Ming Ind. Est #01-32

Policy No: Claim No: C10001625/JM

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A: 25/5/2018

CA / REV / REP. / REV 24 HRS

1/6/18

H.O.D. Endorsement:

Date/Time: 3:27pm @ 3/5/18 Person Contacted: Keren

Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SJG 2099Y -X
	SGB 6523A -X
3/7	L/Ly @ Good email & center (Ref 2004-40, 33/9)

REF: AGI

ASSIGNMENT

From: _____ Date: 1/6/2018

Estimated Cost: _____

OD TP WS TP RES OD RES EVA INV MV

To Inspect Vehicle No: SJG 20994
 at Workshop m/s Wei Lee Motor Works
 of Blk 9 Sin Ming Ind. Est # 01-32

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SJG 20994 Fr Regn: 06 of 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or MPV

Make: Honda ^A Stream c.c. 1799

Colour: M. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 215816 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHM RN 8408 S 203868

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / R Rim / STD A/Rim or

Tyre Size: F: 215/50R17
 R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 812k

IDAC Accident Rport: _____ Consistent? : Yes or No


GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 8123 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{Imp}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken

Front	Rear
R/Bal. 2 mm	R/Bal. 2 mm
L/Bal. 2 mm	L/Bal. 2 mm
D.O.A. 2515118	D.O.I. 116118

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
4/6	File pass to Corbin

RECEIVED 3 JUL 2018

Date/Time. File Pass to? : Preli. Report
 : Final Report

1) _____

Date/Time. File Return to? _____

2) 3/7 - typist

Report Format: TP

Lump Sum / I.B.I: (\$) 4000/-

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation _____

_____ \$ + RE _____ \$

Photos _____

Others _____

TOTAL 250

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18009855/Kvd3

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 31-05-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGB 6523A	Veh. Inspected	SJG 2099Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10001625/JM	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/05/2018	Inspection Date	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18009855/Kvd3

Nivitha (LKK Auto)

From: Julie Mangubat <julie.m@budgetdirect.com.sg>
Sent: Thursday, 31 May 2018 3:00 PM
To: SUR; admin-d@lkkauto.com
Subject: FW: TP survey for vehicle no: SJG2099Y | Our ref: C10001625/JM
Attachments: doc02476820180531145024.pdf

Hi Team

Please accept TPPD survey and survey on a without prejudice basis.

Thank you,
-Julie

From: karen Seah <weileemotorworks@gmail.com>
Sent: Thursday, 31 May, 2018 2:48 PM
To: Claims <claims@budgetdirect.com.sg>
Subject: TP survey for vehicle no: SJG2099Y

Your insured vehicle No: SGB6523A
Accident involving vehicle No; SJG2099Y/SGB6523A/SJH2117Z
DOA{ 25/05/2018 AT PIE near Kallang Bendemeer Exit

Dear officer incharge
I refer to the above case, attached with the accident report n estimate of repair.
Kindly arrange to survey the vehicle ASAP.
Thank you.

--
Best Regards,

Karen Seah

Wei Lee Motor Works
Block 9 Sin Ming Industrial Estate
#01-32 Singapore 575644
Tel: 6456 9830
Fax: 6458 0128
Company registration: 269436/00J



Virus-free. www.avg.com

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
 Owner ID: 1813C

Vehicle Details

Vehicle No.: SJG2099Y
 Vehicle to be Exported: Yes
 Intended De-registration Date: 05 Jun 2018
 Vehicle Make: HONDA
 Vehicle Model: STREAM 1.8L A
 Primary Colour: Blue
 Manufacturing Year: 2008
 Engine No.: R18A12803868
 Chassis No.: JHMRN684085203868
 Maximum Power Output: 103.0 kW (138 bhp)
 Open Market Value: \$20,627.00
 Original Registration Date: 24 Jun 2008
 First Registration Date: 24 Jun 2008
 Transfer Count: 1
 Actual ARF Paid: \$20,627.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 23 Jun 2018
 PARF Rebate Amount: \$10,313.00

Intended COE Rebate Details

COE Expiry Date: 23 Jun 2018
 COE Category: B - Car (1601cc & above)
 COE Period(Years): 10
 QP Paid: \$14,640.00
 COE Rebate Amount: \$73.00
Total Rebate Amount: \$10,386.00

The information contained herein is correct as at 01 Jun 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
 Owner ID: 5673G

Vehicle Details

Vehicle No.: SJG2099Y
 Vehicle to be Exported: Yes
 Intended De-registration Date: 28 Jun 2018
 Vehicle Make: HONDA
 Vehicle Model: STREAM 1.8L A
 Primary Colour: Blue
 Manufacturing Year: 2008
 Engine No.: R18A12803868
 Chassis No.: JHMRN68408S203868
 Maximum Power Output: 103.0 kW (138 bhp)
 Open Market Value: \$20,627.00
 Original Registration Date: 24 Jun 2008
 First Registration Date: 24 Jun 2008
 Transfer Count: 1
 Actual ARF Paid: \$20,627.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 23 Jun 2018
 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 Jun 2023
 COE Category: B - Car (1601cc & above)
 COE Period(Years): 5
 PQP Paid: \$18,953.00
 COE Rebate Amount: \$18,909.00
Total Rebate Amount: \$18,909.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/05/2018 14:58
Date Of Accident	25/05/2018 22:40
Exact Location Of Accident	PIE(TUAS) NEAR TO KALLANG BENDEMEER EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG2099Y
Insured/Policyholder	
Name Of Registered Owner	KH LEASING PTE. LTD.
Co Reg No	201611813C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98514451
Vehicle Particulars	
Manufacturer	HONDA
Model	STREAM-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5100590757
Cover Note Number	
Driver	
Name of Driver	KARUPPIAH KANAN
NRIC No	S1163699C
Date Of Birth	17/07/1956
Occupation	OUTDOOR
Date Of Driving Pass	05/02/2009
Driving Experience	9 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98514451
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address 16 JALAN LANJUT
SINGAPORE

Postcode 577659

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 3

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1
NAME: : NA
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGB6523A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver LEE KWEE YONG

NRIC/Passport Number S1480545A

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJH2117Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RAVIN DEV SIVARAJ
NRIC/Passport Number	S8806982Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:


26/8/18
Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling on PIE along Bendiner Rd and taking Exit suddenly the car in front of me got brake. I managed to stop behind in time but suddenly behind me bang into me and my car was push forward and then gently touch the car in front of me.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: 455-3986
Business Regn No : 269436/00J

6458 012A

*Not Authorized
Bill & A000/
Resurvey After Paint
Fclass*

31, May 2018

Auto & General Insurance (S) Pte Ltd
190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
S 239924

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle No: SGB6523A
Accident involving vehicle No: SJG2099Y/SGB6523A/SJH2117Z
DOA: 25/05/2018 AT PIE(tuas) near to Kallang Bendemeer Exit

Dear officer incharge
Re: estimate of repair for vehicle No: SJG2099Y
To supply--

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Description	Qty		Amount	
Rear bumper	1	<i>BALMA</i>	588.50	✓
Rear bumper retainer @54	2	<i>D/I</i>	108.00	✓
Bumper clip		<i>Na</i>	42.00	✓
Boot weather strip	1	<i>Na/Na</i>	121.60	<i>50.00 60.80</i>
End panel	1	<i>By</i>	306.40	✓
Taillamp @352.40	2	<i>OLSONA</i>	704.80	<i>LT</i>
Lid	1	<i>By</i>	903.40	✓
Lid lock	1	<i>Na</i>	198.60	✓
Lid-H logo	1	<i>Sw</i>	25.70	X
Lid-stream emblem	1	<i>Na</i>	38.50	✓
Front bumper	1	<i>By</i>	635.40	✓
Front bumper retainer @14.70	2	<i>D/I</i>	29.40	✓
Front grille	1	<i>CMA</i>	228.30	✓
Grille chrome	1	<i>Sw</i>	231.50	<i>X</i>
Front bumper enforcement	1	<i>R</i>	218.40	<i>X</i>
		Parts	4,380.50	
		Less 20%	876.10	
			3,504.40	

Vehicle No: SGB6523A

Reverse sensor

CM 220.00 ✓

To remove/transfer rear windscreen glass to new door.

180.00 *1200*

To remove front and rear damaged parts and attachments.

Straighten chassis frames where necessary

Repair/reshape dented/damaed areas.

1,000.00 *900*

Replace/align all parts into position.

1,100.00 *1000*

To spray paint.

6004.40



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18009855/Kvd3n2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 05-07-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGB 6523A	Veh. Inspected	SJG 2099Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10001625/JM	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	31/05/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA STREAM (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JHMRN68408S203868	Colour	METALLIC BLUE
Odometer	215816	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/50 R17	FALKEN	2 mm
L/H Front Tyre	215/50 R17	FALKEN	2 mm
R/H Rear Tyre	215/50 R17	FALKEN	2 mm
L/H Rear Tyre	215/50 R17	FALKEN	2 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/05/2018	Inspection Date	01/06/2018
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
--	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJG 2099Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BENT / CRACKED	588.50	588.50
2	REAR BUMPER RETAINER @\$54.00	DISTORTED	108.00	108.00
1	BUMPER CLIP	NECESSARY	42.00	42.00
1	END PANEL	BENT	306.40	306.40
2	TAILLAMP @\$352.40	O/S CRACKED	704.80	352.40
1	LID	BENT	903.40	903.40
1	LID LOCK	DENTED	198.60	198.60
1	LID-H LOGO	SERVICEABLE	25.70	-
1	LID-STREAM EMBLEM	NECESSARY	38.50	38.50
1	FRONT BUMPER	BUCKLED	635.40	635.40
2	FRONT BUMPER RETAINER @\$14.70	DISTORTED	29.40	29.40
1	FRONT GRILLE	CRACKED	228.30	228.30
1	GRILLE CHROME	SERVICEABLE	231.50	-
1	FRONT BUMPER ENFORCEMENT	TO REPAIR SEE LABOUR	218.40	-
	LESS 20% DISCOUNT		-851.78	-686.18
			3,407.12	2,744.72
1	BOOT WEATHER STRIP (50%)(SN)	DENTED / CUT	121.60	60.80
	LESS 20% DISCOUNT		-24.32	-
			97.28	60.80
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	CRACKED	220.00	220.00
			220.00	220.00
LABOUR				
	TO REMOVE/TRANSFER REAR WINDSCREEN GLASS TO NEW DOOR.		180.00	120.00
	TO REMOVE FRONT AND REAR DAMAGED PARTS AND ATTACHMENTS. STRAIGHTEN CHASSIS FRAMES WHERE NECESSARY. REPAIR/RESHAPE DENTED/DAMAGED AREAS. REPLACE/ALIGN ALL PARTS INTO POSITION. INCLUSIVE OF THE REPAIR OF FRONT BUMPER ENFORCEMENT.		1,000.00	900.00
	TO SPRAY PAINT.		1,100.00	1,000.00
			2,280.00	2,020.00

Report Ref No. CS/AGI18009855/Kvd3n2



GRAND TOTAL		6,004.40	5,045.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00

Report Ref No. CS/AGI18009855/Kvd3n2.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.